



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 1 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/SPS780 Internal
 COMPLAINT:
 01 GREENLIGHT SERVICE INSPECTION COMBINE

1938/1324 HRS

CORRECTION:

Labor: \$1,999.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,999.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/GLOPCLEANS780 Internal
 COMPLAINT:
 02 GREENLIGHT/RECONDITION CLEANING CHECKLIST
 INCLUDES SALES WASH DISCOUNT

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	0.00	-780.00	(\$780.00)	N
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N

Labor: \$2,160.00	Parts: \$0.00	OL&M: \$0.00	Misc: (\$684.00)	Sub-Total: \$1,476.00
--------------------------	----------------------	-------------------------	-------------------------	------------------------------

/101801401S780 Internal
 COMPLAINT:
 03 R&R CONCAVES. LEVEL, ADJUST, AND CALIBRATE (WITH ACI)

REMOVE MAD CONCAVES AND INSTALL FACTORY CONCAVES- SUPPLIED BY CUSTOMER

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 2 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/101801401S780 Internal

THE MAD CONCAVES WERE REMOVED FROM THE MACHINE. THE SMALL WIRE CONCAVES WERE THEN BROUGHT INSIDE AND THE #3 CONCAVE HAD SOME DAMAGE. THE DAMAGE WAS FIXED AND THE CONCAVES WERE THEN THROWN IN AND THE Z BAR WAS THEN ATTACHED. THE CONCAVES WERE THEN LIFTED UP AND PINNED TO THE CYLINDERS. THE CONCAVES WERE THEN LEVELED AND ADJUSTED. THE THRESHING CLEARANCE WAS THEN SET. THE SEPERATOR GRATES WERE REINSTALLED.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	61.07	61.07	\$61.07	N
Labor: \$1,017.75	Parts: \$0.00	OL&M: \$0.00	Misc: \$61.07	Sub-Total: \$1,078.82		

Gen5- Internal

COMPLAINT:
 05 REPLACE MISSING SHIELD FOR FRONT OF OVERSHOT BEATER

CORRECTION:
 RECEIVED SHIELDS FROM CUSTOMER, THERE WAS STILL A COUPLE MISSING. INSTALLED THE MISSING SHIELDS AND TIGHTEND DOWN THE MOUNTING HARDWARE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7298	Flange Nut M8	3.00	1.49	1.49	\$4.47	N
19M7866	Flange Head Cap Screw M8 X 20 GR10.9	5.00	1.78	1.78	\$8.90	N
AXE30254	Guard	1.00	529.25	529.25	\$529.25	N
HXE79256	Sheet	1.00	78.48	78.48	\$78.48	N
Labor: \$88.50	Parts: \$621.10	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$709.60		

/150311S780 Internal

COMPLAINT:
 06 READJUST LOADING AUGER ENGAGEMENT- BOUNCES WHEN RUNNING AT ALL SPEEDS

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 3 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/150311S780 Internal
 ADJUSTED AUGER.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43	

/510004S780 Internal
 COMPLAINT:
 07 REPLACE FEEDER HOUSE DRIVE CHAIN AND REAR IDLER
 OUT OF ADJUSTMENT

CORRECTION:
 REPLACED DRIVE CHAIN, TOOK OUT ONE FULL LINK AND ADDED HALF LINK. REPLACED IDLER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE19940	Idler Sprocket.	1.00	92.46	92.46	\$92.46	N
AXE80368	Feeder House Drive Chain #60 (181 Links)	1.00	315.69	315.69	\$315.69	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.78	4.78	\$4.78	N
Labor: \$79.65		Parts: \$408.15	OL&M: \$0.00	Misc: \$4.78	Sub-Total: \$492.58	

/101711501S780 Internal
 COMPLAINT:
 08 REPLACE RIGHT SIDE REVERSER SHAFT BEARING AND TONE WHEEL

CORRECTION:
 TOOK TWO SPEED GEARS OFF. TOOK SENSOR OFF. UNIDID THREE BOLTS THAT HOLD BEARING AND REMOVED BEARING. INSTALLED NEW BEARING AND TONE WHEEL, HELD SHAFT TIGHT TO RIGHT SIDE AND TIGHTENED TONE WHEEL. PUT SENSOR BACK ON AND TIGHTENED ALL THE BOLTS. INSTALLED TWO SPEED GEARS.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 4 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/101711501S780 Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE68018	Bearing With Housing	1.00	431.51	431.51	\$431.51	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$431.51		OL&M: \$0.00		Misc: \$26.55
Sub-Total: \$900.56						

/150032S780 Internal

COMPLAINT:
 09 REPLACE UPPER FEEDER HOUSE SPROCKETS
 REPLACE BEARINGS WHEN DOING

CORRECTION:

LOOSENED TENSION OFF CHAIN AND PULLED CHAIN OUT. PUT NUT CRACKER ON ALLAN KEYS ON SPROCKETS. TOOK CASTLE NUT OFF THE END OF THE SLIP CLUTCH OF SHAFT. PULLED SLIP CLUTCH OFF. REMOVED SHAFT WITH SPROCKETS. REMOVED SPROCKETS OFF SHAFT AND CLEANED. INSTALLED NEW SPROCKETS WITH NEW KEYS. REPLACED BEARINGS. PUT SHAFT BACK IN WITH SPROCKETS ON AND BEARINGS ON THE END OF SHAFT. TIGHTEN AND TORQUE BEARING HOUSING BOLTS. PUT KEYS ON SPROCKETS, WRAPPED INSTALLED CONVEYOR CHAIN AROUND SPROCKETS. INSTALLED SLIP CLUTCH ON THE END OF THE SHAFT, TORQUED CASTLE NUT AND PUT NEW COTTER PIN IN. SPUN CONVEYOR CHAIN AROUND SPROCKETS TO GET SPROCKETS CENTERED. TIGHTENED SET SCREWS AND TORQUED. TIGHTENED CONVEYOR CHAIN.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7025	Cotter Pin M4 X 63	1.00	0.94	0.94	\$0.94	N
H156580	Set Screw M12 x 16	16.00	5.79	5.79	\$92.64	N
H229470	Shaft Key	5.00	21.62	21.62	\$108.10	N
HXE123463	Feeder Chain Drive Sprocket 13 Teeth	4.00	245.54	245.54	\$982.16	N
JD10020	Ball Bearing	1.00	74.46	74.46	\$74.46	N
JD9373	Ball Bearing	1.00	68.93	68.93	\$68.93	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 2/19/2025	Location: 05	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: Account	Page: 5 of 24
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/150032S780 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	69.03	69.03	\$69.03	N
Labor: \$1,150.50		Parts: \$1,327.23	OL&M: \$0.00	Misc: \$69.03	Sub-Total: \$2,546.76	

/10171150S780 Internal
 COMPLAINT:
 10 R&R FEEDER HOUSE CONVEYOR CHAIN

CORRECTION:
 FED CHAIN THROUGH THE BOTTOM OF THE FEEDER HOUSE WITH RATCHET STRAPS. PULLED CHAIN AROUND SPROCKETS AND INSTALLED CONNECTORS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH220541	#CA557 Connector Link	4.00	23.71	23.71	\$94.84	N
AXE27247	Feeder Chain - 4 Strand	1.00	3,688.80	3,688.80	\$3,688.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$3,783.64	OL&M: \$0.00	Misc: \$26.55	Sub-Total: \$4,252.69	

/110050S780 Internal
 COMPLAINT:
 11 CHANGE OIL IN FEEDER HOUSE REVERSER

CORRECTION:
 DRAINED THE OIL FROM THE REVERSER GEARCASE AND THEN FILLED WITH NEW OIL TO THE PROPER LEVEL.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26408	946ML HD460 SYNTHETIC	4.00	49.37	49.37	\$197.48	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF15	ENVIRO FEE	4.00	0.15	0.15	\$0.60	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 6 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/110050S780 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$197.48	OL&M: \$0.00	Misc: \$4.85	Sub-Total: \$273.13	

/150428S780 Internal
 COMPLAINT:
 12 INSTALL FIRE EXTINGUISHER
 MISSING ON CAB LADDER AND WATER ENGINE BAY. CHECK WITH CUSTOMER BEFORE ORDERING
 *SALES TO CHECK WITH CUSTOMER

CORRECTION:
 THE FIRE EXTINGUISHERS WERE INSTALLED ONTO THE MACHINE.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	1.06	1.06	\$1.06	N
Labor: \$17.70		Parts: \$0.00	OL&M: \$0.00	Misc: \$1.06	Sub-Total: \$18.76	

/110081S780 Internal
 COMPLAINT:
 13 R&R SIEVE AND CHAFFER TO CHECK FOR CRACKS
 CORRECTION:
 REMOVED THE SIEVE AND CHAFFER ELEMENTS AND CHECKED BOTH THE ELEMENTS AND THE FRAMES FOR CRACKS OR ANY OTHER DAMAGES. ALL WAS GOOD. CLEANED OUT THE PRECLEANER. INSTALLED AND CALIBRATED THE ELEMENTS TO THE PROPER SPEC.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$562.86	



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 7 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/15114S780 Internal

COMPLAINT:

14 CLEAN DEBRIS FROM PRECLEANER

CORRECTION:

CLEANED DEBRIS FROM PRECLEANER

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81	

/120564S780 Internal

COMPLAINT:

15 REPLACE LEFT HAND TOP TAILINGS AUGER BEARING

CORRECTION:

REMOVED LOCK COLLAR, UNBOLTED BEARING HOLDER AND REMOVED BEARING OFF THE SHAFT. CLEANED SHAFT. INSTALLED NEW BEARING HOLDER AND BEARING. INSTALLED NEW LOCK COLLAR.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH129452	Eccentric Locking Collar	1.00	22.97	22.97	\$22.97	N
AH168161	Ball Bearing	1.00	84.16	84.16	\$84.16	N
E10018	Pressed Flanged Housing	2.00	7.38	7.38	\$14.76	N
Labor: \$265.50	Parts: \$121.89	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$403.32		

/110058S780 Internal

COMPLAINT:

16 REPLACE UNLOADING AUGER DRIVE CHAIN- NO ADJUSTMENT LEFT



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 8 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/110058S780 Internal

CORRECTION:
 REPLACED CHAIN AND TIGHTENED.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE79735	Roller Chain #80 (199 Links)	1.00	594.00	594.00	\$594.00	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$594.00	OL&M: \$0.00	Misc: \$4.25	Sub-Total: \$669.05	

GEN17- Internal
 COMPLAINT:
 17 FLIP DISK PADDLES ON ADVANCED POWERCAST SPREADER

CORRECTION:
 FLIPPED THE PADDLES ON THE ADVANCED POWER CAST TAILBOARD.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62	

GEN18- Internal
 COMPLAINT:
 18 WELD AND REPAIR SAFETY LOOP ON TAILBOARD

CORRECTION:
 REMOVED THE SAFETY LOOP FROM THE MACHINE. THE AREA THAT NEEDED REPAIR WAS CLEANED UP AND PREPPED. THE BROKEN PIECE WAS THEN WELDED ON TO THE SAFETY LOOP. THE WELD WAS THEN CLEANED UP AND PAINTED. THE SAFETY LOOP WAS INSTALLED.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 9 of 24
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

GEN18- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N		
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62				

/1703160S780 Internal
 COMPLAINT:
 19 REPLACE OUTSIDE LOWER STRAWCHOPPER DRIVE BELT - PEELING

CORRECTION:
 DONE UNDER SEGMENT 20

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE124869	Chopper Drive Belt (2HC)	1.00	780.25	780.25	\$780.25	N
Labor: \$0.00	Parts: \$780.25	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$780.25		

/101720200S780 Internal
 COMPLAINT:
 20 R&R STRAW CHOPPER JACKSHAFT BEARINGS

CORRECTION:





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 10 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/101720200S780 Internal

REMOVED THE TAIL BOARD PUMP SHIELD. REMOVED THE PUMP MOUNTING HARDWARE AND THEN SLUNG THE PUMP UP OUT THE WAY USING A STRAP. REMOVED THE TENSIONER COMPONENTS FROM THE JACKSHAFT THEN INSTALLED THE REMOVAL TOOL. REMOVED ALL MOUNTING HARDWARE AND BELTS. THEN LOWERED THE GEARCASE DOWN. REMOVED THE PULLEYS FROM THE SHAFT AND THEN REMOVED THE BEARINGS AND SHAFT FROM THE HOUSING. CLEANED THE OLD GREASE FROM THE HOUSING. INSTALLED NEW BELT

INSTALLED ONE OF THE BEARINGS AND FOUND THAT IT WAS NOT TIGHT IN THE HOUSING. PEENED THE HOUSING THEN INSTALLED THE BEARING FOR A TIGHTER FIT SO THAT THE OUTER RACE WOULD NOT SPIN. INSTALLED THE SHAFT. FILLED THE HOUSING WITH THE PROPER GREASE THEN INSTALLED THE OTHER BEARING. OPENED ONE OF THE PLUGS AND PUT SOME GEAR OIL IN THE HOUSING.

INSTALLED AND TORQUED DOWN BOTH SHEAVES. LIFTED THE JACKSHAFT INTO PLACE AND INSTALLED ALL THE MOUNTING HARDWARE. TORQUED ALL HARDWARE TO THE PROPER SPEC. INSTALLED ALL THE BELTS AND THE PUMP. ADJUSTED THE TENSION ON ALL THE BELTS ON THE JACKSHAFT.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7533	Hex Nut M30	1.00	23.78	23.78	\$23.78	N
AH221427	Ball Bearing	1.00	187.87	187.87	\$187.87	N
AH221431	Ball Bearing	1.00	357.02	357.02	\$357.02	N
AN102562	CORN HEAD GREASE	2.00	10.10	10.10	\$20.20	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	55.76	55.76	\$55.76	N

Labor: \$929.25 Parts: \$588.87 OL&M: \$0.00 Misc: \$55.76 Sub-Total: \$1,573.88

/10180200S780 Internal

COMPLAINT:
 21 RECONDITION ROTOR VARIABLE DRIVE

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 11 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/10180200S780 Internal

DRAINED THE OIL FROM THE MAIN ENGINE GEARCASE AND THE BELL HOUSING FOR THE ROTOR VARIABLE DRIVE. REMOVED TENSION FROM THE ROTOR DRIVE BELT AND REMOVED IT FROM THE MACHINE. REMOVED HOSE CLAMPS FROM THE AREA AROUND THE VARIABLE DRIVE AND THEN MOVED THE HOSES OUT OF THE WAY OF THE VARIABLE DRIVE. INSTALLED A LIFT STRAP AND THE CRANE TO THE ASSEMBLY. REMOVED ALL HARDWARE HOLDING THE DRIVE TO THE MAIN ENGINE GEARCASE. THEN REMOVED THE DRIVE.

ONCE ON THE GROUND THE PISTON WAS REMOVED FROM THE SHEAVES. THERE WAS OIL WITHIN THE GREASE HOUSING. REMOVED ALL SEALS FROM THE PISTON AND INSTALLED NEW SEALS. THE SHEAVES WERE THEN REMOVED AND GREASE WAS FOUND ON THE INNER AREA OF THE SHEAVES. THIS WAS CLEANED UP AND THE NEW GREASE SEALS WERE INSTALLED. THE OIL SEAL ON THE BELL HOUSING WAS THEN REMOVED AND REPLACE. THE SHEAVES WERE THEN REINSTALLED ON THE SHAFT. THE PISTON WAS THEN REINSTALLED ON THE SHEAVES. THE HARDWARE WAS THEN ALL TIGHTENED DOWN SO THERE WOULD BE NO MOVEMENT OF THE SHEAVES UPON INSTALLATION.

THE ASSEMBLY WAS THEN LIFTED INTO PLACE AND INSTALLED ONTO THE MAIN ENGINE GEARCASE. THE MOUNTING HARDWARE WAS THEN ALL INSTALLED AND TORQUED TO SPEC. THE THREE SHORT BOLTS ON THE RIGHT HAND SIDE OF THE HOUSING WERE SEALED USING THREAD SEALANT TO AVOID ANY LEAKAGE. THE CROSS MEMBER WAS THEN INSTALLED, THE PIN WAS THEN INSTALLED IN THE EYE OF THE CROSS MEMBER WITH THE WASHER AND COTTER PIN. THE NUTS ON THE OPPOSITE END WERE THEN TIGHTENED UP. THE BELT WAS THEN INSTALLED AND GAP WAS SET TO 8 MM.

THE NUT ON THE END OF THE DRIVE WAS THEN TORQUED TO SPEC OF 227 LB FT THE PISTON BOLTS WERE THEN ALSO TORQUED TO SPEC OF 52 LB FT. THE GAP WAS THEN CHECKED AGAIN, ALL WAS GOOD.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH136497	SEAL	1.00	48.70	48.70	\$48.70	N
AH144147	SEAL	1.00	43.35	43.35	\$43.35	N
AH144149	SEAL	1.00	99.90	99.90	\$99.90	N
AHC11303	Seal Kit	1.00	187.50	187.50	\$187.50	N
H150693	O-RING	1.00	32.35	32.35	\$32.35	N
R1225R	O-Ring	2.00	7.43	7.43	\$14.86	N
R26543	O-RING	1.00	18.05	18.05	\$18.05	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 12 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/10180200S780 Internal

R89326	SEAL	1.00	33.11	33.11	\$33.11	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,947.00		Parts: \$477.82		OL&M: \$0.00		Misc: \$96.00
				Sub-Total: \$2,520.82		

/1415781S780 Internal

COMPLAINT:
22 REPLACE DEBRIS MANAGEMENT BLOWER DRIVE BELT IDLERS

CORRECTION:
TOOK BOTH PULLEYS OFF AND REPLACED BEARINGS, INSTALLED AND PUT BELT BACK ON.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
JD29980	Ball Bearing	2.00	8.79	8.79	\$17.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.12	2.12	\$2.12	N
Labor: \$35.40		Parts: \$17.58		OL&M: \$0.00		Misc: \$2.12
				Sub-Total: \$55.10		

/170711S780 Internal

COMPLAINT:
23 REPLACE RUBBER MOUNT BUSHING FOR OVERSHOT BEATER GEARCASE

CORRECTION:
REMOVED THE OLD ISOLATOR BUSHING. THE NEW BUSHING BOTH AND SPRING WERE THEN ALL INSTALLED.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
24H1351	WASHER	2.00	3.66	3.66	\$7.32	N
24M7207	Washer	1.00	0.74	0.74	\$0.74	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 13 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/170711S780 Internal

GX21790	Hex Shoulder Bolt M8 X 63.5	1.00	26.77	26.77	\$26.77	N
H81462	Compression Spring	1.00	10.42	10.42	\$10.42	N
T41770	Isolator	1.00	79.96	79.96	\$79.96	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N

Labor: \$53.10 Parts: \$125.21 OL&M: \$0.00 Misc: \$3.19 Sub-Total: \$181.50

/10172010S780 Internal

COMPLAINT:
 24 R&R STRAW CHOPPER HAMMERS- WORN

CORRECTION:
 REMOVED AND REPLACED CHOPPER HAMMERS WITH NEW HARDWARE, TORQUED BOLTS TO SPEC.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE118760	Lock Nut M10	24.00	2.73	2.73	\$65.52	N
HXE119246	Hex Head Bolt M10 X 55	24.00	5.61	5.61	\$134.64	N
KXE10255	Knife Kit	5.00	405.98	405.98	\$2,029.90	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N

Labor: \$531.00 Parts: \$2,230.06 OL&M: \$0.00 Misc: \$31.86 Sub-Total: \$2,792.92

/140854S780 Internal

COMPLAINT:
 25 TURN STRAW CHOPPER STATIONARY KNIVES

CORRECTION:
 REMOVED THE BANK AND FLIPPED ALL THE KNIVES.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 2/19/2025	Location: 05	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: Account	Page: 14 of 24
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/140854S780 Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$0.00	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$140.72	

/140319AS780 Internal

COMPLAINT:
 26 R&R DRIVEN CLEANING FAN SHEAVE, INSPECT, REPLACE OUTER SHEAVE AND PINS

CORRECTION:
 REMOVED THE OUTER SHEAVE AND DRIVE BELT. THEN REMOVED THE INNER SHEAVE. REMOVED THE BEARING AND FROM THE OLD SHEAVE AND CHECKED IT TO MAKE SURE IT DIDN'T NEED TO BE REPLACED. THE BEARING WAS GOOD. HAMMERED OUT THE OLD PINS AND THEN INSTALLED THE NEW ONES IN THE INNER SHEAVE. REINSTALLED THE INNER SHEAVE AND TORQUED THE HARDWARE TO SPEC. INSTALLED THE BELT AND OUTER SHEAVE, THEN SET THE BELT TO WHERE IT WAS WHEN IT WAS REMOVED.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE40934	Half Sheave, Outer Fan Drive	1.00	1,142.12	1,142.12	\$1,142.12	N
R1964R	Dowel Pin	3.00	42.96	42.96	\$128.88	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	18.59	18.59	\$18.59	N
Labor: \$309.75		Parts: \$1,271.00	OL&M: \$0.00	Misc: \$18.59	Sub-Total: \$1,599.34	

/120562S780 Internal

COMPLAINT:
 27 REPLACE RETHRESHER DRIVE CHAIN IDLERS

CORRECTION:
 TOOK OLD IDLERS OFF AND REPLACED WITH NEW



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 15 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/120562S780 Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE23133	Idler Sprocket 15 Teeth	2.00	89.63	89.63	\$179.26	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	6.90	6.90	\$6.90	N
Labor: \$115.05		Parts: \$179.26		OL&M: \$0.00		Misc: \$6.90
						Sub-Total: \$301.21

/150217S780 Internal

COMPLAINT:
 28 REPLACE ROTARY SCREEN IDLER PULLEY- UPPER OUTER PULLEY

CORRECTION:
 REMOVED BELT, REMOVED IDLER, INSTALLED NEW IDLER. PUT BELT BACK ON

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH169549	Center Sheave	1.00	77.90	77.90	\$77.90	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$77.90		OL&M: \$0.00		Misc: \$3.19
						Sub-Total: \$134.19

/110071S780 Internal

COMPLAINT:
 29 REMOVE HALF LINK FROM CLEAN GRAIN PADDLE CHAIN AND ADJUST

CORRECTION:
 ADJUSTED CHAIN.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 16 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/110071S780 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81	

/110057S780 Internal
 COMPLAINT:
 30 REMOVE HALF LINK FROM TAILINGS PADDLE CHAIN AND ADJUST

CORRECTION:
 ADJUSTED CHAIN.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81	

/100700S780 Internal
 COMPLAINT:
 31 REPLACE HYDRAULIC FILTERS

CORRECTION:
 REMOVED AND REPLACED ALL HYDRAULIC FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH128449	Hydraulic Oil Filter	1.00	142.87	142.87	\$142.87	N
AN207368	Hydraulic Oil Filter Element	1.00	189.06	189.06	\$189.06	N
N309233	O-Ring	1.00	27.13	27.13	\$27.13	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 2/19/2025	Location: 05	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: Account	Page: 17 of 24
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/100700S780 Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N	
Labor: \$132.75		Parts: \$359.06		OL&M: \$0.00		Misc: \$9.97	
					Sub-Total: \$501.78		

/170607S780 Internal
 COMPLAINT:
 32 REPLACE HYDRAULIC FILTER IN RESERVOIR

CORRECTION:
 UNIDID TOP COVER AND CHANGED FILTER. TIGHTENED COVER DOWN. WROTE HOURS ON TOP.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
A52523	Ring	1.00	25.49	25.49	\$25.49	N	
AXE12964	Hydraulic Oil Reservoir Filter	1.00	172.24	172.24	\$172.24	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N	
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
Labor: \$88.50		Parts: \$197.73		OL&M: \$0.00		Misc: \$6.31	
					Sub-Total: \$292.54		

/120000S780 Internal
 COMPLAINT:
 33 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 CHANGED THE ENGINE OIL AND FILTER AND MARKED HOURS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE527285	Engine Oil Filter	1.00	146.95	146.95	\$146.95	N
TY26673	3.78L 15W40 PLUS 50 II	1.00	37.78	37.78	\$37.78	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 18 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/12000S780 Internal		Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26674	946ML 15W40 PLUS 50 II	2.00	9.92	9.92	\$19.84	N
TY26679	18.9L 15W40 PLUS 50 II	2.00	170.86	170.86	\$341.72	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF15	ENVIRO FEE	2.00	0.15	0.15	\$0.30	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$546.29	OL&M: \$0.00	Misc: \$15.77	Sub-Total: \$694.81	

/120018S780 Internal
 COMPLAINT:
 34 REPLACE FUEL FILTERS, AND CLEAN FUEL PRE-SCREEN

CORRECTION:
 TURNED FUEL OFF AND UNIDID PRE CLEANER, CLEANED SCREEN. CHANGED FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	228.91	228.91	\$228.91	N
DZ130550	Primary Engine Fuel Filter	1.00	225.31	225.31	\$225.31	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$454.22	OL&M: \$0.00	Misc: \$9.97	Sub-Total: \$596.94	

/141887S780 Internal
 COMPLAINT:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 19 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/141887S780 Internal
 35 CLEAN DEBRIS MANAGEMENT FILTER

CORRECTION:
 BLEW OUT FILTER AND REINSTALLED.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31
Sub-Total: \$93.81						

/120007S780 Internal
 COMPLAINT:
 36 CLEAN ENGINE AIR FILTERS

CORRECTION:
 BLEW OUT ENGINE AIR FILTER.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$0.00		OL&M: \$0.00		Misc: \$7.97
Sub-Total: \$140.72						

/150029S780 Internal
 COMPLAINT:
 37 REPLACE CAB FILTERS AND CLEAN PLASTIC GRATE

CORRECTION:
 REPLACED FILTER AND CLEANED PLASTIC GRATE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
L214634	Cab Ricirculation Air Filter	1.00	48.62	48.62	\$48.62	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 20 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/150029S780 Internal

TA32591	Cab Fresh Air Filter	1.00	135.85	135.85	\$135.85	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$184.47		OL&M: \$0.00		Misc: \$3.19
				Sub-Total: \$240.76		

/120518S780 Internal

COMPLAINT:
 38 CHANGE OIL IN MAIN ENGINE GEARCASE - NOT MARKED

CORRECTION:
 DRAINED OIL AND FILLED UP TO SPEC. RAN THE MACHINE AND THEN TOPPED UP OIL LEVELS RAN AGAIN AND LET SIT.
 CHECKED THE OIL LEVEL AND TOPPED IT BACK UP.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AR69444	18.9L HYGARD HYD/TRANS OIL J20C	2.00	158.46	158.46	\$316.92	N
TY22062	9.46L HYGARD HYD/TRANS OIL J20C	1.00	85.28	85.28	\$85.28	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$402.20		OL&M: \$0.00		Misc: \$20.28
				Sub-Total: \$643.73		

/142606S780 Internal

COMPLAINT:
 39 REPLACE FILTERS FOR DEF PUMP AND TANK

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 21 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/142606S780 Internal

UNHOOKED ALL COOLANT LINES AND DEF LINES TO HEADER. UNIDID SCREWS. PULLED HEADER OUT OF TANK. REMOVED FILTER, INSTALLED NEW FILTER. HOOKED UP ALL THE LINES AND PUT COVER ON. CHANGED CANISTER FILTER. PURGED COOLANT LINES AND DEF LINES.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ111004	DEF Tank Header Filter Kit	1.00	113.84	113.84	\$113.84	N
DZ114640	DEF Injection Pump Filter Kit	1.00	251.39	251.39	\$251.39	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	23.90	23.90	\$23.90	N
Labor: \$398.25		Parts: \$365.23		OL&M: \$0.00		Misc: \$24.90
						Sub-Total: \$788.38

/110049S780 Internal

COMPLAINT:
 40 CHANGE OIL IN PRIMARY COUNTERSHAFT GEARCASE AND RINSE OUT GEAR CASE - RUSTY

CORRECTION:
 FILLED THE GEARCASE WITH A BOTTLE OF VARSOL TO CLEAN UP THE HOUSING AND SPUN IT OVER A FEW TIMES BEFORE LETTING SIT FOR A BIT. DRAINED THE HOUSING AGAIN. WHEN THE GEARCASE WAS FINISHED DRAINING FILLED WITH GEAR OIL TILL ALL THE CLEANER HAD RUN OUT THEN CLOSED THE DRAIN AND CONTINUED FILLING. FILLED UP TO THE PROPER LEVEL.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6296	946ML 80W90 GL-5	2.00	15.99	15.99	\$31.98	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$31.98		OL&M: \$0.00		Misc: \$11.62
						Sub-Total: \$220.60



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 22 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

GEN41- Internal

COMPLAINT:
 41 TOP UP COOLANT AND PRESSURE TEST SYSTEM

CORRECTION:
 TOPPED UP COOLANT AND PRESSURE TESTED. DID NOT LOOSE PRESSURE OVER 2 HOURS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26576	9.46L COOL-GARD PREMIX	1.00	61.79	61.79	\$61.79	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF240	ENVIRO FEE	1.00	2.40	2.40	\$2.40	N
SERVACCESS	SERVICE ACCESSORIES	1.00	13.81	13.81	\$13.81	N
Labor: \$230.10		Parts: \$61.79	OL&M: \$0.00	Misc: \$16.21	Sub-Total: \$308.10	

/110312S780 Internal

COMPLAINT:
 42 REMOVE CUSTOMER DATA/ SOFTWARE

CORRECTION:
 BACKED UP ALL CUSTOMER DATA ONTO AN EXTERNAL DRIVE. THEN FACTORY RESET THE DISPLAY

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25		Parts: \$0.00	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$46.91	

/170538S780 Internal

COMPLAINT:
 43 ADJUST ALL BELTS AND CHAINS AS PER IS DEPT GUIDELINES

CORRECTION:
 ADJUSTED ALL BELTS AND CHAINS.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 23 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/170538S780 Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62	

/120014S780 Internal

COMPLAINT:

44 GREASE COMBINE

CORRECTION:

GREASED THE MACHINE



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.54	10.54	\$10.54	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

SOUTH COUNTRY
 E Q U I P M E N T



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 05 Work Order Number: [REDACTED] Payment Type: Account Page: 24 of 24
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD S780 COMBINE		1H0S780SHJ0800812	1H0S780SHJ0800812	#4

/120014S780 Internal	SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$10.54	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$198.16		

Customer PO No: Tax Exempt No: Advisor: [REDACTED]

Labor: \$15,513.55
Parts: \$15,846.46
OL&M: \$0.00
Misc: (\$3.99)
Grand Total: \$31,356.02

*** DOCUMENT COPY ***



GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1		148139	USED AG EQUIPMENT
05	40	382	1		815797	INTERNAL LABOR-AG
00	00	178	15		815797	WORK IN PROCESS PARTS -MJ
05	40	482	1		815797	COS INTERNAL LABOR-AG
05	40	398	1		815797	PROMOTIONS-WASHING
05	40	544	1		815797	SUPPLIES EXPENSE
05	30	366	2		815797	JD PARTS-COUNTER
00	00	166	5		815797	JD PARTS-MOOSE JAW
05	30	375	3		815797	PARTS SPECIAL HANDLING
07	30	375	3		815797	PARTS SPECIAL HANDLING
05	30	466	2		815797	JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: