

Syrnyk HD Service

RR 4 COMP 94

Dauphin MB R7N 2T7

2046381818

Parklandhd@hotmail.ca

GST/HST Registration No.:

823461637RT0001

PST MB Registration No.:

823461637MT001

**Invoice**

BILL TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
8101	12-01-2026	\$11,804.86	12-01-2026	Due on receipt	

YEAR/MAKE/MODEL/UNIT

2005 FL Columbia CL-120

MILEAGE

1,030,766 km

VIN

1FUJA6CV65LU09789

ACTIVITY	QTY	RATE	AMOUNT
SERVICES:MANITOBA OVER 4500KG INSPECTION			
MANITOBA OVER 4500KG INSPECTION	4	152.00	608.00
SALES			
31-22 anco wiper blades 22"	2	7.63	15.26
SALES			
38597SH GREEN STRIPE ALLIGN BELT TENSIONER	1	310.97	310.97
SALES			
FAN CLUTCH CORE RETURNED	1	-800.00	-800.00
SAFETY/WHEELS:THUB-858SS - Hubcap			
8" Stainless Steel Rear Dome Hubcap (Office)	4	20.60	82.40
Subcontractor			
R+R DRIVER'S WINDSHIELD	1	132.00	132.00
SALES			
SET427 MILEMATE SET	2	112.15	224.30
SALES			
SET428 MILEMATE SET	2	81.38	162.76
SALES			
P7230SH LUBE ELEMENT	1	64.85	64.85
SALES			
PA4857SH CAB AIR FILTER	1	44.54	44.54
SALES			
PF7761SH FUEL FILTER	1	57.74	57.74

ALL INVOICES ARE TO BE PAID IN FULL BEFORE VEHICLE IS TAKEN OFF THE PROPERTY

OVERDUE ACCOUNTS WILL BE CHARGED 2% INTEREST PER MONTH (24% PER ANNUM)

ACTIVITY	QTY	RATE	AMOUNT
SALES RS3518SH RADIAL SEAL OUTER AIR ELEMENT	1	171.90	171.90
SALES PF7748SH FUEL WATER SEPARATOR	1	48.93	48.93
U JOINTS:5-103X - U Joint Spicer U Joint	2	24.35	48.70
OIL:15W40 Rotella 15W40 Oil Per Liter	40	7.00	280.00
LIGHTS:GRO G3003 - Light 2" LED Amber Clearance Lamp	3	10.65	31.95
LIGHTS:GRO G3002 - Light 2" LED Red Clearance Lamp	1	10.65	10.65
SEALS:11Y47672 - Seal Timken Drive Axle Seal *2 Piece* Stemco #: 392-9131	2	89.66	179.32
SEALS:10P35000 - Seal Timken Front Axle Seal *1 Piece* Stemco #: 382-8036	2	74.38	148.76
OIL:80W90 FLUIDS 80W90 GEAR OIL PER LITRE	38	8.30	315.40
BEARINGS:SET401 - Bearing Timken Bearing Cone & Cup Set (572/580 Set)	2	78.30	156.60
BEARINGS:SET403 - Bearing Timken Bearing Cup and Cone Set (592A/594A Set)	2	91.70	183.40
FLUIDS:50 WEIGHT TRANS FLUID 50 WEIGHT TRANS FLUID	18.70	14.38	268.91
SERVICES:TIRE REPAIR Front steer replace both	2	49.00	98.00
SERVICES:HEAVY EQUIPMENT REPAIRS Troubleshooting and testing transmission shifting issues , rebuild ground and power harness , test tcm ok , test shifter , ok , poor ground and power harness, starter causing excess draw	8	152.00	1,216.00
SERVICES:HEAVY EQUIPMENT REPAIRS R+R STARTER	2.50	152.00	380.00
SERVICES:HEAVY EQUIPMENT REPAIRS REMOVE DRIVESHAFT	0.30	152.00	45.60
SERVICES:HEAVY EQUIPMENT REPAIRS R+R FRONT DRIVE AXLE WHEEL BEARINGS	4	152.00	608.00
SERVICES:HEAVY EQUIPMENT REPAIRS R+R REAR AXLE AIR BAGS	2.50	152.00	380.00
SERVICES:HEAVY EQUIPMENT REPAIRS Drain/Refill front and rear differential oils	0.80	152.00	121.60
SERVICES:HEAVY EQUIPMENT REPAIRS R+R kingpins	4	152.00	608.00

ALL INVOICES ARE TO BE PAID IN FULL BEFORE VEHICLE IS TAKEN OFF THE PROPERTY

OVERDUE ACCOUNTS WILL BE CHARGED 2% INTEREST PER MONTH (24% PER ANNUM)

ACTIVITY	QTY	RATE	AMOUNT
SERVICES:HEAVY EQUIPMENT REPAIRS R+R tie	2.20	152.00	334.40
Rod ends left/right Set toe			
SERVICES:HEAVY EQUIPMENT REPAIRS R+R front steer brake shoes	1	152.00	152.00
SERVICES:HEAVY EQUIPMENT REPAIRS R+R front headlight assemblies left/right	1	152.00	152.00
SERVICES:HEAVY EQUIPMENT REPAIRS Repair battery box aluminum welding	3	152.00	456.00
SERVICES:HEAVY EQUIPMENT REPAIRS R+R PTO U-JOINTS	1.50	152.00	228.00
SERVICES:HEAVY EQUIPMENT REPAIRS Install battery hold down	0.80	152.00	121.60
SERVICES:HEAVY EQUIPMENT REPAIRS Repair lighting roof , box front right , clean box tubing "mouse nest wiring damaged " run new harness from left rear corner to middle light , replace rear middle rear light	2.70	152.00	410.40
SERVICES:HEAVY EQUIPMENT REPAIRS Replace exhaust tip	0.50	152.00	76.00
SERVICES:HEAVY EQUIPMENT REPAIRS Mount fire extinguisher/ replace right door mirror	0.40	152.00	60.80
SERVICES:HEAVY EQUIPMENT REPAIRS Repair drivers door window fuse poor connection	0.50	152.00	76.00
SERVICES:HEAVY EQUIPMENT REPAIRS Drain and fill transmission	0.50	152.00	76.00
SERVICES:HEAVY EQUIPMENT REPAIRS Service unit grease	2.20	152.00	334.40
SERVICES:HEAVY EQUIPMENT REPAIRS R+R fan clutch assembly	5	152.00	760.00
SERVICES:HEAVY EQUIPMENT REPAIRS R+R fan tensioner	0.50	152.00	76.00
Shop Supplies shop supplies consumables base rate	4	19.50	78.00
SERVICES:Shipping heavy box WPG 150 LBS FOR FAN CLUTCH ASSY AND TO RETURN CORE	2	94.25	188.50
Shipping small BRD or WPG FREIGHT TO SUPPLIER (HEADLIGHTS, AIRBAGS, KING PINS, TIE RODS, EXHAUST STACK)	1	71.50	71.50
Shipping small BRD or WPG SMALL PACKAGE FOR MIRROR FOR STARTER FOR FAN CLUTCH ASSY TO SUPPLIER FOR BEARINGS	4	71.50	286.00
Shipping Skid "Mb" Skid	1	165.00	165.00
BRAKES:WK4702Q-23KW - Shoes 15X4 Merit Style Brake Shoe Kit	2	132.65	265.30

ALL INVOICES ARE TO BE PAID IN FULL BEFORE VEHICLE IS TAKEN OFF THE PROPERTY

OVERDUE ACCOUNTS WILL BE CHARGED 2% INTEREST PER MONTH (24% PER ANNUM)

SUBTOTAL	10,572.44
GST @ 5%	528.67
PST (MB) @ 7%	703.75
TOTAL	11,804.86
BALANCE DUE	\$11,804.86

ALL INVOICES ARE TO BE PAID IN FULL BEFORE VEHICLE IS TAKEN OFF THE PROPERTY

OVERDUE ACCOUNTS WILL BE CHARGED 2% INTEREST PER MONTH (24% PER ANNUM)