



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 03
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
FREIGHT		FREIGHT	1	20.00	20.00
Q3959		GIB KEY 3/8X4.5	2 N	22.40	44.80
1500-30		PIN COT 5/16X2-	4	.95	3.80
286909		BEARING, BALL	4 O	62.54	250.16
				PARTS	318.76
				LABOR	620.00
13300056			SEGMENT TOTAL==>		938.76

SEGMENT# 3 C 05396 NA 07/25/22 07/25/22

2- REPALCE ALL 3 FEEDER WEAR PLATES AND BOLTS

2.00 HRS

CORRECTION:

- loosen off feeder chain
- unbolted and removed old feeder chain wear plates
- put in and aligned new feeder chain wear plates and tighten down
- retighten up feeder chain to spec
- clean up tools

FREIGHT	FREIGHT	1	20.00	20.00
SH310203	3/8 FLANG NUT	5	.14	.70
247780	FLANGE NUT 3/8	1	.45	.45
86624124	SCREW, SER	6	3.70	22.20
87299946	KIT, SHAKER BUSH	1 N	631.13	631.13
87523833	SUPPORT	1 N	131.00	131.00
87523842	SUPPORT	1 N	69.75	69.75
87530580	SUPPORT	1 N	33.79	33.79
87613203	WASHER	6 N	5.95	35.70
			PARTS	944.72
			LABOR	310.00
13300056		SEGMENT TOTAL==>		1254.72

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 04
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	HAJ304834	
	2588	X			

SEGMENT# 4 C 05396 NA 07/25/22 07/25/22

2- BEATER BLADES SHOULD BE ADJUSTED - MAY BE MAXED OUT 1.00 HRS

CORRECTION:

- opened up rock trap to see beater blades
- noticed still had alot of adjustment left to them
- slid beater blades out and tighted back up
- cleaned up tools

13300056

LABOR	155.00
SEGMENT TOTAL==>	155.00

SEGMENT# 5 C 05396 NA 07/25/22 07/25/22

3- FEEDER DRIVE GEAR BOX HUB AND CROSS SHAFT WORN OUT 5.00 HRS

CORRECTION:

- drained hydraulic system
- removed hydraulic hoses
- unhook hydraulic cylinder
- unbolted gear box from feeder house
- removed gear box
- removed hydraulic motor from gear box
- un bolted two half's of gear box
- split gear box
- removed big gear out of gear box
- removed slip gears from gear box
- pressed new bearings on to new big gear
- put new seals on bearing holders for big gear
- put apart slip gear assemble
- replaces cone bearings and support bearings on slip gear
- put slip gear back in to gear box
- put big gear back in to gear box
- cleaned up sealing surfaces on both half's of gear box

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 05
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold -
052881	2588	COMBINE	1580	HAJ304834	

2588

X

- sealed and bolted the two half's back together
- clean sealing surfaces on the hydraulic motor and where it mounts to gear case
- sealed and bolted on hydraulic motor
- removed pully off of cross shaft on right hand side
- removed right side bearing
- unbolted and removed bearing from feeder house
- removed cross shaft
- in stalled new cross shaft
- installed new bearings on cross shaft and bolted in to place
- put new spacing collar on to cross shaft
- put new retaining clip on cross shaft
- spun spacing collar out to it was pressed against retaining clip and tighten down set screw
- mounted gear box back on to combine
- hooked up hydraulic lines
- reattached hydraulic cylinder
- filled gear case with hydraulic oil as box says
- refilled hydraulic system
- cleaned up tools

ADDITIONAL DESCRIPTION:

REPLACE HUB, CROSS SHAFT, BEARINGS AND GEAR BOX SEALS

FREIGHT	FREIGHT	3	18.98	56.95
132709	CUP	2 N	8.21	16.42
132710	BEARING, CONE	2 N	14.64	29.28
163024	SEAL	2 N	18.15	36.30
253462A1	RING, SPECIAL	1 N	46.62	46.62
253469A1	COLLAR	1 N	237.44	237.44
253533A1	HUB	1 N	104.21	104.21

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 06
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588 COMBINE	1580	H4J304834			
	2588	X				
330052	BEARING, B	1 N	48.47		48.47	
388771A1	SHAFT	1 N	722.15		722.15	
609654R91	BEARING, BALL	1 M	65.40		65.40	
681627	GEAR	1 N	1075.00		1075.00	
681631	HOUSING	1 N	590.00		590.00	
781754	RING	2 N	30.98		61.96	
86575514	BEARING, BALL	1	162.49		162.49	
87304415	SET SCREW 3/8	5 N	4.30		21.50	
87591960	BEARING, BALL	2 N	45.79		91.58	
9707565	PIN, GROOV	2 N	10.06		20.12	
			PARTS		3385.89	
			LABOR		775.00	
13300056			SEGMENT TOTAL==>		4160.89	

SEGMENT# 6 C 05396 NA 07/25/22 07/25/22

3- CHANGE ECCENTRIC ARM BEARINGS

2.50 HRS

CORRECTION:

- removed eccentric arms from combine
- removed snap rings from center hubs
- pressed center hub out
- removed snap ring holding bearing in to eccentric arms
- press baring out
- pressed new bearings in
- reinstall snap ring
- press center hubs back in
- re install snap ring that holds it in
- cleaned up tools

47509176	BEARING HIGH SP	2	192.24	384.48
			PARTS	384.48
			LABOR	387.50

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 07
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588 COMBINE	1580	HAJ304834			
	2588	X				
13300056				SEGMENT TOTAL==>	771.98	

SEGMENT# 7 C 05396 NA 07/25/22 07/25/22
3- CHANGE SHAKER ARM BEARINGS - RHS ALREADY COLLAPSED 8.00 HRS

CORRECTION:

- remove straw blowers off back
- remove upper sieves
- remove lower sieves
- remove drive belts for shaker decks
- remove slip clutch pulley assemblies to get at right side essentric arm
- removed back right shaker arms
- measured the stick out each bushing
- pressed out the old bushings
- pressed in new bushing to measured depth
- remount shaker arms
- removed left rear shaker arms
- measured stick out of bushing
- pressed old bushing out
- pressed new bushing in to measured depth
- remount shaker arms back on to combine
- removed front left shaker arms
- measured stick out of bushing
- pressed old bushing out
- pressed new bushing in to shaker arms to measured depth
- remounted shaker arms to combine
- removed front right shaker arms
- measured stick out of bushings
- pressed old bushing out
- pressed new bushings in till at measured depth

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 08
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold -
052881	2588	COMBINE	1580	HAJ304834	
	2588		X		
- remounted on to combine - remount lower sieves in to combine - remount upper sieves - reinstall straw spreaders - reinstall slip clutch pulleys - reinstall drive belt and processing belts - clean up tools					
<u>ADDITIONAL DESCRIPTION:</u>					
RESHIM SHAKER FRAME ONCE BACK TOGETHER					
87613198	WASHER	2 N	3.10	6.20	
87613199	WASHER	5 N	.97	4.85	
		PARTS		11.05	
		LABOR		1240.00	
13300056		SEGMENT TOTAL==>		1251.05	

SEGMENT# 8 C 05396 NA 07/25/22 07/25/22
3- REPLACE SUPPORT ASSEMBLY BEARINGS 5.00 HRS

CORRECTION:

- remove support arms on each side and brackets
- pressed out support arm pins
- pressed in new support arm pins
- removed old needle bearings from support arm brackets
- pressed new needle bearings in to support arm brackets
- put new seals in support arm brackets
- reinstall support arm brackets on to combine
- reinstall support arms in to brackets
- reinstall washer spacers on to support arms
- installed new cotter pins holding arms on
- cleaned up tools

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 09
Account No.	Phone No.	Reference No. W37537
Ship via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588 COMBINE	1580 HAJ304834			
	2588	X			
3X BEARINGS EACH SIDE SEALS AND PIN					
FREIGHT	FREIGHT	1	9.00	9.00	
G10642	BEARING NEEDLE	6 N	26.88	161.28	
1979251C1	SHAFT	3 N	100.84	302.53	
2010-55-01	ADAPTER 1/8FNPT	1	16.99	16.99	
372756R91	SEAL	6 M	13.48	80.88	
87399	PIN COTTER 3/16	2 M	3.13	6.26	
			PARTS	576.94	
			LABOR	775.00	
13300056			SEGMENT TOTAL==>	1351.94	

SEGMENT# 9 C 05396 NA	07/25/22 08/15/22			
3- ADJUST BEVEL DRIVE GEARS		1.50 HRS		
<u>CORRECTION:</u>				
- loosen off the brackets the holds drive gears in place				
- slid gears over to make good contact with other gears				
- tighten up brackets holding drive gears in place				
- cleaned up tools				
	LABOR		232.50	
13300056	SEGMENT TOTAL==>		232.50	

SEGMENT#10 C 05396 NA	07/25/22 07/25/22			
3- REPLACE THRUST BEARING ON CLEANING FAN PULLEY		1.00 HRS		
<u>CORRECTION:</u>				
- pulled variable pulley for fan off				
- removed old thrust bearing off end of pulley				
- installed new thrust bearing on to pulley hub				
- re install pulley on to combine				
- clean up tools				
168215C92	BEARING	1	64.63	64.63
			CONTINUED ON PAGE 10	

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 10
Account No.	Phone No.	Reference No. W37537
Ship via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
			PARTS	64.63	
			LABOR	155.00	
13300056			SEGMENT TOTAL==>	219.63	

SEGMENT#11 C 05396 NA 07/25/22 07/25/22
3- PLAY ON VARIABLE PULLEY FOR CLEANING FAN MIGHT BE DOWELS 1.50 HRS

CORRECTION:

- removed pin and cotter pin holding plate
- removed bolt holding pulley on
- removed pulley and belt
- removed half pull off of hub
- pressed dowels out of hub
- pressed new dowels in to hub
- remounted half pulley back on to hub
- removed other half of pulley off combine
- put new half pulley back on to combine
- put bel back on
- put other half of pulley on
- tightened retaining bolt back up
- put cover back on
- put back in pin and cotter pin back in
- greased bearing
- cleaned up tools

ADDITIONAL DESCRIPTION:

OR PULLEY WORN OUT

FREIGHT	FREIGHT	1	9.00	9.00
14463680	O-RING	1	7.44	7.44
244638	RING, SNAP	1 M	4.38	4.38
48007763	PULLEY	1 N	123.22	123.22
81854	DOWEL	3 N	23.24	69.72

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch		
MOOSOMIN		
Date	Time	Page
08/24/22	08:44:29 (O)	11
Account No.	Phone No.	Reference No.
		W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No.
		79759 4660 RT0001
Credit Card No.		Salesperson
		H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
			PARTS	213.76	
			LABOR	232.50	
13300056			SEGMENT TOTAL==>	446.26	
SEGMENT#12 C 05396 NA	07/25/22	08/15/22			
2- FLIP CHOPPER BLADES			2.40	HRS	
CORRECTION:					
remove knives one by one and flip and retighten					
			LABOR	372.00	
13300056			SEGMENT TOTAL==>	372.00	
SEGMENT#13 C 05396 NA	07/25/22	07/25/22			
3- CHOPPER DRIVEN PULLEY SPLINES WORN OUT			1.75	HRS	
CORRECTION:					
- chopper drive pully has play in it					
- removed drive belt					
- removed nut holding on chopper pully					
- removed spacing washers					
- removed old pulley					
- put new pully on to chopper shaft					
- put washers back on in order					
- put nut back on shaft and tighten back up					
- put drive belt back on					
- clean up tools					
84151573	NUT		1	4.15	4.15
87735266	PULLEY		1 N	383.65	383.65
			PARTS		387.80
			LABOR		271.25
13300056			SEGMENT TOTAL==>		659.05

CONTINUED ON PAGE 12

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 12
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS Fold -

052881 2588 COMBINE 1580 HAJ304834

2588 X

SEGMENT#14 C 05396 NA 07/25/22 07/25/22

3- LOWER CLEAN GRAIN AUGER BEARINGS ROUGH 4.00 HRS

CORRECTION:

- removed lock collar
- unbolt bearing holder
- removed bearing
- removed collar that holds elevator chain sprocket chain
- added two shims beside sprocket to get rid of the play
- put back on collar to hold sprocket in place
- put new bearing back on to shaft
- tighten back up bearing holder
- put new bearing lock collar on
- blue lock tight the set screw
- tightened up elevator chain
- cleaned up tools

ADDITIONAL DESCRIPTION:

ALSO SHIM PADDLE DRIVE SPROCKET AND TENSION CHAIN

473093R92	BEARING	1 N	72.27	72.27
47577188	COLLAR	1	25.35	25.35
87613234	WASHER	4 N	3.10	12.40
	PARTS			110.02
	LABOR			620.00
13300056	SEGMENT TOTAL==>			730.02

SEGMENT#15 C 05396 NA 07/25/22 07/25/22

2- REPLACE WOODEN BLOCKS FOR ELEVATOR CHAIN .50 HRS

CORRECTION:

- wooden guide blocks worn out on elevator chain
- removed bolts holding them on
- put new blocks on bolts

CONTINUED ON PAGE 13

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 13
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	HAJ304834	
	2588	X			
- tighten bolts back down in spot					
- clean up tools					
582018R1	BLOCK	2	30.92	61.84	
			PARTS	61.84	
			LABOR	77.50	
13300056		SEGMENT TOTAL==>		139.34	

SEGMENT#16 C 05396 NA 07/25/22 07/25/22
2- REPLACE 2 SPHERICAL BEARING ON ELEVATOR TENSIONER SUPPORT 1.00 HRS

CORRECTION:

- loosened off tension on chain
- unhooked tension rod
- unbolted idler sprockets
- removed front cover
- move chain out of way
- took out pin holding shaft in to the bearings
- removed shaft from bearings
- unbolted bearings
- bolted in new bearings
- put back in shaft threw the bearings and re pined it
- put chain back in to position
- put front cover back on
- put idler sprockets back in
- reattach tensioning rod
- tighten chain back up to proper tensions
- clean up tools

A63366	FLANGE	2 N	19.28	38.56
			PARTS	38.56
			LABOR	155.00
13300056		SEGMENT TOTAL==>		193.56

CONTINUED ON PAGE 14

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 14
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.	Salesperson H40	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	HAJ304834	
	2588		X		

SEGMENT#17 C 05396 NA 07/25/22 07/25/22
3- DELIVERY AUGER HAS END PLAY REPLACE INNER BEARING AND 2.00 HRS

CORRECTION:

- removed drive chain
- removed drive sprocket
- unbolted and removed tailings delivery auger
- removed key way
- pulled off mounting plate off auger shaft
- removed grease seals out of mounting plate
- removed needle bearings out of mounting plate
- put in new needle bearings
- put new grease seals in
- put new thrust bearing on to auger shaft and reinstalled shims
- put mounting plate back on to auger shaft
- mounted auger back on to combine
- put new shims in behind drive sprocket to line up sprockets
- put drive sprocket on
- reinstall drive chain
- greased
- cleaned up tools

ADDITIONAL DESCRIPTION:

SPACER

FREIGHT

G13609

T38017

297931A1

564592R91

FREIGHT

BEARING THRUST

WASHER

PLATE

SEAL

1	20.00	20.00
2 N	8.17	16.34
1 M	12.88	12.88
1 N	31.46	31.46
2 N	20.34	40.68

CONTINUED ON PAGE 15

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 15
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
574940R91		BEARING	2 N	34.69	69.38
86624169		WASHER 1-1/32	3 M	3.00	9.00
87367		WASHER 1"	1 M	2.25	2.25
		PARTS			201.99
		LABOR			310.00
13300056		SEGMENT TOTAL==>			511.99

SEGMENT#18 C 05396 NA 07/25/22 07/25/22

3- ACCESSORY BELT AND TENSIONER NEED REPLACED

1.00 HRS

CORRECTION:

- removed fan belt
- removed a/c belt
- removed tensioner pulley
- installed new tensioner
- installed new fan belt
- reinstalled a/c belt
- cleaned up tools

87317615	TENSIONER, BELT	1 N	282.47	282.47
90487255	V-BELT	1 N	25.82	25.82
	PARTS			308.29
	LABOR			155.00
13300056	SEGMENT TOTAL==>			463.29

SEGMENT#19 C 05396 NA 07/25/22 07/25/22

2- SUCTION HOSES ON HYDRO LEAKING

1.50 HRS

CORRECTION:

- drained hydraulic tank
- removed hose from hydraulic tank over to pto gear box
- replace hose with new one
- refilled hydraulic tank

CONTINUED ON PAGE 16

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 16
Account No.	Phone No.	Reference No. W37537
Salesperson		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588 COMBINE	1580 HAJ304834			
	2588	X			
- cleaned up tools					
FREIGHT		FREIGHT	1	24.00	24.00
1541953C1X		HOSE	6 M	45.68	274.08
				PARTS	298.08
				LABOR	232.50
13300056			SEGMENT TOTAL==>		530.58

SEGMENT#20 C 05396 NA	07/25/22 07/25/22				
3- REPLACE ORING ON COOLANT RESERVOIR SIGHT GLASS			.50 HRS		
<u>CORRECTION:</u>					
-pulled out sight glass					
- removed old o-ring					
- put in new o-ring					
- put sight glass back in and tightened down					
- clean up tools					
272142	O-RING	1	3.41	3.41	
			PARTS	3.41	
			LABOR	77.50	
13300056		SEGMENT TOTAL==>		80.91	

SEGMENT#21 C 05396 NA	07/25/22 07/25/22				
3- WHEEL BEARINGS HAVE PLAY			4.00 HRS		
<u>CORRECTION:</u>					
- lifted up right side rear axel					
- removed bearing cover					
- remove cotter pin from castle nut					
- spun wheel and tighten castle nut to set pre load on					
bearings till there is slight resistance					
- replaced cotter pin locking castle nut					
- cleaned up sealing surface on wheel bearing cover					

CONTINUED ON PAGE 17

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 17
Account No.	Phone No.	Reference No. W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	H4J304834	
	2588		X		
- tighten down wheel bearing cover - lifted up left side rear axel - remove wheel bearing cover - removed cotter pin from castle nut spun wheel and tighten castle nut to set pre load on bearings till there is slight resistance - replaced cotter pin locking castle nut - cleaned up sealing surface on wheel bearing cover - tighten down wheel bearing cover - cleaned up tools					
ADDITIONAL DESCRIPTION:					
SHOULD BE ABLE TO ADJUST					
MRKDIS		MARKETING DISC	1-	1.00	1.00-
OIL1		ENVIRO OIL LTR	1	.15	.15
73344349		MP GREASE 14OZ	1	6.49	6.49
87399		PIN COTTER 3/16	2 M	3.13	6.26
		PARTS			11.90
		LABOR			620.00
13300056		SEGMENT TOTAL==>			631.90

SEGMENT#22 C 05396 NA 07/25/22 07/25/22
3- REPLACE ALL GEARBOX OILS - OIL IS BURNT 4.00 HRS

CORRECTION:

- drained hydraulic tank oil changed filters refilled with new hytran
- drained pto gear box and refilled with new hytran
- drained transmission and refilled with new hytran
- drained final drives and refilled with new hytran
- drained chopper drive gear box and filled with new hytran
- drained unloaded gear box and refilled with 85W-140

CONTINUED ON PAGE 18

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature) _____ (date) _____

(signature) _____ (date) _____



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 18
Account No.	Phone No.	Reference No. W37537
Ship via		Purchase Order
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold --
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
B85143	85W140	2.5G	1	76.30	76.30
FIL2	ENVIR	FILT>8"	2	1.00	2.00
FREIGHT	FREIGHT		1	33.20	33.20
OIL1	ENVIRO	OIL LTR	20	.15	3.00
OIL2	ENVIRO	OIL>30	158	.05	7.90
1329214C1	ELEMENT		1	185.00	185.00
73344238	15W40	OIL BULK	40	5.75	230.00
73344271	HYTRAN	BULK	78	6.25	487.50
		PARTS			1024.90
		LABOR			620.00
13300056		SEGMENT TOTAL==>			1644.90

SEGMENT#23 C 05396 NA 07/25/22 07/25/22
3- FEEDER DRIVE RESERVOIR SHOULD BE DRAINED AND FLUSHED - 2.00 HRS

CORRECTION:

- drained old oil out of reservoir
- flushed with diesel fuel
- refilled with fresh oil
- put in new dipstick
- cleaned up tools
- cleaned up any spilled oil

ADDITIONAL DESCRIPTION:

CONTAMINATED WITH DEBRIS NEEDS NEW DIPSTICK

OIL1	ENVIRO	OIL LTR	8	.15	1.20
336513A1	DIPSTICK		1 N	108.07	108.07
73344316	3.78L	85W140	1	39.53	39.53
		PARTS			148.80
		LABOR			310.00
13300056		SEGMENT TOTAL==>			458.80

CONTINUED ON PAGE 19

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3868
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch		
MOOSOMIN		
Date	Time	Page
08/24/22	08:44:29 (O)	19
Account No.	Phone No.	Reference No.
		W37537
Ship Via		Purchase Order
SE31-15-31W1		G.S.T. No.
		79759 4660 RT0001
Credit Card No.		Salesperson
		H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold -
052881	2588	COMBINE	1580	H4J304834	
	2588	X			
SEGMENT#24 C 05396 NA	07/25/22	08/16/22			
3- SIEVE HARNESS CHAFFING - REPAIR AND RE-ROUTE			2.00	HRS	
<u>CORRECTION:</u>					
- removed protective cover from wiring harness					
- found to worn through wires					
- spliced the wires back together					
- heat shrink and taped over splice					
- put loom over that					
-clean up tools					
13300056			LABOR	310.00	
			SEGMENT TOTAL==>	310.00	

SEGMENT#25 C 05396 NA	07/25/22	07/25/22			
3- ROLLER BEARINGS SEIZED ON LHS			2.50	HRS	
<u>CORRECTION:</u>					
- hooked up header on to combine					
- ran header up					
- found bearing worn out on the drive side for center canvas					
- removed drive belt					
- removed pulley					
- cut lock collar off					
- unbolted bearing and removed bearing					
- installed new bearing					
- installed new lock caller					
- put pulley back on to shaft and aligned it with other pulleys					
- put belt back on					
- cleaned up tools					
- reinstall drive belt					

CONTINUED ON PAGE 20

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch MOOSOMIN		
Date 08/24/22	Time 08:44:29 (O)	Page 20
Account No.	Phone No.	Reference No. W37537
Purchase Order		
SE31-15-31W1		G.S.T. No. 79759 4660 RT0001
Credit Card No.		Salesperson H40

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - -
052881 2588 COMBINE 2588	1580	HBJ304834			
- cleaned up tools	X				
<u>ADDITIONAL DESCRIPTION:</u>					
HEADER 2015 - CCC0021254					
373987A1	HOUSING	1	118.80	118.80	
			PARTS	118.80	
			LABOR	387.50	
13300056			SEGMENT TOTAL==>	506.30	

SEGMENT#26 C 05396 NA	07/25/22 08/18/22			
2- 4 DRAPER BELTS LOOSE WHILST OTHERS TIGHT	3.00 HRS			
<u>CORRECTION:</u>				
- when running up header notice out side belts where not turning				
- pulled the side panels up off the belts so they can turn				
- tighten up the belts up				
- ran header up to make sure all belts turn				
- everything was turning now				
- cleaned up tools				
<u>ADDITIONAL DESCRIPTION:</u>				
RECOMMEND CHANGING - PUT HEADER ON AND CALL DOUG BEFORE CHANGING WHEN REST IS COMPLETE				
		LABOR	465.00	
13300056		SEGMENT TOTAL==>	465.00	

SEGMENT#27 C 05396 NA	07/25/22 08/17/22			
CHECK PROCESSOR BELT	.50 HRS			
<u>CORRECTION:</u>				
- check belt found a crack				
- removed fan belt				
- remove clean elevator chain				

CONTINUED ON PAGE 21

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1200
Moosomin, SK S0G 3N0
Tel: (306) 435-3866
Fax: (306) 435-2415

INVOICE

Ship to:

Invoice to:

Branch		
MOOSOMIN		
Date	Time	Page
08/24/22	08:44:29 (O)	21
Account No.	Phone No.	Reference No.
		W37537
Ship via		Purchase Order
SE31-15-31W1		G.S.T. No.
		79759 4660 RT0001
Credit Card No.		Salesperson
		H40

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
052881	2588 COMBINE	1580	HAJ304834			
	2588		X			
	- remove screening auger chain - removed support bracket to get belt out - removed processing belt - put new belt on - put support bracket back on - put fan belt back on - put clean elevator chain back on - put screening auger chain back on - tighten up all the belts and chains - clean up tools					
87034815		CHN CONN 50		1	2.68	2.68
87476486		BELT		1 N	286.20	286.20
					PARTS	288.88
					LABOR	77.50
13300056				SEGMENT TOTAL==>		366.38

***** WORK ORDER TOTALS *****

PARTS	8903.50
LABOR	10253.25
DISPOSAL FEE	213.74
SHOP SUPPLIES	908.41
DISCOUNT	2307.02-
SUB TOTAL==>	17971.88
GST 797594660	898.63
TOTAL CASH/DEBIT/CHK	18870.51

CHQ# 142

Land Description: Sec_____ Twsp_____ R_____ M_____

CONTINUED ON PAGE 22

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)