



www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To:

A01-I

Invoice To:

Branch		
REPRINT		
Date 05/26/22	Time 22:01:22 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # HYDRAULIC LEAK	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	5866	ZAF118526		
SEGMENT# 1 C 34031 NA		05/18/22	05/18/22		
SERVICE CALL					
MAY 18-SERVICE CALL TO THE FARM (45KM)					
*SPLIT MILEAGE W/					
MAY 24-SERVICE CALL TO THE FARM (93KM)					
SV	Service Call	138	1.40		193.20
	(Vehicle Fee)				
			PARTS		193.20
11030099			SEGMENT TOTAL==>		193.20

SEGMENT# 2 C 34031 NA 05/18/22 05/18/22
DIAGNOSE & REPAIR HYDRAULIC LEAK
++CUSTOMER WAS COMPLAINING OF HYDRAULIC OIL LEAKING BY HIS
+PUMP, UPON INSPECTION FOUND PUMP TO BE WET WITH OIL
++CLEANED PUMP OFF AND OPERATED HYDRAULICS ON TRACTOR TO
+FIND LEAK, FOUND IT COMING FROM A FLANGE FITTING ON THE
PUMP
++REMOVED FLANGES AND INSPECTED O-RING ON TUBE
+NO VISIBLE DAMAGE BUT REPLACED O-RING ANYWAYS
++REINSTALLED TUBE AND OPERATED TRACTOR AGAIN
+STILL HAD A LEAK COMING FROM AROUND FLANGE
++REMOVED FLANGES AND TUBE AND INSPECTED TUBE FOR A CRACK
+USING BRAKE CLEAN, CAN NOT SEE ONE BUT ONE SPOT INSIDE THE
+TUBE HAD SOME DISCOLOURING TO IT LIKE OIL MIGHT BE GETTING
+OUT THERE
++TRIED INSTALLING OTHER NEW O-RING AND RE-POSTIONING
+MATING SURFACES OF FLANGES TO STOP LEAK
+STARTED TRACTOR, LEAK STILL PRESENT
++BELIEVE TUBE TO BE CRACKED

CONTINUED ON PAGE 02

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To:

Branch		
Date 05/26/22	Time 22:01:22 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # HYDRAULIC LEAK	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UT2209	Tractor 4WD ST535Q	5866	ZAF118526		
+CUSTOMER ORDERED NEW TUBE FROM ANOTHER DEALER					
+REMOVED AND REPLACED TRANSMISSION CHARGE PUMP TUBE					
+INSTALLED NEW O-RINGS AND TORQUED FLANGES TO SPEC					
+CLEANED OFF AREA WITH BRAKE CLEAN AND BLEW DRY					
+OPERATED MACHINE FOR 20 MINUTES AND VERIFIED NO LEAKS					
+AROUND TRANSMISSION CHARGE PUMP.					
86529541	O-RING	1		2.34	2.34
9824050	O-RING	1		.86	.86
	PARTS				3.20
	LABOR				1084.05
11030099	SEGMENT TOTAL==>				1087.25

SEGMENT# 3 C 34031 QC 05/18/22 05/18/22
 Young's Complimentary QuickCheck Inspection
 1 HYDRAULIC PUMP - PUMP MOUNTED TO FRONT OF ENGINE IS COVERED IN OILY DIRT
 2 ENGINE HAS A TICKING NOISE, UNSURE IF EXHAUST LEAK OR LOUD ROCKER ARMS
 3 TRACKS ARE GETTING WORN AND STARTING TO SPLIT
 4 SWAP TRACKS FRONT TO BACK TO PROVIDE EVEN WEAR
 5 REPLACE DAMAGED RIGHT SIDE LADDER ASSEMBLY
 6 REPLACE TRANSMISSION TO REAR AXLE DRIVE SHAFT BEARING (WORN)
 7 DIAGNOSE AND REPAIR LEAKS IN ENGINE AREA

***** WORK ORDER TOTALS *****

PARTS	196.40
LABOR	1084.05

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date	Time	Page
05/26/22	22:01:22 (B)	03
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
	HYDRAULIC LEAK	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#

UT2209 Tractor 4WD
ST535Q

HRS

5866

PIN/EIN

ZAF118526

WARRANTY DATE

HRS

shop supplies

86.72

SUB TOTAL==>

1367.17

GST 5%

68.38

TOTAL ON ACCOUNT

1435.55

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business