



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
REPRINT		
Date 09/19/25	Time 22:01:41 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # REDKOP	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
006149	1849	YJG236802		
COMBINE	1			
9240				

SEGMENT# 1 C 34002 NA	08/24/25 08/25/25
SERVICE CALL	
AUG 25-SERVICE CALL TO THE FARM (45KM) *MILEAGE SPLIT	
SEPT 3-SERVICE CALL TO THE FARM (N/C)	
SV	Service Call
	(Vehicle Fee)
11030099	

	45	1.85	83.25
		PARTS	83.25
		SEGMENT TOTAL==>	83.25

SEGMENT# 2 C 34031 NA	08/24/25 08/24/25
REPAIR REDKOP CREEP	
+LEFT SPREADER DROPS BECAUSE A SHOCK IS MISSING	
+THE SHOCK KEEPS IT IN PLACE AND THE ACTUATOR WORKS	
+AGAINST THE SHOCK	
+ORDERED PART	
+BROKEN SPREADER PIVOT PLATES AND MISSING PARTS	
+FOUND PARTS IN MY TRUCK TO MAKE IT WORK	
+REMOVED BOTH SPREADERS	
+GRIND DOWN BROKEN WELDS	
+WELD PIN BACK ONTO THE PIVOT	
+MADE A NEW PIVOT PLATE FOR THE OTHER SIDE	
+WELD PINS AND SPACERS TO THE PLATE	
+PUT SPREADERS BACK ON WITH HOME MADE PARTS	
+CONFIRMED OPERATION	
++SEPT 3/25: RETURNED TO CUSTOMERS COMBINE AND	
+INSTALLED SHOCK FOR THE REDKOP SPREADER	
48105027	SPRING
	1 N
	423.44
	PARTS
	423.44
	LABOR
	483.99
CONTINUED ON PAGE 02	

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

• An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

• Estimates are for the items specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 09/19/25	Time 22:01:41 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # REDKOP	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1849	YJG236802		
	9240	1			
11030099				SEGMENT TOTAL==>	907.43

SEGMENT# 3 C 34002 QC 08/24/25 08/25/25
Young's Complimentary QuickCheck Inspection
1 Repair Spreaders
Pivots broken Fixed while working on the combine.

SEGMENT# 4 C 34031 NA	08/24/25 08/24/25			
SPREADER PIVOT				
++BROUGHT PIN DOWN FOR CUSTOMER BUT CUSTOMER				
+TO INSTALLED AT LATER DATE				
48035495	PIN	1 M	261.80	261.80
			PARTS	261.80
			LABOR	372.30
11030099			SEGMENT TOTAL==>	634.10

SEGMENT# 5 C 34031 NA	08/24/25 09/03/25			
SIEVE SEALS				
++CUSTOMER HAD NOTICED SIEVE SEALS FOR THE TOP SIEVES				
+WERE DAMAGED AND WANTED THEM REPLACED				
++UNBOLTED TOP SIEVES AND PULLED OUT A BIT IN				
+ORDER TO ACCESS SIEVE SEALS				
++REMOVED AND REPLACED SEALS AND REINSTALLED SIEVES				
92173874	STRIP RUBBER	2	109.65	219.30
			PARTS	219.30
			LABOR	422.67
11030099			SEGMENT TOTAL==>	641.97

SEGMENT# 6 C 34031 NA 08/24/25 09/03/25
MISSING HARDWARE

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* (Yes) * Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 09/19/25	Time 22:01:41 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # REDKOP	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1849	YJG236802		
	9240	1			
++WHILE WORKING ON REDKOP NOTICED THAT SOME ++HARDWARE WAS MISSING FOR MOUNTING UP REDKOP ++TO THE COMBINE ++REPLACED ALL MISSING HARDWARE ++ALSO NOTICED A FEW CRACKS IN THE COMBINE FRAME ++WHERE REDKOP MOUNTS UP, CUSTOMER TO HAVE WELDED					
11030099				LABOR	229.95
				SEGMENT TOTAL==>	229.95

***** WORK ORDER TOTALS *****	
PARTS	987.79
LABOR	1508.91
shop supplies	135.80
SUB TOTAL==>	2632.50
GST 5%	131.65
TOTAL ON ACCOUNT	2764.15

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

• An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such point as invoices have been paid.

• Estimates are for the items specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business