



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
REPRINT		
Date 09/19/25	Time 22:01:42 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1856	YJG236802		
	9240	1			
SEGMENT# 1 C 34031 NA 09/04/25 09/03/25					
SERVICE CALL					
SEPT 3-SERVICE CALL TO THE FARM (23KM) *MILEAGE SPLIT					
SEPT 4-SERVICE CALL TO THE FARM (74KM)					
SV	Service Call	97	1.85		179.45
(Vehicle Fee)					
					PARTS 179.45
11030099	SEGMENT TOTAL==>				179.45

SEGMENT# 2 C 34031 NA 09/04/25 09/04/25

REPAIR CONCAVE MOTOR

++SEPT 3/25: DROVE TO CUSTOMERS FIELD

++CONCAVE MOTOR WAS READING LINE DISCONNECTED

++CHECKED FUSES, ALL GOOD

++DISCONNECTED CONCAVE MOTOR AND CHECKED POWER, HAD 12V

++AND GROUND WIRE ALSO GOOD, BELIEVE MOTOR TO HAVE

++SHORTED OUT, PHONED PARTS AND HAD THEM SET MOTOR AND

++MOTOR MOUNT BRACKET IN PICKUP BOX FOR CUSTOMER TO GRAB

++IN THE MORNING

++RETURNED TO SHOP

++SEPT 4/25: RETURNED TO CUSTOMERS COMBINE

++ATTACHED COME-A-LONG AND REMOVED LINKAGE PINS

++FOR THE FRONT CONCAVE CRADLE

++LOWERED CRADLE DOWN ONTO GRAIN PAN

++REMOVED CONCAVE ADJUSTER TUBE AND MOTOR/BRACKET

++FROM THE COMBINE

++ONCE REMOVED DISCOVERED THAT PIECE ON THE ROTOR

++CAGE THAT THE MOTOR BRACKET ATTACHES TO HAD BROKEN

++TALKED TO CUSTOMER AND HAD LOCAL WELDER COME OUT

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

If it is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 09/19/25	Time 22:01:42 (B)	Page 02
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
006149	1856	YJG236802		
COMBINE				
9240	1			

+AND WELD PIECE BACK IN PLACE
++REMOVED BUCKET AND MOTOR FROM ADJUSTER TUBE
++INSTALLED NEW BRACKET AND MOTOR
++REASSEMBLED CONCAVE ADJUSTER ASSEMBLY
++CHECKED OPERATIONS, ALL WORKING GOOD
++RECONNECTED FRONT CRADLE TO ADJUSTER
++RECALIBRATED CONCAVES
++RETURNED TO SHOP

LABOR	1633.74
11030099	
SEGMENT TOTAL==>	1633.74

SEGMENT# 3 C 34031 QC 09/04/25 09/04/25
Young's Complimentary QuickCheck Inspection
1 Replace Redkop
-rear canvas worn
2 Replace Redkop
-hand broken off
3 Repair Fuel sensor
-leaking

***** WORK ORDER TOTALS *****	
PARTS	179.45
LABOR	1633.74
shop supplies	147.03
SUB TOTAL==>	1960.22
GST 5%	98.03
TOTAL ON ACCOUNT	2058.25

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



www.youngs.ca

CASE III
AGRICULTURE

Regina 306
Chamberlain 306
Davidson 306
Moose Jaw 306
Raymore 306
Watrous 306
Weyburn 306
Windthorst 306

Ship To:

Invoice To:

Branch		
REPRINT		
Date 09/19/25	Time 22:01:44 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # CHOPPER	
Tax ID #		
		Salesperson 832

SERVICE INVOICE

STK#/FLEET#
006149

COMBINE
9240

HRS PIN/EIN
1866 YJG236802
1

WARRANTY DATE HRS

SEGMENT# 1 C 34002 NA 09/08/25 09/05/25
SERVICE CALL
SEPT 5-SERVICE CALL TO THE FARM (N/C)
11030099

SEGMENT# 2 C 34002 NA 09/08/25 09/05/25
REPAIR CHOPPER DEFLECTOR
+PINS THAT HOLD THE SPREADER DEFLECTORS KEEP BREAKING.
+PUT IN HOMEMADE PARTS.
+INSPECTED WHY IT IS BREAKING.
+CHOPPER IS BALANCED AND FREE.
+CHECKED ALL BEARINGS.
+RAN COMBINE.
+VIBRATION COMING FROM LEFT SIDE OF MAV CHOPPER.
+FOUND CRACKS, CUSTOMER IS GOING TO CHANGE LEFT BEARING.
+NOTE THE BEARING BEING REPLACED FIXED THE VIBRATION.
+NOTE CUSTOMER REPAIRED THE CRACKS.

11030099

LABOR
SEGMENT TOTAL==> 674.52
674.52

SEGMENT# 3 C 34002 QC 09/08/25 09/05/25
Young's Complimentary QuickCheck Inspection
1 Repair Chopper access door
Broken parts for access to the sieve area.

***** WORK ORDER TOTALS *****
LABOR
CONTINUED ON PAGE 02 674.52

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assignees operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at risk.
An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 7% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates as for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturer do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!