



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
REPRINT		
Date 07/26/22	Time 22:01:31 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			

SEGMENT# 1 C 34003 L. COMBINE 05/30/22 05/30/22
FLAGSHIP COMBINE INSPECTION
++HAD TO BLOW OUT COMBINE BEFORE INSPECTION
++HAD TO CLEAN OUT AND WASH OUT HOPPER OF GRAIN
+BEFORE INSPECTION
11030099

SEGMENT# 2 C 34003 NA 05/30/22
FLAGSHIP COMBINE INSPECTION WASH
W09603

SEGMENT# 3 C 34003 NA	05/30/22	07/25/22		
INSPECTION TRUCKING				
MAY 27-TRUCKED IN WITH PILOT (63KM)				
PLUS RETURN TRUCKING WITH PILOT (63KM)				
BILLED \$599 FOR INSPECTION TRUCKING PLUS PILOT BOTH WAYS				
PILOTLOADED	Pilot Vehicle	126	2.40	302.40
-Taking out a load				
				PARTS 302.40
11030099	SEGMENT TOTAL==>			302.40

SEGMENT# 4 C 34003 NA	07/06/22	07/25/22		
OPERATIONAL CHECKS				
+CHANGED GPS TO 135 FROM 138				
				LABOR 40.23
11030099	SEGMENT TOTAL==>			40.23

SEGMENT# 5 C 34003 NA 07/06/22 07/06/22
ELECTRICAL SYSTEM

CONTINUED ON PAGE 02

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Wayburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS
006149	9240	1101	YJG236802		629
+TESTED FOR POWER AT LIGHTS					
+THERE WAS 12 VOLTS					
+REPLACED LIGHT ASSEMBLIES (THEY ARE SEALED UNITS)					
+LIGHTS WORK NOW					
+UPDATED CONTROLLERS					
+UPDATED MONITOR					
+UPDATED GPS SYSTEM					
+CALIBRATED MACHINE					
+PERFORMED A ROLL CAL					
+CLEANED GROUNDS					
87584890	LIGHT ASSY	2	198.74		397.48
	PARTS				397.48
	LABOR				691.36
11030099	SEGMENT TOTAL==>				1088.84
SEGMENT# 6 C 34003 NA	FEEDERHOUSE	07/06/22	07/06/22		
86610200	INSERT, TH	1	12.54		12.54
	PARTS				12.54
	LABOR				77.48
11030099	SEGMENT TOTAL==>				90.02
SEGMENT# 7 C 34003 NA	FEEDER CHAIN	07/06/22	07/06/22		
+REMOVED OLD BROKEN SUPPORTS FROM CHAIN					
+INSTALL NEW SUPPORTS					
+REPLACED S PINS IN CONNECTOR					
+INSTALL NEW SLAT					
1329837C2	PIN	2	1.16		2.32
CONTINUED ON PAGE 03					

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-267
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 03
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
51453368	KIT	1		95.90	95.90
87283373	LINK, CHAIN	2		19.81	39.62
				PARTS	137.84
				LABOR	315.88
11030099				SEGMENT TOTAL==>	453.72

SEGMENT# 8 C 34003 NA	07/06/22 07/06/22				
FEEDER GEARBOX					
+REPLACED TIN SEAL, FELT SEAL AND BRUSHES					
+GREASED SHAFTS AND REINSTALLED GEARBOX					
+CLEANED BREATHERS					
47510326	SEAL	2		36.24	72.48
84415750	SEAL, FELT	2		14.44	28.88
87282006	GUARD	1		32.97	32.97
				PARTS	134.33
				LABOR	344.19
11030099				SEGMENT TOTAL==>	478.52

SEGMENT# 9 C 34003 NA	07/06/22 07/06/22				
CONCAVES					
+CUT OFF A PIECE OF BAR TO WELD INTO CONCAVE					
+WELDED PIECE IN					
+REPAIRED CONCAVES					
+HEATED AND HIT FRONT EDGE OF CRADLE STRAIGHT					
+TACKED INTO PLACE					
+SET LEVEL, PINCH-POINT AND ZEROED					
				LABOR	1341.00
11030099				SEGMENT TOTAL==>	1341.00

SEGMENT#10 C 34003 NA 07/06/22 07/06/22

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina	306-565-240
Chamberlain	306-638-451
Davidson	306-567-307
Moose Jaw	306-694-180
Raymore	306-746-228
Watrous	306-946-338
Weyburn	306-842-267
Windthorst	306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
CONE					
+REMOVED OLD CONE VANES					
+INSTALLED NEW ONES WITH NEW HARDWARE					
+REMOVED OLD TRANSITION VANES					
+INSTALLED NEW ONES WITH NEW HARDWARE					
100016	NUT	5		.89	4.45
140219	WASHER	5		7.47	37.35
84567289	VANE	1		67.31	67.31
87053359	STIFFENER	3		158.43	475.29
87106338	BOLT	32		6.54	209.28
87107892	ANGLE	1		57.32	57.32
87547587	NUT, LOCK	27		4.65	125.55
	PARTS				976.55
	LABOR				1045.98
11030099	SEGMENT TOTAL==>				2022.53

SEGMENT#11 C 34003 NA	07/06/22 07/06/22				
ROTOR					
+REMOVED OLD SEPERATOR BAR					
+INSTALLED NEW BAR AND TORQUED NEW BOLTS TO 100 FT LBS					
1318976C2	BAR	1		129.94	129.94
86981487	BOLT	2		3.48	6.96
	PARTS				136.90
	LABOR				81.95
11030099	SEGMENT TOTAL==>				218.85

SEGMENT#12 C 34003 NA	07/06/22 07/06/22				
SHOE SYSTEM					
+REMOVED BOLT, LOCTITED AND TORQUED TO 77 FT LBS					
+CLEANED OUT SIEVES					

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at own risk.

* An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-241
Chamberlain 306-638-45
Davidson 306-567-30
Moose Jaw 306-694-18
Raymore 306-746-22
Watrous 306-946-33
Weyburn 306-842-26
Windthorst 306-224-21

Ship To: .

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 05
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
+BENT SIEVE LOUVERS STRAIGHT					
					LABOR
					190.72
11030099				SEGMENT TOTAL==>	190.72

SEGMENT#13 C 34003 NA	07/06/22 07/06/22			
CLEAN GRAIN ELEVATOR				
+REMOVED PULLEY				
+REMOVED OLD BUSHING				
+INSTALLED NEW BUSHING				
+REINSTALLED PULLEY				
51626956	BUSHING	1	2.67	2.67
			PARTS	2.67
			LABOR	295.02
11030099			SEGMENT TOTAL==>	297.69

SEGMENT#14 C 34003 NA	07/06/22 07/06/22			
TAILINGS PROCESSOR				
+REMOVED PADDLE ASSEMBLY				
+REMOVED REAR BEARING AND THE PADDLE				
+REMOVED FRONT BEARING				
+PRESSED PULLEY OFF OF SHAFT				
+INSTALLED NEW PADDLE WITH NEW KEY ONTO NEW SHAFT				
+INSTALLED NEW REAR BEARING				
+INSTALLED NEW FRONT BEARING				
+INSTALLED ASSEMBLY BACK IN				
+INSTALLED PULLEY BACK ON WITH NEW KEY AND ALIGNED PULLEY				
+CLEANED OFF UPPER PADDLE				
84405034	SHAFT	1	105.97	105.97
86996914	KEY	1	19.62	19.62
86997578	KEY	1	34.88	34.88

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the item specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-450
Davidson 306-567-300
Moose Jaw 306-694-180
Raymore 306-746-220
Watrous 306-946-330
Weyburn 306-842-260
Windthorst 306-224-210

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order # INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
87541978		BLOWER	1	507.60	507.60
87605590		BEARING	2	64.88	129.76
		PARTS			797.83
		LABOR			639.21
11030099		SEGMENT TOTAL==>			1437.04

SEGMENT#15 C 34003 NA	07/06/22 07/06/22				
STRAWCHOPPER					
+REMOVED OLD BELT					
+INSTALLED NEW BELT					
+TENSIONED BACK UP					
51407097	V-BELT	1	952.30		952.30
			PARTS		952.30
			LABOR		43.21
11030099	SEGMENT TOTAL==>				995.51

SEGMENT#16 C 34003 NA	07/06/22 07/06/22				
KNIVES AND DISCHARGE PAN					
+REMOVED OLD PLATE					
+INSTALLED NEW PLATE WITH NEW HARDWARE					
+INSPECTED KNIVES					
+FOUND THEY HAD A STOP BRACKET INSTALLED TO KEEP KNIVES IN					
+DOWN POSITION FOR REDEKOP					
+CLEANED OUT MATERIAL BY DIVIDERS					
+REMOVED OLD CHOPPER BLADES					
+INSTALLED NEW KNIVES AND TORQUED TO 220 FT LBS					
+REMOVED PIECE OF HOUSING					
+BENT BROKEN PIECE BACK UP AND WELDED					
+REINSTALLED PIECE OF HOUSING					
47677377	KIT	10	122.32		1223.20

CONTINUED ON PAGE 07

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for five items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 07
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
73340388		PACKAGE	1	182.06	182.06
				PARTS	1405.26
				LABOR	1710.52
11030099			SEGMENT TOTAL==>		3115.78

SEGMENT#17 C 34003 NA	07/06/22 07/07/22				
UNLOADING AUGER					
+REMOVED HALF LINK					
+REINSTALLED CHAIN					
				LABOR	151.98
11030099			SEGMENT TOTAL==>		151.98

SEGMENT#18 C 34003 NA	07/06/22 07/15/22				
ENGINE					
+SILICONED BETWEEN COOLERS					
+DRAINED COOLANT					
+FOUND CLAMP WAS LOOSE					
+REMOVED HOSE					
+INSPECTED HOSE AND FOUND NO CRACKS					
+CLEANED UP HOSE AND REINSTALLED					
+TIGHTENED CLAMP BACK UP					
+ADDED A SECOND CLAMP					
+POURED COOLANT BACK IN					
70922199		CLAMP, HOSE	1	5.89	5.89
				PARTS	5.89
				LABOR	257.77
11030099			SEGMENT TOTAL==>		263.66

SEGMENT#19 C 34003 NA	07/06/22 07/06/22
FUEL SYSTEM	

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-267
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 08
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
	+REMOVED SENSOR				
	+FOUND BAD O-RING				
	+REPLACED O-RING				
	+REMOVED OLD BREATHER				
	+INSTALLED NEW BREATHER				
EHCFLT1	ENV FEE	1		.50	.50
14453080	O-RING	1		4.31	4.31
47437399	FILTER, FUEL	1		58.39	58.39
	PARTS				63.20
	LABOR				137.08
11030099	SEGMENT TOTAL==>				200.28

SEGMENT#20 C 34003 NA	07/06/22 07/06/22				
PTO SYSTEM					
+REPLACED LOOM ON RIGHT HAND SIDE OF BATTERY BOX					
ZQC505103100	LOOM	5		1.80	9.00
	PARTS				9.00
	LABOR				40.23
11030099	SEGMENT TOTAL==>				49.23

SEGMENT#21 C 34003 NA	07/06/22 07/06/22				
HYDRAULIC SYSTEM					
+REMOVED HOSE					
+HAD NEW HOSE MADE					
+INSTALLED NEW HOSE					
+REMOVED OLD COUPLER					
+INSTALLED NEW COUPLER					
+REPLACED O-RING ON HOSE GOING TO COUPLER					
+REINSTALLED HOSE					
CRIMP	END	2		2.00	4.00

CONTINUED ON PAGE 09

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 09
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
P-HR2C08-250		1/2" HYD HOSE	3	5.97	17.91
ZJM68		FITTING	2	43.33	86.66
238-5114		O-RING	1	3.11	3.11
47360258		COUPLING, QUICK	2	88.29	176.58
		PARTS			288.26
		LABOR			140.06
11030099		SEGMENT TOTAL==>			428.32

SEGMENT#22 C 34003 NA 07/06/22 07/06/22
GROUND DRIVE SYSTEM
+CLEANED OUT BREATHERS
+CHECKED COUPLERS AND FOUND RIGHT INNER COUPLER SPLINES
+WERE WORN OUT
+REPLACED COUPLER AND REPLACED BOLT
+JACKED UP RIGHT HAND SIDE OF COMBINE
+REMOVED TIRES
+REMOVED FINAL DRIVE AND SET ON TABLE
+DISASSEMBLED FINAL DRIVE
+REMOVED BAD OUTER SEAL
+INSTALLED NEW SEAL
+REINSTALLED HOUSING WITH SEAL
+REINSTALLED PLANETARIES
+REINSTALLED SUN GEAR AND TORQUED NUT TO 958 FT LBS
+REINSTALLED OUTER HOUSING AND TORQUED NUT TO 225 FT LBS
+RESEALED OUTER CASING WITH SEALANT
+REINSTALLED FINAL DRIVE AND TORQUED BOLTS TO 325 FT LBS
+TORQUED OUTER FINAL DRIVE BOLTS TO 291 FT LBS
+REINSTALLED INNER DUAL AND TORQUED TO 580 FT LBS
+REINSTALLED OUTER DUAL AND TORQUED TO 750 FT LBS
EHC4L EHC CHARGE

1 .88 .88
CONTINUED ON PAGE 10

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum) Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-451
Davidson 306-567-307
Moose Jaw 306-694-180
Raymore 306-746-228
Watrous 306-946-338
Weyburn 306-842-262
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 10
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson PS7

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
100037	NUT	1		1.25	1.25
129796A1	SCREW	1		13.90	13.90
51531	GSKT MAKER	1		29.95	29.95
76927JXYUS	80W90 3.79L	1		30.42	30.42
84439102	WASHER, SEALING	2		1.14	2.28
87586665	BUSHING, SPLINE	1		203.83	203.83
9832264	SEAL	1		138.43	138.43
	PARTS				420.94
	LABOR				2947.22
11030099	SEGMENT TOTAL==>				3368.16

SEGMENT#23 C 34003 NA	07/06/22 07/15/22
CHASSIS	
+FOUND HEAD WAS BROKEN OFF OF BOLT	
+EXTRACTED BOLT	
+INSTALLED NEW BOLT	
	LABOR 71.52
11030099	SEGMENT TOTAL==> 71.52

SEGMENT#24 C 34003 NA	07/06/22 07/06/22
MAINTENANCE	
+REPLACED ENGINE CRANKCASE BREATHER	
+REPLACED PTO OIL AND FILTER 30 L HYTRAN	
+REPLACED HYD OIL AND FILTER 38 L HYTRAN	
+REPLACED TRANS OIL 24 L 80/90	
+REPLACED FINAL DRIVE OILS 14.5 L 80/90	
+REPLACED ROTOR GEARBOX OIL 7 L HYTRAN	
+REPLACED HEADER/FEEDER GEARBOX OILS 6 L HYTRAN	
+REPLACED INCLINE GEARBOX OILS 1 L HYTRAN	
+REPLACED UPPER AND LOWER UNLOAD GEARBOX OILS 1.5 L 80/90	

CONTINUED ON PAGE 11

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs there to. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



www.youngs.ca



Regina 306-565-240
Chamberlain 306-638-450
Davidson 306-567-300
Moose Jaw 306-694-180
Raymore 306-746-220
Watrous 306-946-330
Weyburn 306-842-260
Windthorst 306-224-210

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 11
Account #	Phone #	Inv #
Ship Via	Purchase Order # INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
+REPLACED CAB FILTERS					
+GREASED COMBINE					
+TOPPED UP COOLANT					
EHCFLT1	ENV FEE	1		.50	.50
EHCFLT2	EHC CHARGE	1		1.00	1.00
EHC0IL	EHC CHARGE	82		.05	4.10
EHC5GL	EHC CHARGE	2		4.40	8.80
GLYCOL 1G 50/50	ENVIRO FEE	2		.99	1.98
254353A1	ELEMENT/A	1		155.55	155.55
360260A2	FILTER, CAB	1		123.68	123.68
504387088	GASKET	1		46.87	46.87
51508555	FILTER HYDRAUL	1		151.49	151.49
5801856860	FILTER	1		168.30	168.30
76927QY1US	80W90 18.9L	2		140.91	281.82
76971JXYCA	OT COOLANT3.79L	2		21.27	42.54
77400001US	ULTRACTION BULK	82	RETAIL	5.27	
				4.97	407.54
84217229	FILTER, AIR	1		73.63	73.63
84523925	FILTER, HYDRAUL	1		69.81	69.81
	PARTS				1537.61
	LABOR				941.49
11030099	SEGMENT TOTAL==>				2479.10

***** WORK ORDER TOTALS *****

PARTS	7581.00
LABOR	11504.10
shop supplies	200.00
INSPECT TRUCKNG	599.00
CONTINUED ON PAGE 12	

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!



www.youngs.ca



Regina 306-565-241
Chamberlain 306-638-451
Davidson 306-567-301
Moose Jaw 306-694-181
Raymore 306-746-221
Watrous 306-946-331
Weyburn 306-842-261
Windthorst 306-224-211

Ship To:

Invoice To:

Branch		
Date 07/26/22	Time 22:01:31 (B)	Page 12
Account #	Phone #	Inv #
Ship Via		Purchase Order # INSPECTION
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
006149	COMBINE	1101	YJG236802		
	9240	629			
				10-40 Ser Comb	1699.00
				SUB TOTAL==>	21583.10
				GST 5%	1079.21
				TOTAL ON ACCOUNT	22662.31

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You
We Appreciate Your Business!