



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch		
MAYERTHORPE		*REPRINT*
Date	Time	Page
03/18/25	23:01:33 (B)	01
Account No.	Phone No.	Invoice No.
INTER01		W38558
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4895	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 00747 NA 03/06/25 03/06/25 03/31/25
Unit won't drive check codes 10.33 HRS

***** TECHNICIANS COMMENTS *****

*
*Took truck down to the unit and had a bunch of codes for
*the park brake pressure. Started to check things over from
*the fuse was blown the AUX power replaced the fuse but this
*was unrelated to the no driving issue. Located and checked
*sensor. Did a pin check on it and it was fine. Had power
*down to the sensor. ground was fine as well. sensor plug
*had a bit of oil in it. Released park brake and pushed unit
*out of the
*mud so I could work under it. Checked DTAC found a case for
*the sensor. Said you needed to reinstall new updated sensor
*with a custom built hose. Put unit in come home mode and
*plumbed manual gauge in to make sure pressure was actually
*present and it was when I released the park brake. Parts
*said the stuff to build the custom hose DTAC case wanted
*installed wasn't available so just replaced sensor plugged
*unit in. Took unit out of come home mode and it run fine no
*problems for now. Drove it around yard for a while and shut
*it down and let it sit a couple times and all was good. Put
*floor back in unit .
*

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
03/18/25	23:01:33 (B)	02	
Account No.	Phone No.	Invoice No.	
INTER01		W38558	
Ship Via		Purchase Order	
		Salesperson	
		LAC	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4895	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P

ATC30	FUSE	1		1.99	1.99
FRT05	0-5 LBS FRT	1		14.95	14.95
RE584415	Pressure Sensor	1 M		187.81	187.81
				PARTS	204.75
				LABOR	1859.40
16001001			SEGMENT TOTAL==>		2064.15

***** WORK ORDER TOTALS *****	
	INTERNAL CUSTOMER
PARTS	204.75
LABOR	1859.40
Shop Supplies	185.94
INTERNAL TOTAL	2250.09

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
Invoice to:	INTERNAL AG CUSTOMER
	N/A EDMONTON AB T5S 2L7

Branch		
MAYERTHORPE		*REPRINT*
Date	Time	Page
06/12/24	23:02:44 (B)	01
Account No.	Phone No.	Invoice No.
INTERAG01		W37422
Ship Via		Purchase Order
		Salesperson
		KMA

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4874	1RW6155RAJD033596	08/31/20
	6155R		CD6068U253902	08/31/23
				2000
				5000 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 771 NA 06/05/24 06/05/24 06/21/24

R&R Mirrors

***** TECHNICIANS COMMENTS *****

*
 *Removed both LHS and RHS rear view mirrors.
 *-Replaced large lens on both rear view mirrors.
 *-Replaced small lens on LHS rear view mirror.
 *-Re-installed both LHS and RHS mirrors.
 *

AL225535	Rear View Mirro	2	218.24	436.48
	Rear View Mirror			
AL225536	Rear View Mirro	1 N	289.88	289.88
			PARTS	726.36
			LABOR	248.50
16001001		SEGMENT TOTAL==>		974.86

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	726.36	
LABOR	248.50	
AG SUPPLIES	24.85	

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL AG CUSTOMER
N/A
EDMONTON AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
06/12/24	23:02:44 (B)	02	
Account No.	Phone No.	Invoice No.	
INTERAG01		W37422	
Ship Via		Purchase Order	
		Salesperson	
		KMA	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4874	1RW6155RAJD033596	08/31/20	2000
	6155R		CD6068U253902	08/31/23	5000 P
INTERNAL TOTAL					999.71

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch		
MAYERTHORPE		*REPRINT*
Date	Time	Page
02/15/24	23:02:44 (B)	01
Account No.	Phone No.	Invoice No.
INTER01		W36835
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4869	1RW6155RAJD033596	08/31/20
	6155R			08/31/23
				2000
				5000 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 00747 NA 01/25/24 01/25/24 01/31/24

Check wiper

***** TECHNICIANS COMMENTS *****

*
*Brought the unit up onto the dock and had a look at the
*wiper and the arm was stripped. Tried to tighten the nut
*and it still didn't work. Ordered new arm and installed it
*with new nut. Lined arm up and tested it. Wiper works fine
*now. Topped up washer fluid.
*

AL226822	Wiper Arm	1 N	236.44	236.44
L210658	Fitting	1 N	5.07	5.07
TY25139	BULK HOSE	1	.85	.85
VU1321AB	WINTER W/S FLUI	1	7.68	7.68
14M7780	8mmf	1 N	1.19	1.19
	PARTS			251.23
	LABOR			350.00
16001001	SEGMENT TOTAL==>			601.23

SEGMENT# 2 C 00747 TRACTOR WASH 01/25/24 01/25/24 01/31/24

WASH FOR A TRACTOR

(Yes) Open all shields and wash inside

(Yes) Blow out the radiator & coolers

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch		
MAYERTHORPE		
Date	Time	Page
02/15/24	23:02:44 (B)	02
Account No.	Phone No.	Invoice No.
INTER01		W36835
Ship Via	Purchase Order	
	Salesperson	
	LAC	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4869	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P
(No) Wash and clean battery area					
(Yes) Scrub tractor, rims and loader					
(No) Remove the floor mat and wash mat					
(Yes) Vacuum the cab					
(Yes) Wipe down the cab					
(Yes) Clean the inside windows					
(Yes) Clean the outside windows					
(Yes) Clean the mirrors					
(Yes) Put in an air freshner					
(No) Remove old decals, install new Martin Deerline decal					
			LABOR		405.00
16001001			SEGMENT TOTAL==>		405.00

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	251.23	
LABOR	755.00	
AG SUPPLIES	75.50	
INTERNAL TOTAL	1081.73	

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch		
MAYERTHORPE		*REPRINT*
Date	Time	Page
01/22/24	23:02:17 (B)	01
Account No.	Phone No.	Invoice No.
INTER01		W36812
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4845	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 762 NA 01/17/24 01/17/24 01/31/24

Won't Start-Diagnose

***** TECHNICIANS COMMENTS *****

*
*Diagnose no start. Unit won't start, plugged in. Try to
*get started, test. Requires battery.
*Removed RHS steps to access battery compartment.
*Disconnected battery cables and removed battery hold-down
*plate. Removed battery. Installed new battery and assembled
*in reverse order.
*Unit now starts.
*

CRTY26782B	CORE	1-	54.00	54.00-
TY26783B	BATTERY	1	753.12	753.12
Wet Charged Battery				
CRTY26783B	CORE		54.00	54.00
			PARTS	753.12
			LABOR	236.25
16001001		SEGMENT TOTAL==>		989.37

SEGMENT# 2 C 762 NA 01/17/24 01/18/24 01/31/24

Unit displayed code: ECU.001 94.18 Fuel pres. very low

Unit displayed the following code:

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
01/22/24	23:02:17 (B)	02	
Account No.	Phone No.	Invoice No.	
INTER01		W36812	
Ship Via		Purchase Order	
		Salesperson	
		LAC	

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596 JOHN DEERE 6155R	4845	1RW6155RAJD033596	08/31/20	2000
6155R			08/31/23	5000 P

ECU.001 94.18 Fuel pressure very low:

***** TECHNICIANS COMMENTS *****

*Unit exhibited the following code after the battery was *

```
*Unit exhibited the following code after the battery was      *
*replaced and unit started.                                   *
```

*Added Emergency Thaw to fuel tank, and changed fuel

*Added Emergency Thaw to fuel tank, and changed fuel
*filters. Unit sat approximately 45 minutes to allow
*

*emergency thaw to work. Cleared codes and bled fuel system. *

*Started unit ok. No codes reappeared. Field tested unit, *

```
*still no codes, ok now. Parked unit on dock. *
```

* * *

DZ115391	Filter Element	1	64.38	64.38
DZ115392	Filter Element	1	71.05	71.05
ENV100	ENVIRO CHARGE	1	1.25	1.25
ENV50	ENVIRO CHARGE	1	.55	.55

PARTS 137.23

LABOR	379.75
-------	--------

```
16001001          SEGMENT TOTAL==>          516.98
```

***** WORK ORDER TOTALS *****

INTERNAL	CUSTOMER
<p>1. Product</p> <p>2. Price</p> <p>3. Place</p> <p>4. Promotion</p>	<p>1. Product</p> <p>2. Price</p> <p>3. Place</p> <p>4. Promotion</p>

PARTS 890.35

LABOR	616.00
-------	--------

AG SUPPLIES	61.60
-------------	-------

FUEL	374.98
------	--------

INTERNAL TOTAL	1942.93
----------------	---------

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees.

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Mayerthorpe
Box 570, 4402 52 Street, Mayerthorpe, AB, T0E 1N0
Tel: 780.786.2253 Fax: 780.786.2738
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL AG CUSTOMER
N/A
EDMONTON AB T5S 2L7

Branch		
MAYERTHORPE		*REPRINT*
Date	Time	Page
08/25/23	23:03:03 (B)	01
Account No.	Phone No.	Invoice No.
INTERAG01		W35828
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 761 NA 07/24/23 07/04/23 08/18/23

Repairs 5.00 HRS

***** TECHNICIANS COMMENTS *****

*Compressor was working and the seat would go up and down.

*The seat would leak down over time. Removed the seat and the rubber cover around the seat. Found that the air canister was leaking and the mounting brackets were broke. Tried to cut the line and mount back on the tank. The tank was too damaged and would still leak. Replaced the canister. Drilled out the old rivet and secured the new bracket in place. Placed the canister in position and hooked up the air lines. Tested the operation. The canister does not leak any more.

*Found that the fan in the cab was making bad vibration at high speed.

*Removed seat from tractor. Removed panels to access blower motors. Removed cabin air filters and air ducting. Removed air ducting covering blower motors. Found there was a bunch of dust built up on the fins of the blower motors. Blew clean with compressed air. Installed air ducting back into place. Installed panels. Replaced recirculating and fresh air cabin air filters. Blower motors works good with no more vibration. Installed rubber skirting on seat and

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:

IN STORE PICKUP

Invoice to:

 INTERNAL AG CUSTOMER
 N/A
 EDMONTON AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
08/25/23	23:03:03 (B)	02	
Account No.	Phone No.	Invoice No.	
INTERAG01		W35828	
Ship Via		Purchase Order	
		Salesperson	
		LAC	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P

*reinstalled in tractor. Found that the hood on the tractor *
 *was not *
 *latching correctly. Bent and adjusted tang to get the hood *
 *to latch. Step on left side was cracked. Removed step. *
 *Removed ladder assemble from tractor. Cleaned paint off *
 *with wire wheel. Welded in new step. Fixed crack on top *
 *step as well. Painted and reinstalled on tractor. Installed *
 *new cup holder. Installed new cover on cabin recirculating *
 *filter. Noticed a cab light was not mounted correctly. *
 *Removed trim and positioned it into place. Replaced primary *
 *and secondary engine air filter. Changed oil and filter. *
 *Found that there was oil leaking from under the steering *
 *column. Removed steering wheel gages and plastic cover to *
 *inspect. Found that the steering control unit was leaking *
 *out the top. Removed steering column framing. Removed oil *
 *lines from control unit. Removed control unit from tractor. *
 *Removed the fittings and placed in new control unit with *
 *new o rings. Bolted back into place. Attached oil lines *
 *with new o rings. Mounted steering column framing. Tested *
 *unit steering and found it was not leaking no more. *
 *Attached plastic cover, dash and secured steering wheel *
 *with new nut. Replaced old cup holder. The mounting tab was *
 *broken on the original. *
 *

AL174183	Lock Nut	1 N	12.07	12.07	
AL207960	Holder	1 N	73.54	73.54	
AL209810	Acoustical Upho	1 N	79.21	79.21	
	Acoustical Upholstery				
AL210199	Mounting Parts	1 M	9.51	9.51	

CONTINUED ON PAGE 03

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE
 RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
	INTERNAL AG CUSTOMER N/A EDMONTON AB T5S 2L7

Branch		
MAYERTHORPE		
Date	Time	Page
08/25/23	23:03:03 (B)	03
Account No.	Phone No.	Invoice No.
INTERAG01		W35828
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P
AL215053	Air Filter	1	O	201.70	201.70
AL215054	AIR CLEANER	1		97.87	97.87
AL220527	Air Filter	1		79.78	79.78
AL226435	Reservoir	1	N	961.20	961.20
AL237477	Steering Contro	1	N	1190.90	1190.90
	Steering Control Unit				
BULKGR5	HARDWARE	1		1.75	1.75
ENV100	ENVIRO CHARGE	1		1.00	1.00
ENV200	ENVIRO CHARGE	1		2.00	2.00
ENV50	ENVIRO CHARGE	1		.50	.50
FRT05	0-5 LBS FRT	1		14.95	14.95
FRT199	51-199 LBS FRT	2		20.66	41.32
L102114	STEP	1		69.75	69.75
L214634	Filter	2		39.69	79.38
M76104	O-RING	1		2.23	2.23
RE539279	OIL FILTER	1		41.43	41.43
R44302	TIE STRAP	3		.43	1.29
R502513	SEAL	1		12.61	12.61
TY26675	15W40 P50 9.46L	1		80.59	80.59
TY26679	15W40 P50 18.9L	1		151.42	151.42
W40935	CLAMP	2		13.34	26.68
40M7043	SNAP RING	3		14.25	42.75
51M7043	O-RING	4		3.33	13.32
	PARTS				3288.75
	LABOR				2752.54
16001001	SEGMENT TOTAL==>				6041.29

SEGMENT# 2 C 761 TRACTOR WASH 07/24/23 08/09/23 08/18/23

WASH FOR A TRACTOR

Removed stairs on both sides and removed debris. Blew off

CONTINUED ON PAGE 04

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
Invoice to:	INTERNAL AG CUSTOMER
	N/A EDMONTON AB T5S 2L7

Branch		
MAYERTHORPE		
Date	Time	Page
08/25/23	23:03:03 (B)	04
Account No.	Phone No.	Invoice No.
INTERAG01		W35828
Ship Via		Purchase Order
		Salesperson
		LAC

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20
	6155R			2000
				08/31/23
				5000 P

transmission and washed unit. Cab was cleaned.

- (yes) Open all shields and wash inside
- (yes) Blow out the radiator & coolers
- (yes) Wash and clean battery area
- (yes) Scrub tractor, rims and loader
- (yes) Remove the floor mat and wash mat
- (yes) Vacuum the cab
- (yes) Wipe down the cab
- (yes) Clean the inside windows
- (yes) Clean the outside windows
- (yes) Clean the mirrors
- (yes) Put in an air freshner
- (n/a) Remove old decals, install new Martin Deerline decal

	LABOR	360.00
16001001	SEGMENT TOTAL==>	360.00

SEGMENT# 3 C 00747 NA 07/24/23 08/15/23 08/18/23

Exhaust theft

Went to wash unit found that the exhaust had been attempted to steal. Replaced NOx sensor. Replaced one shield. Installed new mounting clamps around exhaust. Secured exhaust using bolts that they had left and one new one. Attached the remaining heat shields with 15 new screws. Logged time on segment 1

AL214223	Clamp	2 N	295.87	591.74
DZ110621	Chemical Sensor	1	978.56	978.56
L211949	Screw	15 N	.74	11.10
L213288	Heat Shield	1 N	352.89	352.89
19M7825	SCREW	1 M	11.19	11.19
19M7865	CAP SCREW	2	1.52	3.04

CONTINUED ON PAGE 05

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
Invoice to:	INTERNAL AG CUSTOMER
	N/A EDMONTON AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
08/25/23	23:03:03 (B)	05	
Account No.	Phone No.	Invoice No.	
INTERAG01		W35828	
Ship Via		Purchase Order	
		Salesperson	
		LAC	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20
	6155R			08/31/23
				5000 P
			PARTS	1948.52
			LABOR	568.75
	16001001		SEGMENT TOTAL==>	2517.27

SEGMENT# 4 C 761 NA 07/24/23 08/15/23 08/18/23

Loader

***** TECHNICIANS COMMENTS *****

*
 *Noticed that the mast were cracked for the upper pin.
 *Unhooked loader from tractor in the yard. Removed the pins
 *and lifted both mast off. Secured hydraulic cylinder with
 *straps to keep load off hoses. Brought mast to welding shop
 *for repair. Picked them up when finished. Lifted on with
 *forklift and inserted upper pin. Lined up the remaining
 *pins and secured. Installed snap rings and cotter pins.
 *Hooked back up to tractor. Took up to cement pad and
 *greased. Wiped grease off loader.
 *

SUBLET	Welding-Plates	1	607.15	607.15
			LABOR	525.00
			SUBLET	607.15
	16001001		SEGMENT TOTAL==>	1132.15

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	5237.27	
LABOR	4206.29	

CONTINUED ON PAGE 06

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
 (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL AG CUSTOMER
 N/A
 EDMONTON AB T5S 2L7

Branch			
MAYERTHORPE			
Date	Time	Page	
08/25/23	23:03:03 (B)	06	
Account No.	Phone No.	Invoice No.	
INTERAG01		W35828	
Ship Via		Purchase Order	
		Salesperson	
		LAC	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
LR033596	JOHN DEERE 6155R	4842	1RW6155RAJD033596	08/31/20	2000
	6155R			08/31/23	5000 P
				SUBLET	607.15
				AG SUPPLIES	250.00
				INTERNAL TOTAL	10300.71

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
 (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO