

# Chhapa Truck&Trailer Repair LTD.

#### **INVOICE**

**BILL TO:** 

NUMBER: INV0261

PO NUMBER: 2015 / VOLVO / VN VNL ( VIN -

4V4NC9EJ4FN

910222 **DATE**: Oct 30, 2025

**DUE DATE**: On receipt

Description	Quantity	Unit price	GST&PST	Amount	
Installed Webasto Air heat kit ( labour)	8	\$100.00	11.0 %	\$800.00	
Parts - Webasto Air Top 2000 STC Marine 12VKit with SmarTemp Control 3.0 -5013921B(used)	1	\$1,875.00	11.0 %	\$1,875.00	
Installed power inverter	5	\$100.00	11.0 %	\$500.00	
Parts - Xantrex Freedom HF Series Power Inverter(used)	1	\$750.00	11.0 %	\$750.00	
Shop supply	1	\$174.00	11.0 %	\$174.00	
Installed webasto coolant heater	8	\$100.00	11.0 %	\$800.00	
Parts - Webasto Thermo Top EVO Diesel 12v Coolant Heater Truck Kit( used)	1	\$1,550.00	11.0 %	\$1,550.00	
Shop supply	1	\$260.00	11.0 %	\$260.00	

SUBTOTAL: \$6,709.00

GST&PST: \$737.99 TOTAL: \$7,446.99

PAID: \$7,446.99

**Payment instructions** 

Interac e-Transfer chhapapayment@gmail.com

**BALANCE DUE** 

\$0.00



# **Chhapa Truck&Trailer Repair LTD.**

### **INVOICE**

BILL TO:

NUMBER: INV0289

PO NUMBER: 2015 / VOLVO / VN VNL( VIN-

4V4NC9EJ4FN 910222

DATE: Nov 13, 2025

**DUE DATE**: On receipt

Description	Quantity	Unit price	GST&PST	Amount	
Installed drive tire	8	\$40.00	11.0 %	\$320.00	
Tire 22.5	8	\$235.00	11.0 %	\$1,880.00	
Replace steering shaft u-joint	1	\$100.00	11.0 %	\$100.00	
Parts- steering u-joint	1	\$95.00	11.0 %	\$95.00	
Right rear drive wheal sheal Replacement	2.5	\$100.00	11.0 %	\$250.00	
Hub oil ( shop supply )	1	\$23.50	11.0 %	\$23.50	
Wheal sheal for drive parts	1	\$58.00	11.0 %	\$58.00	
Gaskit	1	\$2.00	11.0 %	\$2.00	
Replaced fire extinguisher	1	\$100.00	11.0 %	\$100.00	
Parts fire extinguisher	1	\$55.00	11.0 %	\$55.00	
Left steer kingpin adjustment	3	\$100.00	11.0 %	\$300.00	
Grees job	1	\$55.00	11.0 %	\$55.00	

SUBTOTAL: \$3,238.50 GST&PST: \$356.24

> TOTAL: \$3,594.74 PAID: \$3,594.74

#### **Payment instructions**

Interac e-Transfer chhapapayment@gmail.com

**BALANCE DUE** 

\$0.00