


Fisk Repair & Rental 2023 LTD.

1355 Coteau Avenue West
 Weyburn SK S4H 2T9
 Phone: (306) 842-2303 Ext. Fax: (306) 842-4465
 fiskrepairandrental@gmail.com


INVOICE

DATE March 26, 2026
 NUMBER [REDACTED]
 CUSTOMER NO. [REDACTED]

BILL TO:



SHIP TO:



(306) 842-2775 Ext.

(306) 842-2775 Ext.

P.O. NUMBER	SALESPERSON	ORDER DATE	REQ. DATE	ORDER NUMBER	
		18-Dec-25		[REDACTED]	
F.O.B.	SHIP VIA	TERMS			
[REDACTED]	Best way				
PART NUMBER	UOM	QUANTITY		UNIT	EXTENDED
DESCRIPTION		REQ.	SHIPPED	PRICE	PRICE
TAG 235, Kohler CH25 S Model: CH25s Serial#: 2708619277 Won't run Call in quote before repair					
2509937 Key Switch Assy	EA	1	1	103.78000	103.78
24176150 Wiring Harness	EA	1	1	119.98000	119.98
Both parts ordered from CPT Dec 31/25					
2455910 fuel pump	EA	1	1	235.91000	235.91
5205002 Oil Filter	EA	1	1	31.78000	31.78
2405013 fuel filter	EA	1	1	26.12000	26.12
OIL Oil / litre - bulk	EA	2	2	14.95000	29.90

CONTINUED

Business Number 765383815

Fisk Repair & Rental 2023 LTD.

INVOICE

1355 Coteau Avenue West
 Weyburn SK S4H 2T9
 Phone: (306) 842-2303 Ext. Fax: (306) 842-4465
 fiskrepairandrental@gmail.com

DATE March 26, 2026

BILL TO:



SHIP TO:



(306) 842-2775 Ext.

(306) 842-2775 Ext.

P.O. NUMBER	SALESPERSON	ORDER DATE	REQ. DATE	ORDER NUMBER		
		18-Dec-25				
F.O.B.	SHIP VIA	TERMS				
	Best way					
PART NUMBER	UOM	QUANTITY			UNIT PRICE	EXTENDED PRICE
DESCRIPTION		REQ.	SHIPPED	B.O.		
2475703KIT Carb Repair Kit	EA	1	1		69.54000	69.54
2475708 accelerator pump repair	EA	1	1		137.08000	137.08
SHOP Shop Supplies	EA	1	1		10.00000	10.00
LC1 Hour Labour	EA	2.50000	2.50000		120.00000	300.00
Oil is contaminated with fuel Repaired positive lead before testing. Found faulty key switch, and wiring harness. Order replacement parts Dec 31, 2025 (Back ordered) Replace key switch, and wiring harness - replace fuel pump, filter. - change oil, filter Run engine to test. - found engine to need accelerator pump and carb kit. Text customer to confirm ok with repairs. - Approval confirmed. Clean caruretor, soak in solvent - install carb kit and test unit.						

CONTINUED

Business Number 765383815

Fisk Repair & Rental 2023 LTD.

1355 Coteau Avenue West
 Weyburn SK S4H 2T9
 Phone: (306) 842-2303 Ext. Fax: (306) 842-4465
 fiskrepairandrental@gmail.com

INVOICE

DATE March 26, 2026

BILL TO:



SHIP TO:



(306) 842-2775 Ext.

(306) 842-2775 Ext.

P.O. NUMBER	SALESPERSON	ORDER DATE	REQ. DATE	ORDER NUMBER
		18-Dec-25		

F.O.B.	SHIP VIA	TERMS
	Best way	

PART NUMBER DESCRIPTION	UOM	QUANTITY			UNIT PRICE	EXTENDED PRICE
		REQ.	SHIPPED	B.O.		
Install Carburetor and test unit. - carburetor still not functioning correctly. Call customer to advise. 2485334 Carb	EA	1	1		894.37000	894.37
LC1 Hour Labour March 25, 2026 Carburetor arrived. - install carburetor, - change oil and filter. Run engine to test. Engine runs as it should..	EA	1.50000	1.50000		120.00000	180.00

NET AMOUNT	2,138.46
FREIGHT	
G.S.T.	106.92
P.S.T.	128.31
TOTAL DUE	\$2,373.69

Business Number 765383815