



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

DJ HOG TRD (016810)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		*REPRINT*
Date	Time	Page
04/25/25	23:05:19 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W01308
Ship Via		Purchase Order
		Salesperson
		JH

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036276A	BRANDT 16X125HP	1	136226-19		
	16X125HP		RG6136U016810		

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9730 NA 09/12/24 09/12/24
INFIELD SERVICE - SHAFT BROKE ON THE BACK SIDE OF THE
GEAR BOX GOING INTO THE FLIGHTING - REPAIR AS NEEDED -
DWIGHT IS WORKING ON GETTING THE GRAIN OUT OF THE AUGER
DWIGHT - 780-205-9972

***** TECHNICIANS COMMENTS *****

*
*+took the portable welder
*+found the booster flight had broke off at the gearbox
*+cleaned out grain to get good access around booster flight
*+prepped and welded the shaft so we could get all the grain
*+out
*+removed out of it
*+needed to get auger towed to Horizon for further repair
*+removed end cap to see if flaps were turned over
*+they were ok
*+removed ez reach from auger
*+levelled the auger to remove gear box end of auger
*+removed gear box end and starter flighting
*+disconnected flighting from other flighting
*+cut out flighting from gear box
*+brought gear box inside
*+removed 90 degree gear box from intake tube
*+had to cut shaft it was seized

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

DJ HOG TRD (016810)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
04/25/25	23:05:19 (B)	02
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W01308
Ship Via		Purchase Order
		Salesperson
		JH

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036276A	BRANDT 16X125HP	1	136226-19		
	16X125HP		RG6136U016810		

*+removed main gear box	*
*+removed cut shafts from gear box	*
*+drained gear box oil, installed new seals	*
*+filled with oil	*
*+re-installed gear boxes and tightened hardware to spec,	*
*+installed new flighting into auger	*
*+then installed intake	*
*+rig strap up to easy reach swing auger with forklift	*
*+remove four bolts securing easy reach	*
*+lift easy reach off main auger with forklift	*
*+set on jack stand	*
*+lift main auger with sellick	*
*+get two pallets of wheel weights	*
*+get a lift of pallets and put under	*
*+main auger	*
*+set main auger on pallets	*
*+secured main auger with chain and secured to wheel weights	*
*+cut off weld with torch that we had to make to get auger	*
*+unloaded	*
*+remove hydraulic hoses and never spill spout alarm	*
*+remove ring of bolts securing intake of main auger and	*
*+gearbox assembly	*
*+rig up with strap and forklift and remove and set inside	*
*+lean-too	*
*+use a small forklift and man basket	*
*+remove cap from end of auger	*
*+remove cotter pin	*
*+remove large nut from end of shaft	*
*+go back to other end off auger	*
*+rig up strap to flight	*

CONTINUED ON PAGE 03

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



DJ HOG TRD (016810)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch			
LLOYDMINSTER			
Date	Time	Page	
04/25/25	23:05:19 (B)	03	
Account No.	Phone No.	Invoice No.	
INTER01A	7808754471	W01308	
Ship Via		Purchase Order	
		Salesperson	
		JH	

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
036276A	1	136226-19		
BRANDT 16X125HP				
16X125HP		RG6136U016810		

```

**pull flight out of tube
**till bolt can be accessed
**remove bolt connecting booster flight to main flight
**remove booster flight and set on the ground
**install new booster flight install bolt to connect two
**try removing easy reach 90 degree drive gearbox
**remove bolts securing gearbox
**try air hammering shaft out
**but shaft is seized
**cut gearbox shaft off
**remove bolts holding main gearbox on
**remove main gearbox
**lay gearbox down on its face on some blocks
**grind off weld around collar and shaft from welding shaft
**remove shaft
**shaft is seized and took extra time to remove
**drain oil in gearbox
**remove and replace 4 seals on gearbox that were damaged
**by heat from the torch
**fill gearbox with oil
**reinstall main gearbox on intake off auger
**install new 90 degree easy reach drive gearbox
**install key way
**install bracket and bolts to secure
**install intake on booster flight
**spline gearbox on to shaft of booster flight
**secure intake to main part of auger with bolts
**route hoses and wiring for never spill alarm
**install hitch back on intake
**lift auger to loosen chains

```

CONTINUED ON PAGE 04

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees.

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

DJ HOG TRD (016810)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
04/25/25	23:05:19 (B)	04
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W01308
Ship Via		Purchase Order
		Salesperson
		JH

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036276A	BRANDT 16X125HP	1	136226-19		
	16X125HP		RG6136U016810		

*+remove pallets and wheel weights and return to proper *
*+location *
*+install jack on auger set auger down on ground *
*+rig up forklift to easy reach lift easy reach on to main *
*+auger spline coupler with gearbox shaft *
*+install 4 bolts to secure *
*+customer also wanted bearing changed that was missing the *
*+seal and the bearing balls that where exposed *
*+remove 2 bolts holding gathering trough and lift cylinders *
*+remove bolt holding u joint coupler on *
*+remove from easy reach tube *
*+remove and replace center gathering auger clean up splines *
*+on transition piece *
*+reassemble auger trough back on easy reach tube *
*+install 2 bolts and cylinders to secure *
*+hook customer tractor back on to auger *
*+install drive shaft *
*+hook up couplers *
*+install large nut and cotter pin on end of auger *
*+install cap and bolts to secure *
*+turn auger over slowly first time to check operation *
*+auger seems to run smooth *
*+install all covers and put auger into transport *
*+for road *

B00300810	SEAL VITON	3 S	74.84	224.52
B00300812	VITON SEAL	2	43.83	87.66
B0030205	GEARBOX LOWER	1	1719.38	1719.38
B017266	BRG 1.5W/SETSCR	1	39.12	39.12

CONTINUED ON PAGE 05

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

DJ HOG TRD (016810)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 04/25/25	Time 23:05:19 (B)	Page 05
Account No. INTER01A	Phone No. 7808754471	Invoice No. W01308
Ship Via		Purchase Order
		Salesperson JH

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS
036276A	BRANDT 16X125HP	1	136226-19			
	16X125HP		RG6136U016810			
B0315041	SYN.GEAR 220 1L	10			91.68	916.80
B032161	U-JOINT ASSY.	1			299.67	299.67
FRT	FRGHT/BROKR CHG	2			205.49	410.98
H99923	LOCKNUT-3/8"NC	1			.22	.22
MCD30940	3/8X5/16"SET S.	1			1.13	1.13
11M7100	COTTER-1/4 X 3"			RETAIL	1.43	
		2			1.35	2.70
19H2458	#8BOLT-3/8X3"			RETAIL	5.21	
		1			4.95	4.95
2052630	FLIGHT, LWR 16	1	N		7091.00	7091.00
2062039	SHEILD BEARING	1	N		32.83	32.83
49M4121	KEY-8X10X50MM	1			9.08	9.08
					PARTS	10840.04
					LABOR	17799.33
10104021	16001001			SEGMENT TOTAL==>		28639.37

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	10840.04	
LABOR	17799.33	
Shop Supplies	250.00	
INTERNAL TOTAL	28889.37	

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO