

Enviro Plant Hire Pty Ltd - Work Order Summary

Asset:
EX10 - Hitachi ZH210LC-5 Excavator

Location:
Enviro Yard

Current Tracker Hours:
7491

Current Tracker Kms:
5488

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
19115	Off Hire Cost C250065	05/06/2025	7491	5488	11/06/2025	Off hire repair cost report	Closed	
18979	Off Hire Cost C250020	22/04/2025	7455	5483	01/05/2025	Off hire repair cost report	Closed	
18967	Cleaned	18/04/2025	7455	5483	22/04/2025	Repairs and Inspections	Closed	Shaun Mbloney
18906	7500 hours service	11/04/2025	7454	5482	14/05/2025	Service	Closed	
18875	Change hitch	30/03/2025	7393	5454	30/03/2025	Repairs and Inspections	Closed	
18429	7035 Hour Service Carried Out	07/12/2024	7036	5331	07/12/2024	Service	Closed	Brian Tuohey
18285	Yuri Inspection	12/11/2024	6929	5316	12/02/2025	Inspection Report	Closed	
18275	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylind	11/11/2024	6920	5314	07/12/2024	Major Defects	Closed	
18263	App not up dating the the dates of daily prestarts	08/11/2024	6906	5312	07/12/2024	Major Defects	Closed	
17954	6500 hour service complete	25/08/2024	6497	5240	25/08/2024	Service	Closed	Brian Tuohey
17901	Off Hire C240648	08/08/2024	6437	5230	08/08/2024	Off hire repair cost report	Closed	
17591	Back Charges May 24	31/05/2024	6352	5205	31/05/2024	Modifications	Closed	
17379	H624 - Off Hire Checklist Defect/s	08/04/2024	6331	5202	01/05/2024	Modifications	Closed	
17065	H508 - Off Hire Checklist Defect/s	21/12/2023	5991	5108	07/02/2024	Mnor Defects	Closed	
17064	H508 - Off Hire Checklist Defect/s	21/12/2023	5991	5108	07/02/2024	Modifications	Closed	
17016	6000 hours service	12/12/2023	5953	5096	17/02/2024	Service	Closed	
16844	Tilt bucket fitment, GPS fitment , inspect	07/10/2023	5631	5031	09/10/2023	Off hire repair cost report	Closed	David Waters
16681	H209 - Off Hire Checklist Defect/s	08/06/2023	5626	5026	12/06/2023	Mnor Defects	Closed	
16680	H209 - Off Hire Checklist Defect/s	08/06/2023	5626	5026	12/06/2023	Modifications	Closed	
16679	H209 - Off Hire Checklist Defect/s	08/06/2023	5626	5026	12/06/2023	Mnor Defects	Closed	
16678	H209 - Off Hire Checklist Defect/s	08/06/2023	5626	5026	12/06/2023	Off hire repair cost report	Closed	
16511	5500 hours service	06/03/2023	5455	4866	21/12/2023	Service	Closed	MalcolmMorgan
16361	5000 hours service	17/10/2022	4948	4494	06/12/2023	Service	Closed	MalcolmMorgan
16207	Off hire work	01/07/2022	4674	4276	01/07/2022	Mnor Defects	Closed	michael reynolds
16123	Cutting edge replacement	11/05/2022	4500	4275	07/05/2022	Modifications	Closed	David Waters michael reynolds
16095	4500 hours service	03/05/2022	4446	4270	02/06/2022	Service	Closed	
15949	4000 hours service	22/02/2022	3951	3449	04/03/2022	Service	Closed	michael reynolds
15790	Prestart Defect - Covers & Guards Attached/Closed Failed	05/01/2022			24/01/2022	Mnor Defects	Closed	michael reynolds
15686	Prestart Defect - Hydraulic Oil Level/Leaks	23/11/2021			13/12/2021	Mnor Defects	Closed	
15684	3500 hours service	23/11/2021	3445	3041	13/12/2021	Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	Minor Defects	Closed Item Status	Assigned To/Completed By
15082	Prestart Defect - Hydraulic Oil Level/Leaks	22/11/2021			13/12/2021	Minor Defects	Closed	
15082	3000 hours service	01/09/2021	2945	2185	13/12/2021	Service	Closed	
14925	Prestart Defect - Operations & Maintenance Manual Available i	07/08/2021			13/12/2021	Mnor Defects	Closed	Cormac Sutton
14867	New trenching bucket teeth by 5	05/08/2021	0	0	05/08/2021	Repair at next service	Closed	Mchael Reynolds
14819	Weld on auto greaser	25/07/2021	0	0	13/12/2021	Urgent Machine Down	Closed	MalcolmMorgan
14820	Grease line	25/07/2021	0	0	25/07/2021	Repair at next service	Closed	Michael Reynolds
14861	Fix fire extinguisher	22/07/2021	2717	2111	22/07/2021	Mnor Defects	Closed	michael reynolds
14847	Prestart Defect - Current Hours	19/07/2021			13/12/2021		Closed	Aaron Myler
14829	Prestart Defect - Current Hours	14/07/2021			13/12/2021		Closed	Finn O'Doherty
14697	Prestart Defect - Current Hours	11/06/2021			12/06/2021		Closed	Colm Reilly
14683	Oil Sample - Pump Transmission Single/Front	09/06/2021	2508	2007	11/05/2021	Samples	Closed	
14678	Oil Sample- Engine Single/Front	09/06/2021	2508	2007	28/04/2021	Samples	Closed	
14672	Service	08/06/2021	2508	2007	08/06/2021	Service	Closed	michael reynolds
14573	2500 hours service	25/05/2021	2449	1979	08/06/2021	Service	Closed	michael reynolds
14564	Prestart Defect - Bucket/Blade Security/Condition Failed	24/05/2021			30/05/2021		Closed	Colm Reilly
14529	Oil Sample - Swing Transmission	20/05/2021	2413	1926	20/05/2021	Samples	Closed	
14533	Oil Sample- Travel Transmission R/H	20/05/2021	2413	1926	20/05/2021	Samples	Closed	
14342	Prestart Defect - Grease Lines/Grease Penetration Failed	28/04/2021			01/05/2021	Mnor Defects	Closed	Colm Reilly
14097	2000hr service	03/04/2021	2076	1767	03/04/2021	Service	Closed	michael reynolds
13969	Cutting edge	21/03/2021	1952	1658	21/03/2021	Modifications	Closed	michael reynolds
12466	squeak in quick hitch pump	29/01/2021	1557	1345	11/02/2021	Warranty	Closed	ColumReynolds
11996	1500 hours service	21/01/2021	1491	1300	04/03/2021	Service	Closed	michael reynolds
11747	1000hr Hydraulic oil service sample	15/01/2021	1445	1269	15/01/2021	Service	Closed	michael reynolds
11680	1000hr Engine oil sample	14/01/2021	1444	1267	14/01/2021		Closed	michael reynolds
11679	500hr engine oil sample	14/01/2021	1444	1267	14/01/2021		Closed	michael reynolds
11269	Prestart Defect - Bucket/Blade Security/Condition Failed	06/01/2021			15/01/2021	Samples	Closed	Sean Pearl
9272	1000 Hour Service	22/11/2020	1028	966	22/11/2020	Service	Closed	michael reynolds
7486	Prestart Defect - Any Machine Damage Failed	08/10/2020			08/10/2020	Mnor Defects	Closed	
7495	Prestart Defect - Any Machine Damage Failed	08/10/2020			08/10/2020	Mnor Defects	Closed	
7171	500 hour Service	29/09/2020	607	593	28/09/2020	Service	Closed	michael reynolds
6428	Prestart Defect - Any Machine Damage Failed	10/09/2020			10/09/2020	Mnor Defects	Closed	
6212	Prestart Defect - Any Machine Damage Failed	03/09/2020			10/09/2020		Closed	
6078	Prestart Defect - Fire Extinguishers & Fire Suppression (if f	31/08/2020			03/09/2020		Closed	
5968	250-HOUR SERVICE	27/08/2020	329	305	27/08/2020	Service	Closed	
4171	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylin	25/07/2020			15/08/2020		Closed	
4157	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylin	24/07/2020			15/08/2020		Closed	
4138	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylin	23/07/2020			15/08/2020		Closed	