

## Enviro Plant Hire Pty Ltd - Work Order Summary

**Asset:**  
EX11 - Hitachi ZH210LC-5 Excavator

**Location:**  
Enviro Yard

**Current Tracker Hours:**  
6012

**Current Tracker Kms:**  
8166

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
18993	Hitch rebuild	29/04/2025	6002	8166	29/04/2025	Repairs and Inspections	Closed	Peter Mylett
18968	Cleaned	18/04/2025	6000	8166	12/05/2025	Repairs and Inspections	Closed	Shaun Mbloney
18629	Hitachi Inspection report	10/02/2025	5992	8165	26/09/2024	Inspection Report	Closed	
18230	Off Hire cost C240685	31/10/2024	5987	8165	01/11/2024	Off hire repair cost report	Closed	
17381	6000 Hour Service	08/04/2024	5744	8112	30/09/2024	Service	Closed	Aaron Mc Hugh
17374	Machine failed to start	05/04/2024	5744	8112	27/03/2024	Modifications	Closed	
17110	H587 - Off Hire Checklist Defect/s	22/01/2024	5639	8092	01/02/2024	Mnor Defects	Closed	
17109	H587 - Off Hire Checklist Defect/s	22/01/2024	5639	8092	01/02/2024	Modifications	Closed	
17108	H587 - Off Hire Checklist Defect/s	22/01/2024	5639	8092	01/02/2024	Mnor Defects	Closed	
16913	Hitachi report	14/11/2023	5546	8075	14/11/2023	Mnor Defects	Closed	Malcolm Morgan
16856	hitachi report	16/10/2023	5544	8074	16/10/2023	Service	Closed	Malcolm Morgan
16703	H390 - Off Hire Checklist Defect/s	26/06/2023	5573	8074	14/08/2023	Modifications	Closed	
16577	Hitch sticking and 2 lights not working	28/03/2023	5567	8071	28/03/2023	Mnor Defects	Closed	Jack Davitt
16569	H205 - Off Hire Checklist Defect/s	27/03/2023	5564	8064	28/03/2023	Modifications	Closed	
16568	H205 - Off Hire Checklist Defect/s	27/03/2023	5564	8064	13/04/2023	Mnor Defects	Closed	
16567	H205 - Off Hire Checklist Defect/s	27/03/2023	5564	8064	13/04/2023	Off hire repair cost report	Closed	
16486	5500 hours service	19/02/2023	5450	7979	13/04/2023	Service	Closed	
16351	5000 hours service	28/09/2022	4951	7550	01/11/2022	Service	Closed	
16209	Ready for hire after off hire	01/07/2022	4499	7170	01/07/2022	Mnor Defects	Closed	
16208	Off hired work	01/07/2022	4499	7170	01/07/2022	Mnor Defects	Closed	michael reynolds
16181	4500 hours service	10/06/2022	4450	7147	30/10/2022	Service	Closed	
16158	Hydraulic fitting and bucket teeth	01/06/2022	4406	7104	31/05/2022		Closed	michael reynolds
16073	1000hr service (4000)	28/04/2022	4236	6805	26/06/2022	Mnor Defects	Closed	michael reynolds
15927	fire suppression fault	10/02/2022	3683	6033	14/02/2022	Modifications	Closed	michael reynolds
15804	Prestart Defect - Any Machine Damage Failed	07/01/2022			07/01/2022	Mnor Defects	Closed	
15782	Grease line failed	21/12/2021	3454	5844	05/02/2022	Modifications	Closed	michael reynolds
15781	3500hr service	21/12/2021	3454	5844	21/12/2021	Service	Closed	michael reynolds
15676	Prestart Defect - Grease Lines/Grease Penetration Failed	21/11/2021			13/12/2021	Mnor Defects	Closed	
15632	Prestart Defect - Any Machine Damage Failed	12/11/2021			13/12/2021	Mnor Defects	Closed	Aidan Holohan
15490	3000hr service	22/10/2021	3112	5429	22/10/2021	Service	Closed	Mchael Reynolds
14867	Prestart Defect - Fire Extinguishers & Fire Suppression (if f	25/07/2021			13/12/2021	Mnor Defects	Closed	Cormac Sutton

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
14086	2500hr service	21/07/2021	2594	4043	20/07/2021	Service	Closed	Michael Reynolds
14741	Oil Sample - Hydraulic	18/06/2021	2429	3567	20/05/2021	Samples	Closed	
14728	Prestart Defect - Covers & Guards Attached/Closed Failed	16/06/2021			13/12/2021		Closed	Malcolm Morgan
14681	Oil Sample - Engine Single/Front	09/06/2021	2381	3557	29/04/2021	Samples	Closed	
14675	Oil Sample - Coolant	09/06/2021	2381	3557	11/05/2021	Samples	Closed	
14673	isolators failed	08/06/2021	2372	3553	08/06/2021	Modifications	Closed	michael reynolds
14532	Oil Sample - Travel Transmission R/H	20/05/2021	2257	3532	20/05/2021	Samples	Closed	
14531	Oil Sample - Travel Transmission L/H	20/05/2021	2257	3532	20/05/2021	Samples	Closed	
14528	Oil Sample - Swing Transmission	20/05/2021	2257	3532	20/05/2021	Samples	Closed	
14484	Oil Sample	17/05/2021	2230	3532	13/05/2021	Samples	Closed	
14455	Prestart Defect - Any Machine Damage Failed	14/05/2021			14/05/2021		Closed	
14425	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylin	11/05/2021			13/12/2021		Closed	Malcolm Morgan
14317	Prestart Defect - Quick Hitch Security/Condition Failed	26/04/2021			02/05/2021	Modifications	Closed	Cormac Sutton
14083	2000 hours service	03/04/2021	1945	2738	01/05/2021	Service	Closed	michael reynolds
14071	Prestart Defect - Emergency Hammer Failed	01/04/2021			15/04/2021		Closed	
13696	Grease line broke	07/03/2021	1754	2384	07/03/2021		Closed	michael reynolds
13605	Prestart Defect - Grease Lines/Grease Penetration Failed	04/03/2021			15/04/2021	Mnor Defects	Closed	michael reynolds
13575	Prestart Defect - Emergency Hammer Failed	03/03/2021			15/04/2021	Mnor Defects	Closed	michael reynolds
13270	1500hr service	21/02/2021	1629	2232	20/02/2021	Service	Closed	
11881	Engine oil samples	18/01/2021	1400	1847	18/01/2021	Service	Closed	michael reynolds
11836	Travel motor oil sample	17/01/2021	1390	1846	17/01/2021	Service	Closed	michael reynolds
11746	500hr Travel motor oil sample	15/01/2021	1369	1838	15/01/2021	Service	Closed	michael reynolds
11745	500hr Travel motor oil sample	15/01/2021	1369	1838	15/01/2021	Service	Closed	michael reynolds
11686	500hr engine oil sample	14/01/2021	1362	1829	14/01/2021		Closed	michael reynolds
11427	Prestart Defect - Quick Hitch Security/Condition Failed	09/01/2021			29/03/2021		Closed	michael reynolds
10372	Prestart Defect - Bucket/Blade Security/Condition Failed	11/12/2020			19/12/2020		Closed	
10130	1000 Hour Service	07/12/2020	1091	1162	07/12/2020	Service	Closed	michael reynolds
9984	Prestart Defect - Operations & Maintenance Manual Available i	04/12/2020			04/12/2020		Closed	Wiremu Padlie
8836	Prestart Defect - Quick Hitch Security/Condition Failed	15/11/2020			15/11/2020		Closed	Wiremu Padlie
7697	500 Hour Service	13/10/2020	620	775	12/10/2020	Service	Closed	michael reynolds
7678	Prestart Defect - Pump Drive Oil Level/Leaks Failed	12/10/2020			20/10/2020		Closed	Wiremu Padlie
7540	Prestart Defect - Grease Lines/Grease Penetration Failed	09/10/2020			20/10/2020		Closed	Wiremu Padlie
7310	Prestart Defect - Damage, Wear, Play in Work Equipment, Cylin	03/10/2020			08/10/2020	Modifications	Closed	
6107	Prestart Defect - Any Machine Damage Failed	31/08/2020			01/09/2020		Closed	
5969	250 hour service	27/08/2020	0	0	27/08/2020	Service	Closed	
5234	New asset set up	21/05/2020			21/05/2020		Closed	