

Work Order #	Seg Number	Job Code	Component Code	Scope Code	DateOpened	Model	SerialNumber	EquipmentNumber
3810374	70	SYNCING PRODUCT LINK HRS.	PRODUCT LINK SYSTEM	Repair	04/18/2024	MT965C	C0965PNUTF1003	28-1026
3810374	0	TRAVEL TO FROM	JOB SITE	Repair	04/18/2024	MT965C	C0965PNUTF1003	28-1026
3795243	1	PERFORM	PM 3	Maintenance	03/06/2024	MT965C	C0965PNUTF1003	28-1026
3795243	0	TRAVEL TO FROM	JOB SITE	Maintenance	03/06/2024	MT965C	C0965PNUTF1003	28-1026
3667253	50	REPAIR	HYDRAULIC SYSTEM	Repair	02/23/2023	MT965C	C0965PNUTF1003	28-1026
3667253	0	TRAVEL TO FROM	JOB SITE	Repair	02/23/2023	MT965C	C0965PNUTF1003	28-1026
3656838	1	PERFORM	PM 1	Maintenance	01/19/2023	MT965C	C0965PNUTF1003	28-1026
3656838	0	TRAVEL TO FROM	JOB SITE	Maintenance	01/19/2023	MT965C	C0965PNUTF1003	28-1026
3616104	70	REPAIR	PRODUCT LINK SYSTEM	Repair	08/23/2022	MT965C	C0965PNUTF1003	28-1026
3616104	0	TRAVEL TO FROM	JOB SITE	Repair	08/23/2022	MT965C	C0965PNUTF1003	28-1026
3616050	10	REPAIR	ENGINE	Repair	08/23/2022	MT965C	C0965PNUTF1003	28-1026
3616050	0	TRAVEL TO FROM	JOB SITE	Repair	08/23/2022	MT965C	C0965PNUTF1003	28-1026
3553983	0	TRAVEL TO FROM	JOB SITE	Maintenance	01/18/2022	MT965C	C0965PNUTF1003	28-1026
3553983	1	PERFORM	PM 2	Maintenance	01/18/2022	MT965C	C0965PNUTF1003	28-1026
3553983	2	ADD	GREASE/OILS/LUB/FLUIDS	Maintenance	01/18/2022	MT965C	C0965PNUTF1003	28-1026
3536628	0	TRAVEL TO FROM	JOB SITE	Repair	11/05/2021	MT965C	C0965PNUTF1003	28-1026
3536628	10	REPAIR	ENGINE	Repair	11/05/2021	MT965C	C0965PNUTF1003	28-1026
3524150	71	REPLACE	SUSPENSION SEAT	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	0	TRAVEL TO FROM	JOB SITE	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	72	REMOVE & INSTALL	SUSPENSION SEAT	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	10	TROUBLE SHOOT	ENGINE	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	1	TRAVEL TO FROM	JOB SITE	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	70	INSPECT	SUSPENSION SEAT	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	30	REPAIR	ELECTRIC ARMREST	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	31	REPAIR	JOYSTICK	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3524150	50	REPLACE GASKET/RESEAL	QUICK COUPLER	Repair	09/22/2021	MT965C	C0965PNUTF1003	28-1026
3519275	0	TRAVEL TO FROM	JOB SITE	Maintenance	09/03/2021	MT965C	C0965PNUTF1003	28-1026
3519275	1	PERFORM	PM 1	Maintenance	09/03/2021	MT965C	C0965PNUTF1003	28-1026
3320801	0	TRAVEL TO FROM	JOB SITE	Maintenance	09/30/2020	MT965C	C0965PNUTF1003	28-1026
3320801	2	ADD	GREASE/OILS/LUB/FLUIDS	Maintenance	09/30/2020	MT965C	C0965PNUTF1003	28-1026
3320801	1	PERFORM	PM 3	Maintenance	09/30/2020	MT965C	C0965PNUTF1003	28-1026
3303715	70	PERFORM PRODUCT UPDATE ON	PRODUCT LINK SYSTEM	Other	07/30/2020	MT965C	C0965PNUTF1003	28-1026
3303715	0	TRAVEL TO FROM	PRODUCT LINK SYSTEM	Other	07/30/2020	MT965C	C0965PNUTF1003	28-1026
3232056	0	TRAVEL TO FROM	JOB SITE	Maintenance	10/04/2019	MT965C	C0965PNUTF1003	28-1026
3232056	1	PERFORM	PM 2	Maintenance	10/04/2019	MT965C	C0965PNUTF1003	28-1026
3232056	2	REFILL	GREASE/OILS/LUB/FLUIDS	Maintenance	10/04/2019	MT965C	C0965PNUTF1003	28-1026
3024575	70	INSTALL	PRODUCT LINK SYSTEM	Other	01/17/2017	MT965C	C0965PNUTF1003	28-1026
3024575	0	TRAVEL TO FROM	JOB SITE	Other	01/17/2017	MT965C	C0965PNUTF1003	28-1026