



Towlift Salt Lake City
2530 W 1500 S
SALT LAKE CITY, UT 84104

TOWLIFT

Phone: (801) 685-2535

INVOICE

3407945

Invoice	Date	Customer
7I131524	12/29/2025	70001112

Page 1 of 2

Sold to :

Shipped to :

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

Phone: (801) 766-2592

Branch Invoiced: **TL Salt Lake**

Salesperson :

Dept Invoiced : **Service**

Registration :

Notes :

Quantity	Product Id	Description	Unit Price	Total Price				
Cust PO# :			Entered by :	DIS Tasks				
Work Order :7W119547	Seg 1: No start. Contact Miguel to schedule a tim		11/17/25	Field				
Make	Model	Serial ID/Plate	Year	Date	Odometer	H-Meter	Dealer ID	Customer Eq ID
JCB	510-56	JCB5CGXGH02437251				3,699.00	713019	

11.17.25

Drove to customer location and found the machine had been driven to a different location in the job site and I found it with the boom in the air and a pallet on it indicating that it had been working. When I tried to start it, I only got a click out of it and then nothing happened.

I tested the battery and it had approximately 750 cold cranking amps out of 950. I tried to jump it, and it sucked all the juice out of my jump pack, which was fully charged and still wasn't able to jump it.

Ran out of time today and will have to most likely swap out the battery tomorrow

11.18.25

Drove to the job site and spoke to the foreman, he told me that it was running fine at first and then started to chug and hesitate. They thought it was out of fuel so they filled the tank, but then it wouldn't turn over so they got a pick up truck to jump it. But all that happened was the batteries cables got really hot.

There isn't a battery in the area, so I went to the shop in slc to get one and drove back to test. No change. The starter is seized/burned up and will need replaced.

11.20.25

Drove to job site and pulled the old starter. Tried turning the flywheel with a long pry bar but it wouldn't move in either direction even a little bit. Tried the new starter and it did the same thing that the old one did. So I removed it and disconnected the fuel lines and tried to remove the injectors but they are seized in there pretty good and will need a special tool to remove.

The plastic Y pipes are heat damaged also and brittle. one broke easily. Also found the turbo blade is chewed and torn up and it has been grinding on the compressor walls. Not sure what all is going on, but there's a couple codes and the engine is seized. It will need brought to the shop for easier access

12.3.25

Haven't heard back from the customer. Returned the starter to the parts department since that wasn't the issue. I believe that the customers operators turned the engine over so many times that it flooded the engine and Hydro locked it. So the injectors will have to be pulled to pump out the diesel and relieve the pressure. Otherwise it won't be able to turn over. I can do it in the field or at the shop, whichever the customer prefers.

Total Labor

2,040.00

**TOWLIFT**

Towlift Salt Lake City
2530 W 1500 S
SALT LAKE CITY, UT 84104

INVOICE

3407945

Invoice	Date	Customer
7I131524	12/29/2025	70001112

P: (801) 685-2535

Sold to :

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

Shipped to :

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

P: (801) 766-2592

Branch Invoiced: **TL Salt Lake**

Salesperson :

Dept Invoiced : **Service**

Registration :

Notes :

Quantity	Product Id	Description	Unit Price	Total Price
SS		Service Consumables		125.00
		Total Other Charges		125.00

Due Date	Payment	Amount	Paid	Tax	Basis	Tax Rate	Tax Amount
01/28/26	On Account	2,324.14		UT LEHI OTHER	125.00	0.10%	0.13
				UT LEHI OTHER	2,040.00	0.10%	2.04
				UT LEHI TRANSIT	125.00	1.05%	1.31
				UT LEHI TRANSIT	2,040.00	1.05%	21.42
				UT LOCAL-COUNT'	125.00	1.35%	1.69
				UT LOCAL-COUNT'	2,040.00	1.35%	27.54
				Utah	125.00	4.85%	6.06
				Utah	2,040.00	4.85%	98.95

Detach at line and return with payment

Total Amount :	2,165.00
Sales Tax :	159.14
Total :	2,324.14
Payment :	0.00
To Pay :	2,324.14

**TOWLIFT**

Remit To:

Towlift Salt Lake City
PO BOX 674601
DALLAS, TX 75267-4601

Invoice	7I131524
Date	12/29/2025
Customer	70001112

All amounts are in US Dollars (\$)

Accounts over 30 days are subject to a 1.5 % service charge (annual rate 18 %), and all costs of collection including reasonable attorney's fee.



Towlift Salt Lake City
2530 W 1500 S
SALT LAKE CITY, UT 84104

TOWLIFT

INVOICE

3384245

☎ P: (801) 685-2535

Invoice	Date	Customer
71130514	11/14/2025	70001112

Sold to :

Shipped to :

Page 1 of 2

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

NEXT EXTERIORS

160 S 1350 E
LEHI, UT 84043

P: (801) 766-2592

Branch Invoiced: **TL Salt Lake**

Salesperson :

Dept Invoiced : **Service**

Registration :

Notes :

Quantity	Product Id	Description	Unit Price	Total Price				
Cust PO# :			Entered by :	DIS Tasks				
Work Order :7W118782	Seg 1: **FIELD** CUSTOMER WOULD LIKE OIL PAN REPLA		09/30/25	Field				
Make	Model	Serial ID/Plate	Year	Date	Odometer	H-Meter	Dealer ID	Customer Eq ID
JCB	510-56	JCB5CGXGH02437251				3,699.00	713019	
11.12.25								
Drove to the machine's location on a job site, removed engine, bay cover, drilled out the stripped out bolts that were holding the hydraulic valve onto the boom and removed the old valve. Re used two of the old fittings and replaced their O rings. Went offsite to get four new bolts for the hydraulic valve. Installed the new hydraulic valve, installed new engine oil filter and both engine air filters. Cleaned off hydraulic spillage.								
11.13.25								
Finish installing the remaining filters and remove the old oil pan and install a new one after cleaning off all of the old gasket. Cleaned excess oil from the engine bay, there may be some residual that drips out. Ran and tested the machine and found that there was an error code on the dash indicating an issue with the ECM. But since we don't have the equipment to read a JCB engine, it'll have to be outsourced.								
14	15W40	NR						
1	AIR FILTER	NR						
1	OIL FILTER	NR						
1	OIL PAN	NR						
1	FILTER FUEL	NR						
1	FUEL FILTER	NR						
1	REGEN VALVE BLOCK	NR						
1	AIR FILTER	NR						
Total Parts								
7,697.84								
Total Labor								
2,805.00								
FI	Freight In							
31.25								
Total Misc								
31.25								
SS	Service Consumables							
275.00								
Total Other Charges								
275.00								

**TOWLIFT**

Towlift Salt Lake City
 2530 W 1500 S
 SALT LAKE CITY, UT 84104

INVOICE

3384245

Invoice	Date	Customer
7I130514	11/14/2025	70001112

☎ P: (801) 685-2535

Sold to :

NEXT EXTERIORS
 160 S 1350 E
 LEHI, UT 84043

Shipped to :

NEXT EXTERIORS
 160 S 1350 E
 LEHI, UT 84043

Page 2 of 2

P: (801) 766-2592

Branch Invoiced: **TL Salt Lake**

Salesperson :

Dept Invoiced : **Service**

Registration :

Notes :

Quantity	Product Id	Description	Unit Price	Total Price

Due Date	Payment	Amount	Paid	Tax	Basis	Tax Rate	Tax Amount
12/14/25	On Account	11,601.29		UT LEHI OTHER	31.25	0.00%	0.00
				UT LEHI OTHER	7,972.84	0.10%	7.99
				UT LEHI OTHER	2,805.00	0.10%	2.80
				UT LEHI TRANSIT	31.25	0.00%	0.00
				UT LEHI TRANSIT	7,972.84	1.05%	83.73
				UT LEHI TRANSIT	2,805.00	1.05%	29.45
				UT LOCAL-COUNT	31.25	0.00%	0.00
				UT LOCAL-COUNT	7,972.84	1.35%	107.63
				UT LOCAL-COUNT	2,805.00	1.35%	37.87
				Utah	31.25	0.00%	0.00
				Utah	7,972.84	4.85%	386.69
				Utah	2,805.00	4.85%	136.04

Detach at line and return with payment

**TOWLIFT**

Total Amount :	10,809.09
Sales Tax :	792.20
Total :	11,601.29
Payment :	0.00
To Pay :	11,601.29

Remit To:

Towlift Salt Lake City
 PO BOX 674601
 DALLAS, TX 75267-4601

Invoice	7I130514
Date	11/14/2025
Customer	70001112
All amounts are in US Dollars (\$)	

Accounts over 30 days are subject to a 1.5 % service charge (annual rate 18 %), and all costs of collection including reasonable attorney's fee.