



818 HOFFIES DRIVE
 SIDNEY, NE 69162
 P: (308) 254-5956
 F: (308) 254-6389
 Dealer Code: FAQTD



SERVICE INVOICE: R103018500:01

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE
12/16/2025 10:42:34AM	12/16/2025	SRET	ESTEPHONR	CARD	

YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2020	FREIGHTLINER	CAS	1FUJHHDR5LLKN2083	747	0			952000

Sold Operations

JOB #1 EA EXPRESS ASSESSMENT

COMPLAINT CAUSE EXPRESS ASSESSMENT- CUSTOMER WANTS WATER PUMP REPLACE (LEAKING) TECH HAS PARTS

CORRECTION PULLED UNIT INTO SHOP AND UNIT HAS CODES. 111/1, 111/18 (COOLANT LEVEL LOW) (COOLANT LEVEL VERY LOW). UNIT ALSO HAS CODES 3216/21 (SCR NOx INLET DRIFT LOW) 520342/17 (DEF PUMP SPEED HIGH) 520371/16 (SCR CLOSED LOOP CONTROL MAX LIMIT) 4364/17 (SCR CONVERSION LOW). HAD FRONT COUNTER CONTACT DRIVER AND DRIVER ONLY WANTED THE COOLANT LEVEL CODES LOOKED AT AND WATER PUMP REPLACED. DRAINED COOLANT FROM BLOCK DRAIN, REMOVED THE CAC OUTLET BOOT, BELT, WATER PUMP PULLEY, WATER PUMP, AND ELECTRICAL. REMOVED OLD GASKET MATERIAL FROM THE MOUNTING SURFACE. INSTALLED NEW GASKET AND WATER PUMP. TORQUED TO SPEC. INSTALLED THE PULLEY, TORQUED TO SPEC. INSTALLED THE BELT, ELECTRICAL, CAC BOOT, AND FILLED UNIT WITH COOLANT. POWER WASHED UNITS ENGINE BAY AND TOOK UNIT ON A TEST DRIVE. INSPECTED UNIT WHEN IT CAME BACK FROM THE TEST DRIVE AND FOUND NO FAULTS (LEAKS). THE MIL IS ON DO TO THE AFTERTREATMENT FAULTS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR EA	EXPRESS ASSESSMENT		475.00
1	ELECT	ELECTRONIC HOOKUP FEE	125.00	125.00
1	103D/DDE EA4722002801	LU COOLANT PUMP	1,046.39	1,046.39
1	103D/DDE EA4722002801-CORE	LU COOLANT PUMP	375.00	375.00
-1	103D/DDE EA4722002801-CORE	LU COOLANT PUMP	375.00	-375.00

Prepay: \$0 Parts: \$1,046.39 Labor: \$475.00 Misc: \$125.00 Sublet: \$0 \$1,646.39

JOB #2 QC QUALITY INSPECTIONS

COMPLAINT CAUSE QUALITY INSPECTIONS

CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR QC	QUALITY INSPECTION		0.00

Prepay: \$0 Parts: \$0 Labor: \$0 Misc: \$0 Sublet: \$0 \$0.00