

KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Invoice To:	
	_

Branch					
CAMROSE		*REPI	*TNI		
Date	Time				Page
10/22/24	22:	20:09	(B)		01
Account No	Phone No	,		Inv N	No.
Ship Via		Purchase	Order		
Tax ID No					
			Sale	sperso	on
				137	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C016161 X9 1000 COMBINE 309 1H0X910XHN0820583 08/01/24

X9 1000 226 RG6136U003339 HX404

GST# 895703353

SEGMENT# 1 C 188 NA 09/16/24 09/16/24

BRI inspection

LABOR 2595.00 10104001 SEGMENT TOTAL==> 2595.00

09/19/24 09/19/24

SEGMENT# 2 C 188 NA

FEEDER HOUSE

CORRECTION:

Freed up the lower drive sprocket on the reverser shaft.

Adjusted the feeder chain tension.

Loosened off the feeder drive chain. Removed the chain guide and bracket. Installed the new chain guide and

bracket. Tensioned chain to specification.

ADDITIONAL DESCRIPTION:

-ADJUST FEEDER CHAIN TENSION (0.25) DA

-FREE UP LOWER FEEDER DRIVE SPROCKET (0.5) DA

-REPLACE CHAIN GUIDE AND BRACKET (1.5) DA

AXE99762 Bracket 1 N 673.02 673.02 HXE160082 Guide 1 N 93.20 93.20

PARTS 766.22 LABOR 393.75

10104001 SEGMENT TOTAL==> 1159.97

SEGMENT# 3 C 188 NA

09/19/24 09/19/24

SERVICE

CORRECTION:

-CHANGE ENGINE OIL AND FILTER

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 **WAINWRIGHT:** 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

135.87

Invoice To:			

Time				Page
22:	20:09	(B)		02
Phone No	ı		Inv N	10
	Purchase	Order		
		Sales	sperso	n
			137	
	22:	22:20:09 Phone No	22:20:09 (B) Phone No Purchase Order Sales	22:20:09 (B) Phone No Inv N

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C016161 X9 1000 COMBINE 309 1H0X910XHN0820583 08/01/24

X9 1000 226 RG6136U003339 HX404

- -CHANGE FUEL FILTERS, CLEAN OUT SEDIMENT BOWL
- -CHANGE TRANSMISSION FILTER
- -CHANGE TRANSMISSION RETURN FILTER
- -CHANGE MAIN ENGINE GEAR CASE/ROTOR LUBE FILTER
- -CHANGE FINAL DRIVE OILS
- -CHANGE PRIMARY ENGINE AIR FILTER
- -CHANGE CAB AIR AND CAB RECIRCULATION FILTER
- -TOP UP CHOPPER GEAR CASE OIL
- -RELOCATE LADDER CABLE
- -DISCHARGE WATER EXTINGUISHER AND DRAIN WATER

ADDITIONAL DESCRIPTION:

- -CHANGE ENGINE OIL AND FILTER (1.0) -- JB
- -CHANGE FUEL FILTERS, CLEAN OUT SEDIMENT BOWL (1.0) -- JB
- -CHANGE TRANSMISSION FILTER (0.5) -- JB
- -CHANGE TRANSMISSION RETURN FILTER (1.0) -- JB
- -CHANGE MAIN ENGINE GEAR CASE/ROTOR LUBE FILTER (1.0)
- -CHANGE FINAL DRIVE OILS (1.5)
- -CHANGE PRIMARY ENGINE AIR FILTER (0.25)
- -CHANGE CAB AIR AND CAB RECIRCULATION FILTER (0.25)
- -TOP UP CHOPPER GEAR CASE OIL (0.25)
- -RELOCATE LADDER CABLE (0.5)

AXE103407

-DISCHARGE WATER EXTINGUISHER AND DRAIN WATER (0.25)

	2			
Hydra	ulic Filter			
AXE70605	AIR FILTER	1 N	35.31	35.31
DZ124761	Filter Element	1	147.30	147.30
DZ124786	Filter Element	1	141.51	141.51
EF4663	RECYC FEE OIL	7	1.00	7.00
EF4665	RECYC FEE OIL	5	.40	2.00
EF4666	RECYC FEE OIL	3	2.00	6.00
		CONTI	NUED ON PAGE 03	

1

135.87

Hydraulic Filte

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To:	
•	-

Invoice To:	

Branch					
Branch					
CAMROSE					
Date	Time				Page
10/22/24	22:2	0:09	(B)		03
Account No	Phone No			Inv N	lo lo
Ship Via	F	urchase	Order		
Tax ID No					
	,		Sales	sperso	n
				137	
	-	zurchase	Sales		on

SERVICE INVOICE

STK#/FLEET#		HRS PIN/EIN	WARR	ANTY DATE	HRS	
C016161	X9 1000 COMBINE	309 1H0X910XHN0	820583	08/01/24		
	X9 1000	226 RG6136U0033	39 HX404			
FRT		FREIGHT	1	15.00		15.00
RE284091		FILTER CAB AIR	1	109.84		109.84
RE572785		FILTER ENG OIL	1	136.64		136.64
RE577250		FILTER HYDRAULI	2	141.03		282.06
	Hydraulic Filt	er				
RE577612		FILTER HYDRAUL	1	179.77		179.77
TY26679		15W40 PLUS 18.9	3	159.28		477.84
	Plus-50 II Oil	15W40 CJ4/SN				
TY26815		80W90 3.78L	5	59.21		296.05
14M7298		8MM FLNGE NUT	3	2.11		6.33
19M7897		BOLT M8X35 FLNG	2	3.58		7.16
				PARTS		1985.68
				LABOR		1312.50
10104001			SEGMENT	' TOTAL==>		3298.18

SEGMENT# 4 C 188 NA RIGHT HAND SIDE 09/19/24 09/19/24

CORRECTION:

Loosened off the elevator drive belt. Located the joiner link, loosened off and separated the elevator chain. Disassemble the bearing assembly from the auger. Removed the key and replaced the key. Reassembled in reverse order. Tensioned the chain to specification. Tensioned the drive belt.

ADDITIONAL DESCRIPTION:

-REPLACE KEY ON	CLEAN GRAIN LOWER SPROCKE	T AND TENSION CHAIN	
49M6480	SHAFT KEY	1 6.06	6.06
		PARTS	6.06
		LABOR	262.50
10104001		SEGMENT TOTAL==>	268.56
		CONTINUED ON	PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To:

Invoice To:

Branch						
Date	Time				Page	
10/22/24	22:20	:09	(B)		04	
Account No	Phone No	Phone No		Inv No		
Ship Via	Pu	Purchase Order				
Tax ID No						
			Sale	Salesperson		
				137		

HRS

SERVICE INVOICE

STK#/FLEET#

C016161

X9 1000 COMBINE

X9 1000

HRS PIN/EIN WARRANTY DATE

08/01/24

1H0X910XHN0820583

226 RG6136U003339 HX404

SEGMENT# 5 C 188 NA

RUN AND CHECK

09/16/24 09/16/24

309

LABOR

351.75

10104001

SEGMENT TOTAL ==>

351.75

WORK ORDER TOTALS *****

PARTS

2757.96 4915.50

LABOR

100.00

SERV ACCESORIES SUB TOTAL ==>

7773.46

GST

388.69

1234

MASTERCARD CHARGE

8162.15

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.