



Office Admin Crooked Creek Farms Ltd. <office.ccfarms@gmail.com>

**Invoice 5694 from ShierTech**

1 message

**ShierTech** <quickbooks@notification.intuit.com>  
Reply-To: shiertech2016@gmail.com  
To: office.ccfarms@gmail.com

Wed, Sep 4, 2024 at 9:54 AM

INVOICE 5694 DETAILS



ShierTech

**\$47,097.77**

Print or save

Powered by QuickBooks

*[Handwritten scribble]*

*Just To Approve  
Thomas Approved w/ Just P  
67200*

**POSTED**  
*[Handwritten signature]*

Dear **MONUMENT FARMS,**

Please see your invoice attached. Thank you for your prompt payment.

We appreciate your business!

ShierTech

**\*\* WE NOW ACCEPT ALL MAJOR CREDIT CARDS\*\***  
**(3% FEE/TRANSACTION WILL BE APPLIED)**

**Bill to**

MONUMENT FARMS  
PO Box 2521  
STRATHMORE AB T1P1A0

**Terms**

Due on receipt

**Hours**

3148

**Model**

9470R

**Serial number**

056478

SERVICE CALL

0.80 X \$145.00

\$116.00

REAR DRIVELINE FAILURE, CAUSING DAMAGE TO PARK BRAKE AND GUDGEON COMPONENTS

Cut rear out put shaft bolts off and removed shaft  
Packed rags into output yoke to seal momentarily  
Removed right steering cylinder  
Replaced h circuit pressure sensor  
Started tractor and got to move in r2 and f 10 only  
RECOVER TRACTOR INTO WORKSHOP

Split tractor and remove gudgeon frame  
Pull gudgeon spindle, fuel tank, rear axle frame to remove failed drive shaft  
Replaced:  
Rear driveshaft  
Rear frame spindle  
Spindle nut/cap and bearing  
New gudgeon bushings, thrust washer and seals  
Lower drive shaft assembly

Rear drive shaft yoke  
 Front driveline seal housing  
 Rear output shaft bearing  
 Park brake housing  
 Parkbrake piston plate  
 Park brake friction pack  
 Park brake solenoids  
 Park brake pressure sensor  
 RH steering cylinder assembly  
 Repair transmission wiring harness  
 Replace damaged hose for pto return  
 Replace 2x leaking hoses to steering valve  
 Replace leaking hose for brake signal line  
 Pto temperature sensor  
 New transmission filters  
 Reassemble tractor  
 New oil 116L hygard  
 Road test machine  
 Check park brake function  
 Check for leaks  
 Wash off machine  
 Grease

82.40 X \$145.00

\$11,948.00

## RE217077 - TRANS OIL SENSOR

1 X \$225.79

\$225.79

## RE26738 - SEAL

1 X \$83.13

\$83.13

## YZ502762 - SOLENOID

1 X \$414.51

\$414.51

## YZ502763 - SOLENOID

1 X \$451.46

\$451.46

## RWA11097 - REPAIR WIRE

5 X \$8.40

\$42.00

## 57M11405 - ELEC CONNECT

4 X \$3.92

\$15.68

## LIQUID NITROGEN

1 X \$133.00

\$133.00

## R247733 - BUSHING

2 X \$110.09

\$220.18

## R341446 - HYDRAULIC

1 X \$173.99

\$173.99

## RE224072 - HOSE CLAMP

2 X \$27.37

\$54.74

## DZ123024 - SENSOR

1 X \$83.97

\$83.97

## RE292880 - BEARING

1 X \$116.43

\$116.43

## YZ501843 - PISTON

1 X \$463.59	\$463.59
YZ501845 - SEAL	
1 X \$35.46	\$35.46
YZ501881 - O RING	
1 X \$25.11	\$25.11
YZ501846 - SEAL	
1 X \$40.41	\$40.41
YZ100952 - CLUTCH	
11 X \$105.62	\$1,161.82
TR108559 - BRAKE DISC	
10 X \$54.64	\$546.40
RE577250 - HYDRAULIC	
1 X \$159.20	\$159.20
3962 - EHC FILTER	
2 X \$1.25	\$2.50
RE577612 - FILTER	
1 X \$202.94	\$202.94

## RE217077 - TRANS OIL

1 X \$228.01	\$228.01
--------------	----------

## 57M8625 - ELEC

2 X \$8.05	\$16.10
------------	---------

## R559661 - BEARING

1 X \$314.93	\$314.93
--------------	----------

## T120229 - ORIFICE

2 X \$23.70	\$47.40
-------------	---------

## YZ502846 - COVER

1 X \$1,011.39	\$1,011.39
----------------	------------

## F37030273 - O RING

1 X \$22.81	\$22.81
-------------	---------

## R292881 - BEARING

1 X \$64.71	\$64.71
-------------	---------

## RE597090 - SEAL

2 X \$74.93	\$149.86
-------------	----------

## RE574875 - UNIVERSAL

1 X \$1,048.21	\$1,048.21
----------------	------------

## YZ502316 - V RING

1 X \$44.06

\$44.06

## AHC18385 - HYDRAULIC CYLINDER

1 X \$3,336.94

\$3,336.94

## R104771 - BEARING

2 X \$389.25

\$778.50

## R104770 - THRUST

2 X \$559.94

\$1,119.88

## R104769 - WEAR PLATE

1 X \$138.97

\$138.97

## R248387 - SPINDLE

1 X \$5,811.05

\$5,811.05

## RE584436 - UNIVERSAL

1 X \$5,781.62

\$5,781.62

## R114105 - SCREW

4 X \$18.97

\$75.88

## R98309 - CAP SCREW

1 X \$27.80	\$27.80
W23832 - SPACER	
1 X \$38.05	\$38.05
U11017 - O RING	
1 X \$10.75	\$10.75
RE26738 - SEAL	
2 X \$83.13	\$166.26
U15409 - SNAP RING	
2 X \$38.60	\$77.20
R557734 - CAP	
1 X \$785.45	\$785.45
H208187 - SCREW	
4 X \$8.63	\$34.52
15H558 - PIPE PLUG	
2 X \$8.48	\$16.96
JD7760 - LUBRICANT	
1 X \$1.68	\$1.68

## R86105 - V RING

1 X \$124.40

\$124.40

## RE24390 - BALL BEARING

1 X \$329.49

\$329.49

## R84624 - RETAINER

2 X \$63.27

\$126.54

## RE572678 - UNIVERSAL

1 X \$3,061.27

\$3,061.27

## R124124 - UNIVERSAL

1 X \$1,171.46

\$1,171.46

## RESTOCKING FEE

1 X \$275.00

\$275.00

## R247735 - SEAL

2 X \$32.39

\$64.78

## RE588595 - HYDRAULIC

1 X \$355.16

\$355.16

## KH-201-12 - HOSE ASSY

1 X \$201.26

\$201.26

**KH-201-12 - HOSE ASSY**

1 X \$175.79

**\$175.79**

**HYDRAULIC OIL**

116 X \$8.66

**\$1,004.56**

**SHOP SUPPLIES 5% OF TOTAL TO MAX OF \$100**

1 X \$100.00

**\$100.00**

---

Subtotal	<b>\$44,855.01</b>
GST @ 5%	<b>\$2,242.76</b>
Total	<b>\$47,097.77</b>
Balance due	<b>\$47,097.77</b>

Please be advised there is a 2% interest charge after 14 days on overdue invoices.

**\*Multiple methods of payment accepted\***

---

Please make cheques payable to ShierTech and E-Transfers to shiertech2016@gmail.com

Multiple methods of payment accepted. If you have any questions regarding payment, please don't hesitate to reach out.

**Print or save**

---

**ShierTech**