



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 1 of 10
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**/4WDOP9560R G Internal**

COMPLAINT:

01 RECONDITIONING INSPECTION 4WD TRACTOR

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	90.27	90.27	\$90.27	N
<b>Labor: \$1,504.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$90.27</b>	<b>Sub-Total: \$1,594.77</b>		

**Gen4- Internal**

COMPLAINT:

04 DIAGNOSE COOLANT PRESSURE SENSOR CODE

CORRECTION:

- Added coolant and ran machine, no code came back.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26576	9.46L COOL-GARD PREMIX	1.00	60.49	60.49	\$60.49	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF240	ENVIRO FEE	1.00	2.40	2.40	\$2.40	N
SERVACCESS	SERVICE ACCESSORIES	1.00	19.11	19.11	\$19.11	N
<b>Labor: \$318.60</b>	<b>Parts: \$60.49</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$21.51</b>	<b>Sub-Total: \$400.60</b>		

**/1409689560R F Internal**

COMPLAINT:

05 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:

- Update all controllers.



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 2 of 10
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**/1409689560R F Internal**

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
<b>Labor: \$265.50</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$15.93</b>	<b>Sub-Total: \$281.43</b>	

**/1100019560R F Internal**

COMPLAINT:  
 06 CHANGE ENGINE OIL AND FILTER

CORRECTION:

Disconnect battery ground cable. Drain oil pan and oil filter housing. Remove oil filter. Reinstall to specifications. Check operation of machine and for leaks.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE572785	Engine Oil Filter	1.00	135.70	135.70	\$135.70	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	87.97	87.97	\$87.97	N
TY26679	18.9L 15W40 PLUS 50 II	2.00	167.51	167.51	\$335.02	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
<b>Labor: \$132.75</b>		<b>Parts: \$558.69</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$15.97</b>	<b>Sub-Total: \$707.41</b>	

**/1100689560R F Internal**

COMPLAINT:  
 07 CHANGE FUEL FILTERS

CORRECTION:

- Drain fuel filters, remove and discard. Clean filter base. Install new filter and mark hours and date. Prime fuel system.



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 3 of 10
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**/1100689560R F Internal**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	211.38	211.38	\$211.38	N
RE539465	Primary Engine Fuel Filter	1.00	168.18	168.18	\$168.18	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N

**Labor: \$88.50      Parts: \$379.56      OL&M: \$0.00      Misc: \$7.31      Sub-Total: \$475.37**

**/1100189560R F Internal**

COMPLAINT:  
 08 REPLACE ENGINE AIR FILTERS

CORRECTION:  
 - Remove and discard old filters. Install new filters and mark date and hours on them.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE230985	Engine Secondary Air Filter	1.00	162.22	162.22	\$162.22	N
RE312946	Primary Air Filter	1.00	443.16	443.16	\$443.16	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.12	2.12	\$2.12	N

**Labor: \$35.40      Parts: \$605.38      OL&M: \$0.00      Misc: \$2.12      Sub-Total: \$642.90**

**/9010M9560R F Internal**

COMPLAINT:  
 09 CAB RECIRCULATING AIR FILTERS, R&R OR REPLACE

CORRECTION:



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 4 of 10
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**/9010M9560R F Internal**

- Remove cover on outside of cab, remove filter and discard filter. Clean cover, mark hours and date on new filter and install filter and cover to outside of cab. Remove cover inside cab and remove filter. Discard filter. Mark hours and date on filter. Install filter and cover in cab.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE284091	Cab Fresh Air Filter	1.00	115.62	115.62	\$115.62	N
RE291412	Recirculating Cab Air Filter	1.00	128.04	128.04	\$128.04	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	9.30	9.30	\$9.30	N
<b>Labor: \$115.05</b>		<b>Parts: \$243.66</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$9.30</b>	<b>Sub-Total: \$368.01</b>	

**/1200869560R F Internal**

COMPLAINT:  
 10 REPLACE TRANSMISSION AND HYDRAULIC FILTERS

CORRECTION:

- Remove and discard the 4 filters. Clean filter base. Install 4 new filters with new o-rings. Mark hours and date on them.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R564922	Ring	4.00	14.60	14.60	\$58.40	N
RE577612	Hydraulic Filter	4.00	178.51	178.51	\$714.04	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
EF100	ENVIRO FEE	3.00	1.00	1.00	\$3.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>		<b>Parts: \$772.44</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$13.62</b>	<b>Sub-Total: \$963.06</b>	

**GEN12- Internal**

COMPLAINT:  
 12 CHANGE OR REPAIR ENGINE FAN SHROUD ( CRACKED )



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 5 of 10
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**GEN12- Internal**

**CORRECTION:**

- Remove hood. Disconnect cooling package and move away from engine. Remove engine fan. Remove shroud. Install in reverse order.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
57M9775	ELEC. CONN	1.00	6.59	6.59	\$6.59	N
57M9809	Elec. Connector Terminal	2.00	2.52	2.52	\$5.04	N
R28782	O-RING	1.00	2.99	2.99	\$2.99	N
R320565	GASKET	2.00	19.87	19.87	\$39.74	N
RE285844	Clamp	1.00	163.16	163.16	\$163.16	N
RE52702	CLAMP	1.00	35.37	35.37	\$35.37	N
T77613	#6 Flat Face O-Ring	1.00	3.17	3.17	\$3.17	N
TA20506	Shroud	1.00	425.16	425.16	\$425.16	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
<b>Labor: \$2,124.00</b>		<b>Parts: \$681.22</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$96.00</b>	<b>Sub-Total: \$2,901.22</b>	

**GEN15- Internal**

**COMPLAINT:**

15 CHANGE ORINGS ON AXLE LUBE PRESSURE CONTROL VALVE

**CORRECTION:**

- Clean area around leak. Change o-ring on line, still leaks, it is actually the crimp on the hose leaking. Remove hose. Install new hose with new o-rings.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
51M7047	O-Ring	2.00	7.48	7.48	\$14.96	N



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 6 of 10
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**GEN15- Internal**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
51M7048	O-RING	2.00	7.42	7.42	\$14.84	N
T77857	#8 Flat Face O-Ring	2.00	3.24	3.24	\$6.48	N
X1JS43-8-8	HOSE FITTING FEMALE ORF LONG	2.00	29.23	29.23	\$58.46	N
X487-8-RL	1/2" 4000psi Hydraulic Hose	5.00	11.66	11.66	\$58.30	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	45.66	45.66	\$45.66	N

**Labor: \$761.10      Parts: \$153.04      OL&M: \$0.00      Misc: \$45.66      Sub-Total: \$959.80**

**GEN16- Internal**

COMPLAINT:  
 16 CHANGE SEAT SHOCK ( LEAKS AND MAKES NOISE )

CORRECTION:  
 - Raise seat and block up. Remove seat shock and install new shock. Bleed air from system.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE165499	Actuator	1.00	1,047.32	1,047.32	\$1,047.32	N
RE167426	SEAT KIT	1.00	75.25	75.25	\$75.25	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FREIGHT	FREIGHT	1.00	20.00	20.00	\$20.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

**Labor: \$265.50      Parts: \$1,122.57      OL&M: \$0.00      Misc: \$35.93      Sub-Total: \$1,424.00**

**GEN19- Internal**

COMPLAINT:  
 19 DIAGNOSE HORN NOT WORKING



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 10/29/2024 Location: Work Order Number: Payment Type:  Page: 7 of 10
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**GEN19- Internal**

**CORRECTION:**

- Test horn, doesn't work. Check for power and ground at horn, good. Replace old horn. Test new horn, good.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AL203265	Horn Assembly 113 db	1.00	90.45	90.45	\$90.45	N
R44302	TIE BAND 7"	10.00	0.44	0.44	\$4.40	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	6.37	6.37	\$6.37	N
<b>Labor: \$106.20</b>		<b>Parts: \$94.85</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$6.37</b>
						<b>Sub-Total: \$207.42</b>

**GEN20- Internal**

**COMPLAINT:**

20 REPLACE SCREW IN BOTTOM OF DOOR LATCH COVER ( INSIDE )

**CORRECTION:**

- Install screw in bottom of door latch.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
37M7277	Pan Head Self Tapping Screw M4.2 X 12.7	1.00	0.89	0.89	\$0.89	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
<b>Labor: \$44.25</b>		<b>Parts: \$0.89</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$2.66</b>
						<b>Sub-Total: \$47.80</b>

**/100700309560R G Internal**

**COMPLAINT:**

21 BREAKAWAY COUPLER, R&R

**CORRECTION:**

Replaced 3 breakaway couplers. Run machine to get oil to operating temp and test couplers, good.



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 10/29/2024 Location: Work Order Number: Payment Type:  Page: 8 of 10
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**/100700309560R G Internal**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R186598	SNAP RING	1.00	10.78	10.78	\$10.78	N
RE186600	Coupler Seat Kit	1.00	52.70	52.70	\$52.70	N
RE577560	SCV Breakaway Quick Coupler	3.00	237.72	237.72	\$713.16	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	39.83	39.83	\$39.83	N

**Labor: \$663.75      Parts: \$776.64      OL&M: \$0.00      Misc: \$39.83      Sub-Total: \$1,480.22**

**GEN22- Internal**

COMPLAINT:  
 22 DIAGNOSE PTO NOISE ( POSSIBLE UJOINT OR CAUSED BY WORN HINGE PINS )

CORRECTION:

- Hinge pins and steering cylinder pins have some wear but not bad enough to address right now. Remove drive shaft and install alignment tool, PTO is out of alignment with transmission. Adjust alignment. Install drive shaft.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N

**Labor: \$2,208.96      Parts: \$0.00      OL&M: \$0.00      Misc: \$96.00      Sub-Total: \$2,304.96**

**/1100049560R F Internal**

COMPLAINT:  
 24 GREASE COMPLETE MACHINE

CORRECTION:

Greased unit

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 9 of 10
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

<b>/1100049560R F Internal</b>						
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>		<b>Parts: \$10.31</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.31</b>
				<b>Sub-Total: \$104.12</b>		

**GEN24- Internal**  
 COMPLAINT:  
 25 FINAL CHECK AND RUN

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
LABORDISC	SERVICE LBR DISCOUNT	1.00	0.00	-177.00	(\$177.00)	N
<b>Labor: \$177.00</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: (\$177.00)</b>
				<b>Sub-Total: \$0.00</b>		

**GEN27- Internal**  
 COMPLAINT:  
 27 CHANGE COMPRESSOR INTERSTAGE AIR DUCT

CORRECTION:

- Remove compressor interstage air duct. Clean gasket surfaces and install new pipe with new gaskets and clamps.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ128752	Gasket	1.00	29.35	29.35	\$29.35	N
R528620	Gasket	1.00	115.00	115.00	\$115.00	N
RE541035	Air Duct	1.00	2,867.00	2,867.00	\$2,867.00	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 10/29/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 10 of 10
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

<b>GEN27- Internal</b>								
SERVACCESS	SERVICE ACCESSORIES	1.00	34.72	34.72	\$34.72	N		
<b>Labor: \$578.79</b>	<b>Parts: \$3,011.35</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$34.72</b>	<b>Sub-Total: \$3,624.86</b>				

<b>Customer PO No:</b>	[REDACTED]
<b>Tax Exempt No:</b>	[REDACTED]
<b>Advisor:</b>	[REDACTED]

**Labor:** \$9,655.35  
**Parts:** \$8,471.09  
**OL&M:** \$0.00  
**Misc:** \$361.51  
**Grand Total:** \$18,487.95

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	146887	USED AG EQUIPMENT
	07	40	382	1	797157	INTERNAL LABOR-AG
	00	00	178	17	797157	WORK IN PROCESS PARTS -MJ
	07	40	482	1	797157	COS INTERNAL LABOR-AG
	07	40	544	1	797157	SUPPLIES EXPENSE
	07	30	375	3	797157	PARTS SPECIAL HANDLING
	07	30	366	2	797157	JD PARTS-COUNTER
	00	00	166	7	797157	JD PARTS-MOOSE JAW
	07	30	375	1	797157	PARTS SPECIAL HANDLING
	07	40	397	0	797157	DISCOUNTS
	07	30	466	2	797157	JD PARTS-COUNTER

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....