



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED] Bus Phone: Prv Phone:	[REDACTED] Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 15
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/SPOPT670 Internal
 COMPLAINT:
 01 RECONDITIONING INSPECTION COMBINE

CORRECTION:
 sep hours are 588

Labor: \$1,699.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,699.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/140968T670 Internal
 COMPLAINT:
 02 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:



<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43
------------------------	----------------------	-------------------------	----------------------	----------------------------

/10040200T670 F Internal
 COMPLAINT:
 03 BATTERIES, R&R WONT HOLD CHARGE

CORRECTION:
 REMOVED CABLES, REMOVED HOLD DOWN AND BREATHER. REPLACED BATTERY, CLEANED POSTS AND CLAMPS, INSTALLED CLAMPS AND BREATHERS, INSTALLED HOLD DOWN AND COVER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26783B	Wet Charged Battery, BCI D5,CCA 1400	1.00	831.33	831.33	\$831.33	N
TY26783B-CR	CORE for:Wet Charged Battery	-1.00	54.00	54.00	(\$54.00)	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 2 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/10040200T670 F Internal									
SEVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N			
Labor: \$88.50		Parts: \$777.33		OL&M: \$0.00		Misc: \$5.31		Sub-Total: \$871.14	

/140545S670 Internal
 COMPLAINT:
 04 REPLACE CLEANING FAN BLADES

CORRECTION:
 REPLACED 8 DAMAGED FAN BLADES.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
H210903	Nylon Push Plug	8.00	2.15	2.15	\$17.20	N			
HXE34242	Fan Blade	7.00	205.08	205.08	\$1,435.56	N			
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind			
SEVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N			
Labor: \$619.50		Parts: \$1,452.76		OL&M: \$0.00		Misc: \$37.17		Sub-Total: \$2,109.43	

/110104T670 F Internal
 COMPLAINT:
 05 REMOVE 1/2 LINK FROM UNLOADING AUGER DRIVE CHAIN

CORRECTION:
 LOOSENED CHAIN OFF BROKE FULL LINK OUT, ADDED IN A HALF LINK

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SW800LUS	#80 Offset 1/2 Link (Drives)	1.00	18.72	18.72	\$18.72	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 3 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/110104T670 F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N	
Labor: \$53.10	Parts: \$18.72	OL&M: \$0.00	Misc: \$3.19	Sub-Total: \$75.01			

/10180180AT670 Internal
 COMPLAINT:
 06 REPLACE BEATER DRIVE BELTS. RH

CORRECTION:
 LOOSEN AND RETIGHTEN HEADER/REEL PUMP AND BEATER DRIVE BELT
 REPLACE BEATER BELT. TIGHTEN BEATER BELTS. INSTALL AND TIGHTEN
 HEADER/REEL PUMP DRIVE BELT. CHECK BELT TENSION AND BEATER FUNCTION.

BELTS REPLACED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE42095	Belt Set	1.00	165.17	165.17	\$165.17	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25	Parts: \$165.17	OL&M: \$0.00	Misc: \$13.28	Sub-Total: \$399.70		

/120301T670 F Internal
 COMPLAINT:
 07 REPLACE SINGLE POINT SHEAR BOLTS

CORRECTION:
 REMOVED COTTER PIN AND PUT PROPER SHEER BOLTS IN, ALSO ADDED SPARES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7264	Hex Lock Nut M4	3.00	0.51	0.51	\$1.53	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED] Bus Phone: Prv Phone:	[REDACTED] Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 15
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/120301T670 F Internal
 19M9326 Socket Head Screw M4 X 30 GR12.9 3.00 2.08 2.08 \$6.24 N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N

Labor: \$44.25 Parts: \$7.77 OL&M: \$0.00 Misc: \$2.66 Sub-Total: \$54.68

/120083T670 F Internal
 COMPLAINT:
 08 REPLACE BEATER BLADES

CORRECTION:
 REMOVED BEATER BLADES. INSTALLED NEW ONES



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H147788	BLADE	8.00	279.51	279.51	\$2,236.08	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	84.96	84.96	\$84.96	N

Labor: \$1,416.00 Parts: \$2,236.08 OL&M: \$0.00 Misc: \$84.96 Sub-Total: \$3,737.04

/120015T670 F Internal
 COMPLAINT:
 09 REPLACE BEATER GRATE BENT UP BAD

CORRECTION:
 LOOSENED OFF P CLAMPS, THEN THERE WAS CANVAS HANGING OFF THE BEATER INSIDE, REMOVED 3 SECTIONS OF THE CANVAS AND THEN REMOVED THE MOUNT FOR THE FLAPS, REMOVED COTTER PINS AND REMOVED PINS THAT HOLD BAR IN. LOOSENED I BOLTS, REMOVED BAR. THEN REALIZED I HAD MISSED ONE I BOLT, LOOSENED THAT AND REMOVED THE GRATE. THEN DRAGGED IT OUT THE BACK OF THE WALKERS. CARRIED NEW GRATE IN AND HOOKED IT ON, TIGHTENED THE EYEBOLTS, RAN SHAFT BACK THROUGH GRATE AND PUT PINS BACK IN. STARTED PUTTING ON THE BRACKET FOR THE CANVAS FLAPS, BRACKET WAS BOWED OUT, BENT IT DOWN INTO PLACE AND BOLTED IT ON, PUT FLAPS BACK ON.



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No [REDACTED]

Deliver To:

[REDACTED] Bus Phone: Prv Phone:	[REDACTED] Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 15
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/120015T670 F Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE69784	Grate	1.00	1,870.98	1,870.98	\$1,870.98	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N
Labor: \$708.00		Parts: \$1,870.98		OL&M: \$0.00		Misc: \$42.48
						Sub-Total: \$2,621.46

/120000T670 Internal

COMPLAINT:
 10 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 CHANGED OIL AND FILTERS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE509672	Engine Oil Filter Cartridge	1.00	46.42	46.42	\$46.42	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	89.73	89.73	\$89.73	N
TY26679	18.9L 15W40 PLUS 50 II	1.00	170.86	170.86	\$170.86	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$307.01		OL&M: \$0.00		Misc: \$12.47
						Sub-Total: \$452.23

/120018T670 Internal

COMPLAINT:
 11 REPLACE FUEL FILTERS AND CLEAN FUEL PRE-SCREEN



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED] Bus Phone: Prv Phone:	[REDACTED] Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 6 of 15
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/120018T670 Internal

CORRECTION:
 CHANGED FILTERS AND CLEANED PRESCREEN

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	224.06	224.06	\$224.06	N
DZ130550	Primary Engine Fuel Filter	1.00	220.54	220.54	\$220.54	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$444.60		OL&M: \$0.00		Misc: \$9.97
						Sub-Total: \$587.32

/1007009T670 F Internal

COMPLAINT:
 12 REPLACE HYDRAULIC FILTERS

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH128449	Hydraulic Oil Filter	2.00	135.89	135.89	\$271.77	N
AXE43821	Hydraulic Filter	1.00	500.03	500.03	\$500.03	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
FREIGHT	FREIGHT	1.00	20.00	20.00	\$20.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$771.80		OL&M: \$0.00		Misc: \$29.97
						Sub-Total: \$934.52



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 7 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/120060T670 Internal

COMPLAINT:
 13 REPLACE ENGINE AIR FILTERS

CORRECTION:
 FILTERS REPLACED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE11090	Primary Air Filter	1.00	413.76	413.76	\$413.76	N
HXE11091	Secondary Air Filter	1.00	291.95	291.95	\$291.95	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$705.71		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$799.52

GEN14- Internal

COMPLAINT:
 14 UNSEIZE REAR TAIL BOARD LATCH PIN

CORRECTION:
 LUBED AND BEAT THE PIN BACK AND FOURTH AND WASN'T MAKING ANY PROGRESS, SO I REMOVED THE PIN, IT WAS BENT. I STRAIGHTENED THE PIN AND NOW IT WORKS NICE

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$0.00		OL&M: \$0.00		Misc: \$7.97
						Sub-Total: \$140.72

/170420T670 F Internal

COMPLAINT:
 15 REVERSE STRAW CHOPPER HAMMERS DULL NEEDS TO BE FLIPPED

CORRECTION:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 8 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/170420T670 F Internal
 CHOPPER BLADES FLIPPED

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$562.86		

/120009T670 F Internal
 COMPLAINT:
 16 REPLACE CHOPPER STATIONARY KNIVES (8)

CORRECTION:
 REMOVED KNIFE RACK, REPLACED KNIVES, REINSTALLED RACK

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE13023	BLADE	8.00	32.78	32.78	\$262.24	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75	Parts: \$262.24	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$402.96		

/150029T670 Internal
 COMPLAINT:
 17 REPLACE CAB FILTERS AND CLEAN PLASTIC GRATE

CORRECTION:
 FILTERS CHANGED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
L214634	Cab Ricirculation Air Filter	1.00	43.26	43.26	\$43.26	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 9 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/150029T670 Internal

RE284091	Cab Fresh Air Filter	1.00	115.62	115.62	\$115.62	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N

Labor: \$53.10 Parts: \$158.88 OL&M: \$0.00 Misc: \$3.19 Sub-Total: \$215.17

GEN18- Internal

COMPLAINT:
 18 DIAGNOSE ECU CODE 613.04 CAUSES ENGINE TO SURGE AT MID THROTTLE

CORRECTION:
 WENT IN PULLED CODES, THEN FOLLOWED ONE, CHECKED HARNESS AROUND PCV FOR FUEL RAIL, THEN IT TOLD ME TO CHECK THE PRESSURE RELIEVE VALVE ON THE COMMON RAIL, SO I REMOVED THE FUEL FILTER AND STRUGGLED TO GET THE VALVE UNPLUGGED, CHECKED THAT AND IT CHECKED OUT. WENT THREW CODE DIAGNOSTICS AND CHECKED WIRING FOUND THAT CONNECTOR X5003 WHICH IS ENGINE INTERCONNECT HAD WATER IN CONNECTOR AND CORROSION ON PINS, CLEANED UP PINS AND THEY LOOK GOOD, TOOK EACH PIN OUT OF THE CONNECTOR TO MAKE SURE THERE WAS NO MORE CORROSION ON THE BACK SIDE. ALL OKAY, RAN COMBINE AND IT DOES NOT THROW CODE 613.04 ANYMORE. ALL OKAY ECU CODE 613.04

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	74.34	74.34	\$74.34	N

Labor: \$1,239.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$74.34 Sub-Total: \$1,313.34

/110103T670 FF Internal

COMPLAINT:
 19 FEEDERCHAIN SLAT STRAIGHTEN 12

CORRECTION:
 STRAIGHTEN SLATS

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 10 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/110103T670 FF Internal						
SERVACCESS	SERVICE ACCESSORIES	Quantity	List Price	Net Price	Extended Price	Taxed Ind
		1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$375.24	

/10171250T670 Internal
 COMPLAINT:
 20 ADJUST FEEDER HOUSE CHAIN

CORRECTION:
 GOT IT TENSIONED PROPERLY.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$0.00	OL&M: \$0.00	Misc: \$3.19	Sub-Total: \$56.29	

/120084T670 Internal
 COMPLAINT:
 21 R&R DUALS & CHECK FINAL DRIVE END PLAY (PER SIDE)

CORRECTION:
 RH SIDE HAS 006 LH SIDE HAD 010, REMOVED FINAL DRIVE AND TIGHTENED, NOW IT HAS 004

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
Labor: \$1,062.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$63.72	Sub-Total: \$1,125.72	

/110081T670 Internal
 COMPLAINT:
 22 R&R SIEVE AND CHAFFER TO CHECK FOR CRACKS



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 11 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/110081T670 Internal

CORRECTION:

REMOVED HARVEST TREK SENSORS. HAD TO CLIMB ONTO THE CHAFFERS AND REMOVE THE DIVIDER, REMOVED CHAFFERS AND CLEANED, REMOVED SIEVES. CHECKED FOR CRACKS, NO CRACKS, PUT SIEVES BACK IN AND CALIBRATED, PUT CHAFFERS BACK IN AND PUT DIVIDER BACK ON, CALIBRATED CHAFFER, PUT HARVEST TREK SENSORS BACK ON.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	19.12	19.12	\$19.12	N
Labor: \$318.60		Parts: \$0.00	OL&M: \$0.00	Misc: \$19.12	Sub-Total: \$337.72	

GEN24- Internal

COMPLAINT:

24 INSTALL MISSING RH REAR GULL WING SHOCK.

CORRECTION:

INSTALLED SHOCK, DOOR IS KIND OF DIFFICULT TO CLOSE WHICH IS PROBABLY WHY THE SHOCK WAS REMOVED.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE51549	Gas Operated Cylinder	1.00	192.84	192.84	\$192.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$192.84	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$286.65	

/120541T670 Internal

COMPLAINT:

26 GREASE COMBINE

CORRECTION:

FOUND ALL THE ZERKS AND GREASED THEM

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/23/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 12 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

/120541T670 Internal								
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31			N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62			N

Labor: \$177.00 Parts: \$10.31 OL&M: \$0.00 Misc: \$10.62 Sub-Total: \$197.93

/GLOPCLEANT670 F Internal

COMPLAINT:
 28 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS) WAX IF REQUIRED REMOVE ANY OTHER DEALER DECALS INSTALL SCE DEALERSHIP DECALS ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR CLEAN SEAT AND REMOVE STAINS IF NECESSARY VACUUM CAB THOROUGHLY CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGESWHERE APPLICABLE) ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS(COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS. soaped and rinsed combine, cleaned cab as well

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N

Labor: \$2,065.20 Parts: \$0.00 OL&M: \$0.00 Misc: \$96.00 Sub-Total: \$2,161.20

GEN27- Internal

COMPLAINT:
 29 REPAIR RH BELT TENSION ROD.

CORRECTION:

REMOVED TENSION ROD, REMOVED TENSION ARM, INSTALLED NEW ONES AND TENSIONED BELT

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]	[REDACTED]	Invoice Number: [REDACTED]
[REDACTED]	[REDACTED]	Invoice Date: 9/23/2024
[REDACTED]	[REDACTED]	Location: [REDACTED]
[REDACTED]	[REDACTED]	Work Order Number: [REDACTED]
[REDACTED]	[REDACTED]	Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	Page: 13 of 15
Prv Phone:	Prv Phone:	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

GEN27- Internal

HXE103625	Hook Bolt	1.00	184.04	184.04	\$184.04	N
Z52243	Lever	1.00	149.73	149.73	\$149.73	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N

Labor: \$221.25 Parts: \$333.77 OL&M: \$0.00 Misc: \$13.28 Sub-Total: \$568.30

/160055S670 Internal

COMPLAINT:
 30 R&R FINAL DRIVE, ADJUST BEARINGS.

CORRECTION:
 REMOVED FINAL DRIVE, REMOVED THE CAP WITH SOME DIFFICULTY, REMOVED SNAP RING AND KEY, TIGHTENED FINAL DRIVE AND LOCKED IT BACK IN PLACE. INSTALLED NEW CAP, PUT FINAL DRIVE BACK ON, MEASURED 004

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
CE21678	CAP	1.00	49.82	49.82	\$49.82	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N

Labor: \$531.00 Parts: \$49.82 OL&M: \$0.00 Misc: \$31.86 Sub-Total: \$612.68

GEN32- Internal

COMPLAINT:
 32 DIAGNOSE CLEAN GRAIN ELEVATOR CODE

CORRECTION:
 WENT TO START DIAGNOSING ELEVATOR CODE AND IT WAS THROWING A CHOPPER SPEED CODE NOW FIRST. LC2 521284.01 WENT THREW ALL DIAGNOSTICS WITH IT TESTING WIRES, JUMPED SENSOR AND VOLTAGE CODES CHANGED SO WIRING WAS GOOD, REPLACED SENSOR AND IT NOW ALL WORKS. NO LONGER THROWS CLEAN GRAIN ELEVATOR CODE EITHER. ALL OKAY



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 14 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

GEN32- Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH221249	Speed Sensor	1.00	211.91	211.91	\$211.91	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 21.24	<u>Net Price</u> 21.24	<u>Extended Price</u> \$21.24	<u>Taxed Ind</u> N
Labor: \$354.00		Parts: \$211.91		OL&M: \$0.00		Misc: \$21.24
						Sub-Total: \$587.15

GEN33- Internal

COMPLAINT:
 33 PAINT BEATER PULLEY

CORRECTION:
 INSPECTED BEATER BELT AGAIN AND ITS STILL GOOD, PAINTED BEATER PULLEY AS THERE WHERE BURN MARKS ON IT.
 ALL OKAY

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------





Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 9/23/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 15 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2019 JD T670i COMBINE	857	1Z0T670AJJU115383	1Z0T670AJJU115383	

GEN33- Internal	SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor:	\$88.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total:	\$93.81	

Customer PO No:
 Tax Exempt No:
 Advisor: [REDACTED]

Labor:	\$13,003.60
Parts:	\$9,977.70
OL&M:	\$0.00
Misc:	\$678.92
Grand Total:	\$23,660.22

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147474			USED AG EQUIPMENT
06 40	382	1	785829			INTERNAL LABOR-AG
00 00	178	16	785829			WORK IN PROCESS PARTS -MJ
06 40	482	1	785829			COS INTERNAL LABOR-AG
06 40	544	1	785829			SUPPLIES EXPENSE
06 30	366	2	785829			JD PARTS-COUNTER
00 00	166	6	785829			JD PARTS-MOOSE JAW
06 30	375	3	785829			PARTS SPECIAL HANDLING
06 30	375	1	785829			PARTS SPECIAL HANDLING
06 30	466	2	785829			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: