

OVER THE TOP TRUCK AND REPAIR

23855 COUNTY ROAD 35
LASALLE CO 80645
TELEPHONE (970) 397-8772

WORK ORDERS

Page 1 out of 2
1100
4 Apr 2024

We are open Monday thru Friday 8:am to 5pm
Our Company Appreciate Your Business
ORIGINAL DATE : Thursday, 4 Apr 2024

COMPANY	YEAR 2009
CUSTOMER	MAKE CATERPILLAR
ADDRESS	MODEL ROAD GRADER
	LICENSE # 131
TELEPHONE(S)	V.I.N. D9G01112
	MILES IN AND OUT 0 / 0
EMAIL	HOURS IN AND OUT 13,719. /
DUE BY 4 Apr 24 09:37	COLOR YELLOW
KEY #	UNIT
WRITER	SUBTOTAL TIRES
	ENGINE C9 THX28043

TYPE	LABOR PERFORMED	HOURS	TECH.	LIST PRICE	SALE EACH	SUBTOTAL
1	L WENT TO FIGURE OUT HOW TO OVERRIDE THE STEERING TO BE ABLE TO PUSH IT INSIDE THE SHOP AND IT WAS DEAD. HAD TO GET A 24V CHARGER AND LET IT CHARGE. ONCE I FIGURED OUT HOW TO RUN THE OVERRIDE I WINCH IT INTO THE SHOP. STARTED WITH PULLING THE VALVE COVER AND THEN THE ROCKER SHAFTS, AND INJECTOR HARNESS TO LOOK AND MEASURE FOR A BENT VALVE THE EXHAUST PUSH TUBE ON FIVE WAS THE ONE THAT WAS OFF. VALVES DID NOT LOOK BENT AND WERE ALL THE SAME HEIGHT. TOOL FLASHLIGHT AND LOOKED DOWN IN THE ENGINE AND FOUND THAT THE LIFTER RETAINER WAS BROKEN. NOTIFIED CUSTOMER AND WAS TOLD TO PULL ENGINE AND FIX IT. STARTED WITH REMOVING ALL COVERS OVER TRANS AND ENGINE. THEN TOOK APART ALL CROSS MEMBERS, PULLED AIR FILTER, COOLANT RESERVOIR, CAC TUBE, COOLANT TUBE AND THEN REMOVED THE FRAMING OF THE SIDES. DRAINED ALL FLUIDS, REMOVED MUFFLER, DISCONNECTED BATTERY, REMOVED FUEL FILTER ASSEMBLY. FOUND YOU HAD TO PULL TRANSMISSION WITH ENGINE BECAUSE THERE IS NO WAY TO SPLIT THE ENGINE IN CHASSIS. SO THEN REMOVED ALL LINES AND WIRES FROM THE TANK AND FRAME SUPPORT AND PULLED HYDRAULIC PACK. CONTINUE REMOVING HOUSES WHEN I REALIZED I ALSO HAD TO REMOVED THE COOLING PACK TO GET THE TRANS MISSION UP. THEN DISCONNECTED ALL HARNESSSES AND LINES AND THEN PULLED THE ENGINE MOVED OUT AND SAT ON THE GROUND. ONCE ENGINE WAS ON GROUND I PULLED HEAD AND INSPECTED. LOOKED LIKE THERE IS NO DAMAGED. NOTIFIED CUSTOMER HE SAID CLEAN IT UP REPLACE CAM AND LIFTERS AND PUT IT BACK TOGETHER. PULLED DAMPER, REPLACED CRANK SHAFT SEAL PULLED FRONT COVER AND PULLED LIFTER AND THEN REMOVED THE CAM. FOUGHT TO GET CAM OUT BECAUSE BAD LIFTER WOULD NOT COME OUT THE TOP I HAD TO HOLD IT UP AND THEN LET IF FALL DOWN AND REMOVE IT TO BE ABLE TO GET IT OUT. INSTALLED NEW CAM SET TIMING AND THEN CLEANED PARTS AND PUT BACK TOGETHER IN REVERSE ORDER. SET OVERHEAD. INSTALLED ENGINE IN REVERSER ORDER. REPLACED ALL FLUID AND FILTERS AND PUT DRIVE SHAFT IN AND SKID PLATE.					\$ 22,540.00

TYPE	PARTS SOLD	QTY	TECH.	LIST PRICE	SALE EACH	SUBTOTAL
P	CAT326-1644 - FILTER	1.00			\$ 54.09	\$ 54.09
P	CAT188-8726 - VALVE THERMA	1.00			\$ 215.77	\$ 215.77
P	CAT10R8728 - CAMSHAFT	1.00			\$ 1,189.83	\$ 1,189.83
P	CAT4478670 - GASKET KIT	1.00			\$ 956.05	\$ 956.05
P	CAT3096931 - HYDO ADV 10W 5G	5.00			\$ 128.15	\$ 640.75
P	CAT391-7125 - SWITCH	1.00			\$ 217.33	\$ 217.33

OVER THE TOP TRUCK AND REPAIR

23855 COUNTY ROAD 35
LASALLE CO 80645
TELEPHONE (970) 397-8772

WORK ORDERS

Page 2 out of 2
1100
4 Apr 2024

We are open Monday thru Friday 8:am to 5pm
Our Company Appreciate Your Business
ORIGINAL DATE : Thursday, 4 Apr 2024

COMPANY	YEAR 2009
CUSTOMER	MAKE CATERPILLAR
ADDRESS	MODEL ROAD GRADER
TELEPHONE(S)	LICENSE # 131
EMAIL	V.I.N. D9G01112
DUE BY 4 Apr 24 09:37	MILES IN AND OUT 0 / 0
KEY #	HOURS IN AND OUT 13,719. /
WRITER	COLOR YELLOW
UNIT	SUBTOTAL TIRES
	ENGINE C9 THX28043

P	CAT332-4527 - TUBE AS	1.00	\$ 89.02	\$ 89.02
P	CAT8T9572 - TDTO 30W 5G	4.00	\$ 110.07	\$ 440.28
P	CAT245-6376 - ELEMENT SECOND	1.00	\$ 69.02	\$ 69.02
P	CAT245-6375 - ELEMENT PRIME	1.00	\$ 105.08	\$ 105.08
P	CAT5754995 - LIFTER	12.00	\$ 168.64	\$ 2,023.68
P	CAT4674243 - SPRING GUIDE	12.00	\$ 14.94	\$ 179.28
P	LUB500010048 - ROTELLA T4 15W40 PER GALLON	11.00	\$ 19.46	\$ 214.06
P	LUBZXEDRU1 - COOLANT EXTENDED LIFE	18.00	\$ 13.05	\$ 234.90
P	WASTE OIL - WASTE OIL PER GALLON	55.00	\$ 0.66	\$ 36.30
P	WASTE COOLANT - WASTE COOLANT BY GALLON	18.00	\$ 1.90	\$ 34.20

ORIGINAL ESTIMATE \$ 29,239.64 X:_____

I hereby authorize the above name to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire,theft,or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than ____\$ per day, will be charged unless otherwise agreed to in writing.ALL ACCOUNTS ARE PAID BY THE 10TH OF THE MONTH.ALL CUSTOMERS WILL BE CHARGED A 1.75% SERVICE CHARGE ON ACCOUNTS PAST THE DUE DATE! Signature:_____ Date : _____	SUBTOTAL - LABOR	\$ 22,540.00
	SUBTOTAL - PARTS	\$ 6,699.64
	SUBTOTAL TIRES	
	Shop Supply	\$ 250.00
	Optional Fee 3-Optional Fee ...	
	SUBTOTAL - OTHERS	\$ 250.00
	TOTAL TAX	\$ 428.78
UNDER WARRANTY	DEPOSIT	
NO CHARGE TO THE CUSTOMER		
PAYMENT :	TOTAL SALES	\$ 29,918.42
	TOTAL COLLECTED	\$ 0.00
	AMOUNT DUE	\$ 29,918.42