

Enviro Plant Hire Pty Ltd - Work Order Summary

Asset:
PT02 - Kubota SVL75-2 Positrack PT02

Location:
3779 MOOLIGUNN ROAD, KARRATHA
INDUSTRIAL ESTATE WA 6714

Current Tracker Hours:
5220

Current Tracker Kms:
7815

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
19603	2 way repair	29/08/2025	5220	7815	29/08/2025	Minor Defects	Closed	Zachary Luke Rivett
19598	General lookover	28/08/2025	5220	7815	29/08/2025	Minor Defects	Closed	Zachary Luke Rivett
19291	Radiator removed	08/07/2025	5216	7698	20/08/2025	Major Defects	Closed	
17963	Off hire cost C230440	29/08/2024	4785	7160	24/09/2024	Off hire repair cost report	Closed	
17732	Dpf warning light on dash	09/07/2024	4690	6862	09/07/2024	Modifications	Closed	David Madden
17668	4500 Hour Service	26/06/2024	4600	6785	26/06/2024	Service	Closed	Brian Tuohey
17641	Prestart Defect - Air Conditioner Failed	14/06/2024			26/06/2024	Minor Defects	Closed	
17511	Belts squeaking	11/05/2024	4219	6447	11/05/2024	Minor Defects	Closed	David Madden
17465	Two way radio not working	02/05/2024	4142	6340	02/05/2024	Modifications	Closed	David Madden
17462	Door latch broken	02/05/2024	4142	6340	06/06/2024	Modifications	Closed	David Madden
17308	No start error 26	20/03/2024	3965	6171	05/05/2024	Modifications	Closed	David Madden
17261	4000 hours service	08/03/2024	3949	6166	12/04/2024	Service	Closed	
17156	Prestart Defect - Air Conditioner Failed	08/02/2024			28/02/2024	Modifications	Closed	
16974	Regas aircon and replace 2 way radio	01/12/2023	3798	6046	01/12/2023	Modifications	Closed	Darren Feeley
16957	Fix air con blow out evaporator	27/11/2023	3796	6046	27/11/2023	Modifications	Closed	Darren Feeley
16863	Prestart Defect - Air Conditioner Failed	22/10/2023			06/12/2023	Modifications	Closed	
16698	3750 hours service	23/06/2023	3695	5993	17/07/2023	Service	Closed	
16637	3500 hours service	05/05/2023	3450	5888	17/07/2023	Service	Closed	Malcolm Morgan
16550	3250hr service	23/03/2023	3382	5842	23/03/2023	Service	Closed	michael reynolds
16533	Track failure	13/03/2023	3320	5813	13/03/2023	Modifications	Closed	michael reynolds
16501	Aircon and engine Radiator issues	01/03/2023	3289	5806	02/03/2023	Modifications	Closed	michael reynolds
16345	3000 Hour Service	19/09/2022	2791	4555	17/09/2022	Service	Closed	Jack Davitt
16253	2750 hours service	26/07/2022	2698	4497	19/09/2022	Service	Closed	
16204	Various issues	29/06/2022	2577	4240	29/06/2022	Modifications	Closed	
16197	Multiple Prestart Defects	26/06/2022			19/09/2022	Minor Defects	Closed	
16097	charge pump fitting cracked and 2 way failed	03/05/2022	2439	4063	19/09/2022		Closed	michael reynolds
16096	2500hr service	03/05/2022	2439	4063	03/05/2022	Service	Closed	michael reynolds
16032	Prestart Defect - Air Conditioner Failed	01/04/2022			19/09/2022	Minor Defects	Closed	
15967	2250 hours service	02/03/2022	2201	3784	03/03/2022	Service	Closed	michael reynolds
15695	Prestart Defect - Two Way Radio Communication Failed	24/11/2021			13/12/2021	Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	Service Priority	Closed Item Status	Assigned To/Completed By
15083	Multiple Prestart Defects	01/09/2021			13/12/2021	Minor Defects	Closed	grahamspencerhayes
15055	Multiple Prestart Defects	29/08/2021			13/12/2021	Minor Defects	Closed	grahamspencerhayes
15020	1750 hours service	25/08/2021	1700	3136	13/12/2021	Service	Closed	
14958	Replace tracks	14/08/2021	1663	3118	14/08/2021	Modifications	Closed	
14949	Prestart Defect - Air Conditioner Failed	13/08/2021			13/12/2021	Minor Defects	Closed	Mark Boyle
14882	Prestart Defect - Lights - Head, Stop, Tail, Indicators, Work	29/07/2021			03/09/2021	Urgent Machine Down	Closed	grahamspencerhayes
14792	Multiple Prestart Defects	20/07/2021			28/07/2021	Urgent Machine Down	Closed	Jeff Hull
14572	1500 hours service	25/05/2021	1448	3084	29/05/2021	Service	Closed	
14277	Prestart Defect - Any Machine Damage Failed	22/04/2021			02/05/2021	Minor Defects	Closed	Aidan Holohan
14149	Fan belt failed	07/04/2021	1345	2947	07/04/2021	Modifications	Closed	michael reynolds
14134	Prestart Defect - Air Cleaner Dust Valve - Clean/Inspect Fail	06/04/2021			08/04/2021		Closed	Jeff Hull
14002	Locking pin quick hitch	24/03/2021	1328	2914	24/03/2021	Modifications	Closed	michael reynolds
13741	2 way ariel	08/03/2021	1300	2909	08/03/2021		Closed	michael reynolds
11989	1250 hours service	21/01/2021	1228	2812	22/01/2021	Service	Closed	michael reynolds
10995	Prestart Defect - Air Conditioner Failed	22/12/2020			14/01/2021	Minor Defects	Closed	Colm Reilly
10946	Prestart Defect - Air Conditioner Failed	21/12/2020			14/01/2021	Minor Defects	Closed	Colm Reilly
9593	Prestart Defect - Lights - Head, Stop, Tail, Indicators, Work	27/11/2020			26/01/2021		Closed	Lauri Uibopuu
8901	Prestart Defect - Two Way Radio Communication Failed	16/11/2020			09/03/2021	Minor Defects	Closed	Ryan Dolan
8221	1000 Hour Service	27/10/2020	959	2293	27/10/2020	Service	Closed	michael reynolds
5166	500 hours service	08/12/2019	0	0	21/01/2020	Service	Closed	
2452	Prestart Defect - Air Conditioner Failed	27/11/2019			27/10/2020		Closed	fleet Start
2065	Prestart Defect - Inspect Drive Belts/Guarding Fitted Failed	21/11/2019			27/10/2020		Closed	
1982	Prestart Defect - Two Way Radio Communication Failed	20/11/2019			27/10/2020		Closed	
1706	Prestart Defect - Two Way Radio Communication Failed	15/11/2019			27/10/2020		Closed	
1705	Prestart Defect - Two Way Radio Communication Failed	15/11/2019			27/10/2020		Closed	fleet Start
1652	Prestart Defect - Two Way Radio Communication Failed	14/11/2019			27/10/2020		Closed	fleet Start
1619	Prestart Defect - Two Way Radio Communication Failed	13/11/2019			27/10/2020		Closed	
5070	250H Kubota SVL75 service	01/10/2019	0	0	01/10/2019		Closed	