

Experian AutoCheck Report

Report run: 05/01/2026 17:45:15 EDT

2010 Toyota Tundra Grade


Extended Cab 4D (5.7L V8 SEFI Gasoline)

VIN:	5TFRY5F15AX079364
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	16 year(s)
Estimated In Service:	08/10/2009
Last Reported Odometer:	180,657 (09/13/2021)

Owners - 2



Vehicle Usage
Personal



Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage No Accidents or Damage Reported</p> <p>NO ISSUE</p>
<p>Open Recall Check</p> <p>4 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check Last reported odometer: 180,657 (09/13/2021)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 1 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>NO ISSUES REPORTED</p>



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage

Open Recall Check



Information Reported: AutoCheck found 4 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 10/05/2009

Recall Type - Safety

NHTSA / OEM Recall No. - 09V388 / 90L-1242

Campaign Description - Safety Recall: SAFETY RECALL 90L - POTENTIAL FLOOR MAT INTERFERENCE WITH ACCELERATOR PEDAL
Status: Remedy Available

Recall Date - 01/21/2010

Recall Type - Safety

NHTSA / OEM Recall No. - 10V017 / A0A-57

Campaign Description - Safety Recall: SAFETY RECALL A0A - ACCELERATOR PEDAL REINFORCEMENT BAR INSTALLATION
Status: Remedy Available

Recall Date - 03/04/2011

Recall Type - Safety

NHTSA / OEM Recall No. - 11V148 / B0B-109

Campaign Description - Safety Recall: SAFETY (NON-COMPLIANCE) RECALL B0B - CERTAIN 2008 THROUGH 2011 MODEL YEAR LAND CRUISER, SEQUOIA, TACOMA AND TUNDRA VEHICLES EQUIPPED WITH TOYOTA-RECOMMENDED LIGHT TRUCK TIRES AND TRD ACCESSORY WHEEL
Status: Remedy Available

Recall Date - 09/17/2015

Recall Type - Safety

NHTSA / OEM Recall No. - 15V689 / C0M-2902

Campaign Description - Safety Recall: SAFETY RECALL C0M REMEDY NOTICE - MULTIPLE MODELS AND MODEL YEARS - POWER WINDOW MASTER SWITCH (PWMS)
Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Toyota Dealer](#) to schedule repair.

Recommended Maintenance

[OEM Recommended Maintenance Schedule](#)

OEM Recommended Services



120000 Mile Service

- Check installation of driver's floor mat
- Four Wheel Alignment
- Fuel Induction Service



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2010 Toyota Tundra Grade (5TFRY5F15AX079364) Report Run Date: 05/01/2026 17:45:15 EDT

2009

Vehicle Prep and Other Pre-Titling Events

Location: OK

Preparation Date: 08/2009

Event Date	Location	Odometer	Data Source	Details
08/10/2009	OK		Independent Source	Vehicle Manufactured and Shipped to Dealer

2009

Owner 1

Location: OK

Owned From: 09/2009

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/22/2009	OKLAHOMA CITY, OK	144	Motor Vehicle Dept.	Title(Title #:881109266003) Registration Event/Renewal
10/05/2009			Manufacturer	Manufacturer Recall NHTSA Recall 09V388 / Mfr. Recall 90L-1242 Safety Recall: SAFETY RECALL 90L - POTENTIAL FLOOR MAT INTERFERENCE WITH ACCELERATOR PEDAL LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available
01/21/2010			Manufacturer	Manufacturer Recall NHTSA Recall 10V017 / Mfr. Recall A0A-57 Safety Recall: SAFETY RECALL A0A - ACCELERATOR PEDAL REINFORCEMENT BAR INSTALLATION LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available
09/02/2010	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal

Event Date	Location	Odometer	Data Source	Details
03/04/2011			Manufacturer	Manufacturer Recall NHTSA Recall 11V148 / Mfr. Recall B0B-109 Safety Recall: SAFETY (NON-COMPLIANCE) RECALL B0B - CERTAIN 2008 THROUGH 2011 MODEL YEAR LAND CRUISER, SEQUOIA, TACOMA AND TUNDRA VEHICLES EQUIPPED WITH TOYOTA-RECOMMENDED LIGHT TRUCK TIRES AND TRD ACCESSORY WHEEL LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available
09/16/2011	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal
09/27/2012	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal
09/12/2013	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal
03/31/2014			Manufacturer	Manufacturer Service Bulletin Mfr. Recall BST-626 Service Campaigns: SPECIAL SERVICE CAMPAIGN (SSC) BST MULTIPLE MODEL AND MODEL YEARS SMART STOP TECHNOLOGY LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available Manufacturer Service Bulletin Mfr. Recall BST-626 Service Campaigns: SPECIAL SERVICE CAMPAIGN (SSC) BST MULTIPLE MODEL AND MODEL YEARS SMART STOP TECHNOLOGY LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available Manufacturer Service Bulletin Mfr. Recall BST-626 Service Campaigns: SPECIAL SERVICE CAMPAIGN (SSC) BST MULTIPLE MODEL AND MODEL YEARS SMART STOP TECHNOLOGY LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available
09/11/2014	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal
09/17/2015			Manufacturer	Manufacturer Recall NHTSA Recall 15V689 / Mfr. Recall C0M-2902 Safety Recall: SAFETY RECALL C0M REMEDY NOTICE - MULTIPLE MODELS AND MODEL YEARS - POWER WINDOW MASTER SWITCH (PWMS) LOCATE YOUR NEAREST AUTHORIZED TOYOTA DEALER TO SCHEDULE REPAIR. Status: Remedy Available
09/28/2015	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration
08/22/2016	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration
09/14/2017	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration
09/05/2018	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration
09/17/2019	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration
10/01/2019	TX		Motor Vehicle Dept.	Excluded/Exempt
09/10/2020	OKLAHOMA CITY, OK		Motor Vehicle Dept.	Registration Event/Renewal Pro-Rated Registration

2020

Owner 2

Location: TX

Owned From: 09/2020

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/18/2020	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal
09/26/2020	HOUSTON, TX		Motor Vehicle Dept.	Title(Title #:22036744090150843)
10/01/2020	TX		Motor Vehicle Dept.	Excluded/Exempt
01/22/2021	HOUSTON, TX	179,498	Independent Repair Center	Steering System Serviced
09/13/2021	HOUSTON, TX	180,657	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
09/14/2021	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5TFRY5F15AX079364) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.