

7250 E 56th Avenue | Commerce City, CO 80022 | Phone: (888) 819-7100

MV# 0

Invoice: 23W15924

Date / Hour: 7/8/2025 2:09:51PM

Repair Order: 15924 Customer: DN779900 Branch: DEN

Total Invoice: \$9,781.32

A/R Charge

Page 1 of 4

Bill To: DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

Ship To: DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

Office Phone: (303) 872-8395 Email: GHARDY@DANELLA.COM

Completion Date: 07/03/2025

Work: (303) 872-8395

Customer P/O: 39478 Open Date: 06/13/2025

Add User: chaft Salesperson: cive

Key Tag Lot Location : KEY TAG # 2402

Unit Number: N4215 Model Year: 2026

Type: Tractor VIN: 1M2AX18CXGM034014 Meter: 140441 Miles

In-Service Date: 08/09/2015 ECM Reading: 8009

Task: 1 NEXINSPECT Nextran Assurance Check 22 Inspection

SMV000000 MOTOR VEHICLE INSPECTION

Complaint: 1.) NEX - NEXTRAN ASSURANCE INSPECTION

Cause: ASSURANCE INSPECTION
Correction: ASSURANCE INSPECTION

Task 1 Subtotals

Parts: Labor:

Department: Service

Department: Service

\$0.00 \$0.00 \$0.00

Task 1 Subtotals

Make/Model: MCK

Task: 2 XXX000000 NX - Diagnose Engine Systems

040000000 Engine / Motor Systems Group

Complaint: 2.) CHECK AND ADVISE UNIT HAS ACTIVE FAULTS WITH A CHECK ENGINE LIGHT

Cause: FOUND EXCESSIVE AIR IN THE FUEL

Correction: XY23721/15283/6-13

VERIFIED CEL ON, CHECKED FAULTS, HAS ACTIVE P242B64-EGT SENSOR CIRCUIT RANGE/PERFORMANCE SENSOR 3 PLAUSIBILITY FAILURE AND ACTIVE P20EE00-SCR EFFICIENCY BELOW THRESHOLD. BOTH ONLY ONE COUNT, INSPECTED AFTERTREATMENT COMPONENTS, FOUND T3 SENSOR NOT INSTALLED IN EXHAUST AND HANGING, ADDED PICTURE TO CASE. THIS WOULD CAUSE BOTH OF THESE FAULTS. REINSTALLED SENSOR. UNIT ALSO HAS INACTIVE RECENT FAULTS FOR LOW PRESSURE FUEL SYSTEM, INSPECTED AND FOUND PRIMER PUMP NOT FULLY SEATED, PERFORMED FUEL PRESSURE TEST AND VERIFIED FUEL PRESSURE CAME UP FROM 40 PSI TO 60 PSI AFTER LOCKING DOWN PRIMER PUMP. CLEARED FAULTS. I ALSO NOTICED UNIT HAS A HARD START CONDITION AFTER SITTING FOR 20 MINUTES OR SO. PERFORMED AIR IN FUEL TEST AND FOUND COPIOUS AMOUNTS OF FUEL IN LINE COMING FROM CYLINDER HEAD INDICATING A LIKELY INJECTOR ISSUE. NEED APPROVAL TO REMOVE AND INSPECT INJECTORS FOR WEAR. WENT AHEAD AND QUOTED INJECTORS AS THEY ARE LIKELY WORN. NEED TO PERFORM A SUB REGEN AND ROAD TEST AFTER REPAIRS TO VERIFY CEL DOES NOT RETURN. 15026/XN20830 PERFORMED OPERATIONS TO REPLACE INJECTORS & CUPS. RECOVERED COOLANT, REMOVED AIR FILTER ASSEMBLY, EGR CROSS-OVER TUBE, CCV VENT HOSE, & VALVE COVER. REMOVED VEB LEAF SPRINGS, & ROCKER SHAFT BOLTS. REMOVED ROCKER SHAFT, & VALVE BRIDGES. REMOVED ALL 6 INJECTORS & INJECTOR CUP. INSPECTED INJECTORS & CUPS & CONFIRMED THE DIAGNOSTIC WAS CORRECT. VISIBLE INDICATION OF COMBUSTION LEAK FOUND ON EVERY INJECTOR CUP. IN ADDITION TO THE LEAKING CUPS, THE INJECTORS WERE "WALKING" INSIDE THE CUP & WILL REQUIRE REPLACEMENT. REPLACED ALL 6 INJECTORS/CUPS, & RE-INSTALLED PARTS REMOVED FOR REPAIR. TORQUED INJECTORS, ROCKER SHAFT, & VEB LEAF SPRINGS BOLTS TO SPECS. PERFORMED VALVE ADJUSTMENT & ADJUSTED ROCKERS AS NEEDED. TO COMPLETE THE REPAIR & AVOID ACTIVE DTC'S REMOVED & PROGRAMMED INJECTOR TRIM CODES, RESET FUNCTION PARAMETERS, CLEARED DTC'S & PERFORM SULFUR REGEN. REGEN COMPLETED WITH NO DTC'S. MOVED TO WASH BAY & STEAMED OFF ENGINE. PERFORMED FINAL QC & ROAD TEST TO VERIFY ALL REPAIRS WERE COMPLETE.

15179 I TOOK TRUCK ON A TEST DRIVE AND DID NOT GET ANY DASH LIGHTS, FAULTS OR MESSAGES.

| | | | | | | Extended |
|-------|----------|--------------------------|-----|----------|---------|----------|
| Supp. | Part | Description / Ref Number | U/M | Quantity | Price | Price |
| VPDC | 1677370 | O-RING BREATHER MP7 | EA | 2.0 | \$5.09 | \$10.18 |
| VPDC | 20526428 | SEALING RING | EA | 1.0 | \$11.62 | \$11.62 |



7250 E 56th Avenue | Commerce City, CO 80022 | Phone: (888) 819-7100

MV# 0

Bill To:

Invoice: 23W15924

Date / Hour: 7/8/2025 2:09:51PM

Repair Order: 15924 Customer: DN779900 Branch: DEN Total Invoice: \$9,781.32 ***A/R Charge***

Page 2 of 4

Ship To: DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

Office Phone: (303) 872-8395 Email: GHARDY@DANELLA.COM

Work: (303) 872-8395

DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

| Customer P/O: 39478 | | Open Date | e: 06/13/2025 | Completion Date: 07/03/2025 | | |
|---------------------|-------------|--------------------------------|------------------|-----------------------------|------------|--------------|
| Add User | : chaft | | Salesperson | cive | | |
| VPDC | 21344803 | HEX. SOCKET SCREW 1124 | EA | 12.0 | \$1.22 | \$14.64 |
| VPDC | 23920469 | FUEL FILTER | EA | 1.0 | \$49.87 | \$49.87 |
| VPDC | 24225154 | FUEL FILTER LONG LIFE 23880047 | EA | 1.0 | \$58.84 | \$58.84 |
| VRC | 85144518-C | INJERCTOR KIT -Core | EA | -1.0 | \$1,980.00 | \$(1,980.00) |
| VPDC | 471708 | SEALING RING | EA | 1.0 | \$6.42 | \$6.42 |
| VRC | 85144518 | INJERCTOR KIT | EA | 1.0 | \$3,362.67 | \$3,362.67 |
| VRC | 85144518-C | INJERCTOR KIT -Core | EA | 1.0 | \$1,980.00 | \$1,980.00 |
| VPDC | 983472 | CABLE TIE | EA | 6.0 | \$0.78 | \$4.68 |
| VO IMPERIAL | IS 69921 | BRISTLE DISC 1GREEN 50G | EA | 2.0 | \$12.84 | \$25.68 |
| VO IMPERIAL | IS 917855X5 | DISK, 1" SANDING | EA | 2.0 | \$2.47 | \$4.94 |
| KENTAUT | OTCJ428855 | BRUSH, TUBE 7/16 DIAMETER | EA | 1.0 | \$50.56 | \$50.56 |
| SWC thanl | c you | | | | | |
| KENTAUT | OTCJ428855 | BRUSH, TUBE 7/16 DIAMETER | EA | 1.0 | \$50.56 | \$50.56 |
| | | | Task 2 Subtotals | Parts: | | \$3,650.66 |
| | | | | Core Chg: | | \$1,980.00 |
| | | | | Core Ret: | | (\$1,980.00) |
| | | | | Labor: | | \$3,585.00 |
| | | | | Task 2 Subtotals | | \$7,235.66 |

Task: 3 NEXPUDEL Pick up & Deliver

Complaint: INSPECTION OF UNIT AFTER REPAIRS

Cause: UNIT NEEDS TO BE INSPECTED BY MULTIPLE LEADS/SUPERVISORS AND TAKEN ON ROAD TESTS IN BETWEEN INSPECTIONS.
INSPECT ALL REPAIRS AND FAULTS CODES ACTIVE AND INACTIVE. DOCUMENT RESULTS OF INSPECTION AND ROAD TESTS.

Task 3 Subtotals Parts:

Parts: \$0.00
Labor: \$0.00

Task 3 Subtotals \$0.00

Department: Service

Department: Service

Task: 4 XXX000001 QM - Starting System - Repair

032000000 Cranking System

Complaint: LOAD TEST BATTERIES

Cause: FOUND 2 OF THE 3 BATTERIES LOAD TEST BAD.

Correction: 15455/XM50317- TRAINED ROBERT ON HOW TO LOAD TEST BATTERIES AND QUOTE PARTS.

40153/MD75051- LOAD TESTED THE BATTEIRES FOUND TWO OUT OF THE THREE WHERE BAD. RECOMMEND REPLACEING ALL

THREE BATTEIRES.

15455/XM50317-REPLACED THE BATTERIES AND TRAINED ROBERT ON NAVIGATING THE COMPUTER PROGRAMS

15403/MD75051- REPLACED BATTEIRES, CLEARED CODES, PARKED IN B-5.

| Supp. | Part | Description / Ref Number | U/M | Quantity | Price Extended Price Price |
|-------|---------------|--------------------------|-----|----------|----------------------------|
| | NNEP V31950-C | GROUP 31 BAT-Core | EA | -1.0 | \$22.00 \$(22.00) |



7250 E 56th Avenue | Commerce City, CO 80022 | Phone: (888) 819-7100

MV# 0

Bill To:

Invoice: 23W15924

Date / Hour: 7/8/2025 2:09:51PM

Repair Order: 15924 Customer: DN779900 Branch: DEN Total Invoice: \$9,781.32 ***A/R Charge***

Page 3 of 4

Extended

Ship To: DANELLA RENTAL SYSTEM DANELLA RENTAL SYSTEM 14101 E MONCREIFF PLACE

14101 E MONCREIFF PLACE

AURORA, CO 80011

Office Phone: (303) 872-8395 Email: GHARDY@DANELLA.COM

Work: (303) 872-8395

AURORA, CO 80011

| Customer P/O: 39478 | Open Date: 06/13/2025 | | Completion Date: 07/03/2025 | | | |
|--|-----------------------|------------------|-----------------------------|---------------|-----------|--|
| Add User: chaft | Salesperson: cive | | | | | |
| VO EASTPENNEP V31950 | BATTERY, GROUP 31 | EA | 3.0 | \$99.97 | \$299.91 | |
| please del to bay 29 VO EASTPENNEP V31950-C | GROUP 31 BAT-Core | EA | 3.0 | \$22.00 | \$66.00 | |
| | 5.165. 6.2/11 55.6 | _, , | 0.0 | 421.00 | Ψ00.00 | |
| please del to bay 29 | | Task 4 Subtotals | Parts: | : | \$299.91 | |
| | | | Core Chg: | | \$66.00 | |
| | | | Core Ret: | | (\$22.00) | |
| | | | Labor | | \$597.50 | |
| | | | Task 4 Subtotals | | \$941.41 | |

Task: XXX010252 QM - Replace Air Dryer_Assembly **Department: Service**

Complaint: REPLACE AIR DRYER

A/R Charge

Cause: FOUND THE AIR DRYER LEAKING

Net 30 Days

Correction: 15455/XM50317-TRAINED ROBERT ON HOW TO NAVIGATE COMPUTER PROGRAMS AND REPLACED AIR DRYER

8/7/2025

ASSEMBLY.15403/MD75051- REPLACED AIR DRYER CHECK FOR LEAKS NONE FOUND.

| Supp. | Part | Description / Ref Number | Description / Ref Number | | U/M Quantity | | Price |
|---|----------------|--------------------------|--------------------------|------------------|---------------------|----------|------------|
| VPDC | 21245706 | AIR DRYER | 5618 | EA | 1.0 | \$826.25 | \$826.25 |
| | | | | Task 5 Subtotals | Parts: | | \$826.25 |
| | | | | | Labor: | | \$478.00 |
| | | | | | Task 5 Subtotals | | \$1,304.25 |
| Detail Tax | Info: | | | | | | |
| Adams CO County Tax | | \$0.00 | ſ | | Total Parts: | | \$4,776.82 |
| Colorado CO State Tax | | \$0.00 | | | Total Core Charge: | | \$2,046.00 |
| Commerce City CO City Tax | | \$0.00 | | | _ | | - |
| Rtd Greater Denver CO Special Tax | | \$0.00 | | | Total Core Ret: | \$ | (2,002.00) |
| Scientific & Cultural Fac.(Cd) CO Special Tax | | \$0.00 | | | Total Labor: | | \$4,660.50 |
| | | \$0.00 | | To | otal Shop Supplies: | | \$300.00 |
| | | | | | Invoice Subtotal: | | \$9,781.32 |
| | | | | | Total Tax: | | \$0.00 |
| | | | | | Total Invoice: | \$ | 9,781.32 |
| <u>Paymen</u> | t Method Terms | <u>Due Date</u> | ` | | | | |



7250 E 56th Avenue | Commerce City, CO 80022 | Phone: (888) 819-7100

MV# 0

Invoice: 23W15924

Date / Hour: 7/8/2025 2:09:51PM

Repair Order: 15924 Customer: DN779900 Branch: DEN Total Invoice: \$9,781.32

A/R Charge

Page 4 of 4

Bill To: DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

Ship To: DANELLA RENTAL SYSTEM

14101 E MONCREIFF PLACE

AURORA, CO 80011

Office Phone: (303) 872-8395 Email: GHARDY@DANELLA.COM

Work: (303) 872-8395

Customer P/O: 39478 Open Date: 06/13/2025 Completion Date: 07/03/2025

Add User: chaft Salesperson: cive

Make Payment Online: nextranusa.com/payonline

TERMS: Cash and payable upon receipt of goods unless other arrangements are made in advance. No discounts allowed, No material may be returned without Nextran Truck Center's permission. Claims or returns must be made within ten (10) days of the date purchase, accompanied by this invoice. Returns are subject to a handling charge of not less than twelve percent (12%) of the cost charged for the good to the undersigned. Nextran Truck Center shall be entitled to recover the reasonable attorney's fees and other costs incurred by it in any action or proceeding arising out of or related to the enforcement or collection of this invoice, in addition to any other relief to which it may be entitled. Service charges accrue on unpaid accounts at the rate of 1.5% per month (18% per annum) from the due date.

VENUE: Any litigation or other adversary proceeding arising from or related to this invoice or the parts or repair work referenced in this invoice shall be resolved solely in the courts of competent jurisdiction in the state and county in which Nextran Truck Center dealership providing the goods or services specified in this invoice is located, and each of the undersigned and Nextran Truck Center hereby irrevocably (i) consents to the personal jurisdiction of any such court and (ii) expressly waives any objection to venue and any claim that any such court constitutes an inconvenient forum. The undersigned agrees that the service of process may be made on the undersigned by mailing a copy of the summons and complaint by certified mail, return receipt requested, to the undersigned's address on file with Nextran Truck Center. All parts are new unless otherwise indicated

ABSOLUTELY NO RETURNS ON ELECTRICAL EQUIPMENT, NON STOCKED ITEMS, OR SPECIAL ITEMS.