

Irwin Automotive Ltd

Hwy 2, PO Box 28

Sinclair, MB. R0M 2A0

Phone: 204-662-4524 Fax: 204-662-4584

Servicing our community for 47 years!

INVOICE**60810**GST #102532108 RT 0001
text# 204-813-9274**INVOICE****Fiasco Farms LTD - Alan Clark**

Box 119

MELITA, MB R0M 110

Cell 1 204-522-6040 Alan

Printed Date: 08/11/2025

Work Completed: 08/11/2025

1997 Mack - CH Series - CH-613 - Mack E7 V-MAC II 6 CYL

Lic #:

Odometer In : 0

VIN #: 1M1AA13Y8 VW066695

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Taxes					
GST					257.21
PST					360.09

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	1,599.00
Parts:	3,362.88
Sublet:	123.28
Fee(s):	58.95
SubTotal:	5,144.11
Tax:	617.30
Total:	5,761.41
Bal Due:	\$5,761.41

[Payments -]

Vehicle Received: 2025-07-21

Thank You For your Business!

Customer Number : 3031

"I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree to the extent permitted by law, Irwin Automotive Ltd is not responsible for loss of use or damage to vehicles or articles left in vehicle in case of fire, theft, or any other cause beyond our control. An express mechanics lien hereby acknowledged on above vehicle to secure the amount of repairs thereto. Wheel Nuts are torqued to factory specifications & must be rechecked after 100 KMS. 2% monthly late fees on ALL overdue accounts.

Signature _____

Date _____

Visit us on the web: www.irwinauto.caEmail Address: dick@irwinauto.ca

Service Advisor : S. Perry Tech : R. Colart J. Cody B. Rhett

Irwin Automotive Ltd
Hwy 2, PO Box 28
Sinclair, MB. R0M 2A0
Phone: 204-662-4524 Fax: 204-662-4584
Servicing our community for 47 years!

INVOICE

60810

GST #102532108 RT 0001
text# 204-813-9274

INVOICE

Printed Date: 08/11/2025

Work Completed: 08/11/2025

Fiasco Farms LTD - Alan Clark

1997 Mack - CH Series - CH-613 - Mack E7 V-MAC II 6 CYL

Lic #:

Odometer In : 0

Box 119
MELITA, MB R0M 110
Cell 1 204-522-6040 Alan

VIN #: 1M1AA13Y8 VW066695

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
CLEARANCE LIGHTS 60261	1.00	8.93	8.93	Safety Truck Tractor Over 4500 GVWR	308.00
CLEARANCE LIGHT 45832	1.00	6.94	6.94	oil change	199.00
LIGHT BRACKET GRAY 43960	1.00	9.11	9.11	Replaced engine oil, filters and fuel filters, greased truck, vacuumed out air filter housing and blew out air filter, a2 diff low on oil, topped up with 75-90, a3 diff good.	
Step 20816521	1.00	661.07	661.07	remove decals from doors removed decals with wax wheel and cleaned doors	42.00
Slack adjuster 5396-40010182	1.00	232.61	232.61	Safety Repairs replace 4 tires A2 replaced LHS lower step replaced signal light switch replaced lights and plugs that weren't working checked A1L bearings and adjusted filled hub with oil replaced shifter handle and checked operation fitting broke off compressor discharge had to removed oil fill tube to access removed broken fitting and installed new one	770.00
Turn signal switch 25155885	1.00	299.63	299.63	Safety Defects	
Gr. C-NE8 NYL INS Lock Nut 5/16-18 39652	2.00	0.39	0.78	rear ID light inoperative (done) license plate light inoperative (done) all LHS turn signals inoperative (done) LHS step damaged (done) sifter leaking air (done) wheel bearing loose A1L(done) tire sidewalls damaged A2LR (advise 4 tires)(done) stroke out of spec A2L (done) Parts List	
BOWMALLOY FLAT WASHER 1 / 4 36750	2.00	0.42	0.84	LHS lower step signal stat slack adjuster (A2L)	
GR. 8 HEX HEAD CAP SCREW D39033	2.00	0.57	1.14	Freight into Bulldog	40.20
OIL FILTER 51791	2.00	33.32	66.64	Freight Bulldog truck center IOX21100267	
fuel filter 33219	1.00	31.16	31.16	Freight from Bulldog Brandon	45.56
fuel filter 33216	1.00	40.73	40.73	Freight 86295	
Mobil Delvac 1300 15W40 per litre 15w40bulk	34.00	6.07	206.38	Safety repairs Removed a2l slack adjuster, slack seized to s cam shaft, had to cut through and heat repeatedly to remove, installed new slack adjuster and set brakes.	280.00
ROADX RD796 16 PLY Size: 11R24.5 RX9630525	4.00	379.42	1,517.68	Freight from RCB 115014	37.52
Tire Fee 2	4.00	14.00	56.00	Enviro Fees	2.95
75W90 Mobil Full Syn Gear Oil Sold by 1 Litre 75W90FS	4.00	15.85	63.40		
ELBOW BRASS X124-D	1.00	13.96	13.96		
brass connector 862-2	1.00	4.86	4.86		
Shifter knob A6909	1.00	104.94	104.94		
Air shift adptr;1/8x1/16 mpt 868-2-1	3.00	5.71	17.13		
Shop Supplies			74.95		

Visit us on the web: www.irwinauto.ca

Email Address: click@irwinauto.ca

Service Advisor: S. Perry, Tech: R. Colitz, J. Cody, B. Rhett