

Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7


Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn Windthorst 306-224-2110

Ship To:

**Invoice To:** 



## SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN 3145 018084

WARRANTY DATE

HRS

002724

SEGMENT# 1 C 14005 NA

COMBINE 1680

08/15/17 08/16/17

CHECK OUT BUSHINGS & CHECK RH SHAKER ARM BEARINGS & BUSHING **COMPLAINT:** 

CHECK OUT BACKEND ALIGNMENT

## CORRECTION:

Brought in the unit for the visual check. Found that the left arm pivot bolt was loose. Tightened it in the center of travel. Took the unit outside and ran it. Found that the pivot arms had a click and a rough movement to them. Noticed that the front four bushing were loose and that one pivot arm needed replacing. Brought the unit in. Removed the back end assembly and visually checked the rails, pan, etc. Did the necessary repairs to the parts for the unit. Painted the parts once they came in. Let the parts dry overnight.

o vermighte.				
B94623	KIT	2	38.06	76.12
FRTCP	FREIGHT-CASE	1	42.10	42.10
1321374C91	LEVER ASSY.	1 N	519.75	519.75
175114C1	FINGER	1	8.98	8.98
186597C1	BUSHING	1-	19.03	19.03-
193132C91	BEARING	2	213.15	426.30
85700693	NUT, LOCK	1	1.58	1.58
			PARTS	1055.80
			LABOR	1390.00
11008001		SEGMENT	TOTAL==>	2445.80

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

Received By

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment the reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Stimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!

Thank You! We Appreciate Your Business



Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420




Assiniboia 306-642-5991 Chamberlain 306-638-4516 306-567-3074 Davidson Moose Jaw 306-694-1800 306-746-2288 Raymore Watrous 306-946-3387 Weyburn 306-842-2629 Windthorst 306-224-2110

www.youngs.ca

Ship To:





## SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

002724 3145 018084 COMBINE

1680

PARTS 1055.80 LABOR 1390.00 SHOP SUPPLIES 125.10 2570.90 SUB TOTAL ==> GST 5% 128.57 2699.47 TOTAL CREDIT CARD

• Thereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at mry risk. Young's Equipment inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, lire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment inc. is hereby released from any and all claims follows and/or damage in caused by the negligence of Young's Equipment hic. Every any of the content inc. Young's Equipment hic. It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment hic. is working on, and/or in prossession of the above-rooted equipment.

and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees at own risk.

A new press methanic's tien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment in the reservation of the entering the per annum. Young's Equipment in the reservation of the entering the estimate on the estimate of 2% per month (24% per month (24% per month). The estimate of 2% per month (24% per month (24% per month) and the estimate on the estimate of 2% per month (24% per month (24% per month). The estimate of 2% per month (24% per month (24% per month) and per month (24% per month) and per month (24% per month). The estimate of 2% per month (24% per month) and per month (24% per month) and per month (24% per month) and per month (24% per month). The estimate of 2% p

Thank You! We Appreciate Your Business

Received By

05486Z