



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON *REPRINT*		
Date 08/28/25	Time 22:10:33 (B)	Page 01
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760		X C7900798 899		
SEGMENT# 1 C 3486 ZONE14 05/29/25 06/06/25					
ZONE 14 TRAVEL CHARGE					
<u>COMPLAINT:</u>					
5 trips total for repairs and inspection					
<u>ADDITIONAL DESCRIPTION:</u>					
ZONE 14 TRAVEL CHARGE					
TRAVEL TO AND FROM CUSTOMER LOCATION					
**Please note: fee is per trip to customer location.					
***Fee is based on the closest AgWest dealer to your location.					
ADX					
10400000				LABOR	3705.00
				SEGMENT TOTAL==>	3705.00

SEGMENT# 2 C 8826 NA 05/29/25 05/29/25					
POST HARVEST INSPECTION					
<u>COMPLAINT:</u>					
POST HARVEST INSPECTION					
<u>CAUSE:</u>					
POST HARVEST INSPECTION					
<u>CORRECTION:</u>					
POST HARVEST INSPECTION					
machine has been inspected as per claas inspection pilot					
<u>ADDITIONAL DESCRIPTION:</u>					
\$1500.00 CREDIT APPLIED TO THE QUOTED \$2695.00 COMBINE INSPECTION PRICE					
---					
BOTH COMBINES GET THIS CREDIT*					
				LABOR	1195.00

CONTINUED ON PAGE 02

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

_____	_____
Date	Purchasers Signature
_____	_____
Section	Township Range



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 02
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7	X C7900798		
	LEX 760	899		
10400000			SEGMENT TOTAL==>	1195.00

SEGMENT# 3 C 8826 NA	07/11/25 07/11/25		
Flip aps caps			
<u>COMPLAINT:</u>			
FLIP APS CAPS			
<u>CAUSE:</u>			
APS CAPS WERE SMOOTH ON ONE SIDE			
<u>CORRECTION:</u>			
Removed all hardware on aps caps			
Flipped aps caps reinstalled with new hardware and torqued to spec of 45nm			
<u>ADDITIONAL DESCRIPTION:</u>			
flip aps caps			
2380060		63	2.48
	NUT SECURING		
			156.24
			PARTS 156.24
			LABOR 380.00
10400000		SEGMENT TOTAL==>	536.24

SEGMENT# 4 C 8826 NA	07/11/25 07/11/25
Replace aps cap and holder	
<u>COMPLAINT:</u>	
Replace aps cap and holder	
<u>CAUSE:</u>	
Replace aps cap and holder broken aps cap	
<u>CORRECTION:</u>	
Found one holder to be completely bent and broken.	
Ground out failed holder and welded in new holder.	

CONTINUED ON PAGE 03

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Invoice To:

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 03
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	899	X C7900798		
6176310	Installed new cap and torqued hardware to spec.			1	23.88
6631570	PADDLE			1	19.26
	CAP				
10400000					
				PARTS	43.14
				LABOR	380.00
				SEGMENT TOTAL==>	423.14

SEGMENT# 5 C 8826 NA 07/11/25 07/11/25

Replace pto cover and hardware

COMPLAINT:

Replace pto cover and hardware

CAUSE:

Replace pto cover and hardware

CORRECTION:

Removed front shield.

Removed hardware.

Removed broken bits of pto cover.

Installed new cover with new hardware to spec.

ADDITIONAL DESCRIPTION:

pto cover plastic gone

2362000				1	.51	.51
	BOLT HEXAGONAL					
2369112				1	.13	.13
	FLAT WASHER					
2381320				1	1.06	1.06
	NUT SECURING					
6305590		COVERING		1 M	42.15	42.15
					PARTS	43.85

CONTINUED ON PAGE 04

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 04
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	X C7900798		
10400000		899		
			LABOR	47.50
			SEGMENT TOTAL==>	91.35

SEGMENT# 6 C 8826 NA	07/11/25 07/11/25			
Replace front suction fan belt				
<u>COMPLAINT:</u>				
Replace front suction fan belt				
<u>CAUSE:</u>				
belt had cracks in it				
<u>CORRECTION:</u>				
Removed front feederhouse cover.				
De-tensioned belt.				
Slid old belt out.				
Slid new belt in.				
Tensioned belt.				
Ran machine.				
<u>ADDITIONAL DESCRIPTION:</u>				
Front suction fan belt completely stretched out				
3257281			1	41.23
	V-BELT			41.23
			PARTS	41.23
			LABOR	95.00
10400000			SEGMENT TOTAL==>	136.23

SEGMENT# 7 C 8826 NA	07/11/25 07/11/25			
Replace 7 spreader paddles				
<u>COMPLAINT:</u>				
spreader paddles all bent right up				
<u>CAUSE:</u>				
paddles all bent and broke on radial spreaders				

CONTINUED ON PAGE 05

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Invoice To:

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 05
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS	
AG11531B	USED 2019 LEXION 7 LEX 760	899	X C7900798			
<u>CORRECTION:</u>						
Removed three bolts holding on paddle. Installed new paddle and bushings. Installed new hardware and torqued to spec. Did this for the next 6 paddles.						
<u>ADDITIONAL DESCRIPTION:</u>						
2111790				40 M	4.40	176.00
2379470	BOLT COACH			40	1.36	54.40
2393880	NUT SECURING			40	.38	15.20
7405990	WASHER, CONTACT			40 M	6.26	250.40
7490240	SLEEVE			7 O	90.60	634.20
	FINGER PADDLE					
					PARTS	1130.20
					LABOR	285.00
10400000				SEGMENT TOTAL==>		1415.20

SEGMENT# 8 C 8826 NA 07/11/25 07/11/25  
 Replace/repair top valve stack fitting

COMPLAINT:

leaking oil

CAUSE:

Replace/repair top valve stack fitting leaking due to blown o-ring

CORRECTION:

Removed clamps holding hard line.

CONTINUED ON PAGE 06

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 06
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7	X C7900798		
	LEX 760	899		
Removed hardline. Installed new fittings and new hard line and bolted back onto machine.				
<u>ADDITIONAL DESCRIPTION:</u> Fitting leaking on top of valve stack				
2159220			1	5.87
	O-RING			5.87
2180630		STRAIGHT MALE C	1 N	88.97
7721421		PIPE	1 N	283.71
				PARTS 378.55
				LABOR 95.00
10400000			SEGMENT TOTAL==>	473.55

SEGMENT# 9 C 8826 NA 07/11/25 07/11/25

Replace tail board cylinder hose

COMPLAINT:

Line leaking and spraying oil when moving tail board

CAUSE:

Leaking line on tail board cylinder

CORRECTION:

Removed panel covering line.  
 Removed zip ties.  
 Removed faulty line.  
 Installed new line and torqued to spec.  
 Installed cover.

ADDITIONAL DESCRIPTION:

Leaking line on tail board cylinder

9934610			1 M	85.27
	HOSE PIPE			85.27
				PARTS 85.27

CONTINUED ON PAGE 07

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 07
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	X C7900798 899		
10400000			LABOR	95.00
			SEGMENT TOTAL==>	180.27

SEGMENT#10 C 8826 NA 07/11/25 07/11/25

Replace feeder house tilt cylinder

COMPLAINT:

Leaking cylinder

CAUSE:

Leaking tilt cylinder on feeder house

CORRECTION:

Remove linkage on cylinder.

Remove lines on cylinder.

Remove pins from cylinder.

Remove cylinder.

Installed new cylinder.

Reinstalled lines and linkage.

Ran feeder house tilt calibration and checked for leaks.

ADDITIONAL DESCRIPTION:

Leaking tilt cylinder on feeder house

0409191	HYD CYLINDER AM	1 N	2004.27	2004.27
			PARTS	2004.27
			LABOR	380.00
10400000			SEGMENT TOTAL==>	2384.27

SEGMENT#11 C 8826 NA 07/11/25 07/11/25

Replace rear beacon

COMPLAINT:

Replace rear beacon

CAUSE:

Replace rear beacon

CONTINUED ON PAGE 08

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date	Purchasers Signature	
Section	Township	Range



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 08
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7	X C7900798		
	LEX 760	899		
<u>CORRECTION:</u> Found beacon would turn on but not rotate. Replaced beacon and all worked.				
<u>ADDITIONAL DESCRIPTION:</u> Rear beacon not working				
0155500			1	258.26
	WARNING BEACON			
				PARTS 258.26
				LABOR 47.50
10400000			SEGMENT TOTAL==>	305.76

SEGMENT#12 C 8826 NA	07/11/25	07/11/25		
Repair light under engine cover				
<u>COMPLAINT:</u> Repair light under engine cover				
<u>CAUSE:</u> Light was burned out and switch was defective				
<u>CORRECTION:</u> Removed old light and installed new one. Found that light would not light up. Traced out circuit and found that a faulty switch. Replaced switch and it all worked.				
<u>ADDITIONAL DESCRIPTION:</u> Light under engine cover doesn't light up				
0158600	WORK LIGHT		1 N	204.58
2159571			1	80.03
	SWITCH			
				PARTS 284.61
				LABOR 47.50
10400000			SEGMENT TOTAL==>	332.11

CONTINUED ON PAGE 09

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elle, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Invoice To:

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 09
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	899	X C7900798		
<hr/>					
SEGMENT#13 C 8826 NA		07/11/25	07/11/25		
Replace horn					
<u>COMPLAINT:</u>					
Replace horn					
<u>CAUSE:</u>					
Replace horn					
<u>CORRECTION:</u>					
Removed wiring and hardware from horn. Installed new horn.					
<u>ADDITIONAL DESCRIPTION:</u>					
Horn not working					
0717292				1 M	109.01
	HORN				109.01
				PARTS	109.01
				LABOR	95.00
10400000				SEGMENT TOTAL==>	204.01

SEGMENT#14 C 8826 NA		07/11/25	07/11/25		
Replace windshield washer reservoir					
<u>COMPLAINT:</u>					
Replace windshield washer reservoir					
<u>CAUSE:</u>					
Windshield washer fluid doesn't spray, and tank is full of chaff					
<u>CORRECTION:</u>					
Removed lines from old tank and flushed with air. Installed new tank. Installed new windshield washer motor. Installed new cap on reservoir.					

CONTINUED ON PAGE 10

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_

GST 12920 2008 RT0001



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 10
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7		X C7900798		
	LEX 760	899			
Removed top cover and removed nozzles. Installed new nozzles and ran water through hoses to flush all dirt and debris. Installed lines onto new nozzles. Test ran to see if it sprayed. Machine started working properly. Reinstalled panel.					
<u>ADDITIONAL DESCRIPTION:</u> windshield washer fluid doesn't spray, and tank is full of chaff					
0748791		CONTAINER		1 N 313.16	313.16
5461650				1 6.39	6.39
5462360	COVER	WASHER PUMP		1 N 333.90	333.90
				PARTS	653.45
				LABOR	380.00
10400000				SEGMENT TOTAL==>	1033.45

SEGMENT#15 C 8826 NA 07/11/25 07/11/25

Replace both rotor bearings

COMPLAINT:

Replace both rotor bearings

CAUSE:

Both rotor bearings need replaced they were very hot

CORRECTION:

Tie up rotor with ratchet strap.  
 Remove cover and found grease to be burnt.  
 Hammered out crusty grease and pie plate.  
 Fought to pull the seized bearings off both shafts.

CONTINUED ON PAGE 11

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 11
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	X C7900798 899		
Installed new bearings and trunnions. Installed pie plate. Lifted rotor and lined up bolts. Installed center bearing bolt and torqued to spec. Installed cover. Installed grease line. Greased bearing well. Torqued all hardware twice, very important to check torque. Made sure both bearings were seated well and pie plates were properly installed and torqued. Removed ratchet straps. Ran machine and checked temp, were cool.				
<u>ADDITIONAL DESCRIPTION:</u>				
Both rotor bearings need replaced they were very hot				
2173290			2	336.13
	SPHERICAL ROLLER B			672.26
2358390			2	15.30
	CIRCLIP			30.60
7236960			2	28.25
	O-RING			56.50
7825420			2	17.95
	SPACER			35.90
7825450			2	344.22
	TRUNNION			688.44
				PARTS 1483.70
				LABOR 2280.00
10400000				SEGMENT TOTAL==> 3763.70

SEGMENT#16 C 8826 NA 07/11/25 07/11/25  
 Replace one bent stationary knife

CONTINUED ON PAGE 12

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 12
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS	
AG11531B	USED 2019 LEXION 7 LEX 760	899	X C7900798			
<u>COMPLAINT:</u>						
Bent stationary knife						
<u>CAUSE:</u>						
Bent stationary knife						
<u>CORRECTION:</u>						
Removed pin that holds knives in place.						
Removed broken knife.						
Installed new knife and put pin back through.						
<u>ADDITIONAL DESCRIPTION:</u>						
7376000	Replace one bent stationary knife			1	24.00	24.00
	COUNTER KNIFE					
10400000					PARTS	24.00
					LABOR	95.00
					SEGMENT TOTAL==>	119.00

SEGMENT#17 C 8826 NA	07/11/25 07/11/25					
Replace 4 missing hammers						
<u>COMPLAINT:</u>						
Replace 4 missing hammers						
<u>CAUSE:</u>						
Replace 4 missing hammers						
<u>CORRECTION:</u>						
Put combine spreader system into transport position.						
Installed new hammers onto chopper drum and torqued to spec of 55nm.						
All new knives and hardware.						
<u>ADDITIONAL DESCRIPTION:</u>						
2335720	Replace 4 missing hammers			2	5.38	10.76

CONTINUED ON PAGE 13

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 13
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760 HEXAGON HEAD BOLT		X C7900798		
2380060		899		2	2.48
	NUT SECURING				4.96
5538602				4	40.48
	FREE-SWINGING KNIF				161.92
7368712				4	17.20
	BUSHING				68.80
7558690				4	12.98
	WASHER				51.92
					PARTS 298.36
					LABOR 190.00
10400000				SEGMENT TOTAL==>	488.36

SEGMENT#18 C 8826 NA 07/11/25 07/11/25

Replace main return hose

COMPLAINT:

Hose leaking at tank fitting

CAUSE:

Main return hose leaking at fitting to tank

CORRECTION:

Removed hose from manifold.

Removed hose from tank.

Installed new o-ring into hose at tank.

Installed new hose onto tank.

Zip tied into place properly.

ADDITIONAL DESCRIPTION:

Replace main return hose

18019562	HOSE ASSY	1	M	420.60	420.60
5109172	HOSE SUPPORT	1	M	55.64	55.64
7701018207		1		9.41	9.41

CONTINUED ON PAGE 14

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

Date	Purchasers Signature	
Section	Township	Range

GST 12920 2008 RT0001



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 14
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS	
AG11531B	2019 LEXION 7		X C7900798			
	LEX 760	899				
	O-RING					
10400000						
				PARTS		485.65
				LABOR		190.00
				SEGMENT TOTAL==>		675.65

SEGMENT#19 C 3486 NA 07/11/25 07/11/25

Replace bushings on spreader arms

COMPLAINT:

Excessive play on spreader arms

CAUSE:

Bushings shaft bearings worn

CORRECTION:

Remove spreader arms hardware.

Remove spreader arms.

Remove cylinder.

Remove old bushings fit new bushings.

Spreader arm bearings are seized to shaft.

Replace spreader arms fit new bearings.

Fit new snap rings.

Fit new bushings.

Fit all components back tightened up hardware.

ADDITIONAL DESCRIPTION:

Replace bushings on spreader arms

0085240		4	8.08	32.32
	BUSHING			
6233320		12	19.93	239.16
	BUSHING			
6311800		6	12.42	74.52
	BUSHING			
7848320		6	30.43	182.58

CONTINUED ON PAGE 15

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elle, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 15
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
		Salesperson 157

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#	USED	HRS	PIN/EIN	WARRANTY DATE	HRS	
AG11531B	2019 LEXION 7 LEX 760 PIN	899	X C7900798			
7848971	PIN			4	27.85	111.40
9672940	BUSHING			4	17.06	68.24
					PARTS	708.22
					LABOR	380.00
10400000				SEGMENT TOTAL==>		1088.22

SEGMENT#20 C 8826 NA 07/11/25 07/11/25

Service machine

COMPLAINT:

Service machine

CAUSE:

Service machine

CORRECTION:

Serviced machine as per claas spec customer said he had changed oil and fuel filters so just provided those

ADDITIONAL DESCRIPTION:

Service machine

CL1474470

AGRIHYD HVL P-D NA

0773672

FILTER ELEMENT

0773821

FILTER SAFTEY CART

1R0749

FILTER AS FU

1R1808

FILTER AS-LU

CONTINUED ON PAGE 16

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

GST 12920 2008 RT0001

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_  
 Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_



Ship To: IN STORE PICKUP

Please send payment to:  
 AgWest Ltd.  
 Highway #1 West, PO Box 432  
 Elie, MB R0H 0H0

**AgWest Ltd. Brandon**  
 113011 Hwy #1  
 1 Rusty Way  
 Cornwallis, MB R7A 5Y3  
 (204) 571-2461  
 www.agwest.com

Branch BRANDON		
Date 08/28/25	Time 22:10:33 (B)	Page 16
Account No	Phone No	Inv No W01103
Ship Via	Purchase Order POST HARV INSP	
Tax ID No NW 9 5 27		
	Salesperson 157	

Invoice To:

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
AG11531B	USED 2019 LEXION 7 LEX 760	899	X C7900798		
1473970				1 M	
1474300	AGRISHIFT BLS 80W-			1	
1474931	AGRISHIFT MT 80W-9			1 M	
1801802	AGRISHIFT SYN F			2	
3261643	AGRIMOT PROTEC FE			1	
5100541	FILTER AS			1	
5646982	FILTER ELEMENT			2	
	POCKET FILTER				
				PARTS	2493.60
				LABOR	1140.00
10400000				SEGMENT TOTAL==>	3633.60

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	10681.61
LABOR	11502.50
SHOP SUPPLIES	200.00
DISCOUNT	409.41 -
SUB TOTAL==>	21974.70
GST 5%	1098.77
TOTAL AR CHARGE	23073.47

PURSUANT TO THE MANITOBA GARAGE KEEPERS ACT, THE UNDERSIGNED HEREBY ACKNOWLEDGES THEMSELVES INDEBTED TO AGWEST LTD. IN THE AMOUNT OF THIS INVOICE.  
 AUTHORIZED NAME (PLEASE PRINT):

SIGNED BY: \_\_\_\_\_

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming

**CUSTOMER ORIGINAL**

Internet banking payments accepted at most financial institutions EFT available- call your credit contact for information. Invoice due 30 days from invoice date. Late payment charges of 1.5% per month (18% per year) will be charged on all past due amounts.

Date \_\_\_\_\_ Purchasers Signature \_\_\_\_\_

**GST 12920 2008 RT0001**

Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_