



Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-8351	Yorkton, SK	(306) 783-9469
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2698	Wynyard, SK	(306) 554-2636
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3468
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 47832

Deliver To:

SERVICE INVOICE

DEERE WARRANTY PIP CLAIMS SK		Invoice Number: 2886877 Invoice Date 10/05/2022 Location: 03 Work Order Number: 390998 Payment Type: Account
Bus Phone: Prv Phone:		Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9620R	2192	1RW9620RAGP054122	054122	

Service Reminders:

PIP21RW944A Warranty

COMPLAINT:

01 21RW944A - 9R 15L ROCKER ARM ROLLER IMPROVEMENT - MANDATORY

CAUSE:

21RW944A - 9R 15L ROCKER ARM ROLLER IMPROVEMENT - MANDATORY

CORRECTION:

21RW944A - 9R 15L ROCKER ARM ROLLER IMPROVEMENT - MANDATORY
SECURED MACHINE INTO WORKSHOP.
PLACED ENGINE HOOD INTO SERVICE POSITION.
CLEANED AROUND ROCKER COVER.
REMOVED ROCKER COVER.
INSPECTED CAMSHAFT LOBES AND FOUND LOBES ARE WORN.
OPENED DTAC CASE 2150462.
ORDER NEW CAMSHAFT.
INSTALLED BACK ROCKER COVER.
PLACED ENGINE HOOD INTO OPERATION MODE.
REMOVED ENGINE HOOD.
REMOVED ROCKER COVER.
REMOVED ROCKER SHAFTS.
REPLACED ROCKER LEVERS INTAKE AND EXHAUST.
REPLACED EXHAUST BRAKE LEVERS.
INSTALLED BACK ROCKER SHAFTS.
ADJUSTED VALVE CLEARANCE TO SPEC.
INSTALLED BACK ROCKER COVER.
DID JOB AS PER SERVICE MANUAL.
TORQUED ALL HARDWARE TO SPEC.

FP: 21RW944A
REPAIR: 5HRS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
MPR13258	21RW944 QSX15 Rocker Roller PIP	1.00	386.23	\$386.23	N
REC439308700	LEVER	6.00	777.34	\$4,664.04	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
FRT	FREIGHT	1.00	15.00	\$15.00	N
Labor: \$850.00		Parts: \$5,050.27	OL&M: \$0.00	Misc: \$15.00	Sub-Total: \$5,915.27



Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9469
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 47832

Deliver To:

SERVICE INVOICE

DEERE WARRANTY PIP CLAIMS SK	Invoice Number: 2886877			
Bus Phone:	Invoice Date 10/05/2022			
Prv Phone:	Location: 03			
	Work Order Number: 390998			
	Payment Type: Account			
	Page: 2 of 2			
Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9620R	2192	1RW9620RAGP054122	054122	

Service Reminders:

Customer PO No:	
Tax Exempt No:	ON FILE
Advisor:	Colm Donohoe

Labor:	\$850.00
Parts:	\$5,050.27
OL&M:	\$0.00
Misc:	\$15.00
GST:	\$0.00
PST:	\$0.00
Grand Total:	\$5,915.27

TERMS AND CONDITIONS

Received by:

Date:



Hwy 7 East, Box 1180
 Kindersley, SK S0L 1S0
 Phone: (306) 463-2683
 Fax: (306) 463-6131
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeseville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3468
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



Invoice To Account No: 47832

Deliver To:

SERVICE INVOICE

DEERE WARRANTY PIP CLAIMS SK		Invoice Number: 2886881	
		Invoice Date 10/05/2022	
		Location: 03	
		Work Order Number: 390998	
		Payment Type: Account	
Bus Phone:		Page: 1 of 2	
Prv Phone:			
Make/Model:	Meter	Serial Number:	EQ Id: Fleet No:
JOHN DEERE 9620R	2192	1RW9620RAGP054122	054122

Service Reminders:

PIP21RW944B Warranty

COMPLAINT:

02 21RW944B - 9R 15L ROCKER ARM ROLLER IMPROVEMENT .

CAUSE:

PIP 21RW944 AND FOUND CAMSHAFT LOBES WORN.

CORRECTION:

ORDERED NEW CAMSHAFT.
 DTAC CASE NUMBER = 2150462.
 REMOVED ENGINE HOOD.
 RECOVERED A/C GAS.
 REMOVED AFTERCOOLER.
 REMOVED A/C DRIVE BELT AND TENSIONER.
 REMOVED WATER PUMP BELT AND TENSIONER.
 REMOVED FRONT TIMING COVER.
 REMOVED CAMSHAFT GEAR .
 REMOVED CAMSHAFT.
 INSTALLED NEW CAMSHAFT.
 INSTALLED CAMSHAFT GEAR.
 DID BACK LASH OF THE CAMSHAFT GEAR AND IDLER GEAR.
 INSTALLED BACK FRONT TIMING GEAR COVER WITH NEW GASKET.
 INSTALLED BACK WATER PUMP TENSIONER AND DRIVE BELT.
 INSTALLED BACK A/C PUMP DRIVE BELT AND TENSIONER.
 INSTALLED BACK AFTER COOLER.
 CHARGED A/C SYSTEM UP TO SPEC.
 INSTALLED BACK ENGINE HOOD.
 TESTED MACHINE-ALL GOOD.
 DID JOB AS PER SERVICE MANUAL.
 TORQUED ALL HARDWARE TO SPEC.

DTAC-2150462
 FP: 21RW944B
 Repair: 10.0 hrs

REPAIR: 10.00HRS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
REC367993200	GASKET	1.00	14.27	\$14.27	N
REC368267300	Gasket	1.00	36.97	\$36.97	N



Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 47832

Deliver To:

SERVICE INVOICE

DEERE WARRANTY PIP CLAIMS
SK

Bus Phone:
Prv Phone:

Invoice Number: **2886881**
Invoice Date: 10/05/2022
Location: 03
Work Order Number: 390998
Payment Type: Account

Page: 2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9620R	2192	1RW9620RAGP054122	054122	

Service Reminders:

REC368700700	SEAL	1.00	60.66	\$60.66	N
REC429862900	Camshaft	1.00	3,325.55	\$3,325.55	N
REC429912500	O-RING	1.00	22.82	\$22.82	N

Labor: \$1,700.00 Parts: \$3,460.27 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$5,160.27

Customer PO No:
Tax Exempt No: ON FILE
Advisor: Colm Donohoe

Labor: \$1,700.00
Parts: \$3,460.27
OL&M: \$0.00
Misc: \$0.00
GST: \$0.00
PST: \$0.00

Grand Total: \$5,160.27

TERMS AND CONDITIONS

Received by:

Date: