

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service
Invoice



SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9204342

PAGE 1 SALE TYPE
CASH CUSTOMER NO. 3200187

S TREWIN FARM CORP.
H BOX 102
I
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER 306-223-4468	WORK ORDER NO. 9204342	SEG. 01	DATE OPENED 05MAY25	SALES PRN	
MAKE JD	MODEL C650	SERIAL NO. 1A8C650HJNM795332	EQUIP. NO.	METER 1	AUTHORIZED BY	

DESCRIPTION	AMOUNT
TRAVEL	
CORRECTION: -TRAVEL TO MACHINE LOCATION IN LAIRD AREA AND BACK TO ROSTHERN.	
* LABOR *	210.00
AG SERVICE ACCESSORI	18.90
ENVIRONMENTAL FEE	2.10
>>--> SEG# 01 PRT .00 LAB 210.00 MSC 21.00	231.00
* GST/HST *	11.55
DOWNLOAD AND INSTALL SOFTWARE	
COMPLAINT: -CHECK DTC TEST PROCEDURES AND RECORD DISPLAY ERROR CODES WHILE SEEDING. DISCUSS AND LIST POSSIBLE CAUSES WITH OPERATOR. OPERATOR THEN FOCUS ON ERRATIC SPEED AND DISCUSS WITH CUSTOMER OVER RADIO. CUSTOMER DO VISUAL INSPECTION OF SPEED SENSOR AS SOON AS WE STOPPED. FIND SPEED SENSOR MOUNTING HARDWARE LOST AND DAMAGED SPEED SENSOR. CUSTOMER MOUNT SENSOR AND HAVE ME INSPECT CAP.	
CORRECTION: -OPEN SERVICE ADVISOR JOB AND DOWNLOAD ALL SOFTWARE. INSTALL ALL SOFTWARE.	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. <u> X </u> _____ SIGNATURE _____ DATE	QST # 1226957240	DESCRIPTION	AMOUNT
		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES SALES TAX	
		PLEASE PAY THIS TOTAL ➔	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service
Invoice



JOHN DEERE

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9204342

PAGE
2
SALETYPE
CASH
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
	306-223-4468	9204342	02	05MAY25		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	C650	1A8C650HJNM795332		1		

DESCRIPTION	AMOUNT
CONDITION STILL EXIST AFTER TESTING. CUSTOMER TO REPLACE SENSOR AND MOUNT WITH SPECIFIED HARDWARE.	
* LABOR *	768.75
AG SERVICE ACCESSORI	69.19
ENVIRONMENTAL FEE	7.69
>>--> SEG# 02 PRT .00 LAB 768.75 MSC 76.88	845.63
* GST/HST *	42.28
* TOTAL GST/HST * - GST No. 899544779	53.83

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	0.00
TOTAL LABOR	978.75
MISC. CHARGES	97.88
SALES TAX	0.00
PLEASE PAY THIS TOTAL	1,130.46

CUSTOMER COPY