



western@westernsales.ca
 (306) 518-2270
 westernsales.ca



Ship to:

IN STORE PICKUP

Invoice to:

Dan Roth
 Box 31
 Handel, SK
 Handel SK S0K 1Y0

Branch		
Biggar *REPRINT*		
Date	Time	Page
11/19/24	22:45:33 (B)	01
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via		Purchase Order
		Salesperson
		AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			

 Thank you for choosing Western Sales. For any future service needs contact our Biggar service department directly by text or phone at 306-518-8587.

SEGMENT# 1 C 4830 CMI-W 10/21/24 10/21/24
 CERTIFIED MAINTENANCE INSPECTION (CMI) - WALKER / CTS

Repair:
 -feeder house isolater not going together
 -had to cut out carriage bolt that was rounded replaced bolts
 -put isolator on bracket and mounted
 -ran

ADDITIONAL DESCRIPTION:
 ENSURE SUPPORT CENTER DECAL INSTALLED ON INSIDE OF CAB WITH SERIAL NUMBER FILLED IN

BBADF					
03M7185	M8X25 BOLT	6	.65		3.90
14M7298	M8 FLANGE NUT	6	1.45		8.70
	PARTS				12.60
	LABOR				1999.00
10400	SEGMENT TOTAL==>				2011.60

SEGMENT# 2 C 4832 NA 10/21/24 11/04/24
 FIND WHERE METAL IS BROKEN

SEGMENT# 3 C 4832 NA 10/21/24 10/21/24
 LEAKING INJECTORS

LABOR 180.00
 CONTINUED ON PAGE 02

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 02
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via		Purchase Order
		Salesperson AR

DESCRIPTION

STK#/FLEET#	CTS COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	
007865	CTS	4629	670664			
10400		3120				SEGMENT TOTAL==> 180.00
<hr/>						
SEGMENT# 4 C 4832 NA		10/21/24	10/21/24			
COMBINE WANTS TO DIE AT IDLE						
AH130127		FUEL PUMP		1	186.51	186.51
T77613		#6 O-RING		3	3.17	9.51
					PARTS	196.02
					LABOR	180.00
10400						SEGMENT TOTAL==> 376.02
<hr/>						
SEGMENT# 5 C 4832 NA		10/21/24	11/04/24			
OIL LEAKING AT ENGINE						
					LABOR	14.80
10400						SEGMENT TOTAL==> 14.80
<hr/>						
SEGMENT# 6 C 4832 41.01		11/01/24	11/04/24			
DIAGNOSE LIGHT PROBLEMS						
<u>COMPLAINT:</u>						
Unloading auger light does not work with auger out.						
<u>Repair:</u>						
-removed connector tested bulb						
-bulb burnt out						
-got new light needed connect to go from old to new plug						
-R&R light						
-extended auger once able to light not coming on						
-check for power and continuity in in wires						
-power all the way up to light swapped terminals in wiring harness in for new light						
-light worked						
<u>ADDITIONAL DESCRIPTION:</u>						

CONTINUED ON PAGE 03

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	03
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#	CT	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
Includes R&R of bulb if that was the issue. If more time required, contact service manager.					
AXE84599	Wiring Harness	1	N	56.32	56.32
CXT17293	Floodlamp	1	N	381.63	381.63
	PARTS				437.95
	LABOR				397.75
10400	SEGMENT TOTAL==>				835.70

SEGMENT# 7 C 4832 NA 11/01/24
ADJUST TIRE PRESSURE (OPTED NOT)
COMPLAINT:
Rear tires are low.
Filled to 26psi check again and send for repairs if necessary

SEGMENT# 8 C 4832 120.8 11/01/24 11/04/24
DIAGNOSE SEPARATOR VIBRATION
COMPLAINT:
Bad vibration aligned with cylinder speed. Drive belt is jumping excessively.
Repair:
-ran combine no vibration found after beater blades replaced

ADDITIONAL DESCRIPTION:
ISOLATE DIFFERENT SECTIONS OF SEPARATOR TO DIAGNOSE.
THIS SEGMENT DOES NOT INCLUDE ANY REPAIR.

14M7298	M8 FLANGE NUT	3	1.45	4.35
19M7866	M8X20 FL-BOLT	3	1.74	5.22
	PARTS			9.57
	LABOR			370.00

CONTINUED ON PAGE 04

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to:

IN STORE PICKUP

Invoice to:

Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	04
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#	CTS COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS	4629	670664		
10400		3120			
SEGMENT TOTAL==>					379.57
<hr/>					
SEGMENT# 9 C 4832 41		11/01/24	11/01/24		
R&R LIGHT					
<u>COMPLAINT:</u>					
Front right signal light does not work.					
<u>Repair:</u>					
-removed cover R&R blub					
H133384		BULB		1	7.70
					7.70
					7.70
					74.00
10400					
SEGMENT TOTAL==>					81.70
<hr/>					
SEGMENT#10 C 4832 NA		11/01/24			
CAB MOUNTS (OPTED NOT)					
<u>COMPLAINT:</u>					
Cab mounts are blown out. Replace front mounts.					
Both rear cab mounts blown out.					
<hr/>					
SEGMENT#11 C 4832 110.02		11/01/24	11/04/24		
R&R HALF LINK OUT OF FEEDER CHAIN					
<u>COMPLAINT:</u>					
Needs half link removed					
<u>Repair:</u>					
loosen feeder chain					
-had to cut out half links					
-put new J clips in					
<u>ADDITIONAL DESCRIPTION:</u>					
LOOSEN CHAIN					
ROTATE TO CONNECTOR LINK AND REMOVE					

CONTINUED ON PAGE 05

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 05
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via		Purchase Order
		Salesperson AR

DESCRIPTION

STK#/FLEET#	CTS	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
USE CHAIN BREAKER OR SIDE GRINDER TO REMOVE HALF LINK CONNECT CHAIN AND ADJUST TO APPROPRIATE TENSION					
H84026	CHAIN LINK HOOK	6		.93	5.58
14M7276	M16 NUT	1		3.15	3.15
				PARTS	8.73
				LABOR	222.00
10400				SEGMENT TOTAL==>	230.73

SEGMENT#	C	4832	110.011	11/01/24	11/01/24		
R&R FEEDER CHAIN ADJUSTING BOLTS (PER SIDE)							
<u>COMPLAINT:</u> Both eye bolts are bent.							
<u>Repair:</u> -removed eyes -R&R eyebolts, nuts & bushing -tighten feeder chain							
<u>ADDITIONAL DESCRIPTION:</u> REMOVE SHIELDS AS NECESSARY LOOSEN FEEDER CHAIN REMOVE AND REPLACE HARDWARE. TIGHTEN FEEDER CHAIN. CHECK ALIGNMENT AND OPERATION.							
H131087			BUSHING	2	M	17.75	35.50
H131088			EYEBOLT	2		44.14	88.28
14M7291			M16 FL-NUT	4		4.86	19.44
						PARTS	143.22
						LABOR	370.00
10400						SEGMENT TOTAL==>	513.22

SEGMENT#	C	4832	NA	11/01/24
R&R OUTER REVERSER SEALS (OPTED NOT)				

CONTINUED ON PAGE 06

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch			
Biggar			
Date	Time	Page	
11/19/24	22:45:33 (B)	06	
Account No.	Phone No.	Invoice No.	
658488800	3066584888	W79820	
Ship Via		Purchase Order	
			Salesperson
			AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
<u>COMPLAINT:</u> Leaking from outer seal.					
<u>ADDITIONAL DESCRIPTION:</u> REMOVE LOWER BELT AND LOWER PULLEY REMOVE RH DRIVE CHAIN AND REMOVE FH BACKSHAFT FROM REVERSER REMOVE OUTER QUILL COVER FROM REVERSER (IF NECESSARY) REPLACE BOTH OUTER SEALS. REPLACE O-RING ON FH BACKSHAFT. LUBE ALL SEALS FOR ASSEMBLY. ASSEMBLE IN REVERSE. TOP UP OIL IF NECESSARY.					
SEGMENT#14 C 4832 111.16			11/01/24 11/01/24		
R&R LOWER FH IDLERS					
<u>COMPLAINT:</u> Rearward idler is grinding.					
<u>Repair:</u> R&R idler pulley					
<u>ADDITIONAL DESCRIPTION:</u> LOOSEN BELT, REPLACE IDLER(S)					
AH94450	IDLER PULLEY	1		160.78	160.78
				PARTS	160.78
				LABOR	55.50
10400			SEGMENT TOTAL==>		216.28

SEGMENT#15 C 4832 NA			11/01/24		
R&R AND RECONDITION UPPER FH DRIVE (OPTED NOT)					
<u>COMPLAINT:</u> Play on pulley inner bearing is likely worn into shaft.					
<u>ADDITIONAL DESCRIPTION:</u>					

CONTINUED ON PAGE 07

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	07
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#	CTS	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
LOOSEN UPPER AND LOWER FH BELT. REMOVE UNIT FROM COMBINE. REPLACE BEARINGS. ASSEMBLE AND TENSION.					
<hr/>					
SEGMENT#16 C 4832	124.13		11/01/24	11/01/24	
R&R OR LOCK-TITE SHOE AUGER KEYS					
<u>COMPLAINT:</u>					
All are loose. Loctite and replace keys.					
<u>Repair:</u>					
-backed loosen off clamps					
-R&R keys & lock-tite key					
-set back lash					
<u>ADDITIONAL DESCRIPTION:</u>					
REMOVE LH DRIVE SHAFT IF NECESSARY					
LOOSEN BEVEL GEAR COLLARS.					
REPLACE SHAFT KEY AND ASSEMBLE WITH LOCTITE.					
SET BACKLASH AND TIGHTEN COLLAR.					
H167587		KEY		6	4.04
					24.24
					PARTS 24.24
					LABOR 231.25
10400				SEGMENT TOTAL==>	255.49

SEGMENT#17 C 4832	57.5		11/01/24	11/01/24
R&R TRANSMISSION OIL				
<u>COMPLAINT:</u>				
Exceeded Service Interval				
<u>Repair:</u>				
-R&R oil				
-R&R orings that torn				

CONTINUED ON PAGE 08

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 08
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via		Purchase Order
		Salesperson AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
<u>ADDITIONAL DESCRIPTION:</u>					
REMOVE BOTTOM SECTION OF OIL PUMP TUBE.					
REMOVE OIL TUBE					
DRAIN GEAR OIL.					
FILL WITH NEW GEAR OIL THROUGH FILL PLUG					
EHC-OIL	5¢ PER LITRE	10		.05	.50
EHC-PAIL	10¢ / LITRE CAP	10		.10	1.00
R394R	O-RING	1		3.60	3.60
R495R	O-RING	2		6.02	12.04
TY26815	80W-90 GL5	2		51.75	103.50
TY6296	1L 80W90 OIL	2		15.99	31.98
				PARTS	152.62
				LABOR	185.00
10400				SEGMENT TOTAL==>	337.62

SEGMENT#18	C 4832 55.5		11/01/24	11/01/24	
R&R FINAL DRIVE OIL					
<u>COMPLAINT:</u>					
Exceeded Service Interval					
<u>Repair:</u>					
-final drive oil still good					
-toped up					
EHC-OIL	5¢ PER LITRE	16		.05	.80
EHC-PAIL	10¢ / LITRE CAP	16		.10	1.60
14M7296	M10 FLANGE NUT	1		2.04	2.04
				PARTS	4.44
				LABOR	222.00
10400				SEGMENT TOTAL==>	226.44

SEGMENT#19 C 4832 NA 11/01/24

CONTINUED ON PAGE 09

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to:

IN STORE PICKUP

Invoice to:

Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	09
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			

NOTE - HYDROSTATIC MOTOR LEAKS (OPTED NOT)
COMPLAINT:
B) Sweating from transmission. Not a major leak.

SEGMENT#20 C 4832 NA 11/01/24
BALANCE CYLINDER (OPTED NOT)
COMPLAINT:
Cylinder is out of balance. Needs to be balanced.

SEGMENT#21 C 4832 122.71 11/01/24 11/06/24
R&R BEATER WINGS (BLADES) (2 SETS OF 2)
COMPLAINT:
Multiple broken wear plates all are worn thin. Replace all wear plates
Repair:
-rolled out rotor
-loosen belt
-removed broken blades marked blades 180*
-found 5 of the blades marked cracked
-removed rest of blades to inspect for damage or cracking
-found 13 blades in total in broken or cracked replace 16
-tighten all blades & torqued to spec
-beater blades cause vibration
-no vibration after running
ADDITIONAL DESCRIPTION:
JUST REPLACE THE BROKEN ONES
** If blades are severely bent and require extra persuasion, add extra time to segment **
Perform safety precautions.
Loosen drive belt tension.

CONTINUED ON PAGE 10

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	10
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
	Remove seal half. Remove blades in sets of two, 180 degrees apart. Assemble to specifications.				
H177314	WEAR PLATE			16 N 24.72	395.52
				PARTS	395.52
				LABOR	925.00
10400				SEGMENT TOTAL==>	1320.52

SEGMENT#22 C 4832 60.1		11/01/24	11/01/24		
ADD BRAKE FLUID					
<u>COMPLAINT:</u> Tank is empty. No cracks on tank. Fill and check for leaks.					
<u>Repair:</u> -added brake fluid -insected lines for leaks non found					
TY26180	Brake Fluid			1 10.40	10.40
				PARTS	10.40
				LABOR	111.00
10400				SEGMENT TOTAL==>	121.40

SEGMENT#23 C 4832 NA		11/01/24			
R&R AND RECONDITION ELECTROMAGNETIC HEADER CLUTCH (OPTED NO					
<u>COMPLAINT:</u> Gap is quite large and bearing has lots of play. Remove clutch and replace bearing and clutch.					
<u>ADDITIONAL DESCRIPTION:</u> REMOVE UPPER FH BELT REMOVE CLUTCH ASSEMBLY FROM SHAFT DISASSEMBLE CLUTCH AND REPLACE COMPONENTS AS NECESSARY. ASSEMBLE AND INSTALL.					

CONTINUED ON PAGE 11

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	11
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#	CTS	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
<hr/>					
SEGMENT#24	C 4832 NA	11/01/24	11/01/24		
BEATER GEARCASE					
<u>COMPLAINT:</u>					
Gearbox is very low. Change oil and fill to spec.					
<u>Repair:</u>					
-R&R gear oil filled to spec					
EHC-OIL		5¢ PER LITRE	2	.05	.10
EHC-PAIL		10¢ / LITRE CAP	2	.10	.20
				PARTS	.30
				LABOR	148.00
10400				SEGMENT TOTAL==>	148.30
<hr/>					
SEGMENT#25	C 4832 NA	11/01/24			
R&R SHOE SWING ARM (MAIN) (EACH) (OPTED NOT)					
<u>COMPLAINT:</u>					
All LH and RH arms are cracking.					
<u>ADDITIONAL DESCRIPTION:</u>					
REMOVE COMPONENTS AS NECESSARY TO ACCESS.					
TIGHTEN MID-STROKE.					
<hr/>					
SEGMENT#26	C 4832 125.11	11/01/24	11/01/24		
R&R UPPER CLEANING FAN SHEAVES (INNER & OUTER)					
<u>COMPLAINT:</u>					
Outer sheave is crooked and will not adjust speed. Need to replace outer sheave, belt, and check shaft and other parts.					
<u>Repair:</u>					
-removed speed control arm					
-removed belt and out fan sheave					
-inner fan sheave worn as well stuck on shaft					

CONTINUED ON PAGE 12

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		Biggar	
Date	Time	Page	
11/19/24	22:45:33 (B)	12	
Account No.	Phone No.	Invoice No.	
658488800	3066584888	W79820	
Ship Via		Purchase Order	
		Salesperson	
		AR	

DESCRIPTION

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664	
	CTS	3120		
-bearing worn seized on shaft				
-cut bearing out				
-installed new bearing and lock collar				
-cleaned paint off inside of sheave to fit onto shaft				
-put new bearing for speed control arm				
-shaft not going on smoothy key kept popping out				
-got new sheaves and belt on				
-put speed control arm back on greased				
<u>ADDITIONAL DESCRIPTION:</u>				
R&R CLEANING FAN BELT				
LOOSEN SHOE DRIVE BELT				
REMOVE BOTH SHEAVES AND REPLACE PARTS AS REQUIRED.				
ASSEMBLE IN REVERSE.				
CHECK FULL RANGE OF FAN				
AH133191	ECCENTRIC LOCK	1	25.89	25.89
AH139296	BALL BEARING	1	61.58	61.58
AH14080	SEAL	1	16.13	16.13
AH146463	HALFN SHEAV	1 M	1157.17	1157.17
AH149356	HALF SHEAVE	1 N	1210.53	1210.53
AH229175	THROW-OUT BEARI	1	73.89	73.89
H152146	BELT	1	189.02	189.02
14M7275	M12 NUT	1	1.74	1.74
14M7298	M8 FLANGE NUT	1	1.45	1.45
	PARTS			2737.40
	LABOR			323.75
10400	SEGMENT TOTAL==>			3061.15

SEGMENT#27 C 4832 NA 11/01/24
R&R LH GRAIN TANK CROSS AUGER BEARING (OPTED NOT)
COMPLAINT:

CONTINUED ON PAGE 13

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 13
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via	Purchase Order	
		Salesperson AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			

Both are rumbling.
ADDITIONAL DESCRIPTION:
Remove chain
Remove sprocket
RE&RE bearing.
Assemble, check sprocket alignment.

SEGMENT#28 C 4832 NA 11/01/24
R&R UNLOADING AUGER DRIVE BEARINGS (OPTED NOT)

COMPLAINT:
Bearings are rumbling.
ADDITIONAL DESCRIPTION:
REMOVE SHIELDS
REMOVE BELT AND CHAIN
REMOVE PULLEY AND HUB (USE PULLER)
DISASSEMBLE AND REPLACE BEARINGS
ASSEMBLE IN REVERSE. CHECK OPERATION

SEGMENT#29 C 4832 NA 11/01/24
INSTALL SHEAR PINS - UNLOADING AUGER DRIVE (OPTED NOT)

COMPLAINT:
One missing.

SEGMENT#30 C 4832 NA 11/01/24
ADJUST HYDRO CABLE (OPTED NOT)

COMPLAINT:
Control linkage held with wire.
ADDITIONAL DESCRIPTION:
REMOVE AND REPLACE BALL JOINT
ADJUST BALL JOINT UNTIL NO NEUTRAL CREEP IS ACHIEVED.

CONTINUED ON PAGE 14

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 14
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via		Purchase Order
		Salesperson AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
CHECK RANGE OF MOTION OF HYDRO HANDLE.					

SEGMENT#	DESCRIPTION	START DATE	END DATE			
31 C 4832 NA	REMOVE 1/2 LINK FROM TAILINGS ELEVATOR CHAIN	11/01/24	11/05/24			
	<u>COMPLAINT:</u> Needs half link removed.					
	<u>Repair:</u> -loosen off tensioners on tailings - cotter pins broke while removing replaced with J hooks -removing half link made chain to tight -reconnected chain -adjusted all 3 tensioners till chain tight -found chain to be serviceable one more year					
	<u>ADDITIONAL DESCRIPTION:</u> LOOSEN TAILINGS BELT REPLACE CHAIN TENSION CHAIN CHECK OPERATION					
H139098	Bolt	1	7.82			7.82
H84026	CHAIN LINK HOOK	3	.93			2.79
N61709	Bushing	1 M	27.92			27.92
14M7299	M12 FLANGE NUT	2	2.74			5.48
19M7788	M12X25 BOLT	1	2.90			2.90
24M7047	M12 FLAT WASHER	1	1.25			1.25
	PARTS					48.16
	LABOR					185.00
10400	SEGMENT TOTAL==>					233.16

SEGMENT#32 C 4832 126.12	R&R LH LOWER TAILINGS AUGER BEARING	11/01/24	11/01/24			
--------------------------	-------------------------------------	----------	----------	--	--	--

CONTINUED ON PAGE 15

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	15
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
<u>COMPLAINT:</u>					
Lower outer bearing has play.					
<u>Repair:</u>					
removed shield					
-loosen tension on tailings chain					
-adjuster bolt nuts seized had to heat and air hammer loose					
-removed sprocket and bearing					
-cleaned shafts, flanges & adjuster bolt					
-put new bearing in					
-put sprocket and adjuster bolt back together					
-tighten chain					
<u>ADDITIONAL DESCRIPTION:</u>					
REMOVE SPEED SENSOR					
REMOVE AND REPLACE BEARING.					
JD9313	HEX BEARING			1	32.70
					PARTS 32.70
					LABOR 185.00
10400				SEGMENT TOTAL==>	217.70

SEGMENT#33 C 4832 NA 11/01/24
NOTE - Tailings Drive Chain
COMPLAINT:
B) Worn but will last

SEGMENT#34 C 4832 128.23 11/01/24 11/01/24
R&R STRAW CHOPPER TIGHTENER ROD
COMPLAINT:
Tension rod is worn as well as plastic bushing.
Repair:
R&R straw chopper tension rod, bushing, nuts & cotter pin

CONTINUED ON PAGE 16

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch		
Biggar		
Date	Time	Page
11/19/24	22:45:33 (B)	16
Account No.	Phone No.	Invoice No.
658488800	3066584888	W79820
Ship Via	Purchase Order	
	Salesperson	
	AR	

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
H129207	PIVOT			1 13.65	13.65
H158387	BOLT			1 M 155.65	155.65
11M7021	4.0X25MM PIN			2 .61	1.22
14M7275	M12 NUT			2 1.74	3.48
				PARTS	174.00
				LABOR	92.50
10400				SEGMENT TOTAL==>	266.50

SEGMENT#35 C 4832 NA 11/01/24
SEPARATOR GRATE (OPTED NOT)
COMPLAINT:
One rotor separator grate is missing fingers

SEGMENT#36 C 4832 NA 11/01/24
R&R SHOE ECCENTRIC DRIVE SHAFT BEARINGS (EACH) (OPTED NOT)
COMPLAINT:
RH side has no locking collar.
ADDITIONAL DESCRIPTION:
2.0 PER SIDE
REMOVE SHOE DRIVE BELT AND PULLEY/REMOVE COUNTERWEIGHT
REMOVE SHOE ECCENTRIC BEARINGS
REMOVE AND REPLACE BEARINGS
ASSEMBLE AND CHECK OPERATION

SEGMENT#37 C 4832 121.41 11/01/24 11/01/24
R&R PRIMARY COUNTERSHAFT DRIVE PISTON AND PIN
COMPLAINT:
Leaking from union
Repair:
-removed fitting

CONTINUED ON PAGE 17

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to: IN STORE PICKUP

Invoice to: Dan Roth
Box 31
Handel, SK
Handel SK SOK 1Y0

Branch Biggar		
Date 11/19/24	Time 22:45:33 (B)	Page 19
Account No. 658488800	Phone No. 3066584888	Invoice No. W79820
Ship Via	Purchase Order	
		Salesperson AR

DESCRIPTION

STK#/FLEET#	CTS	HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
put step back on					
<u>ADDITIONAL DESCRIPTION:</u>					
LOOSEN FAN BELT					
REMOVE ROTARY SCREEN DRIVE BELT					
R&R FAN BELT					
CHECK ALIGNMENT					
CHECK OPERATION.					
H153297	FAN BELT			1	146.17
					PARTS 146.17
					LABOR 111.00
10400				SEGMENT TOTAL==>	257.17

SEGMENT#42 C 4832 NA 11/01/24
UPPER CLEAN GRAIN ELEVATOR SHIELDS (OPTED NOT)
COMPLAINT:
Loading auger gear case pulley cover bolt and nut missing

SEGMENT#43 C 4832 8		11/01/24	11/01/24		
R&R HYDRAULIC FILTER - EACH (400 HOURS)					
<u>COMPLAINT:</u>					
Exceeded Service Interval					
<u>Repair:</u>					
-R&R hydraulic filters					
AH128449	HYD FILTER			3	144.50
EHC-BIG	8"OR > \$1.00 @			3	1.00
					PARTS 436.50
					LABOR 216.45
10400				SEGMENT TOTAL==>	652.95

SEGMENT#44 C 4832 7 11/01/24 11/01/24

CONTINUED ON PAGE 20

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

Ship to:

IN STORE PICKUP

Invoice to:

Dan Roth
Box 31
Handel, SK
Handel SK S0K 1Y0

Branch			
Biggar			
Date	Time	Page	
11/19/24	22:45:33 (B)	20	
Account No.	Phone No.	Invoice No.	
658488800	3066584888	W79820	
Ship Via		Purchase Order	
			Salesperson
			AR

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007865	CTS COMBINE	4629	670664		
	CTS	3120			
	R&R FUEL FILTERS (400 HOURS)				
	<u>COMPLAINT:</u>				
	Exceeded Service Interval				
	<u>Repair:</u>				
	R&R fuel filters				
AR86745	FUEL FILTER			1	63.53
EHC-SMALL	<8" 50¢ EACH			1	.50
					PARTS 64.03
					LABOR 148.00
10400				SEGMENT TOTAL==>	212.03

***** WORK ORDER TOTALS *****

PARTS	5462.51
LABOR	7372.50
SHOP SUPPLIES	309.00
SUB TOTAL==>	13135.01
GST (119460401)	656.84
CUSTOMER TOTAL	13791.85

AR

This purchase has been charged to Accounts Receivable
 A service charge will be applied on overdue accounts
 at 2% MONTHLY, minimum \$1.50
 ** Please remit your payment to WESTERN SALES **

If you are not completely satisfied with your experience please let one of our managers know.

I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS.



JOHN DEERE

TERMS: PAYMENT DUE ON RECEIPT OF STATEMENT. SPECIAL ORDER GOODS ARE NOT RETURNABLE. ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE. RETURNED GOODS SUBJECT TO RESTOCKING CHARGE. TITLE TO ALL ITEMS REMAINS WITH THE VENDOR UNTIL PURCHASE PRICE, AND OTHER CHARGES ARE FULLY PAID.

SIGNATURE

CTS COMBINE