



10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Mocosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 828-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



SERVICE INVOICE

Invoice To Account No: 26265

Deliver To:

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number:	3245740
Invoice Date:	08/29/2024
Location:	07
Work Order Number:	458371
Payment Type:	Credit Card
Authorization Number:	V06369G
Page:	1 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:

JSC RADIUS A Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS A.

CORRECTION:

TRAVEL TO AND FROM THE MACHINE
 6 MILES WEST OF HI WAY 40

*Pd BMD # 3380.
 Aug 29/24*

Job Total: **\$698.25**

JGEN02- Retail

COMPLAINT:

02 RUN UP COMBINES

CORRECTION:

PERFORM WALK AROUND INSPECTION ON ALL S SERIES COMBINE
 ADJUST HEADER AIR BAGS
 CALIBRATE 615P PICK UP HEADERS TO COMBINES
 CHECK AND INSTALL NEW SOFTWARE UPDATES
 PERFORM MACHINE RUN UP AND ALL S-SERIES COMBINES

PERFORM MACHINE RUN UP AND 9610 COMBINE
 PERFORM CHECK OVER AND MAKE A LIST OF REPAIRS NEEDED

Labor: \$3,144.70	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,144.70
--------------------------	----------------------	---------------------	---------------------	------------------------------


JGEN01- Retail

COMPLAINT:

03 STEERING MOTOR- R&R

CORRECTION:

LOWER FEEDERHOUSE
 CLEAN DIRT BUILD UP FROM STEERING MOTOR
 DISCONNECT HYDRAULIC HOSES FROM MOTOR
 LOOSEN AND REMOVE HARDWARE FROM STEER





10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2883	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2896	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3468
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 26265

Deliver To:

SERVICE INVOICE

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number: **3245740**
 Invoice Date: 08/29/2024
 Location: 07
 Work Order Number: 458371
 Payment Type: Credit Card
 Authorization Number: V06369G
 Page: 2 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:
 REMOVE STEERING MOTOR ASSEMBLY
 SWAP BRACKET, DUST SEAL AND COUPLING FROM OLD MOTOR TO NEW ONE
 ALIGN STEERING COLUMN COUPLING TO MOTOR COUPLING
 INSTALL NEW STEERING MOTOR ASSEMBLY
 INSTALL AND TIGHTEN ALL HARDWARE
 REPLACE FLAT FACE O-RINGS AND RECONNECT ALL HYDRAULIC HOSES
 TIGHTEN CONNECTION, START ENGINE AND BLEED STEERING SYSTEM
 CHECK FOR LEAKS AND STEERING FUNCTION, ALL GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH142441	Valve	1.00	4,147.63	\$4,147.63	Y
Labor: \$1,230.00	Parts: \$4,147.63	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$5,377.63	

JGEN03- Retail

COMPLAINT:

04 REEL/PICK UP DRIVE CONTROL VALVE- RESEAL

CORRECTION:

CLEAN OIL MESS AND DIRT BUILD UP AROUND REEL CONTROL VALVE
 LOOSEN CLAMP CONNECTOR AND REMOVE ACTUATOR
 LOOSEN AND DISCONNECT HYDRAULIC LINES
 LOCATE AND REMOVE HARDWARE
 REMOVE REEL/PICK UP CONTROL VALVE
 DISASSEMBLE AND RESEAL CONTROL VALVE
 RE-INSTALL IN REVERSE ORDER
 TIGHTEN ALL HYDRAULIC CONNECTION
 RUNS MACHINE AND CHECK FOR LEAKS AND VALVE FUNCTION
 ALL GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH136248	SEAL KIT	1.00	47.07	\$47.07	Y
H114020	Half Clamp	2.00	118.28	\$236.56	Y
Labor: \$615.00	Parts: \$283.63	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$898.63	

JGEN04- Retail

COMPLAINT:

05 SPREADER CONTROL LINKAGE- STRAP AND CONNECTOR NEED REPLACED



10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 862-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 26265

Deliver To:

SERVICE INVOICE

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number: **3245740**
 Invoice Date: 08/29/2024
 Location: 07
 Work Order Number: 458371
 Payment Type: Credit Card
 Authorization Number: V06369G
 Page: 3 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:

CORRECTION:

REMOVE AND REPLACE BROKEN STRAP AND ROD END CONNECTOR TO SPREADER VALVE
 TIGHTEN HARDWARE
 CHECK FUNCTIONS, ALL GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH11015	Clip	1.00	7.26	\$7.26	Y
AH76882	CLIP	1.00	3.24	\$3.24	Y
H177559	Strap	1.00	7.07	\$7.07	Y
Labor: \$51.25		Parts: \$17.57	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$68.82

JGEN05- Retail

COMPLAINT:

06 CLEANING FAN DRIVE SHAFT- R&R

CORRECTION:

REMOVE SIDE SHIELDS
 LOCATE AND DISCONNECT CLEANING FAN DRIVE MOTOR WIRING CONNECTOR
 LOOSEN DRIVE BELT TENSION AND REMOVE MOTOR/ACTUATOR
 ASSEMBLE NEW WORM SCREW
 REMOVE OLD WORM SCREW AND ACTUATOR BRACKET
 SWAP ACTUATOR BRACKET TO NEW WORM SCREW
 INSTALL NEW ASSEMBLY
 RE-INSTALL ACTUATOR AND CONNECT WIRING CONNECTOR
 START ENGINE AND CHECK CLEANING FAN DRIVE FUNCTIONS, ALL GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7382	M16x2.0 LH Nut	4.00	3.36	\$13.44	Y
AH206452	BUSHING	2.00	33.74	\$67.48	Y
AH210762	SHAFT	1.00	140.25	\$140.25	Y
H205401	TRUNNION	1.00	105.71	\$105.71	Y
Labor: \$307.50		Parts: \$326.88	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$634.38

JGEN07- Retail

COMPLAINT:

08 REPLACE STRAW WALKER TENSIONER ROD PLASTIC ISOLATOR



10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 26265

Deliver To:

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number:	3245740
Invoice Date:	08/29/2024
Location:	07
Work Order Number:	458371
Payment Type:	Credit Card
Authorization Number:	V06369G
Page:	4 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:

CORRECTION:

LOOSEN STRAW WALKER BELT TENSION
 REMOVE SPRING AND GAUGE
 REMOVE AND REPLACE PIVOT/PLASTIC ISOLATOR
 RE-INSTALL SPRING AND GAUGE
 TIGHTEN BELT TENSION TO SPECS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H129207	PIVOT	1.00	13.65	\$13.65	Y
Labor: \$51.25		Parts: \$13.65	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$64.90

9610F872017 Retail

COMPLAINT:

09 LEVEL CONCAVE

CORRECTION:

REMOVE SIDE SHIELDS AND INSPECTION DOORS
 REMOVE CYLINDER HOLD DOWN PIN
 CYCLE CONCAVES TO CHECK IF ACTUATOR WORKS
 NOTICE CONCAVES WILL NOT FULLY CLOSE
 OPEN UP ROCK TROUGH AND CURVE DOOR
 FOUND PRODUCT/CHAFF STILL ON CONCAVE
 FULLY OPEN CONCAVE AND REMOVE CHAFF
 PERFORM CONCAVE LEVEL AND CALIBRATION
 RE-INSTALL SIDE SHIELDS AND INSPECTION COVERS

Labor: \$410.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$410.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN08- Retail

COMPLAINT:

10 914 P/U HEADER- REPLACE HYDRAULIC COUPLER AND HOSES

CORRECTION:

TRY REPLACING O-RINGS FROM THE COUPLER
 IF IT LEAKS AGAIN RECOMMEND TO REPLACE BOTH COUPLERS



10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2482
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2896	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 26265

Deliver To:

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number: **3245740**
 Invoice Date: 08/29/2024
 Location: 07
 Work Order Number: 458371
 Payment Type: Credit Card
 Authorization Number: V06369G
 Page: 5 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R21722	O-RING	2.00	4.50	\$9.00	Y
R26375	-8ORB o-ring	2.00	4.04	\$8.08	Y
Labor: \$410.00	Parts: \$17.08	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$427.08	

JGEN09- Retail

COMPLAINT:

11 REPLACE P/U DRUM FINGERS

CORRECTION:

REMOVE DRUM COVERS
 DISCONNECT PICK UP DRIVE SHAFT
 REMOVE AND REPLACE BROKEN DRUM FINGERS AND CLAMP
 RE-INSTALL DRUM COVERS
 CHECK AND ADJUST DRUM HEIGHT AND DRIVE CHAIN TENSION
 RE-CONNECT DRIVE SHAFT
 CHECK FUNCTIONS, ALL GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M8318	Screw M8x45 Flg 10.9	6.00	3.37	\$20.22	Y
H137328	M8x1.25 FlgDT Lock	6.00	2.04	\$12.24	Y
H162662	FINGER	6.00	15.99	\$95.94	Y
Labor: \$369.00	Parts: \$128.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$497.40	

JGEN10- Retail

COMPLAINT:

12 R&R ONE P/U BELT

CORRECTION:

REMOVE AND REPLACE 1 PICK UP BELT

Labor: \$205.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$205.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN11- Retail

COMPLAINT:



10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Mcosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



Invoice To Account No: 26265

Deliver To:

SERVICE INVOICE

[Redacted]
 [Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

[Redacted]
 [Redacted]
 [Redacted]
 Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number: **3245740**
 Invoice Date: 08/29/2024
 Location: 07
 Work Order Number: 458371
 Payment Type: Credit Card
 Authorization Number: V06369G
 Page: 6 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9610	6328	H09610X675974	W150792	

Service Reminders:
 13 TWO SPEED CYLINDER DRIVE CASE- CHANGE OIL

CORRECTION:

GOT CUSTOMER HIRED MAN (KREWZ) TO CHANGE OIL ON 2 SPEED CYLINDER GEARCASE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Inc
TY6296	80W90 946ml GL5	1.00	15.99	\$15.99	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Inc
EF15	ENVIRO FEE	1.00	0.15	\$0.15	Y

Miscellaneous Charges:
 SERVICE ACCESSORIES \$150.00

Labor: \$0.00	Parts: \$15.99	OL&M: \$0.00	Misc: \$150.15	Sub-Total: \$166.14
---------------	----------------	--------------	----------------	---------------------

Credit Card Information		Labor:	\$7,407.95
Customer PO No:	Type: Credit Card	Parts:	\$4,950.83
Tax Exempt No:	Auth No: V06369G	OL&M:	\$0.00
Advisor: DIRK ELS	Amount: \$13,222.58	Misc:	\$234.15
		GST:	\$629.65
		PST:	\$0.00
		Grand Total:	\$13,222.58

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:

Date: