



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		*REPRINT*
Date	Time	Page
10/10/24	23:05:16 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9499 10-000-200 07/31/24 08/09/24
GREENLIGHT INSPECTION == INSPECT X9 COMBINE AS PER 27.00 HRS

CHECKLIST NOTING REPAIRS AND WEAR ITEMS AS FOUND.
PLEASE NOTE PRESSURES TAKEN. CONSULT WITH OWNER OF MACHINE
TO WHICH REPAIRS WE RECOMMEND AND WHICH THEY WISH US TO DO.
HAVE SEGMENTED WORKORDER CREATED, FOR WORK TO BE DONE.
THIS DOES NOT INCLUDE ANY MAJOR CLEANING OR BLOWING OF THE
DUST CHAFF OFF.

-ADD ARROWS TO FEEDERHOUSE AND PLATFORM FOR EASE OF
ALIGNMENT AND HOOKING UP

*TECHNICIAN COMMENTS*****

*

*PERFORMED GREENLIGHT CHECKLIST-WENT THROUGH WITH CUSTOMER *

***** TECHNICIANS COMMENTS *****

*

*+perform greenlight inspection

*

LABOR 3499.00

10501021 16001001

SEGMENT TOTAL==> 3499.00

SEGMENT# 2 C 9768 NA 07/31/24

WASH & DETAIL MACHINE - WASH BAY TO DO

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	02
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP

***** TECHNICIANS COMMENTS *****
*
*+washbay to do
*

SEGMENT# 7 C 9499 NA 09/24/24 09/25/24
FAILED PART: AXE94967 FAILED TYPE (11) 2.84 HRS
HAD 517585.15 COMES ACTIVE WHEN TRYING TO USE THE FOLDING
SPOUT - SPOUT POSITION IS NOT READING -DIAGNOSE AND REPAIR.

***** TECHNICIANS COMMENTS *****
*
*+checked connector on actuator - ok
*+swapped actuator out with known good one
*+no more codes
*+actuator is failed
*+replaced actuator
*+everything works properly
*+no more codes
*

AXE94967	Actuator	1 N	1658.49	1658.49
			PARTS	1658.49
			LABOR	511.20
10501021 16001001		SEGMENT TOTAL==>		2169.69

SEGMENT# 8 C 9499 NA 09/24/24 09/24/24
THRESHING ELEMENTS ON LEFT ROTOR ROWS 1, 2, 3 & RIGHT ROTOR
ROWS 3, 4. - REPLACE

***** TECHNICIANS COMMENTS *****

CONTINUED ON PAGE 03

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	03
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
*			*		
*+replaced damaged elements in sets				*	
*+torqued hardware to spec				*	

KXE10755	Threshing Eleme		3 S	1197.41	3592.23
	Threshing Element				
KXE10756	Threshing Eleme		2	1197.41	2394.82
	Threshing Element				
			PARTS		5987.05
			LABOR		720.00
16001001			SEGMENT TOTAL==>		6707.05

SEGMENT# 9 C 9499 NA 09/24/24 09/24/24
BOTH ROTORS HAVE MAJORITY OF SEPARATOR TINES BROKE -
REPLACE ALL THETINES

***** TECHNICIANS COMMENTS *****

*
*+replaced all the tines on both rotors
*

KXE10959	Tine	26	272.00	7072.00
			PARTS	7072.00
			LABOR	900.00
16001001			SEGMENT TOTAL==>	7972.00

SEGMENT#10 C 9499 NA 09/24/24 09/27/24
3 CONCAVE SECTIONS ARE DAMAGED
REPLACE CONCAVES
VERMILION STORE SENDIGN A SET

CONTINUED ON PAGE 04

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	04
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
STRAIGHTEN THE CONCAVE CRADLES ON BOTH SIDES					
STRAIGHTEN BENT TOP COVER VEINS ON THE RIGHT SIDE					
LEVEL AND CALIBRATE THE CONCAVES					
***** TECHNICIANS COMMENTS *****					
* *					
*+straightened the veins and cradles *					
*+installed new concaves *					
*+leveled and calibrated the concaves *					
* *					

11M7032	COTTER-3/16X2"	4	1.10	4.40	
			PARTS	4.40	
			LABOR	1260.00	
16001001			SEGMENT TOTAL==>	1264.40	

SEGMENT#11 C 9768 NA 09/24/24 09/24/24
ACCELERATOR HAS 16 BENT SUPPORTS & 4 MISSING WEAR STRIPS
VERMILION STORE IS SENDING US ACCELERATOR REPLACEMENT PARTS
***** TECHNICIANS COMMENTS *****
* *
*+Pulled feeder house off of combine *
*+Removed old accelerator *
*+found both bearings failed - replaced *
*+assembled & install new accelerator *
*+when installing feederhouse back on *
*+one bolt broke tap broke inside *
*+removed broken bolt & tapped out threads *
*+installed feederhouse *
*+extra time needed to fix broken bolt *
*+ran machine *

CONTINUED ON PAGE 05

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	05
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
*+repair complete				*	
*				*	

AXE86005	Bearing		1 M	264.33	264.33
AXE86006	Bearing With Ho		1	329.46	329.46
	Bearing With Housing				
19M7787	BOLT M12X20		1	2.51	2.51
19M7804	M10X40 FL/BOLT		2	3.26	6.52
21M7511	Screw		2	2.46	4.92
				PARTS	607.74
				LABOR	1350.00
16001001			SEGMENT TOTAL==>		1957.74

SEGMENT#12 C 9499 NA	09/24/24 09/24/24	
STONE TRAP DOOR TENSIONER & BUSHING ARE MISSING M12 NUTS - REPLACE		
***** TECHNICIANS COMMENTS *****		
*+replaced missing hardware		

14M7275	NUT-M12 REG	1 1.74 1.74
14M7299	NUT-12MM FLG HD	1 2.74 2.74
		PARTS 4.48
		LABOR 72.00
16001001	SEGMENT TOTAL==>	76.48

SEGMENT#13 C 9499 NA	09/24/24 09/25/24
CHAFFER LOUVER ON THE FRONT LEFT SIDE IS DAMAGED - REPLACE	
CALIBRATE SIEVE & CHAFFER.	

CONTINUED ON PAGE 06

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax:780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	06
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
***** TECHNICIANS COMMENTS *****					
* *					
*+repaired louvers					
*+installed sieve and chaffer & calibrated					
* *					

				LABOR	360.00
16001001				SEGMENT TOTAL==>	360.00

SEGMENT#14 C 9499 NA	09/24/24 09/24/24		
CHOPPER HAS ONE BROKEN HAMMER & SEVERAL OTHERS ARE CHIPPED			
REPLACE DAMAGED HAMMERS			
WITH NEED 2 SETS			
***** TECHNICIANS COMMENTS *****			
* *			
*+replaced hammers			
* *			

KXE10761	Knife Kit	2	392.48
			784.96
			PARTS
			784.96
			LABOR
			360.00
16001001		SEGMENT TOTAL==>	1144.96

SEGMENT#15 C 9499 NA	09/24/24 09/25/24		
PREMIUM SEAT FUNCTIONS ARE NOT WORKING - DIAGNOSE AND REPAIR			
***** TECHNICIANS COMMENTS *****			
* *			
*+checked the 4 seat power fuses			
*+found fuse F833 30A was blown			
*+replaced the fuse and tested the seat functions to see			
* *			

CONTINUED ON PAGE 07

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	07
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
*+which one caused the fuse to pop *					
*+everything worked fine until the seat cushion air up was *					
*+pressed and popped the fuse *					
*+followed the schematic to trace and check the wiring for *					
*+the air seat to see if there was an short *					
*+wiring harness appeared to be fine *					
*+checked connectors and all of them seemed fine *					
*+ensured the proper armrest switch was plugged in to the *					
*+seat switch *					
*+found the wrong switch was plugged in to it *					
*+changed it around and the seat function began to work as *					
*+it should *					
*+cleaned up work area *					

57M8163	FUSE 30AMP	2		.83	1.66
				PARTS	1.66
				LABOR	777.60
16001001			SEGMENT TOTAL==>		779.26

SEGMENT#17 C 9768 NA 09/24/24 09/24/24

LH REAR FIELD LIGHT FAILED - REPLACE
LH REAR MARKER LIGHT IS FAILED - REPLACE
REAR BEACON FAILED - REPLACE
LH REAR GULL WING LIGHT FAILED REPLACE

***** TECHNICIANS COMMENTS *****

*
*+replaced beacon light on rear panel
*+found connector xx0339 pins 2 and 3 are pushed back
*+clicked both pins back in

CONTINUED ON PAGE 08

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	08
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
*+all lights are working properly now				*	
*				*	

RE596223	Light Kit		1 N	198.01	198.01
				PARTS	198.01
				LABOR	388.80
	16001001		SEGMENT TOTAL==>		586.81

SEGMENT#18 C 9768 NA	09/24/24 09/24/24		
REPLACE FEEDER DRIVE CHAIN			
***** TECHNICIANS COMMENTS *****			
*			
*+changed feeder drive chain			
*			

AXE82777	FDR DRIVE CHAIN	1	917.68 917.68
			PARTS 917.68
			LABOR 90.00
	16001001	SEGMENT TOTAL==>	1007.68

SEGMENT#19 C 9768 NA	09/24/24 09/30/24		
REMOVE HALF LINK FROM CLEAN GRAIN ELEVATOR CHAIN			
***** TECHNICIANS COMMENTS *****			
*			
*+removed half link from chain			
*+tightened it to spec			
*			

		LABOR	90.00
	16001001	SEGMENT TOTAL==>	90.00

CONTINUED ON PAGE 09

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	09
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP

SEGMENT#20 C 9768 10-300-014 09/24/24 09/24/24
INSTALL FILLER PLATE STORAGE BRACKETS BXE11383AG 1.00 HRS
PART # BXE11383AG

***** TECHNICIANS COMMENTS *****

*
*+installed filler plate brackets
*

BXE11383AG	X9 FPLATE BRKT	1	166.40	166.40
DYN77000	1/16"A.CABLE	2	.54	1.08
DYN77080	1/16"C. SLEEVE	2	1.05	2.10
24H1287	WASHER-1/4"	1	.53	.53
			PARTS	170.11
			LABOR	180.00
16001001			SEGMENT TOTAL==>	350.11

SEGMENT#21 C 9768 NA 09/24/24 09/24/24
ONE FEEDER CHAIN SLAT IS BENT - REPLACE

***** TECHNICIANS COMMENTS *****

*
*+Replaced feeder chain slat
*

HXE113327	SLAT	1	61.30	61.30
			PARTS	61.30
			LABOR	90.00
16001001			SEGMENT TOTAL==>	151.30

SEGMENT#22 C 9768 NA 09/24/24 09/24/24

CONTINUED ON PAGE 10

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	10
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
CLEANING FAN DRIVE BELT IS CRACKED - REPLACE					
***** TECHNICIANS COMMENTS *****					
* *					
*+replaced cleaning belt *					
* *					

HXE176244	V-Belt	1	229.36	229.36	
			PARTS	229.36	
			LABOR	181.80	
16001001		SEGMENT TOTAL==>	411.16		

SEGMENT#23 C 9768 10-440-015	09/24/24 09/24/24			
INSTALL AGLAND PRE SIEVE WRENCH ON COMBINE	.50 HRS			
***** TECHNICIANS COMMENTS *****				
* *				
*+installed pre sieve wrench *				
* *				

PRESIEVETOOL	SIEVE LCKG TOOL	1	69.35	69.35
			PARTS	69.35
			LABOR	90.00
16001001		SEGMENT TOTAL==>	159.35	

SEGMENT#24 C 9768 NA	09/24/24 09/24/24			
SWEEPER STRAP DAMAGED ON SPREADER DRIVE SHAFT - REPLACE				
SPREADER DRIVESHAFT IS MISSING A HOSE CLAMP - REPLACE				
***** TECHNICIANS COMMENTS *****				
* *				
*+removed old strap *				
*+replaced strap *				

CONTINUED ON PAGE 11

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	11
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
*+changed clamp				*	
*				*	

HXE171189	Seal		1 N	89.77	89.77
TY22467	CLMP13/16-1-3/4		1	1.64	1.64
				PARTS	91.41
				LABOR	95.40
16001001			SEGMENT TOTAL==>		186.81

SEGMENT#25 C 9768 NA 09/24/24 09/24/24
ACCELERATOR BELT IS GLAZED & PULLEY IS BURNT - REPLACE BELT
& PAINT THE PULLEY
***** TECHNICIANS COMMENTS *****
*
*+replaced accelerator belt
*+painted the pulley
*

HXE171261 V-Belt 1 250.00 250.00
PARTS 250.00
LABOR 223.20
16001001 SEGMENT TOTAL==> 473.20

SEGMENT#26 C 9499 NA 09/24/24 09/24/24
RH REAR ROTOR COVER HOLD DOWN NUTS ARE SEIZED - REPLACE
HARDWARE
***** TECHNICIANS COMMENTS *****
*
*+replaced seized hardware
*

CONTINUED ON PAGE 12

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	12
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP

HXE167838	Knob		2 M	14.45	28.90
				PARTS	28.90
				LABOR	90.00
16001001			SEGMENT TOTAL==>		118.90

SEGMENT#27 C 9768 NA		09/24/24 09/25/24		
FRONT FEEDER HOUSE DRUM IS DENTED - REPAIR DENT				
***** TECHNICIANS COMMENTS *****				
* *				
*+repaired dent *				
* *				

ENVO114	OIL ENVIRO FEE	1	1.14	1.14
ENV227	CONTAIN ENV FEE	1	2.27	2.27
TY26679	15W40+50II 19L	1	154.45	154.45
	Plus-50 II Oil 15W40 CK4/SN			
14H863	3/4 NF NUT	2	5.32	10.64
			PARTS	168.50
			LABOR	1031.40
16001001			SEGMENT TOTAL==>	1199.90

SEGMENT#28 C 9768 NA		09/24/24 09/24/24	
COMPLETE SERVICE			
CHANGE ENGINE OIL AND FILTER.			
CHANGE FUEL FILTERS.			
CHANGE ALL AIR FILTERS			
CHANGE HYD/ TRANS OIL FILTERS.			
CHANGE FUEL & DEF TANK BREATHERS			
DOUBLE CHECK FLUID LEVELS & GREASE			

CONTINUED ON PAGE 13

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	13
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
***** TECHNICIANS COMMENTS *****					
* * *					
*+change engine oil & filter					
*+change fuel filters					
*+change hydraulic/trans filters					
*+change all air filters					
*+changed fuel & def tank breathers					
*+double checked fluids & greased machine					
* * *					

AXE103407	Hydraulic Filte	1	152.55	152.55	
	Hydraulic Filter				
AXE70605	Air Filter REC	1	35.00	35.00	
AXE73797	HYD. FILTER	1	148.83	148.83	
	Hydraulic Filter				
AXE73798	HYD. FILTER	1	183.21	183.21	
	Hydraulic Filter				
DZ124761	FUEL FILTER PR.	1	146.01	146.01	
DZ124786	FUEL FIL SEC	1	140.27	140.27	
ENVO114	OIL ENVIRO FEE	3	1.14	3.42	
ENV100	ENVIRO CHARGE	7	1.25	8.75	
ENV114	CONTAIN ENV FEE	1	1.14	1.14	
ENV227	CONTAIN ENV FEE	3	2.27	6.81	
ENV23	OIL ENVIRO FEE	1	.23	.23	
ENV46	CONTAIN ENV FEE	1	.46	.46	
ENV50	ENVIRO CHARGE	1	.55	.55	
ENV57	OIL ENVIRO FEE	1	.57	.57	
HXE11090	AIR FILTER PRM.	1	412.99	412.99	
HXE11091	AIR FILTER SEC.	1	291.42	291.42	
H216169	F.TANK BREATHER	2	41.40	82.80	

CONTINUED ON PAGE 14

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	14
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP
RE284091	CAB FILTER	1		108.88	108.88
RE572785	ENG OIL FILTER	1		135.44	135.44
RE577250	HYD.FILTER	2		139.79	279.58
	Hydraulic Filter				
RE577612	Filter Element	1		178.19	178.19
TY22062	HYGARD 9.46L	1		77.09	77.09
TY26673	15W40+50II 3.8L	1		34.15	34.15
	Plus-50 II Oil 15W40 CK4/SN				
TY26679	15W40+50II 19L	3		154.45	463.35
	Plus-50 II Oil 15W40 CK4/SN				
			PARTS		2891.69
			LABOR		1080.00
16001001			SEGMENT TOTAL==>		3971.69

SEGMENT#29 C 9768 NA 09/24/24 09/24/24
REPLACE CHOPPER GEARCASE SIGHT GLASS WITH A PLUG
CHANGE CHOPPER GEARCASE OIL

***** TECHNICIANS COMMENTS *****

* *
*+changed oil in gearcase *
*+replaced sight glass with a plug *
* *

ENV114	CONTAIN ENV FEE	1	1.14	1.14
ENV57	OIL ENVIRO FEE	1	.57	.57
TY22062	HYGARD 9.46L	1	77.09	77.09
X8HP50N-S	3/4" ORB PLUG	1	2.33	2.33
	PARTS			81.13
	LABOR			180.00
16001001			SEGMENT TOTAL==>	261.13

CONTINUED ON PAGE 15

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax:780.875.6606
www.horizonagturf.com

Ship to:

X9 1100 EYBEN TRD(815043)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
10/10/24	23:05:16 (B)	15
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00315
Ship Via	Purchase Order	
	083	
		Salesperson
		NLB

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
033525	X9 1100 EYBEN FARM	873	1H0X911XHLE815043	08/02/23	
	X9 1100	549		01/12/26	1500 PP

SEGMENT#30 C 9768 NA 09/24/24 09/26/24

LH FEEDERHOUSE DRIVE BELT IDLER BEARING GONE

***** TECHNICIANS COMMENTS *****

*

*

*+replaced bearing on idler pulley

*

*

*

AXE73780	Bearing	1	142.05	142.05
			PARTS	142.05
			LABOR	180.00
16001001		SEGMENT TOTAL==>		322.05

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	21420.27	
LABOR	13800.40	
Shop Supplies	250.00	
INTERNAL TOTAL	35470.67	

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

IN STORE PICKUP

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch		
VERMILION		*REPRINT*
Date	Time	Page
06/17/24	23:31:23 (B)	01
Account No	Phone No	Inv No
INTER01	7808754471	J93929
Ship Via	Purchase Order	
		Salesperson
		NDW

DESCRIPTION OF WORK & PARTS

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
033525	X9 1100 EYBEN FARM	X 1H0X911XHLE815043	08/02/23		
	X9 1100		01/12/26	1500 PP	

SEGMENT# 1 C 555 NA 06/12/24 06/13/24
PULL COPPERHEAD CONCAVES AND INSTALL SMALL WIRE CONCAVES
- MIKE SYMES IS CHECKING FOR THE CONCAVES AT LARAMIES FARM
AND WILL BRING THEM IN FOR US.
PULL 2 WAY RADIO AND BOX UP WITH WHATEVER OTHER CUSTOMER
STUFF IS IN THE CAB FOR REINSTALL INTO HIS NEW X9
PREP DOORS ETC FOR TRUCKING - COMBINE IS BEING SENT TO LLOYD
***** TECHNICIANS COMMENTS *****
*
*+removed side covers
*+ran machine to blow to get rid of straw in machine
*+unbolted concaves from Z bar
*+unbolted concaves from cradle
*+removed concaves
*+installed new ones
*+tightened cradle bolts
*+tightened Z bar bolts
*+put side shields on
*+parked combine in yard
*

19M7788 FL/BOLT-M12X25M 3 2.60 7.80
PARTS 7.80
LABOR 1118.00
16001 SEGMENT TOTAL==> 1125.80

SEGMENT# 2 C 555 NA 06/12/24 06/17/24
REMOVE 2 WAY RADIO
***** TECHNICIANS COMMENTS *****

CONTINUED ON PAGE 02

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

IN STORE PICKUP

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch VERMILION		
Date 06/17/24	Time 23:31:23 (B)	Page 02
Account No INTER01	Phone No 7808754471	Inv No J93929
Ship Via		Purchase Order
		Salesperson NDW

DESCRIPTION OF WORK & PARTS

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
033525	X9 1100 EYBEN FARM	X 1H0X911XHLE815043	08/02/23		
	X9 1100		01/12/26	1500 PP	
*					
*+removed 2 way radios from combines			*		
*+cleaned all customer stuff out of cab and tool boxes			*		
*+put one machine on the front line			*		

			LABOR	466.12	
16001			SEGMENT TOTAL==>	466.12	

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	7.80	
LABOR	1584.12	
SHOP SUPPLIES	106.79	
INTERNAL TOTAL	1698.71	

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up