

Rapid Diesel Repair LLC

9519 East 8th Street
 Rancho Cucamonga, CA 91730
 shop@rapiddieselca.com
 909-701-8755


Invoice: 2275
Date: 9/4/2025
Bill To

Ignite Propane
 PO Box 1150
 Toledo, WA 98591
 P: (360) 774-9652

Remit Payment To

Rapid Diesel Repair LLC
 9519 East 8th Street
 Rancho Cucamonga, CA 91730

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
3106	COD	9/4/2025	John Scott		

Item	Description	Quantity	Rate	Amount
Inspection				
Labor	Quality Control: Technician	0.30000	\$0.00	\$0.00
Subtotal				\$0.00

Complaint: Customer states possible blown head gasket. Check and advise.

Cause: Hooked up scanner to pull codes

NO active codes

Inactive ECM codes:

SPN 593 FMI 14 - Engine stopped by IST

SPN 558 FMI 11 - IVS Signal Fault

SPN 91 FMI 2 - APS In Range Fault

SPN 111 FMI 1 - ECL below Warning/Critical Level

SPN 168 FMI 4 - B+ out of Range Low

SPN 8321 FMI 7 - VGT Performance Fault

SPN 8321 FMI 12 - ECM not Receiving VGT CAN Messages

Started truck and felt that the truck had a misfire. Performed cylinder cut out test, found that cylinder 1 and cylinder 6 have a constant misfire. Pressure tested cooling system to 15psi to test for leaks, found that the cooling system held pressure for an extended period of time. Performed Relative Compression test, found that cylinder 1,2,3 & 5 have low compression. Recommend engine overhaul

Labor	Correction:	52.00000	\$179.00	\$9,308.00
Engine / Bottom End / Engine overhaul - Created: 10/29/2024				

Parts	Engine overhaul kit - 240X/PAI 466119-001	1.00000	\$3,281.12	\$3,281.12
Parts	Cylinder head bolts - 240Z/1833029C4INT	24.00000	\$102.48	\$2,459.40
Parts	Thermostat - 240Z/1842130C3	1.00000	\$353.98	\$353.98
Parts	Fuel Filter - 240V/FG FF275	1.00000	\$80.85	\$80.85
Parts	Fuel/Water Separator - 240V/DN P550824	1.00000	\$155.30	\$155.30
Parts	50/50 red coolant - Red Coolant	6.00000	\$21.00	\$126.00
Parts	Engine Oil - 15W-40	5.00000	\$4.50	\$22.50
Parts	Oil Rail Seal Kit - 240X/AP AP0025	1.00000	\$182.48	\$182.48
Parts	Turbo Mounting Kit - 240X/AP AP0170	1.00000	\$75.73	\$75.73
Parts	Injectors - AP66918	6.00000	\$450.00	\$2,700.00
Parts	Camshaft - 02	1.00000	\$766.06	\$766.06
Parts	Cam Roller - 1850160C3	1.00000	\$167.98	\$167.98
Parts	Roller Dog Bones - 490041	6.00000	\$47.93	\$287.58
Parts	Hot Side EGR Cooler - GA604N	1.00000	\$846.67	\$846.67
Parts	Front Cover Reseal Kit (Rear) - 06	1.00000	\$121.55	\$121.55
Parts	Front Cover Reseal Kit (Front) - 01	1.00000	\$459.04	\$459.04
Parts	Oil Pump - 1802666C93	1.00000	\$1,169.02	\$1,169.02
			Subtotal	\$22,563.26

Complaint: Unit needs cylinder compression test.

Cause: During compression testing found low compression in cylinder 1,2,3, and 5.

(Inspection)

Labor	Correction: Engine / Overhaul / Recommend rebuilding engine - Created: 11/18/2024	8.00000	\$179.00	\$1,432.00
Parts	Head Machining - 02	1.00000	\$1,571.46	\$1,571.46
			Subtotal	\$3,003.46

Unit: VIN: 1HTMMAAN59H156462
2009 International MA025
Chassis: 1 Miles

Labor	\$10,740.00
Parts	\$14,826.72
Shop Supplies	\$250.00
Pre-Charge Subtotal	\$25,816.72
CA State (6.25% of \$15,076.72)	\$942.30
San Bernadino County (1% of \$15,076.72)	\$150.77
San Bernardino Cty District (0.5% of \$15,076.72)	\$75.38
Total	\$26,985.17
Payments & Credits	\$26,985.17
Balance Due	\$0.00

Work (Estimate) Authorized at 11:05AM 6/24/2025 by:



Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Payout ID	Amount
6/25/2025	9/4/2025	102027890	Zelle	25252525003		\$5,000.00
6/24/2025	9/4/2025	102027894	Zelle	25241307012		\$5,000.00
9/6/2025	9/6/2025	102529440	Zelle			\$7,500.00
9/10/2025	9/10/2025	102553260	Zelle	26172646006		\$7,500.00
11/18/2025	11/18/2025	103036451	Zelle	27006550273		\$1,985.17

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. **Disclaimer – Customer-Supplied Parts** No warranty is provided on any customer-supplied parts, including labor associated with their installation. We do not guarantee fit, performance, or functionality. All risks and responsibility for defects or failure rest with the customer.

Customer Signature: _____

Printed Name: _____ Date: _____