

P.O Box 5287

Victoria Point Queensland 4165

ABN: 75687910704

Licence:

AIRCON LICENCE AU57719

APPROVED INSPECTION STATION

13303

Tel:0448929128

Email: admin@seqtruckrepairs.com.au

Website: www.seqtruckrepairs.com.au



TAX INVOICE

Tax Invoice Number:7060

Date: 13/01/2026

Due Date:20/01/2026

Payment Term:COD

FOR:

OIL LEAK PASSENGER SIDE

Odometer:730,987 Kms

Engine Hours:9,035.4 Hrs

Model:KENWORTH K200

Reg No:ABMC

Next Service Date:08/02/2026

Next Service Odometer:752,953 Kms

VIN: 6F5000000NA473480

Body Type:PRIME MOVER

Year: 2022

De s c r i p t i o n	Qty.	Unit Price	A m o u n t
REPAIR			
Labour removed fan belt , tensioner and idler pulley took a while because bolt was in a akward position to drill and extract, fitted new idle pully to bracket , fitted bracket to engine fitted tensioner and new belt filled engine oil 13l	5.0	\$165.00	\$825.00
P A R T S			
RUBIA WORKS 4000	13.0	\$9.61	\$124.87
AUTOMATIC BELT TENSIONER H/DRACK52DL	1.0	\$170.19	\$170.19
BELT V RIBBED DAYCO POLY	1.0	\$125.24	\$125.24
PULLEY IDLER	1.0	\$905.30	\$905.30
SCREW HEXAGON FLANGE HEAD CAP BAC2-D6	3.0	\$19.89	\$59.67
WORKSHOP CHARGES			
SUNDRIES	5.0	\$9.00	\$45.00

Subtotal \$2,255.27

GST \$225.53

Total \$2,480.80

Paid \$0.00

Balance Due \$2,480.80

THANKS FOR YOUR BUSINESS!

We are now an approved inspection station, also offering Brake roller testing!

SEQ TRUCK & TRAILER REPAIRS PTY LTD
BSB 013265
ACC 162012661

PLEASE REMEMBER TO CHECK YOUR TRUCK SERVICE INTERVAL REGULARLY AND BOOK IN WHEN YOU
ESTIMATE YOU ARE 3 WEEKS OUT TO AVOID DISAPPOINTMENT.

ALL CARD PAYMENTS WILL INCUR A 1.1% SURCHARGE

Terms of trade are available on request.