

Experian AutoCheck Report

Report run: 01/27/2026 14:17:45 EST

2019 Ford Taurus Police Interceptor

Sedan 4D (3.7L V6 SMPI Flex Fuel)

VIN:	1FAHP2MK0KG108477
Class:	Car - Midsize
Country of Assembly:	United States
Vehicle Age:	7 year(s)
Last Reported Odometer:	88,531 (11/13/2023)



Vehicle Usage
Lease



AutoCheck Score

Similar vehicles usually range between 79 and 89

Vehicle History at a Glance



State Title Brand



Auction Brand / Issues



CLEAN

Structural Damage



Accident / Damage

Multiple Damage Events



SEVERE



Open Recall Check



Insurance Loss / Transfer



Odometer Check

Last reported odometer:
88,531 (11/13/2023)



3 OPEN RECALL(S)



NO ISSUE



NO ISSUE



Certified Pre-Owned



Service / Repair



Additional History



NO CPO INFO AVAILABLE



NO ISSUE



NO ISSUES REPORTED




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)



Accident & Damage



Airbag Deployed



Structural Damage



Overturned



Severe

Damage Date	Damage Type	Severity
09/13/2020	Collision	Moderate
03/11/2023	Collision	Severe
11/17/2023	Structural Damage	Severe

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check



Information Reported: AutoCheck found 3 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 03/30/2020

Recall Type - Emission

NHTSA / OEM Recall No. - N/A / 20E01

Campaign Description - Emissions Recall: POWERTRAIN CONTROL MODULE REPROGRAMMING

Status: Remedy Unknown

Recall Date - 09/15/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25V611 / 25S91

Campaign Description - Safety Recall: EXTERIOR B-PILLAR APPLIQUE TRIM INSPECTION

Status: Remedy Not Available

Recall Date - 10/14/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25v695 / 25SA9

Campaign Description - Safety Recall: REAR VIEW CAMERA INSPECTION

Status: Remedy Not Available

[More information](#) including remedy or risk factors. Locate your nearest authorized **Ford Dealer** to schedule repair.

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2019 Ford Taurus Police Interceptor (1FAHP2MK0KG108477) Report Run Date: 01/27/2026 14:17:45 EST

2018

Vehicle Prep and Other Pre-Titling Events

Preparation Date: 12/2018

Event Date	Location	Odometer	Data Source	Details
12/04/2018			Independent Source	Vehicle Manufactured and Shipped to Dealer

2019

Owner 1

Location: SC

Owned From: 02/2019

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
02/15/2019	SC	25	Motor Vehicle Dept.	Odometer Reading from DMV Registration Event/Renewal
02/18/2019	COLUMBIA, SC		Motor Vehicle Dept.	Title(Leased Vehicle)
03/30/2020			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 20M01 Customer Satisfaction Program - Multi Repair: CATALYTIC CONVERTER EXTENDED COVERAGE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
03/30/2020			Manufacturer	Manufacturer Recall Mfr. Recall 20E01 Emissions Recall: POWERTRAIN CONTROL MODULE REPROGRAMMING LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
09/13/2020	RICHLAND COUNTY, SC		State Agency	Left Rear Impact with Another Vehicle(Case #:20264425) Moderate Damage Reported Accident Reported(Report #:BLTC20CAD121695)
10/07/2020	COLUMBIA, SC	39,616	Damage Report	Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Rear Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Wheels Reported
03/11/2023	RICHLAND COUNTY, SC		State Agency	Right Side Impact with Another Vehicle(Case #:23229208) Air Bag Deployed Vehicle Damage Reported as Disabling Vehicle Was Towed Accident Reported(Report #:BLTC23CAD038053)
11/13/2023	SOUTHEASTERN REGION	88,531	Auto Auction	Reported at Auto Auction
11/17/2023	SOUTHEASTERN REGION		Auto Auction	Auction Announced as Structural Damage



09/13/2020	RICHLAND COUNTY, SC		State Agency	Left Rear Impact with Another Vehicle(Case #:20264425) Moderate Damage Reported Accident Reported(Report #:BLTC20CAD121695)
10/07/2020	COLUMBIA, SC	39,616	Damage Report	Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Rear Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Wheels Reported
03/11/2023	RICHLAND COUNTY, SC		State Agency	Right Side Impact with Another Vehicle(Case #:23229208) Air Bag Deployed Vehicle Damage Reported as Disabling Vehicle Was Towed Accident Reported(Report #:BLTC23CAD038053)



09/13/2020	RICHLAND COUNTY, SC		State Agency	Left Rear Impact with Another Vehicle(Case #:20264425) Moderate Damage Reported Accident Reported(Report #:BLTC20CAD121695)
10/07/2020	COLUMBIA, SC	39,616	Damage Report	Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Rear Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Wheels Reported
03/11/2023	RICHLAND COUNTY, SC		State Agency	Right Side Impact with Another Vehicle(Case #:23229208) Air Bag Deployed Vehicle Damage Reported as Disabling Vehicle Was Towed Accident Reported(Report #:BLTC23CAD038053)



11/13/2023	SOUTHEASTERN REGION	88,531	Auto Auction	Reported at Auto Auction
11/17/2023	SOUTHEASTERN REGION		Auto Auction	Auction Announced as Structural Damage

Event Date	Location	Odometer	Data Source	Details
09/15/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25V611 / Mfr. Recall 25S91 Safety Recall: EXTERIOR B-PILLAR APPLIQUE TRIM INSPECTION LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available
10/14/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25v695 / Mfr. Recall 25SA9 Safety Recall: REAR VIEW CAMERA INSPECTION LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FAHP2MK0KG108477) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptersms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.