

Experian AutoCheck Report

Report run: 11/05/2025 14:24:58 EST

2020 Ford Explorer Police Interceptor Utility

SUV 4D (3.3L V6 DI Flex Fuel)

VIN:	1FM5K8AB3LGA71246
Class:	CUV - Large
Country of Assembly:	United States
Vehicle Age:	5 year(s)
Last Reported Odometer:	45,135 (06/05/2024)

Owners - 2



Vehicle Usage
Government



AutoCheck Score

Similar vehicles usually range between 89 and 94

Vehicle History at a Glance

 State Title Brand CLEAN	 Auction Brand / Issues NO ISSUE	 Accident / Damage DAMAGE REPORTED
 Open Recall Check 3 OPEN RECALL(S)	 Insurance Loss / Transfer NO ISSUE	 Odometer Check Last reported odometer: 45,135 (06/05/2024) NO ISSUE
 Certified Pre-Owned NO CPO INFO AVAILABLE	 Service / Repair 1 Service Record(s) Reported NO ISSUE	 Additional History NO ISSUES REPORTED



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More



Accident & Damage





Point of Impact Not Available



Airbag Deployed



Structural Damage



Overturned



Unknown

Damage Date	Damage Type	Severity
02/12/2022	Collision	Unknown
Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.		

Open Recall Check



Information Reported: AutoCheck found 3 open recall(s).
It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 05/04/2022
Recall Type - Safety
NHTSA / OEM Recall No. - 22V255 / 22S27
Campaign Description - Safety Recall: EXPLORER REAR AXLE BOLT FRACTURE Status: Remedy Available
Recall Date - 08/12/2024
Recall Type - Safety
NHTSA / OEM Recall No. - 24V598 / 24S52
Campaign Description - Safety Recall: ENGINE BLOCK BREACHES POWERTRAIN CONTROL MODULE UPDATE Status: Remedy Available
Recall Date - 02/17/2025
Recall Type - Safety
NHTSA / OEM Recall No. - 25V093 / 25S09
Campaign Description - Safety Recall: LOOSE OR MISSING SEAT RESTRAINT FASTENERS Status: Remedy Available
More information including remedy or risk factors. Locate your nearest authorized Ford Dealer to schedule repair.

Odometer Check



Your Vehicle Checks Out
No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2020 Ford Explorer Police Interceptor Utility (1FM5K8AB3LGA71246) Report Run Date: 11/05/2025 14:24:58 EST

2019

Vehicle Prep and Other Pre-Titling Events

Preparation Date: 09/2019

Event Date	Location	Odometer	Data Source	Details
09/19/2019			Independent Source	Vehicle Manufactured and Shipped to Dealer

2019

Owner 1

Location: PA

Owned From: 10/2019

Usage: Government

Event Date	Location	Odometer	Data Source	Details
10/17/2019	ARDMORE, PA	15	Motor Vehicle Dept.	Title(Title #:81135368)
10/22/2019	ARDMORE, PA		Motor Vehicle Dept.	Registration Event/Renewal Municipal Use Local Government
02/12/2022	PA		Police Report	Accident Reported(Report #:2202120130)
03/22/2022	PA	36,740	Service Record	Vehicle Inspected Transmission Serviced Exhaust System Serviced
05/16/2023			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 22N17 Warranty Extension - Single Repair: POWER WINDOW SWITCH CHROME TIP REPLACEMENT LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
06/05/2024	FL	45,135	Motor Vehicle Dept.	Odometer Reading from DMV

2024

Owner 2

Location: FL

Owned From: 06/2024

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
06/06/2024	CLERMONT, FL		Motor Vehicle Dept.	Title(Title #:0155105799)
06/06/2024	CLERMONT, FL		Motor Vehicle Dept.	Registration Event/Renewal
06/13/2024			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 24M01 Customer Satisfaction Program - Multi Repair: REPLACE CATALYTIC CONVERTERS FOR DIAGNOSTIC TROUBLE CODE DTC P0420 OR P0430 AND INSPECT WIRE HARNESS FOR RUNS ROUGHMISFIRE CONDITION LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown

Event Date	Location	Odometer	Data Source	Details
12/11/2024			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 24N10 Warranty Extension - Single Repair: ENGINE BLOCK BREACHES LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
09/19/2025	CLERMONT, FL		Motor Vehicle Dept.	Registration Event/Renewal

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FM5K8AB3LGA71246) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.