

Experian AutoCheck Report


Report run: 01/27/2026 16:24:16 EST

2021 Ford E-150 Lariat / XL / XLT

Crew Cab 4D (2.7L V6 DI Gasoline)

VIN:	1FTEW1EP3MKE59226
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	5 year(s)
Last Reported Odometer:	117,539 (02/21/2025)

One Owner
AutoCheck
Vehicle Usage
 Personal



AutoCheck Score

Similar vehicles usually range between 90 and 95

Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage</p> <p>No Accidents or Damage Reported</p> <p>NO ISSUE</p>
<p>Open Recall Check</p> <p>2 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check</p> <p>Last reported odometer: 117,539 (02/21/2025)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair</p> <p>2 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>Lien Reported</p> <p>EVENTS REPORTED</p>



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage

Open Recall Check



Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 05/12/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25V315 / 25S49

Campaign Description - Safety Recall: REAR CAMERA SCREEN SOFTWARE UPDATE
Status: Remedy Available

Recall Date - 07/08/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25V455 / 25S75

Campaign Description - Safety Recall: LOW PRESSURE FUEL PUMP FAILURE
Status: Remedy Not Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ford Dealer](#) to schedule repair.

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2021 Ford F-150 Lariat / XL / XLT (1FTEW1EP3MKE59226) Report Run Date: 01/27/2026 16:24:16 EST

2022

Vehicle Prep and Other Pre-Titling Events

Location: TX

Preparation Date: 04/2022

Event Date	Location	Odometer	Data Source	Details
04/08/2022	TX	58	Service Record	Vehicle Inspected Promotional Service Performed
04/25/2022	TX	59	Service Record	Vehicle Inspected Chassis Serviced Electrical System Serviced

2022

Owner 1

Location: SC

Owned From: 05/2022

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
05/25/2022	PASADENA, TX		Motor Vehicle Dept.	Registration Event/Renewal
08/25/2022	TX	67	Motor Vehicle Dept.	Title(Title #:10149344788085456) (Lien Reported)
05/07/2024	TX	91,824	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
05/09/2024	TX		Motor Vehicle Dept.	Registration Event/Renewal
02/21/2025	TX	117,539	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
05/01/2025	TX		Motor Vehicle Dept.	Registration Event/Renewal
05/12/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25V315 / Mfr. Recall 25S49 Safety Recall: REAR CAMERA SCREEN SOFTWARE UPDATE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Available
07/08/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25V455 / Mfr. Recall 25S75 Safety Recall: LOW PRESSURE FUEL PUMP FAILURE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available

Unreported Event Dates

The following events have been reported to AutoCheck without a specified date.

Event Date	Location	Odometer	Data Source	Details
Unreported			Independent Source	Vehicle Manufactured and Shipped to Dealer

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FTEW1EP3MKE59226) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.