



1-15 INGLEWOOD DRIVE, ST. ALBERT, A.B. T8N 5E2 780-458-7272

RIDE RIVERSIDE.COM

Repair Order Invoice

Doc Number: 70394
Service Writer: Ian Martens
Date Printed: 07/31/2023
Date Promised: 05/19/2023
Cashier: Ian Martens
Cashier Date: 07/31/2023

JIM HOLT

Customer Information

Home Phone: 780-220-3501

Fold Here

Summary

Approve	Decline	Unit	Job	Job Total
☒	☐	2019 POLARIS R19RRU99A9	CREATED FROM SERVICE SCHEDULER	\$1,820.86
☒	☐	2019 POLARIS R19RRU99A9	EBS/HELIX IMPROVEMENTS	WARRANTY

Repairs
Polaris

Side By
Side

Job Subtotal:	\$1,820.86
Misc:	\$47.50
Job Parts Subtotal:	\$910.86
Job Labor Subtotal:	\$910.00
GST - 5.00%:	\$92.852
ENVIRO FEE - 100.00%:	\$0.25
GST - 5.00%:	\$2.59
Total:	\$1,962.03
Less Deposits:	\$0.00
Visa:	(\$1,962.03)
Total Due:	\$0.00

Thank You For Your Business!

Customer Signature

GST#121415871 RT0001

Polaris 1000

Signature: _____

Polaris

Detail

Unit 2019 POLARIS R19RRU99A9 RGR XP 1000
EPS NORTHSTAR PPC
VIN/Serial No:4XARRU997K8893723

Color:

Keyboard:

Plate:

Odom/Hrs In:6,632

Out:6,632

CREATED FROM SERVICE SCHEDULER

Description:APT 4

CHECK AND ADVISE FOR INTERMITTENT WON'T BE ABLE TO GET IT IN GEAR WHILE IT'S RUNNING, HAVE TO TURN IT OFF TO GET IT IN GEAR

INSPECT AND ADVISE FOR HAVING TO PRESS THE BRAKE EXCESSIVELY HARD WHEN TRYING TO START THE UNIT IN GEAR

PERFORM CHECKOVER WITH FRONT AND REAR DIFF FLUID CHANGE

Resolution:CHECKED FOR CUSTOMER CONCERN, FOUND PRIMARY CLUTCH WORN AND HELIX POPPING OUT, FOUND BRAKE PRESSURE SWITCH FAULTY, FRONT BRAKE PADS WORN, CALIPER MOUNTS WARPED, AND RIGHT FRONT ROTOR OUT OF ROUND.
INSTALLED NEW CLUTCH PARTS AND UPDATED HELIX, ADHERED HELIX BACK IN PLACE, REPLACED FRONT AND REAR DIFF FLUIDS, INSTALLED NEW FRONT BRAKE PADS AND CALIPER MOUNTS AND RIGHT FRONT ROTOR. INSTALLED NEW BRAKE PRESSURE SWITCH. NOTED COOLANT AFTER MARKET, RADIATOR IS FULL BUT RESERVOIR IS A BIT LOW.

Parts

Part #	Qty	Description	Price	Discount	Total
2879594	1.50	AGL GEARCASE OIL 55 GAL DR	\$20.99	(\$2.10)	\$28.34
2877922	0.00	DEMAND DRIVE PLUS,QT	\$25.99	(\$2.60)	\$0.00
2877922	1.00	DEMAND DRIVE PLUS,QT	\$25.99	(\$2.60)	\$23.39
1323565	3.00	ASM-WEIGHT-SHIFT,32-114(3)	\$23.49	(\$2.35)	\$63.42
7520585	3.00	BUSHED SHIFT WEIGHT BOLT	\$6.99	\$0.00	\$20.97
7541906	3.00	NUT FLEXLOC(10)	\$3.99	\$0.00	\$11.97
1323717	3.00	ASM-SPIDER ROLLER,P90X	\$32.99	(\$3.30)	\$89.07
5453844	6.00	WASHER-CLUTCH,SPIDER ROLLER	\$3.99	\$0.00	\$23.94
5140978	3.00	PIN-SPIDER	\$12.99	\$0.00	\$38.97
5453433	6.00	BUTTON-CLUTCH,22MM	\$25.99	(\$2.60)	\$140.34
2205949	2.00	K-ASM,PAD,BRAKE,DB,1.375	\$57.99	(\$5.80)	\$104.38
4081117	1.00	SWITCH-BRK,M10X1.25,DBL	\$128.49	(\$12.85)	\$115.64
5413212	2.00	SEAL-STAT-O-3/8,70EP	\$12.99	\$0.00	\$25.98
7082265	1.00	FILTER-AIR	\$54.99	(\$5.50)	\$49.49
1912496	2.00	ASM-CAL/MNT,DB,1-3/8,METRIC	\$44.99	(\$4.50)	\$80.98
5263266	1.00	ROTOR,BRAKE	\$89.99	(\$9.00)	\$80.99
7518863	1.00	SCR-M10X1.0X8,SOC SET-OD	\$12.99	\$0.00	\$12.99
Parts Subtotal					\$910.86

Labor

Description	Technician	Hours	Total
	Jason Blais (JASONBL)	7	\$910.00
Labor Subtotal			\$910.00
Job Subtotal			\$1,820.86
Approve: ☒			Decline: ☐

14257A4502 - EBS/HELIX IMPROVEMENTS

Description:IMPROVEMENTS APPROVED BY POLARIS AS GOODWILL ON PARTS ONLY

Parts

Part #	Qty	Description	Price	Discount	Total
2885174	1.00	K-SERVICE,EBS HELIX	WARRANTY	WARRANTY	WARRANTY
Parts Subtotal					WARRANTY

Labor

Description	Technician	Hours	Total
	Jason Blais (JASONBL)	WARRANTY	WARRANTY
Labor Subtotal			WARRANTY
Job Subtotal			WARRANTY
Approve: ☒			Decline: ☐

All Jobs Subtotal: \$1,820.86
Shop Supplies: \$45.50
Environmental Fee: \$2.00