

Work Order	Plant Description	Status	Type	Work Description	Finish Date	Actual Cost	
047655	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Supply of parts as per Cummins quote	21/06/2021	712.02	
045973	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Cummins to quote on engine repairs	2/07/2021	6,181.20	
050021	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	@ 352282 klms B&H supply front diff centre for breakdown	30/07/2021	10,291.74	
051852	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Supply front diff	27/08/2021	9,951.01	7837hrs
059079	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	reseal front diff and output shaft seal	17/12/2021	3,924.23	
059083	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	repair crack in rear diff	16/12/2021	1,999.13	
061643	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	B&H 30.12.2021 : ESTDIFREB Strip down, inspect, rebuild if	3/02/2022	0.00	9995hrs
063016	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	B&H: 07.10.2021 ESTDIFREB Strip down, inspect, rebuild if	18/02/2022	9,884.00	10150hrs
075756	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	NPR047467 Cummins repair gear housing cracked & leaking &	15/08/2022	20,105.55	13769hrs
078434	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Repair cracked diff housing	6/09/2022	0.00	
078944	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	REPLACED FLEP PIPE AT GEAR OF EXHAUST PUT 2ND EXHAUST CLAMPS	24/09/2022	0.00	
080949	KENWORTH T659 6X4 PM *PERMIT	Complete	PM	Replace rear diff assy	28/10/2022	8,369.91	14885hrs
083782	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace gear box harness - part number P92-4313	15/11/2022	0.00	
086524	KENWORTH T659 6X4 PM *PERMIT	Complete	PM	Strip and assess front diff 5258226	22/12/2022	0.00	
087013	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Remove gearbox	3/01/2023	0.00	16138hrs
086910	KENWORTH T659 6X4 PM *PERMIT	Complete	PM	Rebuild engine quote 6636009	5/01/2023	29,214.49	16138hrs
097601	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace gearbox	27/04/2023	16,171.98	17750hrs
099297	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace F.Diff LH Hub seal & brakes	14/05/2023	0.00	
100832	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace diff sensor	14/06/2023	185.92	
102261	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Repairs to diff 5258226	30/06/2023	7,392.04	19051hrs
104194	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace engine assy	4/08/2023	85,065.48	19735hrs
109510	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace front drive diff head	5/10/2023	0.00	
121249	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Driveline Vibration	17/01/2024	0.00	
121020	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Remove and replace gearbox and clutch	10/03/2024	0.00	
120406	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace gearbox	11/03/2024	0.00	23523hrs
123588	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Engine Derated	21/04/2024	0.00	
132588	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Quote to repair diff 299715	8/08/2024	12,534.35	26123hrs
135784	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Engine light on	27/08/2024	0.00	
135167	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Quote to repair diff 260579	12/09/2024	9,832.55	26627hrs
145880	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace engine oil+filter, replaced gearbox oil+filter,	16/02/2025	0.00	
145724	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace engine harness	24/02/2025	1,873.99	
147097	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	In chassis engine rebuild	27/03/2025	51,516.88	29134hrs
151411	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Replace front diff	21/05/2025	12,616.90	30250hrs
159079	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	REPLACE ENGINE HARNESS ECM	10/09/2025	521.12	
162278	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	Removed & refitted gear box	6/10/2025	0.00	
162276	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	REPLACED ENGINE FAN	7/10/2025	0.00	
165337	KENWORTH T659 6X4 PM *PERMIT	Complete	P2	REPLACED DAMAGED ENGINE FAN	19/11/2025	0.00	