

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
 Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
 Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Branch TABER, AB		
Date 07/31/24	Time 13:42:59 (O)	Page 01
Account No UNRUH002	Phone No 4036542862	Inv No W31601
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 309

Invoice To: BRENT UNRUH
 PO BOX 441
 VAUXHALL AB TOK 2K0

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
U110015	8450	4WD TRACTOR	9480 RW8450H003821	
	8450			

GST No. 103596318

Visit www.westerntractor.ca to sign up for your secure access to WT Mobile.
 Your information, at your convenience.

SEGMENT# 1 C 1258 N/A 04/29/24 04/29/24

Check Fuel in Oil

CORRECTION:

Remove primer pump and pressure up and check for leaks
 Talked to Swift Current Diesel and they said if was common
 for the elements to leak fuel down into the crank case
 pump has close to 10000 hours needs to be overhauled any
 way.

Remove pump and injectors and sent out to be overhauled.
 Install new conduit on wiring harnesses.
 Tie up wiring harnesses.

Replace fuel filters

Run unit and check for leaks

Install new o ring on either can along with new can

ADDITIONAL DESCRIPTION:

SWIFT CURRENT DIESEL INC. PO# T7645 \$5781.66

AR86745	FUEL FILTER	2	60.45	120.90
RE556468	STARTING FLUID	1	15.47	15.47
R502011	GASKET	1	19.02	19.02
R520526	GASKET	1	13.56	13.56
R79605	PACKING	6	4.47	26.82
SUBLETAG	OVERHAUL PUMP	1	5781.66	5781.66
TY26186	3/8" CONDUIT	9	1.63	14.67
TY26188	Conduit	4	2.18	8.72
TY26190	3/4" CONDUIT	5	2.66	13.30

CONTINUED ON PAGE 02

X

Received By _____

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Branch TABER, AB		
Date 07/31/24	Time 13:42:59 (O)	Page 02
Account No UNRUH002	Phone No 4036542862	Inv No W31601
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 309

Invoice To: BRENT UNRUH
PO BOX 441
VAUXHALL AB TOK 2K0

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
U110015	8450	4WD TRACTOR	9480 RW8450H003821	
	8450			
3750		INBD FRT&HDL-AG	2 133.13	266.25
		\$51.15 LOOMIS EXPRESS TO SWIFT CURRENT.		
		\$215.10 PUROLATOR COLLECT TO TABER.		
		PARTS		498.71
		LABOR		2450.00
		SUBLET		5781.66
10906002		SEGMENT TOTAL==>		8730.37

SEGMENT# 2 C 1258 HAULING 04/29/24 05/01/24
Semi Hauling & Misc Charges (Office Use Only)
Pick up April 28, \$450.00
Deliver July 16 \$450.00

* Vintage Labor Discount -\$1373.75 Given as per Mitch *

10906002

SEGMENT# 3 C 1258 NA 04/29/24 06/28/24
Check Rear Axle Leak
CORRECTION:
Left rear axle seal leaking oil.
Drain transmission oil and remove rear fenders.
Remove final drive and disassemble
Replace bearings and seals
Set bearings to correct rolling torque
Assemble and install original oil
Oil is very dark looks like engine oil, it could be leaking
from the rear engine seal, customer will have to keep an eye
on the oil levels.
AR75527 SEAL 1 90.57 90.57

CONTINUED ON PAGE 03

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
 Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
 Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Branch TABER, AB		
Date 07/31/24	Time 13:42:59 (O)	Page 03
Account No UNRUH002	Phone No 4036542862	Inv No W31601
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 309

Invoice To: BRENT UNRUH
 PO BOX 441
 VAUXHALL AB TOK 2K0

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
U110015	8450	4WD TRACTOR 8450	9480 RW8450H003821	
JD8248		BEARING CU	1	102.72
JD9018		BEARING CO	1	143.38
JD9092		BEARING CO	1 N	229.43
JD9147		BEARING CU	1 N	115.16
RE31702		SEAL	1	132.18
R58861		SPACER	1 N	108.23
R59074		OIL CUP	1 M	59.17
				PARTS
				LABOR
10906002			SEGMENT TOTAL==>	4655.84

SEGMENT# 4 C 1258 NA 04/29/24 07/11/24

Check A/C

CORRECTION:

A/C system burst a line when I was running the tractor checking operation of the fuel injection pump.

Replaced the line and charged the system and checked operation.

System would not operate because the expansion valve was stuck closed

Sucked the system dry and replaced the expansion valve and receiver dryer

charged the system and checked a/c operation

charged 3 1/2 pounds.

P51212		O-RING	3	1.92	5.76
RE212795		ELBOW FITTIN	1	52.27	52.27
RE57347		HOSE	1 N	394.41	394.41
RE576834		Receiver-Dryer	1	104.24	104.24
RE577432		Control Valve	1	130.84	130.84
R10093		O-RING	4	2.63	10.52

CONTINUED ON PAGE 04

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax: 403-328-2599
 Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
 Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Branch TABER, AB		
Date 07/31/24	Time 13:42:59 (O)	Page 04
Account No UNRUH002	Phone No 4036542862	Inv No W31601
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 309

Invoice To: BRENT UNRUH
 PO BOX 441
 VAUXHALL AB TOK 2K0

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
U110015	8450	4WD TRACTOR	9480 RW8450H003821	
	8450			
R57637		PACKING	1	.74
TY15709		REFRIG TAPE	58	.17
T143169		O-RING	2	3.03
		PARTS		714.70
		LABOR		525.00
10906002		SEGMENT TOTAL==>		1239.70

SEGMENT#	5 C 1258 1	04/29/24	07/11/24
	R&R Engine Oil & Filter		
	<u>CORRECTION:</u>		
	Install new engine oil and filters.		
DZ118156	Filter Kit	1	57.01
TY26679	15W40+50II/20L	1	156.16
	Plus-50 II Oil 15W40 CK4/SN		
T13119	O-RING	1	3.52
3661	ENV FEE-8"+JD	1	1.25
3662	ENV FEE-8"-JD	2	.55
3665	ENV FEE 18.9L	1	3.42
	PARTS		222.46
	LABOR		218.75
10906002	SEGMENT TOTAL==>		441.21

***** WORK ORDER TOTALS *****

PARTS	2416.71
LABOR	6868.75
SUBLET	5781.66
R134A FREON	157.50
SERV SUPPLIES	375.00

CONTINUED ON PAGE 05

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
 Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
 Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6
 Ph: 403-223-3588 • Fax: 403-223-2273
 Toll Free: 1-877-666-9300
www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Branch TABER, AB		
Date 07/31/24	Time 13:42:59 (O)	Page 05
Account No UNRUH002	Phone No 4036542862	Inv No W31601
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 309

Invoice To: BRENT UNRUH
 PO BOX 441
 VAUXHALL AB TOK 2K0

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
U110015	8450	4WD TRACTOR		
	8450			

T SEMI DELIVERY	900.00
VINTAGE DISC	1373.75-
SUB TOTAL==>	15125.87
GST No. 103596318	756.32
TOTAL CREDIT CARD	15882.19

07367J

I agree to pay above total amount according to card issuer agreement (Merchant agreement if credit voucher).

PAID

X

 Received By