


INVOICE

Fly By Night Mechanics
5001 50 St
Myrmam, AB T0B 3K0
Receiver General Registration No.
819974577RT0001



Bill to
[Redacted]
[Redacted]

Invoice details
Invoice no.: 202594
Terms: Due on receipt
Invoice date: 2026-07-28
Due date: 2026-08-13

Serial Number/Engine Hours: RED AND WHITE PETE

#	Date	Product or service	Description	Qty	Rate	Amount	Tax
1.		Labour /h	INSTALLED SLAVE VALVE AND REBUILT HI/LO CYLINDER, TEST DROVE, STILL HAS ISSUES	2.5	\$140.00	\$350.00	G
2.		Parts	SLAVE VALVE ASSEMBLY	1	\$210.67	\$210.67	G
3.		Parts	ORING KIT - RTL0149-20918 SPL	1	\$62.38	\$62.38	G
4.		Labour /h	AC WORK, PRESSURE TESTED WITH NITROGEN TWO TIMES, FOUND EVAPORATOR LEAKING IN SLEEPER.	1	\$140.00	\$140.00	G
5.		Labour /h	REMOVED HVAC BOX FROM SLEEPER, DISASSEMBLED AND REMOVED EVAPORATOR, CLEANED OUT HVAC BOX, INSTALLED NEW EVAPORATOR AND REINSTALLED BOX. LOST SOME COOLANT FROM HEATER CORE, TOPPED UP	3	\$140.00	\$420.00	G
6.		Parts	EVAPORATOR	1	\$721.43	\$721.43	G
7.		Labour /h	CHARGE AC SYSTEM, ENSURE NOT LEAKS	1.5	\$140.00	\$210.00	G
8.		Parts	AC REFRIGERANT /LBS	5	\$27.99	\$139.95	G

9.	Parts	COOLANT 4L JUG	1	\$17.99	\$17.99	G
10.	Labour /h	REPAIRED AND INSTALLED TUB FENDER	0.5	\$140.00	\$70.00	G
11.	Labour /h	REMOVE AND INSTALL TRANSMISSION	8	\$140.00	\$1,120.00	G
12.	Labour /h	WASHED UNDERCARRIAGE, TRANSMISSION AND CLEANED OUT BELL HOUSING	1	\$140.00	\$140.00	G
13.	Labour /h	REFURBISHED CUSTOMER TRANSMISSION, PAINTED	1	\$3,100.00	\$3,100.00	G
14.	Labour /h	REMOVE FLY WHEEL TO HAVE IT SHAVED, CHANGED REAR MAIN SEAL, REINSTALLED FLY WHEEL	2	\$140.00	\$280.00	G
15.	Parts	REAR MAIN SEAL	1	\$129.65	\$129.65	G
16.	Parts	FLY WHEEL TURN	1	\$165.00	\$165.00	G
17.	Parts	CLUTCH ASSEMBLY	1	\$1,150.00	\$1,150.00	G
18.	Labour /h	REMOVE CLUTCH LINKAGE, REPLACED ROD, HIEM JOINTS AND 1 BUSHING, REINSTALLED AND SET	4	\$140.00	\$560.00	G
19.	Parts	NEW THREADED ROD, 4 HIEM JOINTS	1	\$229.30	\$229.30	G
20.	Labour /h	CUT OUT OLD, SEIZED MOTOR MOUNTS AND INSTALLED NEW ONES	4	\$140.00	\$560.00	G
21.	Parts	MOTOR MOUNTS AND BOLTS	4	\$49.99	\$199.96	G
22.	Parts	50W TRANSMISSION FLUID	15	\$19.74	\$296.10	G
23.	Parts	HIGH HEAT TRANSMISSION COOLER LINES - MADE	2	\$189.99	\$379.98	G
24.	Labour /h	REMOVE, WASH, RESEAL, MEASURE BACK LASH AND INSTALL PTO	3	\$140.00	\$420.00	G
25.	Labour /h	REMOVE AND INSTALL EXHAUST, CUSTOM, FIXED CROOKED Y PIPE	4	\$140.00	\$560.00	G
26.	Parts	5" FLEX PIPE /FT	4	\$48.97	\$195.88	G
27.	Parts	5" EXHAUST STEP CLAMPS	7	\$16.99	\$118.93	G

28.	Parts	BENDIX AIR DRYER	1	\$289.28	\$289.28	G
29.	Labour /h	REMOVE OLD AIR DRYER AND INSTALL NEW ONE	1.5	\$140.00	\$210.00	G
30.	Labour /h	GREASE AND INSPECT TRUCK	0.5	\$140.00	\$70.00	G
31.	Shop Supplies	Shop supplies is 10% of the labour amount charged. 10% of 140\$ is 14\$. CAPPED AT 200\$	37.5	\$5.3333333	\$200.00	G

Note to customer

- Retorque any removed wheels to 100kms
- Shop Supplies is 10% of the labour charged
- Payment with credit card is an additional 3.99%

Subtotal	\$12,716.50
GST @ 5% on \$12,716.50	\$635.83
Total	\$13,352.33