



Phone

• Fax

www.youngs.ca

CASE III
AGRICULTURE

Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

A01-53

Invoice To:

Branch		
REPRINT		
Date 06/27/23	Time 22:02:08 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # RATE ISSUE	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#

UP0858

HC Sprayer
4420

HRS

3633

PIN/EIN

Y8T022720

WARRANTY DATE

HRS

SEGMENT# 1 C 34032 NA

06/12/23 06/12/23

SERVICE CALL

JUNE 12-SERVICE CALL TO THE FARM (N/C)

JUNE 13-SERVICE CALL TO THE FARM (N/C)

JUNE 14-SERVICE CALL TO THE FARM (N/C)

JUNE 17-SERVICE CALL TO THE FARM (130KM)

JUNE 23-SERVICE CALL TO THE FARM (128KM)

SV

Service Call

258

1.85

477.30

(Vehicle Fee)

PARTS

477.30

SEGMENT TOTAL==>

477.30

11030099

SEGMENT# 2 C 34032 NA

06/12/23 06/12/23

DIAGNOSE AND REPAIR RATE ISSUE

+TESTED FLOW METER.

+FLOW METER TESTED GOOD.

+TESTED HARNESS.

+WHEN JUMPING HARNESS MONITOR WOULD NOT CHANGE.

+TESTED WIRES.

+POWER WIRE WAS ONLY RECEIVING 6 VOLTS.

+FOLLOWED HARNESS COULD NOT FIND ANY PROBLEM WITH HARNESS.

+GROUND WAS SHOWING HIGH RESISTANCE.

+CLEANED BATTERY GROUNDS AND ALL GROUND POINTS.

+GROUND WAS STILL SHOWING HIGH RESISTANCE.

+JUMPED RAN GROUND WIRE STRAIGHT FROM BATTERY.

+MONITOR STILL WOULD NOT READ WHEN JUMPING HARNESS.

+DIAGNOSED TO BE MASTER FLOW CONTROLLER.

+INSTALLED SHOPS MASTER FLOW CONTROLLER AND TESTED SPRAYER.

+CUSTOMER IS RUNNING SPRAYER WITH SHOP CONTROLLER WHILE.

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc. It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment. Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at OWN RISK. Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid. Equipment is not to be used for any purpose not provided in the estimate only, and is non-binding. Equipment is not to be used for any purpose not provided in the estimate only, and is non-binding.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone: _____ Fax: _____
www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: _____

Invoice To: _____

Branch		
Date 06/27/23	Time 22:02:08 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # RATE ISSUE	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
UP0858 HC Sprayer 3633 Y8T022720

+NEW CONTROLLER IS ON ORDER.
+ARRIVED AT MACHINE.
+REMOVED AIM COVER AND AIM MASTER FLOW CONTROLLER.
+INSTALLED NEW CONTROLLER.
+FLOW TESTED SPRAYER AND VERIFIED OPERATION; GOOD.
+CUSTOMER COMPLAINT OF SAME ISSUE RE-OCCURRING DAYS
+LATER; RE-SET OLD CONTROLLER AND SWAPPED OUT WITH NEW
+CONTROLLER; RATE BEGAN FUNCTIONING PER NORMAL.
+AFTER MORE TESTING RATE BEGAN FLUCTUATION AGAIN.
+VERIFIED MONITOR SETTINGS, TESTED ALL AIM CONTROLLERS AND
+HARNESSES UP TO AIM CONTROLLERS; GOOD.
+MULTIPLE LOCATIONS OF BARE WIRING GOING TO CONTROLLERS;
+REPAIRED ANY BARE WIRING THAT COULD LEAD TO THIS ISSUE;
+AFTER REPAIRING WIRING TO AIM CONTROLLER RATE BEGAN
+FUNCTIONING AS PER NORMAL; CUSTOMER WANTS WORN HARNESSES
+REPLACED; ORDERED APPLICABLE HARNESSES.
+MACHINE STOPPED WORKING AGAIN DURING THIS TIMEFRAME;
+INSTALLED NEW FLOWMETER AND RATE TESTED.
+CUSTOMER BELIEVES THIS WAS THE ISSUE; HARNESSES
+WILL BE REPLACED DURING WINTER INSPECTION.
+FLOWMETER WAS NOT INTERNALLY INSPECTED DURING
+FIRST TWO DIAGNOSTICS DUE TO CHEMICAL IN SPRAYER.

FC220	CLAMP- FLANGE 2	1	9.59	9.59
FRTCP	FREIGHT-CASE	4	33.75	135.00
G2	2" CAMLOCK GSKT	1	1.62	1.62
M220CPG	COUPLER- MANIFO	1	19.15	19.15
47974262	METER	1	1493.63	1493.63
87630208	HARNESS, W	1 N	4786.15	4786.15
87630216	HARNESS	1 N	3179.18	3179.18
	PARTS			9624.32

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on and/or in possession of the above-noted equipment.
Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
Estimates are for the items specifically identified in the estimate only, and are non-binding.
Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By _____

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone:

Fax

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Branch		
Date 06/27/23	Time 22:02:08 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # RATE ISSUE	
Tax ID #		
		Salesperson

Invoice To:

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer	3633	Y8T022720	
	4420			
11030099			LABOR	5441.60
			SEGMENT TOTAL==>	15065.92

SEGMENT# 3 C 34032 QC 06/12/23 06/14/23
Young's Complimentary QuickCheck Inspection
1 Tie harnesses up on right boom to avoid damage by cradle
2 Repair wheel fenders
3 Install loom on harnesses

***** WORK ORDER TOTALS *****	
PARTS	10101.62
LABOR	5441.60
shop supplies	300.00
SUB TOTAL==>	15843.22
GST 5%	792.15
TOTAL ON ACCOUNT	16635.37

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc. It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment. Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!