



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

[REDACTED] 59

Invoice to:

[REDACTED]

Branch		
[REDACTED]	Time	Page
03/29/21	14:38:04 (O)	01
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	[REDACTED]
Ship via	Purchase Order	
[REDACTED]	[REDACTED]	
G.S.T. No.		[REDACTED]
Credit Card No.	Salesperson	
	J77	

## Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
142849	4530 FLOATER	3425 YCT033438		
	4530			

SEGMENT# 1 5 01861 NA 03/05/21 03/09/21

### ROOF REPAIRS

#### CORRECTION:

attempt to unbolt roof. applied different types of anti rust components to remove lock nuts holding the roof panel onto the frame attempted to make small cups to hold CLR to soak studs. gave up on trying to save the studs twisted out studs and removed roof panel. removed buddy seat and rear cab post corner cover removed antennas from the roof that no longer are needed and were never used. got three people to assist in removing old roof panel customer wants to keep and repair at a later time. boxed up damaged pieces. cleaned out holes for mounting studs mixed up epoxy and fitted new studs. double nutted all studs to install into fiberglass roof. after epoxy set, lifted new roof panel up into place installed new rubber seals washers and new nyloc nuts applied never seize to studs before assembly changed over radio antenna and nut switched over roof blank plugs.

FREIGHT	FREIGHT	3	34.56	103.68
411601	reflective tape	3	2.00	6.00
47566134	ROOF	1 A	1928.00	1928.00
84111	EPOXY	1	11.57	11.57
84322608	STUD	12 A	9.18	110.16
84576905	DECAL	1 A	10.24	10.24
86528579	NUT, LOCK	12	.98	11.76
86900237	WASHER	12	2.39	28.68
87000585	SPACER	12	7.08	84.96
	PARTS			2295.05

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

[Redacted]

Invoice to:

[Redacted]

Branch		
[Redacted]		
Date	Time	Page
03/29/21	14:38:04 (O)	02
Account No.	Phone No.	Reference No.
[Redacted]	[Redacted]	[Redacted]
Ship via	Purchase Order	
	G.S.T. No.	
	[Redacted]	
Credit Card No.	Salesperson	
	J77	

## Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
142849	4530 FLOATER	3425 YCT033438			
	4530				
13000051			LABOR	495.00	
			SEGMENT TOTAL==>	2790.05	

SEGMENT# 2 S 01861 NA 03/05/21 03/09/21

GPS REPAIRS

### CORRECTION:

assembled new mounting bracket riveted on new latch installed onto roof. ran new cable across roof and clamped into place with p clips and new lock nuts tied up cable modified cab skirt to fit new cable in a place that wouldn't get damaged over time. ran cable under seat and pulled down head liner to remove the old cables. hooked up new antenna new cable cut off plug for power and installed key switch plug. graham set up new antenna to talk to the raven gps tested gps operation and auto steer

FREIGHT	FREIGHT	4	19.50	78.00
ZTN50166	CABLE, ELECTRIC	1	400.00	400.00
10450590	CLAMP	4	5.51	22.04
187103A1	CONNECTION	1	74.95	74.95
241637	PLUG	1 N	12.10	12.10
353-421	PLUG	1 N	10.94	10.94
47854899	PLATE	1	54.46	54.46
47933424	372 RECEIVER	1 N	3932.00	3932.00
84416197	BRACKET	1 N	63.18	63.18
87308841	RIVET	2 N	4.07	8.14
87308870	LATCH	1 N	76.81	76.81
87681210	NUT, FLANG	3	1.25	3.75
	PARTS			4736.37
	LABOR			774.20
13000051	SEGMENT TOTAL==>			5510.57

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

[Redacted]

Invoice to:

[Redacted]

Branch		
[Redacted]		
Date	Time	Page
03/29/21	14:38:04 (O)	03
Account No.	Phone No.	Reference No.
[Redacted]	2048710759	[Redacted]
Ship via		Purchase Order
		G.S.T. No.
		[Redacted]
Credit Card No.		Salesperson
		J77

## Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
142849	4530 FLOATER	3425	YCT033438			
	4530					

Fold - - -

SEGMENT# 3 S 01861 NA 03/05/21 03/09/21

RADIATOR LEAK

### CORRECTION:

Rad hose leaking at thermostat housing attempt to drain coolant from rad but the drain is seized and could damage the rad. pulled upper pipe off removed rad hose and clamps replaced rad hose and clamps installed pipe and clamped filled with coolant. ran unit and checked for leaks

ANT1	ENVIRO ANTIFRZ	20	.18	3.60
BN324394	HOSE	1 N	33.24	33.24
B30205C	ANTI PREMIX 10L	2	26.45	52.90
FREIGHT	FREIGHT	1	16.00	16.00
M10X35X1.25	metric bolt	4	1.25	5.00
86050197	CLAMP, HOSE	3	3.04	9.12
	PARTS			119.86
	LABOR			582.40
13000051	SEGMENT TOTAL==>			702.26

SEGMENT# 4 S 01861 NA 03/05/21 03/09/21

ELECTRICAL ISSUE

### CORRECTION:

remove pins one by one inspect and install into new fuse holder changed out broken pins installed two new relays one modified and one corroded. test operation.

F-D3600	grn weather pac	2	4.25	8.50
F-F4800	12077411-L PACK	1	9.09	9.09
F-F5000	12110847-1 pk	1	9.09	9.09
87312843	FUSE BOX	1 N	204.08	204.08
87655334	RELAY	2	19.60	39.20

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

[Redacted]

Invoice to:

[Redacted]

Branch		
[Redacted]		
Date	Time	Page
03/29/21	14:38:04 (O)	04
Account No.	Phone No.	Reference No.
[Redacted]	[Redacted]	[Redacted]
Ship via		Purchase Order
		G.S.T. No.
		[Redacted]
Credit Card No.		Salesperson
		J77

## Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
142849	4530 FLOATER	3425	YCT033438			
	4530					
				PARTS		269.96
				LABOR		493.00
13000051				SEGMENT TOTAL==>		762.96

### \*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	7421.24
LABOR	2344.60
DISPOSAL FEE	46.89
SHOP SUPPLIES	199.29
SUB TOTAL==>	10012.02
GST 797594660	500.60
TOTAL CHARGE	10512.62

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)