

RITCHIE BROS. Diagnostic Report
 Auctioneers®
2021 International LT**Test Information**

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X1u20D1500C00000*80258878*0000000000
VIN	3HSDZAPR2MN537149
Driveline	Class 8 6x4
Body	Truck-Tractor
Test Time	Aug. 19, 2026, 12:29 p.m.
File Length	41.78 s
Test Time	Aug. 19, 2026, 12:27 p.m.
File Length	107.561 s

Usage

Label	Value	Units
Engine Odometer	877,858	mi
Odometer (Instrument Cluster #1)	877,847	mi
Engine Total Hours of Operation	24,570.15	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	57	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Cab A/C Refrigerant Compressor Outlet Pressure	Low-most severe	2
Active	Body Controller	Cab A/C Refrigerant Compressor Outlet Pressure	Low-most severe	2
Active	Body Controller	Kneeling Control Mode Request	Erratic, Intermittent, or Incorrect	2
Active	Body Controller	Kneeling Control Mode Request	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Unknown	High-most severe	10
Previous	Body Controller	Cab A/C Refrigerant Compressor Outlet Pressure	High-most severe	13
Previous	Body Controller	Kneeling Control Mode Request	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	Cab A/C Refrigerant Compressor Outlet Pressure	High-most severe	13
Previous	Body Controller	Unknown	High-most severe	10
Previous	Lighting - Operator Controls	Manufacturer Assignable SPN (first entry)	Erratic, Intermittent, or Incorrect	1
Previous	Lighting - Operator Controls	Manufacturer Assignable SPN (first entry)	Erratic, Intermittent, or Incorrect	1
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	5
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	5
Previous	Communications Unit, Cellular	Network Antenna Status 2	Voltage Below Normal	126
Previous	Communications Unit, Cellular	Network Antenna Status 2	Voltage Below Normal	126
Previous	Proprietary	Source Address 33	Abnormal Update Rate	42
Previous	Proprietary	Source Address 33	Abnormal Update Rate	42
Previous	Proprietary	Source Address 33	Abnormal Update Rate	4
Previous	Proprietary	Source Address 33	Abnormal Update Rate	4
Previous	Proprietary	Manufacturer Assignable SPN	Data Error	1
Previous	Proprietary	Manufacturer Assignable SPN	Data Error	1