

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-35	New, Puncture	25/09/2023		0	0	0		ANL Tyres	\$0.00
R-1604	Brakes	15/01/2025	15/01/2025	745,794	0	0		Internal Workshop Carry out A service on trailer as outlined on service sheet. Remove Tyres and hub and replace drive brakes. found wheel bearings to have excessive movement. Replaced left side wheel bearings and packed with grease.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-927	A - 10K	15/01/2025	15/01/2025	745,794 12,401		0		Orkhan Combe Carry out A service on trailer as outlined on service sheet. Remove Tyres and hub and replace drive brakes. found wheel bearings to have excessive movement. Replaced left side wheel bearings and packed with grease.	\$0.00
R-1409	TYRE	19/12/2024	19/12/2024	741,481	0	0		Internal Workshop - Remove + replace LHF inner + outer dolly tyres with new + tension - Keep inner for runout	\$0.00
R-1290	TYRE	09/12/2024	09/12/2024	736,995	0	0		Internal Workshop Plug Tyres	\$0.00
R-1280	TYRE	06/12/2024	06/12/2024	736,196	0	0		Internal Workshop Plug, R/R/l trailer tyre.	\$0.00
R-1158	Lights	21/11/2024	21/11/2024	733,392	0	0	494		\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1241	C - 100K Annual	20/11/2024	21/11/2024	733,393 733,393	0	0		Internal Workshop C service Completed.	\$0.00
S-567	A - 10k	10/09/2024	10/09/2024	721,826 12,154		0		Ely Cameron	\$0.00
S-467	A - 10k	30/07/2024	30/07/2024	709,672 4,680		0		Orkhan Combe	\$0.00
S-458	A - 10k	06/07/2024	06/07/2024	704,992 54,204		0		Ely Cameron	\$0.00
T-257	Trailer Tyre	11/04/2024	11/04/2024	695,000	0	0		Internal Workshop remove, patch and refit	\$40.00
R-498	Air System	26/03/2024	26/03/2024	694,314	0	0		Internal Workshop Remove worn lines and replace with new	\$0.00
R-497	Brake Booster	26/03/2024	26/03/2024	694,314	0	0		Internal Workshop Remove and replace brake booster, reposition slack adjuster into correct position,	\$0.00
T-229	Trailer Tyre	14/03/2024	13/03/2024	688,695	0	0		Internal Workshop Remove strip and refit 4 x trailer tyres to rear of dolly	\$875.60

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-494	Tarp	12/03/2024	12/03/2024	688,419	0	0		Internal Workshop Remove and replace old motor with new one	\$0.00
R-467	Air System	05/03/2024	05/03/2024	686,937		0		Internal Workshop Repair rub through in 3/8" dolly airline + reloom	\$40.00
R-466	Brake Booster	05/03/2024	05/03/2024	686,937		0		Internal Workshop RHR dolly 30/30 brake booster internally leaking... remove + replace booster with new	\$80.00
T-203	Trailer Tyre	27/02/2024	27/02/2024	683,983		0		Internal Workshop 2nd axle LH outer strip + fit new due to sidewall damage + tension	\$40.00
R-450	Lights	23/02/2024	23/02/2024	683,586		0		Internal Workshop Remove dodgy + broken wiring @ rear taillights + rewire clearance lights into wiring harness + reloom	\$80.00

