



**Westlock**  
10803 - 100 Street, Westlock, AB, T7P 2R7  
Parts: 825.602.5343 Service: 825.500.5159 Sales: 780.349.3391  
www.horizonagturf.com

Ship to:

MCMILLAN TRADE

Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch			
WESTLOCK		*REPRINT*	
Date	Time	Page	
09/20/24	23:05:26 (B)	01	
Account No.	Phone No.	Invoice No.	
INTER01		W61978	
Ship Via		Purchase Order	
		Salesperson	
		MEC	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556		
	9870 STS	2201			

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 43529 NA 08/27/24 08/28/24  
WALKAROUND INSPECTION

		LABOR	
10102010	16001001	720.00	
SEGMENT TOTAL==>		720.00	

SEGMENT# 2 C 43529 NA 08/27/24 09/03/24  
CLEAN UP FOR RESALE

		LABOR	
10102010	16001001	800.00	
SEGMENT TOTAL==>		800.00	

SEGMENT# 3 C 43529 NA 08/29/24 08/29/24  
SERVICE

2.50 HRS

\*\*\*\*\* TECHNICIANS COMMENTS \*\*\*\*\*

\*  
\*Replaced hazard light.  
\*Changed primary gearcase oil.  
\*Topped up engine oil.  
\*Replaced missing clips.  
\*Cleaned fuel strainer.  
\*

\*\*\*\*\*

AA45032	TURN SIGNA	1 N	47.90	47.90
---------	------------	-----	-------	-------

Turn Signal Lamp

ENV06	OIL ENVIRO FEE	2	.06	.12
-------	----------------	---	-----	-----

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH  
( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



**SIGNATURE**  
**RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO**



**Westlock**  
10803 - 100 Street, Westlock, AB, T7P 2R7  
Parts: 825.602.5343 Service: 825.500.5159 Sales: 780.349.3391  
www.horizonagturf.com

Ship to:

MCMILLAN TRADE

Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch			
WESTLOCK			
Date	Time	Page	
09/20/24	23:05:26 (B)	02	
Account No.	Phone No.	Invoice No.	
INTER01		W61978	
Ship Via		Purchase Order	
		Salesperson	
		MEC	

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556			
	9870 STS	2201				
ENV12	CONTAIN ENV FEE	2		.12		.24
ENV23	OIL ENVIRO FEE	1		.23		.23
ENV46	CONTAIN ENV FEE	1		.46		.46
M72598	QUICK LOCK	8		3.23		25.84
TY26673	15W40 P50 3.78L	RETAIL		34.15		
		1		30.73		30.73
TY6296	80W90 GL5 946ML	RETAIL		14.45		
		2		13.00		26.00
				PARTS		131.52
				LABOR		450.00
10102010	16001001			SEGMENT TOTAL==>		581.52

SEGMENT#						
4	C	43529	NA	08/29/24	08/29/24	
						5.00 HRS
REVERSER						
AH208250		PISTON	1 N	160.04		160.04
AH215259		SEAL	1 N	319.69		319.69
AH216871		SEAL	1 N	58.07		58.07
CE18531		SEAL	1	51.00		51.00
DE30216		Seal	2	39.85		79.70
ENV06		OIL ENVIRO FEE	5	.06		.30
ENV12		CONTAIN ENV FEE	5	.12		.60
FRT05		0-5 LBS FRT	1	14.95		14.95
H223849		RING	1	12.80		12.80
TY26408		SYN HD460 946ML	RETAIL	44.63		
			5	40.17		200.85
				PARTS		898.00
				LABOR		900.00
10102010		16001001		SEGMENT TOTAL==>		1798.00

SEGMENT# 5 C 43529 NA 08/29/24 08/29/24

CONTINUED ON PAGE 03

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH  
( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch			
WESTLOCK			
Date	Time	Page	
09/20/24	23:05:26 (B)	03	
Account No.	Phone No.	Invoice No.	
INTER01		W61978	
Ship Via		Purchase Order	
		Salesperson	
		MEC	

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556		
	9870 STS	2201			

## CONCAVES

3.00 HRS

\*\*\*\*\* TECHNICIANS COMMENTS \*\*\*\*\*

\*

```

**Found position sensor was not holding properly in small
*tab on end of rod. Removed sensor and ran thru motion.
*Sensor reads 0-52 fully open and fully closed (X)
***When adjusting concaves, when worm gear is bottomed out
*its moves out of position which causes adjusting motor to
*spin but not grab worm gear sprocket** **Will inspect to
*see if worm gear is bent and if there are any adjustments
*that can be made**

```

\*

\*\*\*\*\*

AH143997	WIRING HARNE	1 N	279.81	279.81
AH201526	RELAY	2	32.76	65.52
AXE58085	Sensor	1	246.99	246.99
FRT05	0-5 LBS FRT	1	14.95	14.95
49M4821	SHAFT KEY	1	4.05	4.05

PARTS 611.32

LABOR	900.00
-------	--------

```
10102010      16001001      SEGMENT TOTAL==>      1511.32
```

SEGMENT# 6 C 43529 NA 08/29/24 08/29/24

BELTS 2.00 HRS

- alternator belt
- rotary screen jackshaft belt
- rotary screen belt

\*\*\*\*\* TECHNICIANS COMMENTS \*\*\*\*\*

\*

\*Replaced all three belts.

CONTINUED ON PAGE 04

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH ( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees.

**SIGNATURE**

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



**Westlock**  
10803 - 100 Street, Westlock, AB, T7P 2R7  
Parts: 825.602.5343 Service: 825.500.5159 Sales: 780.349.3391  
www.horizonagturf.com

Ship to:

MCMILLAN TRADE

Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch		
WESTLOCK		
Date	Time	Page
09/20/24	23:05:26 (B)	04
Account No.	Phone No.	Invoice No.
INTER01		W61978
Ship Via		Purchase Order
		Salesperson
		MEC

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556		
	9870 STS	2201			
*****					
H213353	V-BELT	1	41.97	41.97	
H221273	V-BELT	1	67.97	67.97	
R503505	V-BELT	1	95.31	95.31	
			PARTS	205.25	
			LABOR	360.00	
10102010	16001001		SEGMENT TOTAL==>	565.25	

SEGMENT# 7 C 43529 NA	08/29/24 08/29/24			
ELEVATORS / CHOPPER		4.00 HRS		
***** TECHNICIANS COMMENTS *****				
*Removed half link and tightened chains.				
*Installed missing bolts.				
*****				
BULK109	HARDWARE	4	4.46	17.84
H215004	BLADE	39	12.23	476.97
H84026	HOOK	2	.99	1.98
			PARTS	496.79
			LABOR	810.00
10102010	16001001		SEGMENT TOTAL==>	1306.79

SEGMENT# 8 C 43529 NA	08/29/24 08/29/24			
HEADER		7.00 HRS		
***** TECHNICIANS COMMENTS *****				
*-replace drive belt (X)				
*-get middle canvases to turn (X)				

CONTINUED ON PAGE 05

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH  
( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



**SIGNATURE**  
**RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO**



**Westlock**  
10803 - 100 Street, Westlock, AB, T7P 2R7  
Parts: 825.602.5343 Service: 825.500.5159 Sales: 780.349.3391  
www.horizonagturf.com

Ship to:

MCMILLAN TRADE

Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch		
WESTLOCK		
Date	Time	Page
09/20/24	23:05:26 (B)	05
Account No.	Phone No.	Invoice No.
INTER01		W61978
Ship Via		Purchase Order
		Salesperson
		MEC

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556		
	9870 STS	2201			

\*-header lights not working (X) \*

\*-multicopper cable seized to release pins (X) \*

\*-replace shear bolts for handle (X) \*

\*-drive bearings by drive shaft have loose lock collars (X) \*

\*-replace tension bolt and coupler nut LHS (X) \*

\*\*\*found missing lug nut on RHS guage wheel\*\* \*

\*Moulti coupler wirring harness pins bent. \*re-pin and new \*

\*plug. Snap ring missing on combine side causing harness to \*

\*push in. \*What caused bent pins\*\* \*

\* \*

AH207405	PUSH PULL	1	501.97	501.97
H175881	SNAP RING	1	7.21	7.21
PMF184219	BELT	1	58.08	58.08
PMF184228	BEARING	2 S	107.39	214.78
SSQC12-3	SQ SET SCREW	1	7.29	7.29
14M7264	LOCK NUT	4	.51	2.04
141-922	1/2 COUPLING	1	5.28	5.28
19M9326	SCREW	4	2.08	8.32
57M16151	Elec. Connector	1	161.49	161.49
	Elec. Connector Housing			
57M8164	ELEC. CONN	11	1.42	15.62
	Elec. Connector Terminal			
			PARTS	982.08
			LABOR	1260.00
10102010	16001001	SEGMENT TOTAL==>		2242.08

SEGMENT# 9 C 31452 NA 08/29/24 09/06/24

WELDING

1.50 HRS

\*\*\*\*\* TECHNICIANS COMMENTS \*\*\*\*\*

CONTINUED ON PAGE 06

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH  
( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



**Westlock**  
10803 - 100 Street, Westlock, AB, T7P 2R7  
Parts: 825.602.5343 Service: 825.500.5159 Sales: 780.349.3391  
www.horizonagturf.com

Ship to:

MCMILLAN TRADE

Invoice to:

INTERNAL CUSTOMER  
INTERNAL CUSTOMER  
INTERNAL W/O AB T5S 2L7

Branch		
WESTLOCK		
Date	Time	Page
09/20/24	23:05:26 (B)	06
Account No.	Phone No.	Invoice No.
INTER01		W61978
Ship Via		Purchase Order
		Salesperson
		MEC

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
150835B	JOHN DEERE 9870 ST	3200	H09870S725556		
	9870 STS	2201			
* * * * *					
*cracks in tailings elevator - grind off the paint and					
*grind through the cracks and weld back together.					
*#####Cole found a broken canvas adjuster bolt that was					
*seized into the nut-cut the nut off the frame of the header					
*and weld a new one in place#####					
*##### left side of header side shield- ;lift into place					
*and weld the bracket back together#####					
* * * * *					
*****					
			LABOR		312.50
10102010	16001001		SEGMENT TOTAL==>		312.50

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	3324.96	
LABOR	6512.50	
Fuel	414.75	
Shop Supplies	200.00	
INTERNAL TOTAL	10452.21	

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH ( 24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

**SIGNATURE**  
**RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO**