

A01-14

Axess Heavy Duty Services Ltd.

P.O. Box 2284
 Rosetown, SK S0L 2V0, CA
 service@axesshd.com
 306-831-5775

Invoice: **8066**Date: **14/10/2025****Bill To****Remit Payment To**


Mailing
 P.O. Box 2284
 Rosetown, SK S0L 2V0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
3738	Due Upon Receipt	14/10/2025			

Item	Description	Quantity	Rate	Amount
Complaint: DIAGNOSE NO START				
Cause: Customer request				
Labor	Correction: Engine / Electrical / ORIGINAL MILEAGE PRIOR TO ECM REPLACEMENT IS 642693KM DUE TO NOT BEING ABLE TO COMMUNICATE WITH ORIGINAL ECM SOME PARAMETERS WERE NOT TRANSFERABLE.	4.00000	\$188.00	\$752.00
	SERVICE CALL TO DIAGNOSE NO START, ENGINE CRANKS BUT WILL NOT FIRE, VERIFY FUEL SUPPLY AND PRESSURE, ATEMPT TO COMMUNICATE WITH ECM NO SUCCESS. VERIFY ALL POWERS AND GROUNDS TO ECM- GOOD. REMOVE ECM AND BENCH TEST NO COMMUNICATION ECM HAS FAILED INTERNALLY. SEND ECM FOR REPAIR BUT INTERNAL PARTS NOT READILY AVAILABLE. ORDER NEW ECM AND HAS BASE PROGRAMMED. INSTALL NEW ECM AND VERIFY OPERATION.			
Parts	ECM	1.00000	\$5,644.92	\$5,644.92
Parts	ECM PROGRAMMING	1.00000	\$525.00	\$525.00
			Subtotal	\$6,921.92

Unit: VIN: 2HSCEAXR94C090215
 2004 International 9200i
Chassis: 642,693 Kilometers

Labor	\$752.00
Parts	\$6,169.92
Pre-Charge Subtotal	\$6,921.92
GST (5% of \$6,921.92)	\$346.10
Total	\$7,268.02
Payments & Credits	\$0.00
Balance Due	\$7,268.02



Thank you for your business. We accept payment through e-transfer, credit card, or cheque. **Due to the ongoing Canada Post strike, mail delivery may be delayed. We kindly ask that cheques be dropped off at the shop, if possible to help ensure timely processing of payments. We appreciate your understanding and cooperation.**

Net payable 15 days from date of invoice. Charge Accounts are processed 15 days from the invoice date. Overdue invoices > 30 days are subject to 5% interest charged.

Axess Heavy Duty Services Ltd. retains ownership of all materials until payment is made in full.