



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	1 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

/SPS780 Retail

COMPLAINT:

01 GREENLIGHT SERVICE INSPECTION COMBINE

CAUSE:

CORRECTION:

PERFORMED A COMPLETE G/L INSPECTION ON S780

Labor: \$1,999.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,999.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/GLOPCLEANS780 Retail

COMPLAINT:

02 GREENLIGHT/RECONDITION CLEANING CHECKLIST
 -COMPLETE WASH

CAUSE:

CORRECTION:

CLEANED OUT FEEDER HOUSE AREA. CLEANED/BLEW OUT STONE TRAP AND FEED ACCELERATOR AREAS. BLEW OUT CONVEYOR AUGERS AND TROUGH AREAS. BLEW OFF COMPLETE COMBINE. WASHED OUT HOPPER AND FOLDING COVERS. WASHED AND DETAILED COMPLETE COMBINE. CLEANED CAB AND WINDOWS.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	-\$397.50	-\$397.50	Y
SERVACCESS	SERVICE ACCESSORIES	1.00	\$96.00	\$96.00	Y
Labor: \$1,875.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$301.50	Sub-Total: \$1,573.50	

/110176S780 Retail

COMPLAINT:

03 CHECK OUT ALL CODES FOUND ON GREENLIGHT

CAUSE:

CORRECTION:



Box 30
609 Highway 48
Montmartre, SK S0G 3M0
Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

RAN COMPLETE COMBINE AFTER ALL REPAIRS WERE COMPLETED. GOOD- ALL FUNCTIONS OPERATE PROPERLY AS REQUIRED/ NO CODES PRESENT NOW

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$11.16	\$11.16	Y
Labor: \$186.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

/140968AS780 Retail

COMPLAINT:

04 UPDATE ALL MACHINE CONTROLLERS SOFTWARE(9)

CAUSE:

CORRECTION:

UPDATED ALL CONTROLLER SOFTWARE AS REQUIRED. ALL CONTROLLERS WERE UPDATED SUCCESSFULLY. ALL CONTROLLERS NOW HAVE THE LATEST SOFTWARE INSTALLED

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$27.90	\$27.90	Y
Labor: \$465.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$27.90	Sub-Total: \$492.90	

/141410S780 Retail

COMPLAINT:

05 REPLACE ONE FRONT SHOE AUGER BEARING LH OUTSIDE (LOOSE)

CAUSE:

CORRECTION:

REMOVED OUTER LEFT HAND CONVEYOR AUGER ASSEMBLY FROM COMBINE. REPLACED FRONT BEARING FLANGES, BEARING, LOCKING COLLAR, AND ALL HARDWARE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
03M7188	BOLT	3.00	\$2.05	\$6.15	Y
14M7298	FLANGE NUT	3.00	\$1.53	\$4.59	Y
AXE39453	Bearing	2.00	\$67.52	\$135.04	Y



Box 30
609 Highway 48
Montmartre, SK S0G 3M0
Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	3 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

H103264	Pressed Flanged Housing	2.00	\$4.13	\$8.26	Y
JD8554	ECCENTRIC LOCKING COLLAR	1.00	\$11.03	\$11.03	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$16.74	\$16.74	Y

Labor: \$279.00 Parts: \$165.07 OL&M: \$0.00 Misc: \$16.74 Sub-Total: \$460.81

/10174080S780 Retail

COMPLAINT:

06 R&R SHOE AUGER DRIVE SHAFT (BENT)
-OUTER DRIVE PULLEY HAS A FAIR BIT OF WOBBLE TO IT

CAUSE:

CORRECTION:

REMOVED COMPLETE SLIP CLUTCH ASSEMBLY FROM CONVEYOR AUGER DRIVE SHAFT (RIGHT SIDE). LOOSENED OFF ALL BEVEL GEARS ON ORIGINAL DRIVE SHAFT, REMOVED ALL BEARINGS FROM SHAFT ENDS AND REMOVED COMPLETE CONVEYOR AUGER DRIVE SHAFT FROM COMBINE. INSTALLED A NEW CONVEYOR AUGER DRIVE SHAFT, BEARING FLANGES, BEARINGS AND LOCKING COLLARS, AND ALL HARDWARE. INSTALLED NEW BEVEL GEAR KEYS AND ADJUSTED BEVEL GEARS FOR PROPER BACKLASH AND OPERATION. REPLACED KEY ON SLIP CLUTCH AND REINSTALLED COMPLETE SLIP CLUTCH ASSEMBLY BACK ONTO NEW SHAFT.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7298	FLANGE NUT	9.00	\$1.53	\$13.77	Y
19M7866	SCREW	9.00	\$1.78	\$16.02	Y
26M4226	SHAFT KEY	1.00	\$4.41	\$4.41	Y
AXE49248	Tone Wheel	1.00	\$87.66	\$87.66	Y
AXE51888	Ball Bearing	1.00	\$135.64	\$135.64	Y
H103264	Pressed Flanged Housing	5.00	\$4.13	\$20.65	Y
H161529	Pressed Flanged Housing	2.00	\$10.78	\$21.56	Y
HXE116497	SHAFT	1.00	\$766.63	\$766.63	Y
HXE87355	Bracket	1.00	\$75.97	\$75.97	Y
HXE87355	Bracket	1.00	\$73.37	\$73.37	Y
JD8554	ECCENTRIC LOCKING COLLAR	2.00	\$11.03	\$22.06	Y
JD8665	1" Ball Bearing	3.00	\$25.62	\$76.86	Y
M48583	SHAFT KEY	4.00	\$16.27	\$65.08	Y
PM233731	LOCTITE 290 THREADLOCKER 10ML	1.00	\$33.99	\$33.99	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	4 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:					
SERVACCESS	SERVICE ACCESSORIES		1.00	\$96.00	\$96.00 Y
Labor: \$1,860.00	Parts: \$1,413.67	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$3,369.67	

/170380S780 Retail

COMPLAINT:

07 REMOVE HALF LINK FROM FEEDER HOUSE CONVEYOR CHAIN AND ADJUST

CAUSE:

CORRECTION:

REMOVED A 1/2 LINK FROM FEEDER CHAIN AND ADJUSTED CHAIN TO PROPER TENSION.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$11.16	\$11.16	Y
Labor: \$186.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

/10171030S780 Retail

COMPLAINT:

08 R&R FEED ACCELERATOR BELT (CRACKED)

CAUSE:

CORRECTION:

REPLACED FEED ACCELERATOR DRIVE BELT AND ADJUSTED NEW BELT TO PROPER TENSION.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE54503	V-Belt	1.00	\$368.31	\$368.31	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$13.95	\$13.95	Y
Labor: \$232.50	Parts: \$368.31	OL&M: \$0.00	Misc: \$13.95	Sub-Total: \$614.76	

/10180250AS780 Retail

COMPLAINT:

09 CONCAVE LEVEL, ADJUST AND CALIBRATE (WITH ACI)



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	5 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

CAUSE:

CORRECTION:

REINSTALLED CONCAVES. TWO LARGE WIRES IN FRONT AND SMALL WIRE IN REAR. LEVELED CONCAVES AND CALIBRATED AS PER SERVICE ADVISOR INSTRUCTIONS.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$25.11	\$25.11	Y
Labor: \$418.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$25.11	Sub-Total: \$443.61	

/10040060S780 Retail

COMPLAINT:

10 REPLACE FRONT ROTOR GRAIN LOSS PAD
 -NOT RESPONDING

CAUSE:

CORRECTION:

REPLACED VISION TRACK FRONT ROTOR SENSOR. RETESTED COMPLETE VISION TRACK SYSTEM. GOOD- ALL SENSORS NOW RESPOND PROPERLY

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE55969	Sensor	1.00	\$294.15	\$294.15	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$13.95	\$13.95	Y
Labor: \$232.50	Parts: \$294.15	OL&M: \$0.00	Misc: \$13.95	Sub-Total: \$540.60	

/170001S780 Retail

COMPLAINT:

11 ADJUST ROTOR BELT SHEAVE GAP, AND GREASE

CAUSE:

CORRECTION:

ADJUSTED ROTOR DRIVE BELT SHEAVE GAP TO PROPER SPEC (8MM). GREASED BOTH ROTOR DRIVE SHEAVES PROPERLY.



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	6 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$11.16	\$11.16	Y
Labor: \$186.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

/120562S780 Retail

COMPLAINT:

12 REPLACE RETHRESHER DRIVE CHAIN

CAUSE:

CORRECTION:

REPLACED ACTIVE TAILINGS DRIVE CHAIN AND ADJUSTED NEW CHAIN TO PROPER TENSION (JD PRE CUT CHAIN).

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE54619	Roller Chain #60 114 Links	1.00	\$352.02	\$352.02	Y
Labor: \$120.90	Parts: \$352.02	OL&M: \$0.00	Misc: \$7.25	Sub-Total: \$480.17	

/120071S780 Retail

COMPLAINT:

13 REPLACE CLEAN GRAIN ELEVATOR CHAIN
 -NO HALF LINKS LEFT, AT THE END OF ADJUSTMENT

CAUSE:

CORRECTION:

REMOVED OLD/WORN OUT CLEAN GRAIN ELEVATOR CONVEYOR CHAIN FROM HOUSING. INSTALLED A NEW CLEAN GRAIN ELEVATOR CONVEYOR CHAIN AND ADJUSTED NEW CHAIN TO PROPER TENSION.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE72667	Roller Chain	1.00	\$1,153.53	\$1,153.53	Y
H84026	HOOK	3.00	\$0.95	\$2.85	Y
Labor: \$120.90	Parts: \$352.02	OL&M: \$0.00	Misc: \$7.25	Sub-Total: \$480.17	



Box 30
609 Highway 48
Montmartre, SK S0G 3M0
Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	7 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

Labor: \$186.00 Parts: \$1,156.38 OL&M: \$0.00 Misc: \$11.16 Sub-Total: \$1,353.54

/10190090S780 Retail

COMPLAINT:

14 REPLACE UPPER CLEAN GRAIN SHAFT BEARINGS AND SPROCKET
-SPROCKET IS FAIRLY WORE

CAUSE:

CORRECTION:

REPLACED CLEAN GRAIN UPPER SPROCKET AND KEY. REPLACED BEARING FLANGES, BEARINGS AND LOCKING COLLARS, AND ALL HARDWARE ON UPPER DRIVE SHAFT (SHAFT/KEY WAY WAS GOOD).

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7191	BOLT	6.00	\$1.71	\$10.26	Y
14M7296	FLANGE NUT	6.00	\$2.15	\$12.90	Y
49M6480	SHAFT KEY	1.00	\$4.85	\$4.85	Y
49M6480	SHAFT KEY	1.00	\$5.03	\$5.03	Y
AH133191	ECCENTRIC LOCKING COLLAR	2.00	\$26.48	\$52.96	Y
H153308	Pressed Flanged Housing	4.00	\$16.05	\$64.20	Y
H228385	CHAIN SPROC	1.00	\$125.07	\$125.07	Y
JD39104	BALL BEARING	2.00	\$58.94	\$117.88	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$55.80	\$55.80	Y

Labor: \$930.00 Parts: \$393.15 OL&M: \$0.00 Misc: \$55.80 Sub-Total: \$1,378.95

/13030SS780 Retail

COMPLAINT:

15 REPLACE CLEAN GRAIN LOWER CROSS AUGER SPROCKET
-FAIRLY WORE/HOOKED

CAUSE:

CORRECTION:

REPLACED CLEAN GRAIN LOWER DRIVE SPROCKET AND KEY. REPLACED RIGHT HAND BEARING ASSEMBLY (INCLUDES HOUSING) AND LOCKING COLLAR.



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	8 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
49M6480	SHAFT KEY	1.00	\$5.03	\$5.03	Y
H228383	Chain Sprocket	1.00	\$115.88	\$115.88	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$19.53	\$19.53	Y

Labor: \$325.50 Parts: \$120.91 OL&M: \$0.00 Misc: \$19.53 Sub-Total: \$465.94

/10230113S780 Retail

COMPLAINT:

16 LOWER CLEAN GRAIN AUGER, REPLACE
 -AUGER FLIGHTING IS VERY WORE/SHARP

CAUSE:

CORRECTION:

REPLACED CLEAN GRAIN LOWER CROSS AUGER, LEFT HAND BEARING FLANGES, BEARING, LOCKING COLLAR/TONING WHEEL, AND ALL HARDWARE

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7184	BOLT	3.00	\$1.28	\$3.84	Y
14M7298	FLANGE NUT	3.00	\$1.53	\$4.59	Y
AH133191	ECCENTRIC LOCKING COLLAR	1.00	\$26.48	\$26.48	Y
AXE23392	Bearing With Housing	1.00	\$287.54	\$287.54	Y
AXE48370	STONE WHEEL	1.00	\$81.19	\$81.19	Y
AXE59539	Auger	1.00	\$1,783.79	\$1,783.79	Y
H103264	Pressed Flanged Housing	1.00	\$4.13	\$4.13	Y
JD39102	Ball Bearing	1.00	\$35.76	\$35.76	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$27.90	\$27.90	Y

Labor: \$465.00 Parts: \$2,227.32 OL&M: \$0.00 Misc: \$27.90 Sub-Total: \$2,720.22

/120007S780 Retail

COMPLAINT:

17 BLOW OUT OUTER ENGINE AIR FILTER



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	9 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:
 CAUSE:

CORRECTION:

CLEANED AND BLEW OUT ENGINE AIR FILTER HOUSING AND AIR DUCT. CLEANED/BLEW OUT INNER AND OUTER ENGINE AIR FILTERS.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$5.58	\$5.58	Y
Labor: \$93.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58	

/110078S780 Retail

COMPLAINT:

18 CLEAN FUEL TANK BREATHER

CAUSE:

CORRECTION:

CLEANED OUT FUEL TANK BREATHER AND TUBE.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$3.35	\$3.35	Y
Labor: \$55.80	Parts: \$0.00	OL&M: \$0.00	Misc: \$3.35	Sub-Total: \$59.15	

/141887S780 Retail

COMPLAINT:

19 BLOW OUT DEBRIS MANAGEMENT OUTER FILTER

CAUSE:

CORRECTION:

BLEW OUT DEBRIS MANAGEMENT FILTER HOUSING AND AIR DUCT. CLEANED/BLEW OUT INNER AND OUTER DEBRIS MANAGEMENT FILTERS.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$5.58	\$5.58	Y
Labor: \$93.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58	



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	10 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:

/120014S780 Retail

COMPLAINT:

20 GREASE COMBINE

CAUSE:

CORRECTION:

GREASED COMPLETE COMBINE (1 TUBE OF JD MULTI PURPOSE GREASE).

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	\$10.87	\$10.87	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$11.16	\$11.16	Y

Labor: \$186.00 Parts: \$10.87 OL&M: \$0.00 Misc: \$11.16 Sub-Total: \$208.03

/141014S780 Retail

COMPLAINT:

21 BLOW OUT CAB FILTERS

CAUSE:

CORRECTION:

CLEANED AND BLEW OUT OUTER CAB FILTER HOUSING AND AIR DUCT. CLEANED/BLEW OUT INNER AND OUTER CAB FILTERS.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$5.58	\$5.58	Y

Labor: \$93.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.58 Sub-Total: \$98.58

GEN22- Retail

COMPLAINT:

22 REPAIR RIGHT HAND REAR DISCHARGE LIGHT NOT WORKING -BULB?

CAUSE:



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	11 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:
 CORRECTION:

REPLACED REAR RIGHT HAND DISCHARGE LIGHT AND RECHECKED OPERATION. GOOD- ALL LIGHTS NOW FUNCTION PROPERLY AS REQUIRED

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH208904	BULB	1.00	\$39.45	\$39.45	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$2.79	\$2.79	Y

Labor: \$46.50 Parts: \$39.45 OL&M: \$0.00 Misc: \$2.79 Sub-Total: \$88.74

/170538S780 Retail

COMPLAINT:

23 ADJUST ALL BELTS AND CHAINS AS PER IS DEPT GUIDELINES

CAUSE:

CORRECTION:

ADJUSTED ALL BELTS AND CHAINS TO PROPER TENSIONS.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$11.16	\$11.16	Y

Labor: \$186.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$11.16 Sub-Total: \$197.16

GEN24- Retail

COMPLAINT:

24 TRUCKING

CAUSE:

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
PV08	PILOT VEHICLE MM	172.00	\$3.40	\$584.80	Y
SEMI17005	SEMI MILEAGE 17005	86.00	\$9.75	\$838.50	Y



Box 30
 609 Highway 48
 Montmartre, SK S0G 3M0
 Phone: 306-424-2212
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	07/02/2025
Location:	08
Work Order Number:	
Payment Type:	
Authorization Number:	
Page:	12 of 12

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2018 JOHN DEERE S780	2105	1H0S780SCJ0800828	1H0S780SCJ0800828	# 3

Service Reminders:					
SEMI47004	SEMI MILEAGE 47004		86.00	\$9.75	\$838.50 Y
Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$2,261.80	Sub-Total: \$2,261.80	

GEN25- Retail

COMPLAINT:

25 GREENLIGHT PARTS DISCOUNT

CAUSE:

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
GLPDISCPTS	GL PARTS DISCOUNT PARTS	1.00	-\$327.07	-\$327.07	Y
GLPDISCSVC	GL PARTS DISCOUNT SERVICE	1.00	-\$327.06	-\$327.06	Y
Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$654.13	Sub-Total: -\$654.13	

Customer PO No:	
Tax Exempt No:	
Advisor:	Kerrigan Schnurr

GST Registration No: 897357802

Labor:	\$10,700.20
Parts:	\$6,541.30
OL&M:	\$0.00
Misc:	\$1,700.14
GST:	\$947.15
PST:	\$0.00
Total:	\$19,888.79

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: Date: