

PATTISON AGRICULTURE LIMITED
Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.
SHAUNE SWITZER
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
Prv Phone:

PHANTOM VALLEY FARMS LTD.
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
Prv Phone:

Invoice Number:	3436351
Invoice Date	08/14/2025
Location:	03
Work Order Number:	497255
Payment Type:	Credit Card
Authorization Number:	V07146G
Page:	1 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
MACDON FD75		289862-16	FD-75	

Service Reminders:

JGLHDR JD ALL Retail

COMPLAINT:

01 STRAIGHT CUT HEADER VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER.

CORRECTION:

STRAIGHT CUT HEADER VALUEMAX GREEN LIGHT SERVICE INSPECTION

DOES THIS UNIT GET A VALUEMAX STICKER ___ YES ___ N ___ NO
HAS THE STICKER BEEN INSTALLED ___ YES ___ N ___ NO
THIS UNIT HAS HAD A FINAL CHECKOVER ___ CS ___ (INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB ___ BS ___ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS

Labor: \$1,300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,300.00
-------------------	---------------	--------------	--------------	-----------------------

JGEN02- Retail

COMPLAINT:

03 TRANSPORT BRACKETS-- REPLACE REAR LATCHING ARM AND CLEAN/ADJUST LATCHING PIN FOR RH SIDE

CORRECTION:

TOOK OFF OLD ARM, FOUND BRACKET TO BE CRACKED. CLEANED METAL AND CLEANED SURFACE. WELDED CRACK.
REPLACED ARM. ALL IS GOOD

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
MCD144324	BRACE WELDMNT	1.00	302.98	\$302.98	Y
Labor: \$250.00	Parts: \$302.98	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$552.98	

JGEN06- Retail

COMPLAINT:

07 REPLACE 5 POLY SKIDS AND 1 SHORTER CENTER SKID

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.
SHAUNE SWITZER
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

PHANTOM VALLEY FARMS LTD.
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
Prv Phone:

Bus Phone: (403)664-0376
Prv Phone:

Invoice Number:	3436351
Invoice Date	08/14/2025
Location:	03
Work Order Number:	497255
Payment Type:	Credit Card
Authorization Number:	V07146G
Page:	2 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
MACDON FD75		289862-16	FD-75	

Service Reminders:

TOOK OFF OLD THE 5 POLY SKIDS USING 18 WRENCH
INSTALLED NEW POLY SKIDS USING 18 WRENCH
WAS TOLD NOT TO TAKE OFF OR INSTALL SHORTER CENTER SKID

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
FH318499	WEAR PLATE	5.00	16.90	\$84.50	Y
Labor: \$200.00		Parts: \$84.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$284.50

JGEN07- Retail

COMPLAINT:

08 REPLACE FEED DRUM 5 FINGER RETAINERS.

CORRECTION:

WAITING ON ONE NUT TO HOLD GUIDE IN

STRUGGLED TO FIND THE RIGHT PARTS AND HAD TO FIND THE FIVE WORST FINGERS CHANGED FINGERS AND RETAINERS AND ALL IS GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
MCD123084	BOLT SPECIAL	10.00	1.02	\$10.20	Y
MCD123202	NUT - TEE	10.00	1.57	\$15.70	Y
MCD220938	FINGER ASSEMBLY (BOX OF 5)	5.00	177.98	\$889.90	Y
MCD7642	SPRING PIN	5.00	0.59	\$2.95	Y
PMF337143	GUIDE	5.00	2.69	\$13.45	Y
Labor: \$600.00		Parts: \$932.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,532.20

JGEN08- Retail

COMPLAINT:

09 REPLACE INNER U JOINT ON DRIVE SHAFT

CORRECTION:

REMOVED DRIVE SHAFT FROM HEADER.
SPLIT DRIVESHAFT AND REMOVED COVER.
REMOVED AND INSTALLED NEW U-JOINT ONTO DRIVE SHAFT.
INSTALLED COVER AND PUT BACK TOGETHER.
INSTALLED ONTO HEADER.

PATTISON AGRICULTURE LIMITED
Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.
SHAUNE SWITZER
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
Prv Phone:

PHANTOM VALLEY FARMS LTD.
BOX 37
ATTN: SHAUNE SWITZER
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
Prv Phone:

Invoice Number:	3436351
Invoice Date	08/14/2025
Location:	03
Work Order Number:	497255
Payment Type:	Credit Card
Authorization Number:	V07146G
Page:	3 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
-------------	-------	----------------	--------	-----------

MACDON FD75	289862-16	FD-75
-------------	-----------	-------

Service Reminders:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
MCD142777	CROSS & BRG KIT	1.00	200.12	\$200.12	Y

Labor: \$300.00	Parts: \$200.12	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$500.12
------------------------	------------------------	-------------------------	---------------------	----------------------------

JGEN10- Retail

COMPLAINT:

11 ADJUST REEL DRIVE CHAIN

CORRECTION:

LOOSENED THE BOLTS OFF AND TIGHTENED THE CHAIN AND BOLTS. REINSTALLED COVER. ALL IS GOOD

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN11- Retail

COMPLAINT:

12 REEL END SHIELD- REPLACE 1 SECTION OF END SHIELD AND MOUNTING BRACKET

CORRECTION:

REMOVED REEL END SHIELDS AND BRACKET.
INSTALLED NEW REEL END SHIELD AND BRACKET.
TIGHTENED HARDWARE.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
MCD123767	DECAL - STRIPE - GREEN LH	1.00	17.29	\$17.29	Y
MCD123773	DECAL - LH MACDON FLEX (NRS)	1.00	67.23	\$67.23	Y
MCD164754	ENDSHIELD - 5 BAT SEGMENTED	1.00	50.50	\$50.50	Y
MCD164958	SUPPORT - ENDSHIELD REEL	1.00	46.29	\$46.29	Y
MCD220915	ENDSHIELD - LHC/W REFLECTORS	1.00	688.31	\$688.31	Y

Labor: \$200.00	Parts: \$869.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,069.62
------------------------	------------------------	-------------------------	---------------------	------------------------------

JHYDDIAG1 JD ALL Retail

COMPLAINT:

13 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS-- FORE/AFT CYLINDERS LEAKING WHEN NOT COMMANDED OR CONNECTED(LEAKING PAST CYLINDERS OR VALVE)

PATTISON AGRICULTURE LIMITED
Hwy 7 East, Box 1180
Kindersley, SK S0L 1S0
Phone: (306) 463-2683
Fax: (306) 463-6131
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD. SHAUNE SWITZER BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0 Bus Phone: (403)664-0376 Prv Phone:	PHANTOM VALLEY FARMS LTD. BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0 Bus Phone: (403)664-0376 Prv Phone:	Invoice Number: 3436351 Invoice Date: 08/14/2025 Location: 03 Work Order Number: 497255 Payment Type: Credit Card Authorization Number: V07146G Page: 4 of 6
--	--	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
MACDON FD75		289862-16	FD-75	

Service Reminders:

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:
INSPECTED AND FOUND REEL WAS COMMANDING FORWARD.
INSPECTED VALVE AND FOUND O-RING WAS LEAKING BY SLOWLY.
INSTALLED NEW OWN SUPPLIED O-RING.
RETESTED AND FOUND ALL WAS GOOD.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
MCD113435	SEAL KIT	2.00	70.86	\$141.72	Y
Labor: \$532.84	Parts: \$141.72	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$674.56	

J07171102 MD FD75 Retail

COMPLAINT:

14 REPLACE SIDE DRAPER (RIGHT)

CORRECTION:

LOOSENED BELT.
TOOK OUT BELT SPLICING AND REMOVED OLD BELT
INSTALLED NEW BELT WITH NEW SPLICING AND TIGHTENED BELT
ALL IS GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AFH209072	40" DRAPER BELT	1.00	1,790.62	\$1,790.62	Y
Labor: \$560.00	Parts: \$1,790.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,350.62	

JGEN13- Retail

COMPLAINT:

15 UPPER CROSS AUGER-- REPLACE CENTER SHAFT, U JOINTS AND CENTER MOUNT BUSHINGS

CORRECTION:

TOOK OFF THE LH SIDE PEA AUGER AND REMOVED AUGER, TOOK OFF THE CENTER MOUNT, CHANGED BEARINGS AND BUSHING AND INSTALLED CENTER ARM BACK ON TO HEADER AND REINSTALLED PEA AUGER AND ALL IS GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
------------	-------------	----------	-----------	----------------	-----------

PATTISON AGRICULTURE LIMITED

Hwy 7 East, Box 1180
 Kindersley, SK S0L 1S0
 Phone: (306) 463-2683
 Fax: (306) 463-6131
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 654-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.
 SHAUNE SWITZER
 BOX 37
 ATTN: SHAUNE SWITZER
 SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
 Prv Phone:

PHANTOM VALLEY FARMS LTD.
 BOX 37
 ATTN: SHAUNE SWITZER
 SIBBALD AB T0J3E0

Bus Phone: (403)664-0376
 Prv Phone:

Invoice Number: **3436351**
 Invoice Date: 08/14/2025
 Location: 03
 Work Order Number: 497255
 Payment Type: Credit Card
 Authorization Number: V07146G
 Page: 5 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
MACDON FD75		289862-16	FD-75	

Service Reminders:

MCD172507	BEARING BALL	2.00	29.37	\$58.74	Y
MCD174081	SHAFT HEX	1.00	146.56	\$146.56	Y
MCD21810	BUSHING RUBBER	4.00	22.33	\$89.32	Y

Labor: **\$600.00** Parts: **\$294.62** OL&M: **\$0.00** Misc: **\$0.00** Sub-Total: **\$894.62**

JGEN14- Retail

COMPLAINT:

16 RIGHT HAND LIFT CYLINDER LEAKING FROM BREATHER-- RESEAL

CORRECTION:

TOOK OFF CYLINDER AND RESEALED CYLINDER INSTALLED TESTED ALL IS GOOD

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
MCD132474	SEAL KIT	1.00	56.73	\$56.73	Y
MCD132475	SEAL KIT	1.00	65.39	\$65.39	Y

Labor: **\$250.00** Parts: **\$122.12** OL&M: **\$0.00** Misc: **\$0.00** Sub-Total: **\$372.12**

J07001010 MD FD75 Retail

COMPLAINT:

17 ADJUST FLOAT AND WING BALANCE.

CORRECTION:

AS PER MANUAL.

JD/CS: CHECK AND ADJUST THE FLOAT , FLOAT WAS EVEN ON BOTH SIDES HAD 2.5 AND 2.5 DIDNT ADJUST WITHIN SPEC , CHECK WING BALANCE RIGHT SIDE WAS 2 AND 2 ON THE TORQUE TOOL DIDNT HAVE TO ADJUST WITHIN SPEC , LEFT SIDE WAS TOO HEAVY TOOK WEIGHT OFF TO BE IN SPEC 2.5 AND 2.5

Labor: **\$300.00** Parts: **\$0.00** OL&M: **\$0.00** Misc: **\$0.00** Sub-Total: **\$300.00**

JGEN15- Retail

COMPLAINT:

18 MULTI POINT COUPLER-- UPPER RIGHT HAND COUPLER SNAP RING NOT GOING IN PLACE