

**rb** **RITCHIE BROS. Diagnostic Report**  
Auctioneers™

**2010 International DuraStar 4300**

Test Information	
<b>Engine</b>	International DT466/Maxxforce DT (7.6)
<b>Engine Serial</b>	INT *466224240711696M07*5001779726--
<b>VIN</b>	<a href="#">1HTMNAAL5AH190319</a>
<b>Driveline</b>	Class 6 4x2
<b>Body</b>	Truck MDHD: Conventional
<b>Test Time</b>	May 25, 2026, 2:47 p.m.
<b>File Length</b>	34.002 s

Usage		
Label	Value	Units
Engine Odometer	70,493	mi
Odometer (Instrument Cluster #1)	70,630	mi
Engine Total Hours of Operation	11,377.35	h

Engine On/Off
Engine running

Check Engine Light
No check engine lights on

Emissions Deleted/Tampered
No

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Failure	1
Previous	Instrument Cluster #1	Source Address 3	Abnormal Update Rate	1
Previous	Body Controller	Tractor Rear High Mounted Work Lights	Current Below Normal	126
Previous	Body Controller	Manufacturer Assignable SPN	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	12
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	13
Previous	Body Controller	Cab HVAC Recirculation Door Control Actuator	Erratic, Intermittent, or Incorrect	4
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	14
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	16
Previous	Body Controller	Source Address 0	Data Error	3
Previous	Body Controller	Source Address 228	Special Instruction	2
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	11
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	126